

Date/Time: 26.12.2017 10:21

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC No 305100729

CUSTOMER
R/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)

REGN NO: SHA7678Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 23.12.2017 10:20
YR OF MANU. 28.05.2015	TARGET DATE
CHASSIS CODE KMHLB41UMFU069204	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 23.12.2017
NATURE: 3P 23.12.2017

S/NO LABOR CODE DESCRIPTION

ALA - taxi Rear damage
Lick/Kilim -

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA7678Z
LARRY

Vehicle No.: SHA7678Z

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard