

ASS. REC. BY:

REF:

CS3/AIG17024452/Wd312

DAR 2 days

Special Insurance:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

11:17am @ 27/12/17

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SV 7303X

Insured:

SKX 2365C

at Workshop m/s

King's Auto Air Conditioning Service

Tel:

6457 8629

of B/k 176 Sin Ming Drive #02-10

Policy No:

Claim No:

2276917172SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/12/17

CA / REV / REP. / REV 24 HRS

lupr

H.O.D. Endorsement:

Date/Time:

11:48am @ 27/12/17

Person Contacted:

Anne

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SV 7303 X-CC3/AIG10067628/Fa2f2q2

D.O.A.: 16/04/2010

PRS

REP

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To report Vehicle No: **STV 7303 X**
 Workshop No: **King Auto**
176, Sun King Drive #02
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

NS	OS

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Back Market Value: _____
 DAD Accident Report Consistent? Yes or No
 DAD PR Report Consistent? Yes or No
 Est. Repairs **5** days Res Yes or No
 Lump Sum: _____ Val Yes or No
 CA / REV / REP / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

Vehicle No: **STV 7303 X** Page: **10**
 Type: **M.Capt / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or
 Make: **Hyundai Avante** 1591
 Colour: **Silver** Insured / Std / Nil / NA
 Sp. Reading: **122901** Insured / Std / Nil / NA
 Engine: _____
 Chassis: **KMH DU 413MAU962570**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Mod: **Nil / S/Rim / STD A.Rim** or
 Tyre Size: **F: 195/60 R15**
R: 195/60 R15
 BS: **DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**
 TOYO / YOKO or **Wentok (R)**
Kinney (R)
 Front
 P Bal: **4** R Bal: **4**
 L Bal: **4** L Bal: **4**
 D.C.A: **20**
 Survey held at: **As Above**
 Des of Damages: **Fr / Rear / O/S / N/S / U/C / Rooftop** or
Right Front
 The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction
27/12/17
11/1/18 **No Accident Report Given**
Submit DAR report.

RECEIVED 11 APR 2018

Date Time File Pass: ☐ : Prel. Report
☐ : Final Report
 Date Time File Return: _____
 Report Format: **DAR**
 Lump Sum / I.B: _____
 Days Of Repair: **5**
 Resurvey No. of Trip: _____
 Add Fee: ☐ Site Insp \$
☐ Inter. evl \$
☐ Tech. Ins. \$
☐ Demans \$
 Survey Fee: **180**
 Transportation: _____
 I.B + A.R: _____
 P.M.S: _____
20
200

- FW: Re:Our Ref: L.17.1896.AT// PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX2365C AND SJV7303X ON 16/12/2017

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Wednesday, 27 December, 2017 11:17:58 AM
Attachments:  [img-Z26154649.pdf](#)

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Wednesday, December 27, 2017 8:59 AM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Fan, Winnie-LW
Subject: Re:Our Ref: L.17.1896.AT// PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX2365C AND SJV7303X ON 16/12/2017

Dear Sirs

We confirm that you have **objected** to our client's list of surveyors. Our client's vehicle is at the following address:

**King's Auto Air-conditioning Service
Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721**

Tel: 6457 8629

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards
Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJV7303X		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HYUNDAI		
Vehicle Model :	AVANTE 1.6 AT ABS D/AB 2WD 4DR		
Chassis No. :	KMH DU41BMAU962570		
Propellant :	Petrol		
Engine No. :	G4FC9U797563		
Engine Capacity :	1591 cc		
Maximum Power Output :	89.7 kW (120 bhp)		
Maximum Laden Weight :	1760 kg		
Unladen Weight :	1264 kg		
Year Of Manufacture :	2009		
Original Registration Date :	08 Feb 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$19,989.00		
COE Expiry Date :	07 Feb 2020		
Road Tax Expiry Date :	07 Aug 2018		
PARF Eligibility Expiry Date :	07 Feb 2020		
Inspection Due Date :	07 Feb 2019		
Intended Transfer Date :	11 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4663Z
Vehicle Details	
Vehicle No.:	SJV7303X
Vehicle to be Exported:	No
Intended De-registration Date:	11 Apr 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U797563
Chassis No.:	KMH DU41BMAU962570
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,513.00
Original Registration Date:	08 Feb 2010
First Registration Date:	08 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$11,513.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2020
PARF Rebate Amount:	\$6,332.00
Intended COE Rebate Details	
COE Expiry Date:	07 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$19,989.00
COE Rebate Amount:	\$3,645.00
Total Rebate Amount:	\$9,977.00

The information contained herein is correct as at 11 Apr 2018

OK

Condition (CON)

(01) Bent (2) Dented (3) Disarmed (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Stuffed (9) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (7)
(4) Not Consistent (NC)

Aug 2015

Vehicle No: SJV T303 X

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper	DD ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer (RH):	NEW		
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy	SRV		
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
		Frt RH Fender	DD ✓		
		Frt Lower Grille	DD ✓		
		Frt RH Ring	SRV		
		Frt Bonnet	R		

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

5 Days
Repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Edit Reg		27 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ONG HUN GIAP , Co. Reg. No.: -									
Main Claimant: YEONG SIEW CHONG									
Vehicle Reg. No.: SJV7303X		Date of Loss: 16/12/2017 00:00 - :59 [94 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2276917172SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SKX2365C		Policy No. (Claimant):							
		Excess:							
Repairer: King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 12/04/2018]									
Claimant's Solicitor: Kuru & Co									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (04/04/2018): NO TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV7303X (2276917172SG)
 [SKX2365C]
 TP
 YEONG SIEW CHONG
 Dec 16 2017 12:00AM
 [ONG HUN GIAP]
 King's Auto Air-Conditioning Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	10/04/18 16:46	Odometer Reading														Load JPG				
2	10/04/18 16:46	General View														Load JPG				
3	10/04/18 16:46	General View														Load JPG				
4	10/04/18 16:46	Chassis Number														Load JPG				
5	10/04/18 16:46	General View														Load JPG				
6	10/04/18 16:46	General View														Load JPG				
7	10/04/18 16:46	General View														Load JPG				
8	10/04/18 16:46	General View														Load JPG				
9	10/04/18 16:46	General View														Load JPG				
10	10/04/18 16:46	General View														Load JPG				
11	10/04/18 16:46	General View														Load JPG				
12	10/04/18 16:46	General View														Load JPG				
13	10/04/18 16:46	General View														Load JPG				
14	10/04/18 16:46	General View														Load JPG				
15	10/04/18 16:46	General View														Load JPG				
16	10/04/18 16:46	General View														Load JPG				
17	10/04/18 16:46	General View														Load JPG				
18	10/04/18 16:46	General View														Load JPG				
19	10/04/18 16:46	General View														Load JPG				
20	10/04/18 16:46	General View														Load JPG				
21	10/04/18 16:46	General View														Load JPG				
22	10/04/18 16:46	General View														Load JPG				
23	10/04/18 16:46	General View														Load JPG				
24	10/04/18 16:46	General View														Load JPG				
25	10/04/18 16:46	General View														Load JPG				
26	10/04/18 16:46	General View														Load JPG				
27	10/04/18 16:46	General View														Load JPG				
28	10/04/18 16:46	General View														Load JPG				
29	10/04/18 16:46	General View														Load JPG				
30	10/04/18 16:46	General View														Load JPG				
31	10/04/18 16:46	General View														Load JPG				
32	10/04/18 16:46	General View														Load JPG				
33	10/04/18 16:46	General View														Load JPG				
34	10/04/18 16:46	General View														Load JPG				
35	10/04/18 16:46	General View														Load JPG				
36	10/04/18 16:46	General View														Load JPG				
37	10/04/18 16:46	General View														Load JPG				

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 15:03	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17024452/WD3E2

Date: 13/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJV7303X

Insured Vehicle No : SKX2365C

Date of Loss: 16/12/2017

Nature of Claim: TP

Claim No: 2276917172SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJV7303X

Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)

Engine No: G4FC9U797563

Reg. Date: 08/02/2010 (Man. Year: 2009)

Chassis No: KMHDU41BMAU962570

Colour: Silver

Odometer: 122901 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side: Hankook 4 mm

Rear Left Side:

Kinergy 4 mm

Front Right Side: Hankook 4 mm

Rear Right Side:

Kinergy 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/12/2017

Date Inspected: 27/12/2017 Inspected At:

King's Auto Air-Conditioning Service (HQ)
Block 176 Sin Ming Drive, #02-10
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER SIDE RETAINER (RH)	Necessary	0.00 F	*- F
3	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
4	1		*FRT RH FENDER	Dented	0.00 F	*- F
5	1		*FRT LOWER GRILLE	Distorted	0.00 F	*- F
6	1		*FRT RH RIM	Scratched	0.00 F	*- F
7	1		*FRT BONNET	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >