

22/03/2002

ASS. REC. BY:

REF: CS3/MSG17024457/R1d37

Special Instructions: Range

SPECIALTY:

ASSIGNMENT (Office)

Menimen

From (Person): Christina Wong of MSIG Date/Time: 26/12/17 @ 4:23pm

Estimated Cost: Bill to:

OD: TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBM 1603L Insured: FBJ 2447E

at Workshop m/s Hua chin (2000) Tel: 689 666 19

of 50, Bkt Batok street 23 # 02-02

Policy No: MSD/VM7/17-98 3362 Claim No: MSC/V/17-001985

Sum Insured: Excess:

Make of Veh: D.O.A. 18/12/17

(Client's Record)

(wp)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:09am @ 27/12/17 Person Contacted: Mr. Lim Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	FBM 1603L-X
	FBJ 2447E-X
	Demantle: 26/1/2018

Pram

REF: MS16

62926

cc: July 2027

ASSIGNMENT

From: Date 23/01/2018

Van No: FBM 1603L Mr. Pagn: 2017 July

Estimated Cost:

Type: M/Car / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: FBM 1603L

Make: HONDA 400X M

cc: 399

at Workshop in: Hua chin (2006) Trading Motor

Colour: Red

A.O. Insured / Std / NI / NA

of 50, Bkt Batok St. 23 #02-02

Sp. Reading: 5369

T. Radio: Insured / Std / NI / NA

Insured

Eng. No:

Policy No:

O. No: NC471200/63

Claims No:

Gen. Cond: Good / ☒ Poor / Burnt

Sum Insured:

Excess:

Steering: In order / ☒ Jammed / Leaked / Burnt or

(Client's Record)

68966619 @ Mr. Lim

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / ☒ STD A/Rim or

(Policy Condition)



Remark: The veh. had commenced its repair at the time of inspection.

Tyre Size: F: 120/70ZR17

R: 160/60ZR17

BS ☒ / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bel. or Market Value:

Front

Rear

IDAO Accident Rpt: Consistent? : Yes or No

R/Bal: 4 mm

R/Bal: 4 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal: mm

L/Bal: mm

Est. Repairs: 3 (days) Res: Yes or No

D.O.A: 18/12/17

D.O.I: 23/01/18

Lum Sum: % 3 Val: Yes or No

Survey held at: Hua chin

CA / REV / REP. / 24 HRS 'wp

Des. of Damages: Frt / Rear ☒ / N/S / UIC / Rooftop or

Date

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction:

* Repair Estimate : S\$ ~~4500~~ 5500
1.5K to 2K.

RECEIVED 02 MAY 2018

* 3 days

Date/Time File Pass to:

☐

: Preli. Report

Days Of Repair: 3

File

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time File Return to:

Survey Fee

Transportation

File

Add Fee:

☐

Site Insp: S

☐

Interview: S

☐

Test: S

☐

Lab: S

Report Format:

PRS

Lump Sum / KB: S

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017		26 Dec 2017 16:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YEOW HIONG S/O RAMZAN ALI, ID: S1194268G		
Main Claimant:	MOHD SAMAT BIN BANGI, ID: S1596292E		
Vehicle Reg. No.:	FBM1603L	Date of Loss:	18/12/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-983362 Coverage: 05/06/2017 - 04/06/2018
Vehicle Reg. No. (Insured):	FBJ2447E	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533
TEL: 62252355 FAX: 62279913

YOUR REF: FBJ 2447 E

22 December 2017

OUR REF: MAB/10644/17/ana

YEOW HIONG S/O RAMZAN ALI
Blk 28 Marsiling Drive
#07-265
Singapore 730028**URGENT**

Dear Sir

CLAIMANT: MR MOHD SAMAT BIN BANGI
ACCIDENT INVOLVING FBJ 2447 E & FBM 1603 L ALONG JURONG WEST STREET
51 HEADING TOWARDS JURONG WEST AVE 1 ON 18/12/2017 AT ABOUT 5.55 PM

We are instructed by *Mr Molid Samat Bin Bangi*, the owner of motorcycle no. FBM 1603 L, to notify you of a road traffic accident on the 18/12/2017 at about 5.55 pm involving our client's vehicle registration no. FBM 1603 L and vehicle registration no. FBJ 2447 E ridden by you/your rider at the material time. A copy of the Traffic Police Report lodged by our client is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you or your insurer within the stipulated timeline, our client shall proceed to repair the vehicle further reference to you.

Yours faithfully



Enc

cc. Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01, SGX Centre 2
Singapore 068807
Your Ref: FBJ 2447 EFAX & MAIL
6225 7402**URGENT**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2017 10:34
Date Of Accident	18/12/2017 17:55
Exact Location Of Accident	JURONG WEST ST 51
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM1603L
Insured/Policyholder	
Name Of Registered Owner	MOHD SAMAT BIN BANGI
NRIC No	S1596292E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97876335
Alternative Phone No	Office-97876335

Vehicle Particulars

Manufacturer	HONDA
Model	MOTOR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/17-984934-WTT
Cover Note Number	

Driver

Name of Driver	MOHD SAMAT BIN BANGI
NRIC No	S1596292E
Date Of Birth	02/02/1963
Occupation	INDOOR
Date Of Driving Pass	02/09/1987
Driving Experience	30 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97876335
Fax Number	
Contact Number	OFFICE-97876335
E-Mail Address	NOEMAIL

Address	BLK 413 JURONG WEST ST 42 #04-817
Postcode	640412
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG WEST NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ2447E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	RIDER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM1603L
Were seat belts worn?	

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Reporting Centre
Tel: 6590 6332 Fax: 6599 0722
Name: Email: vacbb@singnet.com.sg
NRIC/FIN No.:

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is a vertical margin line on the left side, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled sheet of paper.

I/We declare the foregoing particulars are true in every respect.

Wp/12/17

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Reporting Officer: Mr. S. G. LEE
Name: Mr. S. G. LEE
Email: vacbb@singnet.com.sg
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171219/2004

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3
Report No. T/20171219/2004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/12/2017 01:17	Vide Report No.:	Station Diary No.: 9
--	------------------	-------------------------

Informant's Particulars

Name of Informant: MOHD SAMAT BIN BANGI			Address: APT BLK 413 JURONG WEST STREET 42 #04-817 SINGAPORE 640413	
ID Type / ID No.: NRIC NO / S1596292E			Contact No.: Home/Office: Mobile: 97876335	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 54	Date of Birth: 02/02/1963	Type of Informant: Rider	
Race: Boyanese			Language:	Institution / School Name:
Occupation: WAREHOUSE ASSISTANT			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/12/2017 17:55	Type of Location: Straight Road
Location: Along Road 1 JURONG WEST STREET 51 JURONG WEST ST 51 HEADING TOWARDS JURONG WEST AVE 1				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ2447E	Motorcycle	YAMAHA	FZ 16	Black	Slightly Damaged	0
FBM1603L	Motorcycle	HONDA	400X MANUAL	Red	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM1603L	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60756130	28/07/2017	27/07/2018

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20171219/2004

2 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20171219/2004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHD SAMAT BIN BANGI	ID No.	S1596292E
Related Vehicle	FBM1603L (Motorcycle)	Contact No.	97876335
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	18/12/2017	Date Discharge	18/12/2017
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 18/12/17 at 1756hrs I was driving a red Honda FBM1603L along Jurong West St 51 heading towards Jurong West Ave 1 on the left most lane on a 2 lane road. The traffic light showed red light thus, my motorcycle was parked and not in motion behind 2 vehicles. I suddenly felt an impact on my left rear and I fell to the side with my motorcycle. I then observed that another motorcycle a black Yamaha FBJ2447E had collided against me and had hit my left leg. My motorcycle suffered slight scratches.

Traffic police and ambulance was not at scene. I then went to Ng Teng Fong General Hospital as my left leg had become swollen. I then received medical certificate for 4 days from 19/12/2017 to 22/12/2017.

I do not have any dash camera recording the accident. I would like to state that the motorcyclists of FBJ2447E refused to provide me his NRIC and mobile number.



**SINGAPORE
POLICE FORCE**



T/20171219/2004

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20171219/2004

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 SITI KHAIRUNNISA BINTE RAMANAH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt LEE SOON LYE

Contact No.: 65476239

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

19/12/2017 01:17

Classification Of Case:

Singapore Police Force

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6292E
Vehicle Details	
Vehicle No.:	FBM1603L
Vehicle to be Exported:	No
Intended De-registration Date:	02 May 2018
Vehicle Make:	HONDA
Vehicle Model:	400X MANUAL
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	NC47E1200164
Chassis No.:	NC471200163
Maximum Power Output:	-
Open Market Value:	\$7,582.00
Original Registration Date:	28 Jul 2017
First Registration Date:	28 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$2,041.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,851.00
COE Rebate Amount:	\$5,402.00
Total Rebate Amount:	\$5,402.00

The information contained herein is correct as at 02 May 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Dec 2017		26 Dec 2017 16:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YEOW HIONG S/O RAMZAN ALI, ID: S1194268G		
Main Claimant:	MOHD SAMAT BIN BANGI, ID: S1596292E		
Vehicle Reg. No.:	FBM1603L	Date of Loss:	18/12/2017 00:00 - :59 [4 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/17-001985	Policy/Cover Note No.:	MSD/VMT/17-983362 Coverage: 05/06/2017 - 04/06/2018
Vehicle Reg. No. (Insured):	FBJ2447E	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 27/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM1603L (MSC/V/17-001985)**
[FBJ2447E]




































TP
















MOHD SAMAT BIN BANGI

Dec 18 2017 12:00AM

[YEOW HIONG S/O RAMZAN ALI]

Hua Chin (2000) Trading Motor Service Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 16:46	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/04/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/04/18 16:46	General View	 Load JPG	✓
37	06/04/18 16:46	General View	 Load JPG	✓
38	06/04/18 16:46	General View	 Load JPG	✓
39	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
40	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
41	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
42	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
43	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
44	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
45	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
46	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
47	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
48	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
49	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
50	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
51	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
52	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
53	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
54	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
55	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
56	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
57	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
58	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
59	02/05/18 14:05	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 16:15	PRI	 Load PDF	
2	26/12/17 16:24	FBM1603L GIA Rpt	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17024457/R1D3S2
Date: 03/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMT/17-983362
Claimant Vehicle No: FBM1603L Insured Vehicle No: FBJ2447E
Date of Loss: 18/12/2017 Nature of Claim: TP Claim No: MSC/V/17-001985

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM1603L Engine No: NC47E1200164
Make & Model: HONDA 400X, 399cc Chassis No: NC471200163
Reg. Date: 28/07/2017 (Man. Year: 2017) Odometer: 5369 km
Colour: Red
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70ZR17 Rear Tyre Size: 160/60ZR17
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/12/2017
Date Inspected: 23/01/2018 Inspected At: Hua Chin (2000) Trading Motor Service Centre (HQ)
50 BUKIT BATOK STREET 23, #02-02 MIDVIEW
BUILDING
Singapore 659578
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/3/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$2,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 May 2018)	
Parts:	N/A	HONDA 400X 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM1603L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >