

PDI TUAS

PDI TUAS

SHARON NATASHA THAM WY-LING
344 YISHUN AVENUE 11
#01-161
Singapore, 760344
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV020105
Quote No. SER/QUO/1702110
QuoteDate 21/12/17
Salesperson Daniel Tan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF MATCH 1.4 TSI (DSG)	29,346	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKG5755E	WVWZZZ1KZDW034764	20/09/12	Daniel Tan
Engine Code	Labor Type	Engine No.	Model Code
	1K	CAX C09743	5K12G5

No.	Description	Qty.	UoM	Unit Price	Amount
P D&P ALEX LABOUR	LABOUR	2	UNIT		420 1,680.00
P D&P ALEX PAINT	SPRAY PAINT	2	UNIT		400 1,600.00
P D&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P D&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				4,040.00
P 5K0857508AE9B9	WING MIRROR HOUSING RH	1	Pieces		DE 802.90
	Predecessor 5K0857508T 9B9				
P 5K0857522D	MIRROR GLASS RH	1	Pieces		CRA 230.55
P 5K0857538 GRU	MIRROR COVER RH	1	Pieces		SD 127.38
	Use Predecessor 6R0857538 GR				
	Sum Item				1,160.83

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Explanations

Acknowledged by Repairer

P = Proportionately Charged

Signature:

Date:

Payment Terms

No Credit

Sum Labor 4,040.00
Sum Item 1,160.83

Total SGD 5,200.83
7% GST 364.06
Total SGD Incl. GST 5,564.89

Payments to:

- BBN: - Acc.-No.: