

SIGNALY:

Menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time: 26/12/17 @ 6.43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ 3782K

Insured:

SLT8060 B

at Workshop m/s

MG Solution

Tel:

91886931

of 2 Kaki Bukit ave 4 #02-03 B

Policy No:

A28966571MKF

Claim No:

542401

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/12/2017

CA / REV / REP. / REV 24 HRS

28/12/17

H.O.D. Endorsement:

Date/Time:

9.53am @ 27/12/17

Person Contacted:

Ms. Honey

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJ 3782K - NS3/INCH001568/K1bs4

D.O.A : 23/01/2017

SLT8060 B-x

29/12/17 @ 3.40pm Informed Elaine Ngu, we are pending for estimate from repairer.

01/3/18 @ 3.45pm revised to Elaine Ngu via Menmen.

LS \$4500, 9 days (Red \$18494.04, 80%)

REF:

ASSIGNMENT

10/09/08

2008 Sept

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJ13782K Yr Regn: 2008 SeptType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: chevrolet chevrolet Aveo 1399Colour: silver A/C: Insured / Std / NI / NASp. Reading: 148566 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: KLISA69719B267521Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 28/12/17Survey held at: M6 SolutionDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16

MV: 10.51K

PV: 6K

Nett: 4.51K

RECEIVED 02 MAR 2010

Date/Time, File Pass to?

☐

Preli. Report

1) 07/13 final

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)☐ B-RS (\$)

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B. (\$)

MER-TP

4500

300

10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2017		26 Dec 2017 18:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GREAT AUTO, Co. Reg. No.: 53289146E		
Main Claimant:	ONG SOK NGOR, ID: S1785826B		
Vehicle Reg. No.:	SJJ3782K	Date of Loss:	22/12/2017 12:00 - :59
Claim Type:	TP / 542401	Policy/Cover Note No.:	A28966571MKF (Third Party Only) Coverage: 05/06/2017 - 04/06/2018
Vehicle Reg. No. (Insured):	SLT8060B	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/12/2017]		
Driver/Custodian (Insured):	MAHMUD BIN OMAR (), NRIC: S1714135Z, Tel: +6590589445		
Adj Asg. Remarks:	REQUEST ADRIAN LING TO SURVEY		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024461/Aqd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 8060B	Veh. Inspected	SJJ 3782K
Policy No.	A28966571MKF	Coverage (\$)	0.00
Claim No.	542401	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/12/2017	Inspection Date
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: *CS/MSG/7074461/Agd 3*
 Policy Type: OD / TP / TP RES / TL / EVA

SSJ 3782K

Case Handler

Typist

Admin (*Nirv*): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	☒			
C	Customer Code	☒			
N	Assign From	☒			
C	Assign Date	☒			
C	Veh No (Inspected)	☒			
C	Veh No (Insured)	☒			
C	D.O.A	☒			
C	Policy No	☒			
C	Claim No	☒			
C	Insurance Authorisation (CA /REV/REP)	☒			
C	Report Type	☒			
C	Weekend Charges	☒			
N	Survey held at/Repairer	☒			
C	Excess				

Surveyor (*Adrian*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	☒			
C	Regn Month/Year	☒			
N	Vehicle Type	☒			
N	Make & Model	☒			
C	Engine Capacity. (C.C)	☒			
N	Colour	☒			
C	Odometer. (Sp.Reading)	☒			
C	Chassis No	☒			
N	General Condition	☒			
N	Steering	☒			
N	Brake	☒			
N	Modification (Modi)	☒			
C	Tyre Size	☒			
N	Tyre Make	☒			
C	Tyre Balance	☒			
C	Date of Inspection	☒			
N	Survey held	☒			
N	Des.of Damages	☒			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	☒			
---	--------------------------------------	-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	☒			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	☒			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	☒			
---	-------------------------	-------------------------------------	--	--	--

Check By: *[Signature]* *01/3/18*
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 01 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLT8060B	Accident Date	: 22/12/2017
TP Vehicle No	: SJJ3782K	Assignment Date	: 26/12/2017
Make	: CHEVROLET AVEO	Est. Duration of Repair	: 9
Date of Inspection	: 28/12/2017		
Inspection At	: MG Solution		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,994.04
Revised Amount	:S\$	13,213.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,213.32
Lump Sum Repair	:S\$	4,500.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,500.00
COE / PARF Rebate	:S\$	5,984.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,516.00

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 29 December, 2017 3:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJJ 3782K (YOUR REF: 542401)

This mail is associated with :

***SJJ3782K (542401)**

[SLT8060B]

TP

ONG SOK NGOR

Dec 22 2017 12:00PM

[GREAT AUTO]

MG Solution Pte Ltd

Dear Elaine,

Please be informed that we have inspected the vehicle SJJ 3782K on 28/12/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5826B
Vehicle Details	
Vehicle No.:	SJJ3782K
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	CHEVROLET
Vehicle Model:	AVEO 1.4AUTO TH
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	F14D36874401
Chassis No.:	KL1SA69719B267521
Maximum Power Output:	69.0 kW (92 bhp)
Open Market Value:	\$10,641.00
Original Registration Date:	10 Sep 2008
First Registration Date:	10 Sep 2008
Transfer Count:	3
Actual ARF Paid:	\$10,641.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2018
PARF Rebate Amount:	\$5,320.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$9,501.00
COE Rebate Amount:	\$664.00
Total Rebate Amount:	\$5,984.00

The information contained herein is correct as at 28 Dec 2017



Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

 Username / Email Add

 password

[Sign Up New Account](#)
[Forgot Password](#)

[Advanced Search](#)

Used Car Comparison

— Comparing 3 Vehicles —

Chevrolet Aveo 1.4A

Chevrolet Aveo5 1.4A

Chevrolet Aveo 1.4A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to see to compare.

CAR DETAILS

Price	\$9,900	\$12,800	\$9,800
Instalment	\$883	\$837	\$997
Registration Date	16-Sep-2008	23-Dec-2008	28-Jul-2008
Manufactured	2008	2008	2007
Mileage	-	117,766 km	-
Transmission	Auto	Auto	Auto
Engine Cap	1,399 cc	1,399 cc	1,399 cc
Road Tax	\$626 /yr	\$626 /yr	\$626 /yr
Power	69.0 kW (92 bhp)	69.0 kW (92 bhp)	69.0 kW (92 bhp)
Curb Weight	1,115 kg	1,135 kg	1,135 kg
Features	-	1.4L DOHC Engine, 4 Speed Automatic Transmission, SRS Airbags, ABS, Reverse Sensors, Knockdown Rear Seats.	-
Accessories	-	Factory Fitted Audio System, Blind-spot Mirrors, Spoiler.	-
Description	Most Value Buy! Well Maintained, Original Stock Condition, Neat And Clean Interior, No Repair Needed, Come With Spacious Boots Space. Call Now!	Interest From As Low As 1.99%! Just 1 Owner! Very Low Mileage! Value For Money! Extended Warranty Available! Choice Of Leather Seats / Sports Rims! Well Maintained In Excellent Condition, Test Drive To Feel It! A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Drop By Our Aircon Showroom To Appreciate It In Pristine Condition Today!	\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need Guarantor Or Minimum Income! Fast And Easy Loan Approval! High Loan Or Over Trade Welcome! All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics.
COE	\$9,501	\$7,721	\$14,101
OMV	\$10,109	\$11,636	\$11,650
ARF	\$10,109	\$11,636	\$11,650
Depreciation	\$6,780 /yr	\$7,100 /yr	\$6,880 /yr
No. of Owners	4	1	1
Type of Vehicle	Sedan	Hatchback	Sedan
Category	PARF Car	PARF Car	PARF Car, Premium Ad Car
Availability	Available	Available	Available

SELLER INFORMATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 15:40
Date Of Accident	22/12/2017 12:00
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE LOR 6 TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ3782K
Insured/Policyholder	
Name Of Registered Owner	ONG SOK NGOR
NRIC No	S1785826B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91916967
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	CHEVROLET
Model	AVEO-1.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088407644
Cover Note Number	

Driver

Name of Driver	LIM SHENG HUI
NRIC No	S9208698D
Date Of Birth	15/03/1992
Occupation	OUTDOOR
Date Of Driving Pass	23/07/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97552888
Fax Number	
Contact Number	
Email Address	DAVIDLIM1992@HOTMAIL.COM

Address	BLK 304 UBI AVE 1 #03-123
Postcode	400304
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 22/12/2017 AT ABOUT 1200HRS AT ALONG PIE TOWARDS CHANGI BEFORE LOR 6 TOA PAYOH EXIT. I WAS TRAVELLING ON THE EXTREME RIGHT LANE AND WHEN MY FRONT VEHICLE SLOW DOWN AND STOP DUE TO HEAVY TRAFFIC HENCE I FOLLOW SUIT AND CAME TO A COMPLETE STOP. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND THE GREAT IMPACT FORCED MY VEHICLE (A) FORWARD AND HIT ONTO THE REAR PORTION OF VEHICLE (C). WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. IT WAS A CHAIN COLLISION OF TOTAL 8 VEHICLES INVOLVED. I HAVE 4 PASSENGERS INSIDE MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PLEASE GET FROM WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLT8060B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SDR9378J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKE8453S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLQ5369Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SJF4396G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SHB4628H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number SDM7882J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PASSENGER 1

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJJ3782K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name PASSENGER 2

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJJ3782K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name PASSENGER 3

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJJ3782K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the basis of the insured's contention.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and not claim in the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim including the settlement of my claims and any subsequent investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); or
 - (v) complying with applicable laws with managing processing, storing, transfer and/or use of my personal data for the purpose(s).
- (b) I (Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (c) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (d) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (e) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (f) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (g) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (h) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (i) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (j) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (k) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (l) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (m) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (n) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (o) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (p) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (q) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (r) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (s) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (t) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (u) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (v) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (w) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (x) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (y) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;
- (z) I (my Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, including permitted third parties, subsidiaries and assigns my Insurers' information for the purpose(s) stated in (a) above;

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Insuring Dealer/Personnel's Signature
Name:
NRIC/N No.:

Sketch Plan Pg. 2

SKETCH PLAN

PTE towards Changi before Lor 6 Toa Payoh



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/12/2017 at about 1200 hrs at along PTE towards Changi before Lor 6 Toa Payoh Exit. I was travelling on the extreme Right Lane and when my front vehicle slows down and stop due to heavy traffic hence I follow suit and came to a complete stop. Suddenly I heard a loud bang from behind and the great impact forced my vehicle (A) forward and hit onto the Rear Portion of Vehicle (C). When I alighted, I realised that it was Vehicle (C) who hit onto my Rear Portion of my vehicle (A) causing damages to my vehicle. It was a chain collision of total 8 vehicles involved. I have 4 passengers inside my vehicle.

DECLARATION

I/we declare the foregoing particulars are true and correct.

Policeholder's signature
Date & Time:

Driver's signature
If driver is not the policeholder
Date & Time:

Reporting Centre Personnel signature
Name:
Date & Time:

[Signature]

Sketch Plan Pg. 3

SKETCH PLAN

Handwritten sketch of a road layout with a large 'X' and a curved line.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten list of vehicle details:

- (A) SJJ 3782K
- (B) SLT 8060 B
- (C) SDR 9378 J
- (D) SKE 8453 S
- (E) SLG 5369 Y
- (F) SJF 4396 G
- (G) SHB 4628 H
- (H) SDM 7882 J

Handwritten signature 'LA' and a large curved line.

DECLARATION

(We declare the foregoing contents are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
National No.:

Handwritten signature: L. Smart

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: MSIG INSURANCE	DATE	: 26/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJJ3782K		
MODEL	: CHEVROLET AVEO 1.4A		
CHASSIS NO			KLISA69719B267521
<u>ACCIDENT DETAILS</u>		DATE	: 22-Dec-17
		TIME	: 12:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>Detached</i>	1	\$ 1,815.00	\$ 1,815.00
2	FRONT BUMPER <i>Detached</i>	1	\$ 1,022.00	\$ 1,022.00
3	FRONT BUMPER SIDE RETAINER	2	\$ 47.00	\$ 94.00
4	FRONT BUMPER SPONGE <i>cut</i>	1	\$ 242.00	\$ 242.00
5	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 697.00	\$ 697.00
6	FRONT BUMPER LOWER GRILLE <i>New</i>	1	\$ 370.00	\$ 370.00
7	FRONT NUMBER PLATE GARNISH <i>Detached</i>	1	\$ 130.00	\$ 130.00
8	CENTER GRILLE <i>from New</i>	1	\$ 349.00	\$ 349.00
9	CENTER GRILLE CHROME <i>cut</i>	2	\$ 98.00	\$ 196.00
10	CENTER GRILLE LOGO <i>New</i>	1	\$ 62.00	\$ 62.00
11	HEADLAMP <i>cracked</i>	2	\$ 655.00	\$ 1,310.00
12	FRONT SUPPORT PANEL <i>Rytec</i>	1	\$ 781.00	\$ 781.00
13	AIR CON CONDENSER <i>2 Best</i>	1	\$ 794.00	\$ 794.00
14	RADIATOR <i>2 Best</i>	1	\$ 849.00	\$ 849.00
15	RADIATOR FAN MOTOR <i>New</i>	1	\$ 474.00	\$ 474.00
16	RADIATOR FAN COWLING <i>cut</i>	1	\$ 246.00	\$ 246.00
17	RADIATOR FAN BLADE <i>New</i>	1	\$ 193.00	\$ 193.00

1186

1600

403

18	HORN <i>Ne n</i>	2	\$ 89.00	\$ 178.00	+
19	BOOT LID <i>Distad</i>	1	\$ 728.00	\$ 728.00	—
20	BOOT LID LOGO <i>Ne</i>	1	\$ 55.00	\$ 53.00	—
21	BOOT LID LOCK <i>Rogd</i>	1	\$ 133.00	\$ 133.00	—
22	BOOT LID CATCH <i>Ne n</i>	1	\$ 79.80	\$ 79.80	+
23	BOOT LID KEYLOCK <i>Ne n</i>	1	\$ 166.00	\$ 166.00	+
24	BOOT LID HINGE <i>Ne n</i>	2	\$ 89.00	\$ 178.00	+
25	BOOT LID WEATHER STRIP <i>ut</i>	1	\$ 155.00	\$ 155.00	—
26	BOOT LID INSULATOR <i>ne n</i>	1	\$ 133.00	\$ 133.00	+
27	REAR BUMPER <i>Distad</i>	1	\$ 968.00	\$ 968.00	—
28	REAR BUMPER SIDE RETAINER <i>Ne n</i>	2	\$ 62.40	\$ 124.80	—
29	REAR BUMPER REINFORCEMENT <i>Distad</i>	1	\$ 556.00	\$ 556.00	383
30	REAR BUMPER REINFORCEMENT SIDE BRACKET <i>Ne n</i>	2	\$ 133.00	\$ 266.00	+
31	REAR BUMPER AIR VENT <i>Ne n</i>	2	\$ 79.00	\$ 158.00	+
32	TAILLAMP <i>culd</i>	2	\$ 566.00	\$ 1,132.00	848.
33	TAILLAMP PANEL <i>Ryir</i>	2	\$ 123.00	\$ 246.00	+
34	REAR NUMBER PLATE LAMP(SET) <i>Ne n</i>	1	\$ 211.00	\$ 211.00	+
35	REAR FENDER INNER TRIM <i>Ne n</i>	2	\$ 312.00	\$ 624.00	+
36	REAR END PANEL <i>Distad</i>	1	\$ 796.00	\$ 796.00	—
37	REAR END PANEL TOP GARNISH <i>Distad</i>	1	\$ 165.00	\$ 165.00	—
38	REAR FLOOR PANEL <i>Ryir</i>	1	\$ 824.00	\$ 824.00	+
39	REAR FLOOR PANEL TOP BOARD <i>Distad</i>	1	\$ 217.00	\$ 217.00	—

11114.8

TOTAL PRICE \$ 17,715.60

10003.32

LESS 10% \$ 1,771.56

SUB TOTAL PRICE \$ 15,944.04

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE Bert	1	\$ 50.00	\$ 50.00
2	BONNET SEALANT Ne n	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER CLIP(SET) Ne	1	\$ 20.00	\$ 20.00
4	FRONT BUMPER LOWER GRILLE CLIP(SET) Ne n	1	\$ 20.00	\$ 20.00
5	CENTRE GRILLE CLIP(SET) Ne	1	\$ 20.00	\$ 20.00
6	FRONT SUPPORT PANEL SEALANT Ne n	1	\$ 80.00	\$ 80.00
7	REAR NUMBER PLATE Bert	1	\$ 50.00	\$ 50.00
8	BOOT LID SEALANT Ne n	1	\$ 80.00	\$ 80.00
9	BOOT LID INSULATOR CLIPS(SET) Ne n	1	\$ 20.00	\$ 20.00
10	REAR BUMPER CLIPS(SET) Ne	1	\$ 20.00	\$ 20.00
11	TAIL LAMP CLIPS(SET) Ne n	1	\$ 20.00	\$ 20.00
12	REAR FENEDR INNER TRIM CLIPS(SET) Ne	1	\$ 20.00	\$ 20.00

13	REAR END PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	60
14	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	10
15	REAR FLOOR PANEL INSULATION <i>new</i>	1	\$ 150.00	\$ 150.00	+
16	REVERSE SENSOR <i>changed</i>	1	\$ 220.00	\$ 220.00	200
440			TOTAL	\$ 950.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,000.00	300	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,000.00	400	
3	WIRING CHECK	\$150.00	30	
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$120.00	x	
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$80.00	x	
6	REFOCUS HEADLAMP BEAM	\$60.00	x	
TOTAL		\$2,410.00	730	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,600.00	900	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,400.00	1000	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 120.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x	
6	TRANSFER BOOTLID MECHANISM	\$80.00	x	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	60	
TOTAL		\$3,690.00	2040	

LKK Auto Consultants hence notify the **ESTIMATE REPORT**:

- To resurvey before/after spray painting
- TOTAL PARTS COST** : \$ 16,894.04
- Parts prices are based on *market*
- TOTAL LABOUR COST** : \$ 6,100.00
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- TOTAL REPAIR COST** : \$ 22,994.04
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

APPROVED DETAILS

SURVEYOR :
Acknowledged by Repairer
Signature:
Date:

Adrian Lim total: 13213.32
 4/s 28/12/17. 4/s: A.S.L.C.
 09 Days.

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024461/AQD3N2

Date: 05/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28966571MKF
Claimant Vehicle No :	SJJ3782K	Insured Vehicle No :	SLT8060B
Date of Loss:	22/12/2017	Nature of Claim:	TP
		Claim No:	542401

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ3782K	Engine No:	F14D36874401
Make & Model:	CHEVROLET AVEO, 1.4 (A)	Chassis No:	KL1SA69719B267521
Reg. Date:	10/09/2008 (Man. Year: 2008)	Odometer:	148566 km
Colour:	Silver		
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,894.04	10,443.32	6,450.72	38.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,100.00	2,770.00	3,330.00	54.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,994.04	13,213.32	9,780.72	42.54
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	22,994.04	4,500.00	18,494.04	80.43
+ GST 7.00/7.00% (S\$)	1,609.58	315.00	1,294.58	80.43
Nett Amount (S\$)	24,603.62	4,815.00	19,788.62	80.43

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 28/12/2017 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2018)
Parts: 143	CHEVROLET AVEO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ3782K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented	1,815.00 FL	*1,196.00 FL
2	1	*FRONT BUMPER	Deformed	1,022.00 FL	*1,022.00 FL
3	2	*FRONT BUMPER SIDE RETAINER	Necessary	94.00 FL	*94.00 FL
4	1	*FRONT BUMPER SPONGE	Cracked	242.00 FL	*242.00 FL
5	1	*FRONT BUMPER REINFORCEMENT	Bent	697.00 FL	*403.00 FL
6	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	370.00 FL	*- FL
7	1	*FRONT NUMBER PLATE GARNISH	Deformed	130.00 FL	*130.00 FL
8	1	*CENTER GRILLE	Not Necessary	349.00 FL	*- FL
9	2	*CENTER GRILLE CHROME	Cut	196.00 FL	*196.00 FL
10	1	*CENTER GRILLE LOGO	Necessary	62.00 FL	*62.00 FL
11	2	*HEADLAMP	Cracked	1,310.00 FL	*1,310.00 FL
12	1	*FRONT SUPPORT PANEL	Repair	781.00 FL	*- FL
13	1	*AIR CON CONDENSER	Bent	794.00 FL	*794.00 FL
14	1	*RADIATOR	Bent	849.00 FL	*849.00 FL
15	1	*RADIATOR FAN MOTOR	Not Necessary	474.00 FL	*- FL
16	1	*RADIATOR FAN COWLING	Cracked	246.00 FL	*246.00 FL
17	1	*RADIATOR FAN BLADE	Not Necessary	193.00 FL	*- FL
18	2	*HORN	Not Necessary	178.00 FL	*- FL
19	1	*BOOT LID	Dented	728.00 FL	*728.00 FL
20	1	*BOOT LID LOGO	Necessary	53.00 FL	*53.00 FL
21	1	*BOOT LID LOCK	Damaged	133.00 FL	*133.00 FL
22	1	*BOOT LID CATCH	Not Necessary	79.80 FL	*- FL
23	1	*BOOT LID KEYLOCK	Not Necessary	166.00 FL	*- FL
24	2	*BOOT LID HINGE	Not Necessary	178.00 FL	*- FL
25	1	*BOOT LID WEATHER STRIP	Cut	155.00 FL	*155.00 FL
26	1	*BOOT LID INSULATOR	Not Necessary	133.00 FL	*- FL
27	1	*REAR BUMPER	Distorted	968.00 FL	*968.00 FL
28	2	*REAR BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
29	1	*REAR BUMPER REINFORCEMENT	Distorted	556.00 FL	*383.00 FL
30	2	*REAR BUMPER REINFORCEMENT SIDE BRACKET	Not Necessary	266.00 FL	*- FL
31	2	*REAR BUMPER AIR VENT	Not Necessary	158.00 FL	*- FL
32	2	*TAILLAMP	Cracked	1,132.00 FL	*848.00 FL
33	2	*TAILLAMP PANEL	Repair	246.00 FL	*- FL
34	1	*SET REAR NUMBER PLATE LAMP	Not Necessary	211.00 FL	*- FL
35	2	*REAR FENDER INNER TRIM	Not Necessary	624.00 FL	*- FL
36	1	*REAR END PANEL	Distorted	796.00 FL	*796.00 FL
37	1	*REAR END PANEL TOP GARNISH	Deformed	165.00 FL	*165.00 FL
38	1	*REAR FLOOR PANEL	Repair	824.00 FL	*- FL
39	1	*REAR FLOOR PANEL TOP BOARD	Deformed	217.00 FL	*217.00 FL
40	1	*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
41	1	*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
42	1	*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
43	1	*SET FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	20.00 FS	*- FS
44	1	*SET CENTRE GRILLE CLIP	Necessary	20.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
47	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*SET BOOT LID INSULATOR CLIPS	Not Necessary	20.00 FS	*- FS
49	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
50	1		*SET TAIL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
51	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
52	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
54	1		*REAR FLOOR PANEL INSULATION	Not Necessary	150.00 FS	*- FS
55	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,665.60	11,554.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,771.56	1,111.48
Total Parts (\$\$)	16,894.04	10,443.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,000.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	WIRING CHECK	New	150.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	-
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	-
6	REFOCUS HEADLAMP BEAM	New	60.00	-
7	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	New	1,600.00	900.00
8	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	New	1,400.00	1,000.00
9	TUFF COAT	New	250.00	60.00
10	WIRING CHECK	New	120.00	30.00
11	CONDUCT WATER LEAKAGE TEST	New	120.00	-
12	TRANSFER BOOTLID MECHANISM	New	80.00	-
13	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
Gross Labour Cost (\$\$)			6,100.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >