

ASS. REC. BY:

REF: CS3/SM017024469/Tld3² range 2 days
Special Instruction:

Surveyor

Tuan Ah.

ASSIGNMENT (Office)

From (Person):

Gracie Teo

of

SMO

Date/Time:

9.25am @ 27/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA5379E

Insured:

PA 9752J

at Workshop m/s

V-Tech Auto

Tel:

62646211

of

No.1 Soon Lee Street #06-04 - 07

Policy No:

Claim No:

CMTD1704670 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp?

02/01/2018

H.O.D. Endorsement:

Date/Time:

2.45pm @ 27/12/17

Person Contacted:

Ms. Chong

Vehicle IN (OUT)

Date/Time

Action/Instruction (X) Estimate

PA5379E - X

PA9752J - X

Tangshan

COS 2020 April

Yen No. PHS 3712 Yr Recd 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Nissan Murano 3.0m cc 2983

Colour White A/C Insured / Std / NI / NA

Sp. Reading 1 T/Radio Insured / Std / NI / NA

Enc/Ne

C/No JN1 164E 4340702392

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order, Jammed / Leaked / Burnt or

Brake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim, or

Tyre Size: F: 145 (R1)

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm

LBal. 6 mm LBal. 6 mm

D.O.A. D.O.I. 242 02/01/18 @ 1110

Survey held at: V-Tech.

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision:

\$5,000 - \$6,000.

☐: Prelim. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: Site Inc: \$

150 王 明

0

Report Format :

Lump Sum / (B) / \$

Interval: 5

722 陈 华

[illegible]

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 27 December, 2017 9:25 AM
To: Sim Teo Koon; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong; Chan, Shu Hui Agnes; Henry, Irene James; 'V-TECH AUTO SERVICE'
Subject: CMTD1704670/GPL - Accident invlg PA9752J & PA5379E on 21.12.2017
Attachments: SAS PA5379E.pdf

Your Reference: JEQ/170983/1217/VT (ZL)
Our Reference: CMTD1704670/GPL

Without Prejudice

Date: 27th December 2017

Attention:
M/S JUSEQUITY LAW CORPORATION

Accident invlg PA9752J & PA5379E on 21.12.2017

Dear Sir/ Madam,

We refer to your email reply dated 26/12/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Tuesday, December 26, 2017 5:16 PM

To: Teo, Grace

Cc: Gnoh, Pau Loong; Chan, Shu Hui Agnes; Henry, Irene James; 'V-TECH AUTO SERVICE'

Subject: RE: CMTD1704670/GPL - Accident invlg PA9752J & PA5379E on 21.12.2017

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. PAL'S APPRAISER PTE LTD
2. LCW APPRAISER PTE LTD
3. MC-COY APPRAISER PTE LTD
4. TREASURE APPRAISAL SERVICES
5. UNITED Appraisal And Management Pte Ltd
6. PROMINENT APPRAISER SERVICES
7. ST APPRAISAL SERVICES
8. AEON AUTO CONSULTANTS LLP
9. CL APPRAISER PTE LTD
10. CONSTANT APPRAISER SERVICES

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

V-Tech Auto Service

No. 1 Soon Lee Street #06-04 to 07

Singapore 627605

Tel : 6264-6211 Fax : 6264-6233

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

Sim Teo Koon

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6488 / 6536 9339
Fax: 6536 5368
E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Tuesday, December 26, 2017 3:27 PM
To: juseq@singnet.com.sg
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1704670/GPL - Accident invlg PA9752J & PA5379E on 21.12.2017

Your Reference: JEQ/170983/1217/VT (ZL)
Our Reference: CMTD1704670/GPL

Without Prejudice
EMAIL ONLY

Date: 26th December 2017

Attention:
M/S JUSEQUITY LAW CORPORATION

Accident invlg PA9752J & PA5379E on 21.12.2017

Dear Sir/ Madam,

We refer to your Notice of Accident dated 26/12/2017.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	

		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2017 10:53
Date Of Accident	21/12/2017 06:50
Exact Location Of Accident	TUAS ROAD - ROUNDABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA5379E
Insured/Policyholder	
Name Of Registered Owner	CHUN YEOW MENG
NRIC No	S1286747F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91804892
Alternative Phone No	OFFICE-91804892

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5038665089-08
Cover Note Number	

Driver

Name of Driver	CHUN YEOW MENG
NRIC No	S1286747F
Date Of Birth	09/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1978
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91804892
Fax Number	
Contact Number	OFFICE-91804892
E-Mail Address	NOEMAIL

Address	BLK 549 CHOA CHU KANG STREET 52 #06-09
Postcode	680549
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - ROUNDABOUT
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : PATRICK RUNAS GENDER: : MALE
Passenger 2	NAME: : LEA NINOBLA GENDER: : FEMALE
Passenger 3	NAME: : NA GENDER: : FEMALE
Passenger 4	NAME: : NA GENDER: : MALE
Passenger 5	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9752J
Vehicle Make/Model/Colour	COACH BUS
Details Of Properties	LEFT FRONT PORTION
Vehicle Category	BUS
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1


Name	PATRICK RUNAS
Approximate Age	
Injuries Sustain	NA
Injured person in which vehicle?	PA5379E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	G5450183N
	NA
Postcode	NA

DETAILS OF INJURED PERSON 2

Name	LEA NINOBLA
Approximate Age	
Injuries Sustain	NA
Injured person in which vehicle?	PA5379E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	G3113487R
	NA
Postcode	NA

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Rectr - police report
7/2017/221/2046

DECLARATION

(Witnesses Sign the following declaration and attach to the police report)

I declare that the above is a true and correct statement of the facts of the accident.
Date & Time:

I declare that the above is a true and correct statement of the facts of the accident.
Date & Time:

I declare that the above is a true and correct statement of the facts of the accident.
Date & Time: RUMAH KUDAT

SKETCH PLAN

I understand, acknowledge, agree and consent that

Signature: Richard M. Wolf

Common Statement



**SINGAPORE
POLICE FORCE**



T/20171221/2046

1 of 3

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No: T/20171221/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2017 12:39	Video Report No.:	Station Diary No.: 74
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: CHUN YEOW MENG			Address: APT BLK 549 CHOA CHU KANG STREET 52 #06-09 SINGAPORE 680549	
ID Type / ID No.: NRIC NO / S1286747F			Contact No.: Home/Office: Mobile: 91804892	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 59	Date of Birth: 09/05/1958	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Bus driver			Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/12/2017 06:50	Type of Location: Roundabout
Location: Along Road 1 TUAS ROAD				
Flyover/underpass				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA5374E	Bus/Coach/Mi nibus				Slightly Damaged	5
PA9752J	Bus/Coach/Mi nibus				Slightly Damaged	0

Details of Person Involved

Details of Person Involved:	
Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

Common Statement



**SINGAPORE
POLICE FORCE**



T/20171221/2046

2 of 3

Report No. T/20171221/2046

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Driver			
Name	CHUN YEOW MENG		ID No. S1286747F
Related Vehicle	PA5379E (Bus/Coach/Minibus)		Contact No. 91804892
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	Unknown Driver		ID No. NIL
Related Vehicle	NIL		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On the 21/12/2017 at about 0650hrs, I had an accident with a bus PA9752J. While driving PA5379E along Tuas Road Roundabout with 5 passengers, under the flyover, the vehicle PA9752J front bumper collided with the right side of my rear wheel. We both came down to assess the situation and came into a agreement of settling the matter with individual insurances. At the moment of time, no one was injure. There were passengers in the vehicle PA9752J, but Im unsure of the number.

On the same day at about 0800hrs, two of my passengers namely Patrick, G5450183N and Lea Ninobla, G3113487R had informed me that they are not feeling well. I would like to state that I am lodging this report for record purpose. That is all.

Common Statement



SINGAPORE
POLICE FORCE



T/20171221/2046

3 of 3

Report No. T/20171221/2046

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 JASON TAY MING HUI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHARI

Contact No : 65476219

Signature Of Informant:

Date/Time:

21/12/2017 12:39

Classification Of Case:

Authentication Stamp

NP168



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO17024469/T1d3s2	
50 RAFFLES PLACE #05-01/06		Date: 05-04-2018	
SINGAPORE LAND TOWERSINGAPORE 048623			
Code: SMO			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PA 9752J	Veh. Inspected	PA 5379E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704670/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2017
2. Vehicle Particulars & Condition			
Make & Model	NISSAN URVAN 3.0 M	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JN1TG4E25Z0702392	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information			
Accident Date	21/12/2017	Inspect Date / Time	02/01/2018 (11:10 AM)
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/SMO17024469/T1d3s2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.