

INS CASE OWNER:

Shawn

CC4 / AIG17024476

1 Gys3 JV

Surveyor:

XGA

DOI:

ASSIGNMENT

26/2/17

Date / Time:

26/2/17

Registered in Marimen:

26/2/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGJ 788B

Name of Insured:

TAN WEE KIAN BERNARD

Insured Tel No.:

HP: 97960407

Excess Sec II :SS

D.O.A: 26/2/17

Is driver the owner?

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age: TED SOOK FERN DOROTHY

Driver Tel No.: 9688 7456

(V/L: YES/NO)

Claim No.:

921918520756

Policy No.:

900667724

Make / Model:

DAIHATSU TERIOS

Place of Accident:

ALONG VICTORIA STREET

OI GHA REPORT: YES/NO; TP GHA REPORT: YES/NO

Insured Liability: % Final ? Yes/No

SLK 3163T



INSRS:

WSP: S Three Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

09/01/18 (THUR PM)

SLK 3163T - X; SGJ 788B - X

10/1/18 12:48pm

SPOKE TO OI Mr Bernard 97860407 agreed to settle on TP claims, aware of NED issue. will send out letter

12/01/18

Letter sent out.

RECEIVED 01 FEB 2018

RECEIVED 14 MAR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 10/1/18 7:30pm

After call ltr to OI: 12/01/18 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GHA:

Medical Bill:

PDR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$ 9100

(8 days) Reduction:

74 %

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

100

(Agreed / Assessed) BOLA S/N No.:

24

Email

Call

Repair Cost:

W/681 S\$ 8667.00

Loss of Rental (LOR):

S\$ 1,100.00

(11 days) x 100

Loss of Use (LOU):

S\$ (3 x days)

Loss of Income (LOI):

S\$ (3 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/Independent)

Total:

S\$ 9767.00

Grand Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 9,767.00

Name 1:

S Three Automotive Recovery Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 14/03/18





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                  |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                     |                                                                                                  | Ref : CC4/AIG17024476/Gus3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                          |                                                                                                  | Date : 27-12-2017          |            |  |
|                                                                                                                                        |                                                                                                  | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                  |                            |            |                                                                                     |
| Insured Veh.                                                                                                                           | SGJ 7818B                                                                                        | Veh. Inspected             | SLK 3163T  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                                  | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                                                  | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                            | MERIMEN                                                                                          | Assign Date                | 26/12/2017 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                  |                            |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                                  | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                           | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                                  | Colour                     |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                                                | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                                                  | Modification               |            |                                                                                     |
| General                                                                                                                                |                                                                                                  |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                  |                            |            |                                                                                     |
|                                                                                                                                        | Size                                                                                             | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                                  |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                                  |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                                  |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                                  |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                  |                            |            |                                                                                     |
|                                                                                                                                        |                                                                                                  |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                  |                            |            |                                                                                     |
| Accident Date                                                                                                                          | 20/12/2017                                                                                       | Inspection Date            | 26/12/2017 |                                                                                     |
| Survey held at                                                                                                                         | S THREE AUTOMOTIVE & RECOVERY PTE LTD<br>BLK 8 SIN MING IND EST<br>#01-64/66<br>SINGAPORE 575643 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                  |                            |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                  |                            |            |                                                                                     |

**S Three Automotive Recovery Pte Ltd** (Co.Reg.No:201325741R)  
 Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C  
 Singapore 575643  
 Tel: 62841542 / 62841575 Fax: 64875315 Email: sthreeautomotive@gmail.com

**TP INSURER:** **AIG Asia Pacific Insurance Pte. Ltd. (Express)**  
**HITACHI CAPITAL ASIA PACIFIC PTE LTD**

Singapore

#### PARTICULARS OF CLAIM

|                   |                       |               |            |
|-------------------|-----------------------|---------------|------------|
| Claim Type:       | THIRD PARTY           | Ref. No:      |            |
| Policy No:        |                       | Date of Loss: | 20/12/2017 |
| Vehicle Reg. No.: | <b>SLK3163T</b>       | Driveable?    |            |
| Party At Fault:   | THIRD PARTY           |               |            |
| Driver (TP):      | VICTOR GAN SIAU THONG |               |            |

  

|                 |                      |                    |            |
|-----------------|----------------------|--------------------|------------|
| Make/Model:     | HONDA VEZEL, 1.5 (A) | Vehicle Reg. Date: | 12/01/2017 |
| Vehicle Colour: | SILVER               | Chassis No:        | RU31211300 |
| Engine No:      | LEB5911310           |                    |            |
| Odometer:       | 0 KM                 |                    |            |

  

|                               |           |
|-------------------------------|-----------|
| Paint Type:                   |           |
| List Item Discount:           | 20.00 %   |
| Total Loss?                   | <b>NO</b> |
| Est. Duration of Repair (day) | 14        |

Present Location: S THREE AUTOMOTIVE RECOVERY PTE LTD (HQ)

#### COST OF CLAIMS

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 26,274.56        |
| Miscellaneous Items      | 10.00            |
| Labour                   | 4,430.00         |
| Paintwork Labour         | 0.00             |
| Towing                   | 0.00             |
| <b>Gross Total (S\$)</b> | <b>30,714.56</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>2,150.02</b>  |
| <b>Nett Amount (S\$)</b> | <b>32,864.58</b> |

This claim is handled by: MICHELLE LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2017)

**Parts:** M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLK3163T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                     | %Disc | %Depr | Amount            |
|-----|-----|----------|-------------------------------------------------|-------|-------|-------------------|
| 1   | 1   |          | *REAR BUMPER / Re <del>cut</del> NN             | 20.00 | 0.00  | 800 *963.50 FL    |
| 2   | 1   |          | *REAR BUMPER SIDE RH X NN                       | 20.00 | 0.00  | X *390.00 FL      |
| 3   | 1   |          | *REAR BUMPER SIDE LH X NN                       | 20.00 | 0.00  | 195 *390.00 FL    |
| 4   | 1   |          | *REAR BUMPER RETAINER RH X NN                   | 20.00 | 0.00  | X *32.00 FL       |
| 5   | 1   |          | *REAR BUMPER RETAINER LH X NN                   | 20.00 | 0.00  | / *32.00 FL       |
| 6   | 1   |          | *REAR BUMPER BRACKET RH X NN                    | 20.00 | 0.00  | X *60.00 FL       |
| 7   | 1   |          | *REAR BUMPER BRACKET LH X NN                    | 20.00 | 0.00  | X *60.00 FL       |
| 8   | 1   |          | *REAR BUMPER REFLECTOR RH X NN                  | 20.00 | 0.00  | X *151.10 FL      |
| 9   | 1   |          | *REAR BUMPER REFLECTOR LH X NN                  | 20.00 | 0.00  | / *151.10 FL      |
| 10  | 1   |          | *REAR BUMPER LOWER COVER X NN                   | 20.00 | 0.00  | 325 *395.00 FL    |
| 11  | 1   |          | *REAR BUMPER INNER SHIELD LH X NN               | 20.00 | 0.00  | 75 *150.00 FL     |
| 12  | 1   |          | *REAR FENDER PROTECTOR RH X NN                  | 20.00 | 0.00  | 180 *185.00 FL    |
| 13  | 1   |          | *REAR FENDER PROTECTOR LH X NN                  | 20.00 | 0.00  | 150 *185.00 FL    |
| 14  | 1   |          | *TAILLAMP RH X NN                               | 20.00 | 0.00  | / *652.00 FL      |
| 15  | 1   |          | *TAILLAMP LH X NN                               | 20.00 | 0.00  | / *652.00 FL      |
| 16  | 1   |          | *TAILLAMP INNER LOWER SIDE PANEL X NN           | 20.00 | 0.00  | X *428.00 FL      |
| 17  | 1   |          | *TAILLAMP INNER PANEL LH X NN                   | 20.00 | 0.00  | X *535.00 FL      |
| 18  | 1   |          | *REAR END PANEL X NN                            | 20.00 | 0.00  | 580 *680.00 FL    |
| 19  | 1   |          | *REAR END INNER GARNISH X NN                    | 20.00 | 0.00  | 100 *192.30 FL    |
| 20  | 1   |          | *REAR FENDER INNER TRIM RH X NN                 | 20.00 | 0.00  | X *340.00 FL      |
| 21  | 1   |          | *REAR FENDER INNER TRIM LH X NN                 | 20.00 | 0.00  | 240 *340.00 FL    |
| 22  | 1   |          | *REAR TOOLS BOX X NN                            | 20.00 | 0.00  | 197.8 *495.00 FL  |
| 23  | 1   |          | *REAR TOOLS BOARD COVER X NN                    | 20.00 | 0.00  | 187.6 *398.00 FL  |
| 24  | 1   |          | *REAR FENDER TRIM GARNISH RH X NN               | 20.00 | 0.00  | X *420.00 FL      |
| 25  | 1   |          | *REAR FENDER TRIM GARNISH LH X NN               | 20.00 | 0.00  | X *420.00 FL      |
| 26  | 1   |          | *TAILGATE X NN                                  | 20.00 | 0.00  | 1100 *1,380.00 FL |
| 27  | 1   |          | *TAILGATE LOCK X NN                             | 20.00 | 0.00  | / *126.00 FL      |
| 28  | 1   |          | *TAILGATE INNER TRIMBOARD X NN                  | 20.00 | 0.00  | 225 *425.00 FL    |
| 29  | 1   |          | *TAILGATE OUTER HANDLE X NN                     | 20.00 | 0.00  | / *320.00 FL      |
| 30  | 1   |          | *TAILGATE OUTER HANDLE LOGO X NN                | 20.00 | 0.00  | 25 *45.00 FL      |
| 31  | 1   |          | *TAILGATE NO PLATE LAMP LH X NN                 | 20.00 | 0.00  | 38 *76.00 FL      |
| 32  | 1   |          | *TAILGATE LAMP RH X NN                          | 20.00 | 0.00  | 285 *450.00 FL    |
| 33  | 1   |          | *TAILGATE LAMP LH X NN                          | 20.00 | 0.00  | 285 *450.00 FL    |
| 34  | 1   |          | *TAILGATE HINGE RH X NN                         | 20.00 | 0.00  | 80 *80.00 FL      |
| 35  | 1   |          | *TAILGATE HINGE LH X NN                         | 20.00 | 0.00  | 80 *80.00 FL      |
| 36  | 1   |          | *TAILGATE INNER TRIM COVER X NN                 | 20.00 | 0.00  | X *166.00 FL      |
| 37  | 1   |          | *TAILGATE LOCK CATCH X NN                       | 20.00 | 0.00  | X *58.00 FL       |
| 38  | 1   |          | *TAILGATE STOPPER LH X NN                       | 20.00 | 0.00  | X *60.00 FL       |
| 39  | 1   |          | *TAILGATE RUBBER BEARING X NN                   | 20.00 | 0.00  | 165 *185.00 FL    |
| 40  | 1   |          | *TAILGATE EMBLEM VEZEL X NN                     | 20.00 | 0.00  | / *56.20 FL       |
| 41  | 1   |          | *TAILGATE LOCK AUTO SWITCH HANDLE X NN          | 20.00 | 0.00  | X *175.00 FL      |
| 42  | 1   |          | *TAILGATE LOCK AUTO CONTROL UNIT X NN           | 20.00 | 0.00  | X *380.00 FL      |
| 43  | 1   |          | *TAILGATE INNER HANDLE X NN                     | 20.00 | 0.00  | 27.5 *78.00 FL    |
| 44  | 1   |          | *HYBRID AIR RESOLATOR BOX X NN                  | 20.00 | 0.00  | 300 *780.00 FL    |
| 45  | 1   |          | *HYBRID AIR DUCT X NN                           | 20.00 | 0.00  | X *390.00 FL      |
| 46  | 1   |          | *HYBRID TOP PANEL COVER X NN                    | 20.00 | 0.00  | 215 *330.00 FL    |
| 47  | 1   |          | *TAILGATE WINDSCREEN MOULDING X NN              | 20.00 | 0.00  | 121.8 *138.00 FL  |
| 48  | 1   |          | *REAR SPARE TYRE PANEL X NN                     | 20.00 | 0.00  | X *1,130.00 FL    |
| 49  | 1   |          | *REAR SPARE TYRE BOARD X NN                     | 20.00 | 0.00  | X *380.00 FL      |
| 50  | 1   |          | *KEYLESS SENSOR X NN                            | 20.00 | 0.00  | 1.5 *280.00 FL    |
| 51  | 1   |          | *KEYLESS SENSOR RELAY X NN                      | 20.00 | 0.00  | 85 *128.00 FL     |
| 52  | 1   |          | *HYBRID BATTERY CONTROL UNIT SYSTEM X NN        | 20.00 | 0.00  | X *12,600.00 FL   |
| 53  | 1   |          | *TAILGATE TRIM CLIPS X NN                       | 0     | 0.00  | 30 *80.00 FS      |
| 54  | 1   |          | *TAILGATE REVERSE CAMERA X NN                   | 0     | 0.00  | X *680.00 FS      |
| 55  | 1   |          | *TAILGATE NO PLATE X NN                         | 0     | 0.00  | 40 *50.00 FS      |
| 56  | 1   |          | *TAILGATE TOP COVER & CENTER GARNISH CLIPS X NN | 0     | 0.00  | 30 *150.00 FS     |
| 57  | 1   |          | *REAR BUMPER CLIPS X NN                         | 0     | 0.00  | 40 *80.00 FS      |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

| No. | Qty | Part No. | Particulars                             | %Disc | %Depr | Amount         |
|-----|-----|----------|-----------------------------------------|-------|-------|----------------|
| 58  | 1   |          | *REAR REVERSE SENSOR / DM               | 0     | 0.00  | 200 *280.00 FS |
| 59  | 1   |          | *REAR BUMPER LOWER COVER CLIPS - MC     | 0     | 0.00  | 20 *80.00 FS   |
| 60  | 1   |          | *REAR BUMPER INNER SHIELD CLIPS RH X NN | 0     | 0.00  | X *120.00 FS   |
| 61  | 1   |          | *REAR BUMPER INNER SHIELD CLIPS LH X MC | 0     | 0.00  | 20 *120.00 FS  |
| 62  | 1   |          | *REAR END PANEL SEALANT X MC            | 0     | 0.00  | 30 *100.00 FS  |
| 63  | 1   |          | *REAR END PANEL PRIMER AND CLEANER X    | 0     | 0.00  | *100.00 FS     |
| 64  | 1   |          | *TAILLAMP INNER CLIPS RH X              | 0     | 0.00  | *60.00 FS      |
| 65  | 1   |          | *TAILLAMP INNER CLIPS LH X NN           | 0     | 0.00  | *60.00 FS      |
| 66  | 1   |          | *TAILLAMP INNER HOLDER RH X             | 0     | 0.00  | *60.00 FS      |
| 67  | 1   |          | *TAILLAMP INNER HOLDER LH X             | 0     | 0.00  | *60.00 FS      |
| 68  | 1   |          | *REAR SPARE TYRE PANEL SEALANT X        | 0     | 0.00  | *80.00 FS      |
| 69  | 1   |          | *REAR SPARE TYRE PANEL INSULATOR X      | 0     | 0.00  | *280.00 FS     |
| 70  | 1   |          | *REAR END INNER PANEL MEMBER X          | 20.00 | 0.00  | *350.00 FL     |

F=Franchise part. S=Spchett. L=ListItemDisc.

|                                        |           |
|----------------------------------------|-----------|
| Sub Total (\$\$)                       | 32,233.20 |
| - List Item Discount on L Items (\$\$) | 5,958.64  |
| Total Parts (\$\$)                     | 26,274.56 |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

Rear LH Fender - Buc \$1050 - 900

9097  
20%: 7277.6  
SN: 410  
2470  
10157.6  
20%: 8100

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount |
|----------------------------|-----|----------------------|--------|
| <u>Miscellaneous Items</u> |     |                      |        |
| 1                          | 1   | OD/TP Case (Insurer) | 10.00  |
| Sub Total (S\$)            |     |                      | 10.00  |

## Estimates on Labour

| No                      | Particulars                                   | Lab.Type                           | Amount   |
|-------------------------|-----------------------------------------------|------------------------------------|----------|
| <u>Labour Items</u>     |                                               |                                    |          |
| 1                       | STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA    | New <del>600</del> <sup>1000</sup> | 1,600.00 |
| 2                       | SPRAY PAINTING ON ACCIDENT AREA               | New <del>600</del> <sup>1000</sup> | 1,400.00 |
| 3                       | R&R TAILGATE COMPARTMENT                      | New 60                             | 200.00   |
| 4                       | R&R CARPET AND INNER TRIM TO ASSIST REPAIR    | New 60                             | 200.00   |
| 5                       | R&R REAR SEAT AND FRONT SEAT TO ASSIST REPAIR | New 60                             | 280.00   |
| 6                       | R&R REAR BUMPER REVERSE SENSOR                | New 40                             | 120.00   |
| 7                       | R&R REVERSE CAMERA & CALIBRATION SYSTEM       | New 40                             | 120.00   |
| 8                       | R&R CAMERA AND INSTALLING WIRING SYSTEM       | New NN x                           | 120.00   |
| 9                       | R&R WINDSCREEN GLASS                          | New 120                            | 150.00   |
| 10                      | CHECK & REPAIR WIRING SYSTEM                  | New 30                             | 120.00   |
| 11                      | RESPRAY TUFF KOTE ON ACCIDENT AREA            | New 60                             | 120.00   |
| 2470                    |                                               |                                    |          |
| Gross Labour Cost (S\$) |                                               |                                    | 4,430.00 |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

7 Days. (8).  
Gao Qian - 82880282  
After repair photos.  
Lumpsum repair.  
26/12/17.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Print Received Message

This mail is associated with :

SLK3163T (9219185207SG)

[SGJ78188]

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Dec 20 2017 3:00PM

[Tan Wee Kian Bernard]

S Three Automotive Recovery Pte Ltd

From: AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 07/02/2018 09:56 AM.  
To: LKK\_HQ  
Subject: Alert - Adj Mandate Revoked - SLK3163T - Claim Handler: Wui, Shawn-KJ

Revoked: Please assist to check the damages consistency of item 12, rear fender protector RH. Major impact at LH. Is it because of the bumper deformation and caused the damages at rear fender protector RH.

BC - 134.

Damages is consisten.

Rear fender protector RH was attached with Rear Bumper. It will broken when dismatle the Rear Bumper.

## Print Received Message

This mail is associated with :

**SLK3163T (9219185207SG)**

**[SGJ7818B]**

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Dec 20 2017 3:00PM

[Tan Wee Kian Bernard]

S Three Automotive Recovery Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 08/03/2018 17:09 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9767.00) - SLK3163T - Claim Handler: Wui, Shawn-KJ

Approved:9767.00:Please assist to check the damages consistency of item 12, rear fender protector RH. Major impact at LH. Is it because of the bumper deformation and caused the damages at rear fender protector RH.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG17024476/Gus3**

10 JANUARY 2018

**TAN WEE KIAN BERNARD**  
BLK 131 SERANGOON NORTH AVENUE 1  
#02-102  
SINGAPORE 550131

Dear Sir/Madam,

**ACCIDENT INVOLVING SGJ 7818B AND SLK 3163T ON 20.12.2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti  
Case Handler  
DID: 6256 3561  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

LETTER OF INDEMNITY AND AUTHORITY

TO: S THREE AUTOMOTIVE RECOVERY PTE LTD

Re: Accident on 20/1/17 involving my / our motor vehicle no. SLK 3163T along

Victoria St towards Kallang

1. Mr Hitachi Capital Asia Pacific Pte Ltd Nric / ACR / UEN No. \_\_\_\_\_  
of SLK 3163T the owner of Motor Vehicle No. \_\_\_\_\_

hereby authorize you to act as my agent and on my behalf  
to: - (a) commence repairs on my / our vehicle forthwith (b) instruct and deal with surveyors / experts and  
whoever else necessary in order for you to assist in my / our claim (c) instruct my / our solicitors to negotiate a  
settlement, sue, reject or accept any offer of settlement as you deem fit from the third party driver and / or his  
insurers and / or from my / our insurers (d) where applicable and permitted, claim against my / our own insurance  
company for your costs and any other losses recoverable under my / our own insurance policy if the third party  
claim is rejected our unsuccessful or if no payment is received. In this case, I/we understand that any "Excess"  
applicable under my / our insurance policy is to be borne by me / us. I/We also accept that my / our own insurer  
may reject my / our own damage claim for whatever reason (s) sign all Discharge Vouchers / Indemnity Forms  
and all necessary papers in connection with this matter on my / our behalf.

2. If for whatever reason, my / our claim is not successful or is rejected or no payment is received whether in whole or part, I/we agree and undertake to pay full/balance amount of the repair costs, survey fees, (rental fees for the replacement vehicle if any), and other expenses reasonably incurred on my / our behalf as the case may be.
3. As I/we have not paid our repair cost nor reimbursed you for the survey report fee (nor rental fees for the replacement vehicle if any), I/we agreed that upon settlement of my / our claim, the compensation / settlement monies shall be irrevocably assigned and paid to you after deduction of the costs and disbursements of my / our solicitors in this matter.
4. If I am / we are contacted by the third party or his insurers or their agents to discuss anything about my / our claim in the above accident, I/we will not entertain their queries and will direct them to contact my / our lawyers. I/We will not enter into any agreement with third party or his insurers or their agents. If I/we receive any monies from the third party or his insurers or their agents, I/we hereby undertake to forward all the monies received to you in full immediately.
5. I/We undertake to co-operate fully with you and all parties concerned including but not limited to (if necessary) attending meetings at my / our solicitors' office, attending at the accident site, arranging for my / our vehicle to be re-inspected at your premises and attending Court to see the claim to its conclusion.

HITACHI CAPITAL ASIA PACIFIC PTE. LTD.

Date this

day of

20



XGQ

K. Saite  
Senior Manager  
Owner's Signature

Witness' Signature

(Company stamp, if applicable)

Full Name: XING GUO GUANG

**RELEASE VOUCHER**

**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, S THREE AUTOMOTIVE RECOVERY PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8,667.00 (Repair Cost), S\$1,100.00 (Loss of Rental/Use) - (Disbursement), for vehicle no. SLK 3163T that was damaged pursuant to the accident which occurred on 20/12/2017 (date) along VICORIA STREET (location) involving vehicle no/s SGJ 7818B.

This is pursuant to the inspection conducted on 26/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HITACHI CAPITAL ASIA PACIFIC PTE LTD ("the third party claimant") of vehicle no. SLK 3163T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLK 3163T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of March (month) 2018 (year)

Signed by appointed surveyor




Signed by "the workshop" (with chop)

**S THREE AUTOMOTIVE RECOVERY PTE LTD**  
 Blk 8 Sin Ming Industrial Estate  
 #01-64/66 Singapore 575643  
 Tel: 6284 1542 / 6284 1575  
 Fax: 6487 5315  
 sthreeautomotive@gmail.com



# S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate  
#01-84/66 Singapore 575643

Tel: (65) 6284 1542, (65) 6284 1575 Fax: (65) 6487 5315  
Reg. No: 201325741R

## TAX INVOICE

GST Reg. No: 201325741R

### Name & Address:

HITACHI CAPITAL AISIA PACIFIC PTE LTD  
83839600

|                |             |
|----------------|-------------|
| Date           | 30/01/2018  |
| Number:        | S3-9320     |
| Vehicle Number | SLK3163T    |
| Job Sheet      |             |
| Make and Model | HONDA VEZEL |

|                |  |
|----------------|--|
| Payment Method |  |
| Cheque No.     |  |

| S/No.                      | Description                                             | Qty | Amount             |
|----------------------------|---------------------------------------------------------|-----|--------------------|
| 1                          | REPAIR COST FOR VEHICLE SLK3163T<br>Standard Rated (7%) |     | 8,100.00<br>567.00 |
| Total amount excluding GST |                                                         |     | \$8,100.00         |
| Add GST @ 7%               |                                                         |     | \$567.00           |
| Total amount payable       |                                                         |     | \$8,667.00         |

STHREE AUTOMOTIVE RECOVERY PTE LTD

Name

RECEIVED BY

# Invoice

Customer:

HITACHI CAPITAL ASIA PACIFIC PTE LTD  
 VICTOR GAN SIAN THONG  
 BLK 210D PUNGGOL FIELD  
 #10-274 (S) 824201

|              |           |
|--------------|-----------|
| Invoice Date | 24/1/2018 |
| Invoice No.  | STAR2230  |

|       |                  |         |
|-------|------------------|---------|
| Terms | Customer Veh No. | VRA No. |
|       | SLK3163T         | 1831    |

| Description                                            | No. of Days | Price  | Amount           |
|--------------------------------------------------------|-------------|--------|------------------|
| SGC6161E TOYOTA VIOS<br>FROM: 20/12/2017 TO 06/01/2018 | 17          | 100.00 | 1,700.00         |
| <b>Total Amount</b>                                    |             |        | <b>S1,700.00</b> |

Authorized by:

Joey Kho





# STAR CAR LEASING PTE LTD

Blk 8 Sin Ming Industrial Estate #01-84/86 Singapore 575643

Tel : (65) 9766 2745 / 9636 4376 / 9642 0017

REG. No: 201325738Z

VRA No: 1831

Mar 22 30

## VEHICLE RENTAL AGREEMENT

### HIRER'S PARTICULAR

Name: (as in I/C) HITACHI CAPITAL ACN

NRIC/PASSPORT No: \_\_\_\_\_

Address (Res): \_\_\_\_\_

Name & Address of Employer: \_\_\_\_\_

Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_

Driving Licence No: \_\_\_\_\_ D/L Type: Local / International

Issue Date: \_\_\_\_\_ Date of Birth: \_\_\_\_\_

Tel: (O) \_\_\_\_\_ (R) \_\_\_\_\_ HP/PG \_\_\_\_\_

### ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) Victor Gan Gan Thong

NRIC/PASSPORT No: S7727831A

Address (Res): 21K MON PUNGGOI FIELD

#10-274 (C) 24401

Driving Licence No: \_\_\_\_\_ D/L Type: Local / International

Issue Date: \_\_\_\_\_ Date of Birth: \_\_\_\_\_

Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_

VEHICLE No: SLR 316 ST REPLACE VEH No: SAC 6161 E

Mileage Out: \_\_\_\_\_ Mileage Out: \_\_\_\_\_

Make & Model: TOYOTA VIOS Auto / Manual Group: \_\_\_\_\_

OUT : Date 20/12/17 Time: 1740HRS

Charges starting on the day of hire

HIRE/PERIOD EXPIRY \_\_\_\_\_

COLLISION DAMAGE WAIVER EXCESS \$3000 YES / NO

PERSONAL ACCIDENT INSURANCE YES / NO

CHARGES

Daily \_\_\_\_\_ per day

Weekly 0\$ per week

Monthly 0\$ per month

Hours 0\$ per hour

Others 0\$

CDW 0\$ per day/month

PAI 0\$ per day/month

Delivery Service 0\$

SUB-TOTAL \$

PETROL LEVEL

Out E 1/4 1/2 3/4 F

In E 1/4 1/2 3/4 F

EXTENSION

Collection Service

Misc.

TOTAL CHARGES \$

For Singapore use only

Hirer's Signature

Addition Driver's Signature

### VEHICLE CHECK LIST

D - DENTS  
S - SCRATCHES

INDICATE :  
A - ACCIDENTS



RIGHT



REAR



FRONT



TOP



LEFT

### ACCESSORIES CHECK

☐ Ashtray ☐ Cig Ligher ☐ S/Tyre

☐ STD Tools ☐ Jack ☐ Hub Caps

☐ Radio / Cass ☐ CD ☐ Catridges

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given STAR CAR LEASING PTE LTD in connection with this agreement is true.

### \* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE
- ALL VEHICLES ARE SUPPLIED WITH A FULL TANK AND SHOULD BE RETURNED WITH A FULL TANK.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF COW AND/OR PAI WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY STAR CAR LEASING PTE LTD.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO STAR CAR LEASING PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

| DATE IN | TIME IN | MILEAGE | CHECKED BY | REMARKS                   |
|---------|---------|---------|------------|---------------------------|
| 2/1     | 11am    |         |            |                           |
|         |         |         |            | SIGNATURE OF HIRER/DRIVER |

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

#### CLAIM SUBFOLDER TRACKING

| Case | Notified                                             | Est Submitted                               | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
|------|------------------------------------------------------|---------------------------------------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 22 Dec 2017<br>12:55<br><a href="#">Sendback Est</a> | 22 Dec 2017<br>13:19<br><b>S\$30,714.56</b> | 26 Dec 2017<br>09:22<br><a href="#">Edit Adj Rpt</a> | <b>S\$8,100.00</b><br><a href="#">Edit Estimates</a> | <b>S\$8,100.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                            | Reference                                                                                                                                 | Claim Details          | Documents                       | Show All                          |         |             |              |            |       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------|-----------------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                                                                                                                                                                  |                                                                                                                                           |                        |                                 |                                   |         |             |              |            |       |
| Insured:                                                                                                                                                                                                                                                                        | Tan Wee Kian Bernard, ID: S6844772J, Tel: +6583839600                                                                                     |                        |                                 |                                   |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                                                                                                                  | HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N                                                                            |                        |                                 |                                   |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                                                                                                                               | SLK3163T                                                                                                                                  | Date of Loss:          | 20/12/2017 15:00 - :59          |                                   |         |             |              |            |       |
| Claim Type:                                                                                                                                                                                                                                                                     | TP / 9219185207SG                                                                                                                         | Policy/Cover Note No.: | 0100667724 (Comprehensive)      |                                   |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                                                                                     | SGJ78188                                                                                                                                  | Policy No. (Claimant): | MSD/VPCP/17-000270              |                                   |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                 | Excess:                                                                                                                                   |                        |                                 |                                   |         |             |              |            |       |
| Repairer:                                                                                                                                                                                                                                                                       | S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575 |                        |                                 |                                   |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                                                                                                                               | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ]<br>Shawnkaijye.Wui@aig.com              |                        |                                 |                                   |         |             |              |            |       |
| Claimant's Insurer:                                                                                                                                                                                                                                                             | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888                                                                            |                        |                                 |                                   |         |             |              |            |       |
| Adjuster:                                                                                                                                                                                                                                                                       | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/01/2018]                         |                        |                                 |                                   |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>                                                                                                                                                                                                                                                 |                                                                                                                                           |                        |                                 |                                   |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                 |                                                                                                                                           |                        | <a href="#">View All</a>        | <a href="#">Compose Case Mail</a> |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (08/03/2018): Alert - Adj Mandate Approved (S\$9767.00) - SLK3163T - Claim Handler: Wui, Shawn-...</li> <li>AIG_SG_EXPRESS (07/02/2018): Alert - Adj Mandate Revoked - SLK3163T - Claim Handler: Wui, Shawn-KJ</li> </ul> |                                                                                                                                           |                        |                                 |                                   |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>                                                                                                                                                                                                                                                     |                                                                                                                                           |                        |                                 |                                   |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                 |                                                                                                                                           |                        | <a href="#">View All</a>        | <a href="#">Search Tasks</a>      |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                 |                                                                                                                                           |                        | <a href="#">Create New Task</a> | <a href="#">Complete</a>          |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                                                                        | Priority                                                                                                                                  | Type                   | Task Group                      | Subject                           | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                                                                     |                                                                                                                                           |                        |                                 |                                   |         |             |              |            |       |

## Claim Documents

SLK3163T (9219185207SG)  
[SGJ7818B]  
TP  
HITACHI CAPITAL ASIA PACIFIC PTE LTD  
Dec 20 2017 3:00PM  
[Tan Wee Kian Bernard]  
S Three Automotive Recovery Pte Ltd

|                         |                 |                                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                     |                 |  |  |
|-------------------------|-----------------|------------------------------------------------------------------------------------|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|-----------|------------|-------------------------------------|-------------------------------------|-----------------|--|--|
| Upload Documents        |                 |                                                                                    | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |           | View       |                                     |                                     | View in Browser |  |  |
| Letters/Correspondences |                 |                                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                                                  |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                     |                 |  |  |
| 1                       | (Draft)         | Third Party Express Settlement – Payment Breakdown                                 |               |  |  |                    |  |  |              |  |  |              |  | Edit      |            |                                     |                                     |                 |  |  |
| Assessment Reports      |                 |                                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    | S Three Automotive Recovery Pte Ltd (HQ)                                           |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                     |                 |  |  |
| 1                       | 22/12/17 13:19  | Repairer Estimates                                                                 |               |  |  |                    |  |  |              |  |  |              |  | Load HTM  |            |                                     |                                     |                 |  |  |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                          |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                     |                 |  |  |
| 1                       | 08/01/18 10:00  | Accident Statement<br>From: SC – Reg. No: SGJ7818B, Claimant: TAN WEE KIAN BERNARD |               |  |  |                    |  |  |              |  |  |              |  | Load HTM  |            |                                     |                                     |                 |  |  |
| Photos/Images           |                 |                                                                                    |               |  |  |                    |  |  |              |  |  |              |  |           | 3 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    | S Three Automotive Recovery Pte Ltd (HQ)                                           |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                     |                 |  |  |
| 1                       | 26/12/17 08:44  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 2                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 3                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 4                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 5                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 6                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 7                       | 26/12/17 09:19  | Accident Photo                                                                     |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                  |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                     |                 |  |  |
| 1                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 2                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 3                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 4                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 5                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 6                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 7                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 8                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 9                       | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 10                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 11                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 12                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 13                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 14                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 15                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 16                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 17                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 18                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 19                      | 31/01/18 17:02  | General View                                                                       |               |  |  |                    |  |  |              |  |  |              |  | Load JPG  |            |                                     |                                     |                 |  |  |

|    |                |                    |   |          |                                     |
|----|----------------|--------------------|---|----------|-------------------------------------|
|    |                |                    |   |          | <input checked="" type="checkbox"/> |
| 20 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 52 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 53 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 54 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 55 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 56 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 57 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 58 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 59 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 60 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 61 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 62 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 63 | 31/01/18 17:02 | General View       | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 64 | 31/01/18 17:02 | Odometer Reading   | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 65 | 31/01/18 17:02 | Chassis Number     | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 66 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 67 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 68 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |

|     |                |                    |   |          |                                     |
|-----|----------------|--------------------|---|----------|-------------------------------------|
| 69  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 70  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 71  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 72  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 73  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 74  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 75  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 76  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 77  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 78  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 79  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 80  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 81  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 82  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 83  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 84  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 85  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 86  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 87  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 88  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 89  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 90  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 91  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 92  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 93  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 94  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 95  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 96  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 97  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 98  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 99  | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 100 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 101 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 102 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 103 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 104 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 105 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 106 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 107 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 108 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 109 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 110 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 111 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 112 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 113 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 114 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 115 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 116 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 117 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 118 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |

|     |                |                    |   |          |                                     |
|-----|----------------|--------------------|---|----------|-------------------------------------|
| 119 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 120 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 121 | 31/01/18 17:03 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 122 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 123 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 124 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 125 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 126 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 127 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 128 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 129 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 130 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 131 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 132 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 133 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 134 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 135 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 136 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 137 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 138 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 139 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 140 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 141 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 142 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 143 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 144 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 145 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 146 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 147 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 148 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 149 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 150 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 151 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 152 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 153 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 154 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 155 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 156 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 157 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 158 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 159 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 160 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 161 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 162 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 163 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 164 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 165 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 166 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 167 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 168 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |

|     |                |                    |   |          |                                     |
|-----|----------------|--------------------|---|----------|-------------------------------------|
| 169 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 170 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 171 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 172 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 173 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 174 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 175 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 176 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 177 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 178 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 179 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 180 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 181 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 182 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 183 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 184 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 185 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 186 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 187 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 188 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |
| 189 | 31/01/18 17:04 | Reinspection Photo | 1 | Load JPG | <input checked="" type="checkbox"/> |

| Documentation |                 |                                          | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|------------------------------------------|------------|-------------------------------------|
| No            | Finalized On    | S Three Automotive Recovery Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 26/12/17 08:43  | E-filed GIA report                       | 1          | <input checked="" type="checkbox"/> |
| 2             | 26/12/17 08:43  | E-filed GIA report                       | 1          | <input checked="" type="checkbox"/> |
| 3             | 26/12/17 08:43  | E-filed GIA report                       | 1          | <input checked="" type="checkbox"/> |
| 4             | 26/12/17 08:43  | E-filed GIA report                       | 1          | <input checked="" type="checkbox"/> |
| 5             | 26/12/17 08:43  | Drivers Driving License                  | 1          | <input checked="" type="checkbox"/> |
| 6             | 26/12/17 08:43  | Certificate of Insurance                 | 1          | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)        | Thumbnail  | Print                               |
| 1             | 28/12/17 15:37  | TP GIA REPORT                            | 1          |                                     |
| 2             | 28/12/17 15:37  | TP ESTIMATE- MARKED                      | 1          |                                     |
| 3             | 10/01/18 14:35  | LETTER TO OI                             | 1          |                                     |
| 4             | 05/02/18 16:33  | RENTAL RECEIPT                           | 1          |                                     |
| 5             | 16/03/18 12:39  | WORKSHOP INVOICE                         | 1          |                                     |
| 6             | 16/03/18 12:39  | AUTHORISATION TO ACT FORM                | 1          |                                     |
| 7             | 16/03/18 12:39  | Release Voucher                          | 1          |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                                                                                                                                                                                                                       | Reset | Save | Print |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                                                                                                                                                                                                                              |       |      |       |
| <div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> <div></div> <div></div> </div> </div> </div> <div> <b>Show Remarks To:</b> <input type="checkbox"/> Repairer           <input type="checkbox"/> Handling Insurer<br/> <small>Note: Remarks are private unless you show it to other parties.</small> </div> |       |      |       |



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                     |
|-------------------|---------------------|--------|---------------------|
| Vehicle No:       | SGJ7818B (Insd veh) | Model: | HONDA VEZEL 1.5 (A) |
|                   | SLK3163T (TP veh)   |        |                     |
| Date of Accident: | 20/12/2017          |        |                     |

|                       |   |                              |                                        |                        |
|-----------------------|---|------------------------------|----------------------------------------|------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |                        |
| Repair Estimate       | : | \$                           |                                        | <b>32,864.58</b>       |
| Final Repair Cost     | : | \$                           |                                        | 8,667.00               |
| Loss of Use           | : | \$                           |                                        | days at \$0.00 per day |
| Rental (if any)       | : | \$                           |                                        | 11 days                |
| LTA / GIA Search Fee  | : | \$                           |                                        | 0.00                   |
| Others:               | : | \$                           |                                        | 0.00                   |
|                       | : | \$                           |                                        |                        |
| Final Settlement Sum  | : | \$                           |                                        | 9,767.00               |

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                                     |   |          |
|----------------------------------------|-------------------------------------|---|----------|
| 1)                                     | S Three Automotive Recovery Pte Ltd | : | 9,767.00 |
| 2)                                     |                                     | : | \$       |

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
16 Mar  
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17024478/GYS3Q2

Date: 16/03/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100667724  
 Claimant Vehicle No: SLK3163T Insured Vehicle No: SGJ7818B  
 Date of Loss: 20/12/2017 Nature of Claim: TP Claim No: 9219185207SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLK3163T  
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5911310  
 Reg. Date: 12/01/2017 (Man. Year: 2016) Chassis No: RU31211300  
 Colour: Silver Odometer: 30233 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                            | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                     | 26,274.56        | 7,687.60         | 18,586.96        | 70.74        |
| Miscellaneous Items                       | 10.00            | 10.00            | 0.00             | 0.00         |
| Labour                                    | 4,430.00         | 2,470.00         | 1,960.00         | 44.24        |
| Paintwork Labour                          | 0.00             | 0.00             | 0.00             |              |
| Towing                                    | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>       | <b>30,714.56</b> | <b>10,167.60</b> | <b>20,546.96</b> | <b>66.90</b> |
| <b>Approved Total (Overridden) (S\$)</b>  |                  | <b>8,100.00</b>  |                  |              |
| (S\$)                                     | 30,714.56        | 8,100.00         | 22,614.56        | 73.63        |
| + GST 7.00/7.00% (S\$)                    | 2,150.02         | 567.00           | 1,583.02         | 73.63        |
| <b>Nett Amount (S\$)</b>                  | <b>32,864.58</b> | <b>8,667.00</b>  | <b>24,197.58</b> | <b>73.63</b> |
| + Car Rental (11.0 x S\$100.00/day) (S\$) |                  | 1,100.00         |                  |              |
| <b>Nett Liability (S\$)</b>               |                  | <b>9,767.00</b>  |                  |              |

## INSPECTION

Date of Assignment: 26/12/2017 Present Location: S Three Automotive Recovery Pte Ltd (HQ)  
 Date Inspected: 26/12/2017 Inspected At: S Three Automotive Recovery Pte Ltd (HQ)  
 Blk 8 Sin Ming Industrial Estate, #01-64/66

Sector C  
Singapore 575643

Estimated Period of Repair: 8.0 days

---

**Adjuster:** XING GUO QIANG

**Manager:** Jasmine Khine Phoo Wai

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                      | Deformed      | 963.50 FL   | *800.00 FL   |
| 2   | 1   |          | *REAR BUMPER SIDE RH              | Not Necessary | 390.00 FL   | *- FL        |
| 3   | 1   |          | *REAR BUMPER SIDE LH              | Cut           | 390.00 FL   | *195.00 FL   |
| 4   | 1   |          | *REAR BUMPER RETAINER RH          | Not Necessary | 32.00 FL    | *- FL        |
| 5   | 1   |          | *REAR BUMPER RETAINER LH          | Deformed      | 32.00 FL    | *32.00 FL    |
| 6   | 1   |          | *REAR BUMPER BRACKET RH           | Not Necessary | 60.00 FL    | *- FL        |
| 7   | 1   |          | *REAR BUMPER BRACKET LH           | Not Necessary | 60.00 FL    | *- FL        |
| 8   | 1   |          | *REAR BUMPER REFLECTOR RH         | Not Necessary | 151.10 FL   | *- FL        |
| 9   | 1   |          | *REAR BUMPER REFLECTOR LH         | Cracked       | 151.10 FL   | *151.10 FL   |
| 10  | 1   |          | *REAR BUMPER LOWER COVER          | Deformed      | 395.00 FL   | *325.00 FL   |
| 11  | 1   |          | *REAR BUMPER INNER SHIELD LH      | Torn          | 150.00 FL   | *75.00 FL    |
| 12  | 1   |          | *REAR FENDER PROTECTOR RH         | Broken        | 185.00 FL   | *150.00 FL   |
| 13  | 1   |          | *REAR FENDER PROTECTOR LH         | Deformed      | 185.00 FL   | *150.00 FL   |
| 14  | 1   |          | *TAILLAMP RH                      | Cracked       | 652.00 FL   | *652.00 FL   |
| 15  | 1   |          | *TAILLAMP LH                      | Cracked       | 652.00 FL   | *652.00 FL   |
| 16  | 1   |          | *TAILLAMP INNER LOWER SIDE PANEL  | Not Necessary | 428.00 FL   | *- FL        |
| 17  | 1   |          | *TAILLAMP INNER PANEL LH          | Not Necessary | 535.00 FL   | *- FL        |
| 18  | 1   |          | *REAR END PANEL                   | Buckled       | 680.00 FL   | *580.00 FL   |
| 19  | 1   |          | *REAR END INNER GARNISH           | Deformed      | 192.30 FL   | *100.00 FL   |
| 20  | 1   |          | *REAR FENDER INNER TRIM RH        | Not Necessary | 340.00 FL   | *- FL        |
| 21  | 1   |          | *REAR FENDER INNER TRIM LH        | Cracked       | 340.00 FL   | *240.00 FL   |
| 22  | 1   |          | *REAR TOOLS BOX                   | Deformed      | 495.00 FL   | *197.80 FL   |
| 23  | 1   |          | *REAR TOOLS BOARD COVER           | Deformed      | 398.00 FL   | *187.60 FL   |
| 24  | 1   |          | *REAR FENDER TRIM GARNISH RH      | Not Necessary | 420.00 FL   | *- FL        |
| 25  | 1   |          | *REAR FENDER TRIM GARNISH LH      | Not Necessary | 420.00 FL   | *- FL        |
| 26  | 1   |          | *TAILGATE                         | Buckled       | 1,380.00 FL | *1,100.00 FL |
| 27  | 1   |          | *TAILGATE LOCK                    | Bent          | 126.00 FL   | *126.00 FL   |
| 28  | 1   |          | *TAILGATE INNER TRIMBOARD         | Deformed      | 425.00 FL   | *225.00 FL   |
| 29  | 1   |          | *TAILGATE OUTER HANDLE            | Cracked       | 320.00 FL   | *320.00 FL   |
| 30  | 1   |          | *TAILGATE OUTER HANDLE LOGO       | Necessary     | 45.00 FL    | *25.00 FL    |
| 31  | 1   |          | *TAILGATE NO PLATE LAMP LH        | Cracked       | 76.00 FL    | *38.00 FL    |
| 32  | 1   |          | *TAILGATE LAMP RH                 | Cracked       | 450.00 FL   | *285.00 FL   |
| 33  | 1   |          | *TAILGATE LAMP LH                 | Cracked       | 450.00 FL   | *285.00 FL   |
| 34  | 1   |          | *TAILGATE HINGE RH                | Bent          | 80.00 FL    | *40.00 FL    |
| 35  | 1   |          | *TAILGATE HINGE LH                | Bent          | 80.00 FL    | *40.00 FL    |
| 36  | 1   |          | *TAILGATE INNER TRIM COVER LH     | Not Necessary | 166.00 FL   | *- FL        |
| 37  | 1   |          | *TAILGATE LOCK CATCH              | Not Necessary | 58.00 FL    | *- FL        |
| 38  | 1   |          | *TAILGATE STOPPER LH              | Not Necessary | 60.00 FL    | *- FL        |
| 39  | 1   |          | *TAILGATE RUBBER BEARING          | Twisted       | 185.00 FL   | *165.00 FL   |
| 40  | 1   |          | *TAILGATE EMBLEM VEZEL            | Necessary     | 56.20 FL    | *56.20 FL    |
| 41  | 1   |          | *TAILGATE LOCK AUTO SWITCH HANDLE | Not Necessary | 175.00 FL   | *- FL        |
| 42  | 1   |          | *TAILGATE LOCK AUTO CONTROL UNIT  | Not Necessary | 380.00 FL   | *- FL        |
| 43  | 1   |          | *TAILGATE INNER HANDLE            | Missing       | 78.00 FL    | *27.50 FL    |
| 44  | 1   |          | *HYBRID AIR RESOLATOR BOX         | Cracked       | 780.00 FL   | *300.00 FL   |
| 45  | 1   |          | *HYBRID AIR DUCT                  | Not Necessary | 390.00 FL   | *- FL        |
| 46  | 1   |          | *HYBRID TOP PANEL COVER           | Bent          | 330.00 FL   | *215.00 FL   |
| 47  | 1   |          | *TAILGATE WINDSCREEN MOULDING     | Necessary     | 138.00 FL   | *121.80 FL   |
| 48  | 1   |          | *REAR SPARE TYRE PANEL            | Repair        | 1,130.00 FL | *- FL        |
| 49  | 1   |          | *REAR SPARE TYRE BOARD            | Not Necessary | 380.00 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                | Condition     | Repairer's                                                | Amount                    |
|-----|-----|----------|--------------------------------------------|---------------|-----------------------------------------------------------|---------------------------|
| 50  | 1   |          | *KEYLESS SENSOR                            | Damaged       | 280.00 FL                                                 | *105.00 FL                |
| 51  | 1   |          | *KEYLESS SENSOR RELAY                      | Damaged       | 128.00 FL                                                 | *85.00 FL                 |
| 52  | 1   |          | *HYBRID BATTERY CONTROL UNIT SYSTEM        | Not Necessary | 12,600.00 FL                                              | *- FL                     |
| 53  | 1   |          | *TAILGATE TRIM CLIPS                       | Necessary     | 80.00 FS                                                  | *30.00 FS                 |
| 54  | 1   |          | *TAILGATE REVERSE CAMERA                   | Not Necessary | 680.00 FS                                                 | *- FS                     |
| 55  | 1   |          | *TAILGATE NO PLATE                         | Cut           | 50.00 FS                                                  | *40.00 FS                 |
| 56  | 1   |          | *TAILGATE TOP COVER & CENTER GARNISH CLIPS | Necessary     | 150.00 FS                                                 | *30.00 FS                 |
| 57  | 1   |          | *REAR BUMPER CLIPS                         | Necessary     | 80.00 FS                                                  | *40.00 FS                 |
| 58  | 1   |          | *REAR REVERSE SENSOR                       | Damaged       | 280.00 FS                                                 | *200.00 FS                |
| 59  | 1   |          | *REAR BUMPER LOWER COVER CLIPS             | Necessary     | 80.00 FS                                                  | *20.00 FS                 |
| 60  | 1   |          | *REAR BUMPER INNER SHIELD CLIPS RH         | Not Necessary | 120.00 FS                                                 | *- FS                     |
| 61  | 1   |          | *REAR BUMPER INNER SHIELD CLIPS LH         | Necessary     | 120.00 FS                                                 | *20.00 FS                 |
| 62  | 1   |          | *REAR END PANEL SEALANT                    | Necessary     | 100.00 FS                                                 | *30.00 FS                 |
| 63  | 1   |          | *REAR END PANEL PRIMER AND CLEANER         | Not Necessary | 100.00 FS                                                 | *- FS                     |
| 64  | 1   |          | *TAILLAMP INNER CLIPS RH                   | Not Necessary | 60.00 FS                                                  | *- FS                     |
| 65  | 1   |          | *TAILLAMP INNER CLIPS LH                   | Not Necessary | 60.00 FS                                                  | *- FS                     |
| 66  | 1   |          | *TAILLAMP INNER HOLDER RH                  | Not Necessary | 60.00 FS                                                  | *- FS                     |
| 67  | 1   |          | *TAILLAMP INNER HOLDER LH                  | Not Necessary | 60.00 FS                                                  | *- FS                     |
| 68  | 1   |          | *REAR SPARE TYRE PANEL SEALANT             | Not Necessary | 80.00 FS                                                  | *- FS                     |
| 69  | 1   |          | *REAR SPARE TYRE PANEL INSULATOR           | Not Necessary | 280.00 FS                                                 | *- FS                     |
| 70  | 1   |          | *REAR END INNER PANEL MEMBER               | Not Necessary | 350.00 FL                                                 | *- FL                     |
| 71  | 1   |          | *REAR LH FENDER                            | Buckled       | -                                                         | *1,050.00 FL              |
|     |     |          |                                            |               | <b>Sub Total (S\$)</b>                                    | <b>32,233.20 9,507.00</b> |
|     |     |          |                                            |               | <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | <b>5,958.64 1,819.40</b>  |
|     |     |          |                                            |               | <b>Total Parts (S\$)</b>                                  | <b>26,274.56 7,687.60</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars          | Repairer's | Amount |
|----------------------------|-----|----------------------|------------|--------|
| <u>Miscellaneous Items</u> |     |                      |            |        |
| 1                          | 1   | OD/TP Case (Insurer) | 10.00      | 10.00  |
| Sub Total (\$\$)           |     |                      | 10.00      | 10.00  |

## Recommended Labour

| No                       | Particulars                                   | Lab.Type | Repairer's | Amount   |
|--------------------------|-----------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>      |                                               |          |            |          |
| 1                        | STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA    | New      | 1,600.00   | 1,000.00 |
| 2                        | SPRAY PAINTING ON ACCIDENT AREA               | New      | 1,400.00   | 1,000.00 |
| 3                        | R&R TAILGATE COMPARTMENT                      | New      | 200.00     | 60.00    |
| 4                        | R&R CARPET AND INNER TRIM TO ASSIST REPAIR    | New      | 200.00     | 60.00    |
| 5                        | R&R REAR SEAT AND FRONT SEAT TO ASSIST REPAIR | New      | 280.00     | 60.00    |
| 6                        | R&R REAR BUMPER REVERSE SENSOR                | New      | 120.00     | 40.00    |
| 7                        | R&R REVERSE CAMERA & CALIBRATION SYSTEM       | New      | 120.00     | 40.00    |
| 8                        | R&R CAMERA AND INSTALLING WIRING SYSTEM       | New      | 120.00     | 0.00     |
| 9                        | R&R WINDSCREEN GLASS                          | New      | 150.00     | 120.00   |
| 10                       | CHECK & REPAIR WIRING SYSTEM                  | New      | 120.00     | 30.00    |
| 11                       | RESPRAY TUFF KOTE ON ACCIDENT AREA            | New      | 120.00     | 60.00    |
| Gross Labour Cost (\$\$) |                                               |          | 4,430.00   | 2,470.00 |

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

&lt; END OF ESTIMATES &gt;