

ASS. REC. BY:

REF:

CS/SM017024495/Agb

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 27/12/2017 12:15pm

Estimated Cost: Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 6336E Insured: SDH 3988H

at Workshop m/s SK Automobile Tel:

of 8 Kaki Bukit Ave 4 #08-46

Policy No: Claim No: CMTD1704679 / NSW

Sum Insured: Excess:

Make of Veh: D.O.A. 22/12/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

28/12/2017

H.O.D. Endorsement:

Date/Time: 27/12/2017 4:01pm Person Contacted: An Xiong Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate.
	SLR 6336E - X
	SDH 3988H - CS / ALH 160204495 / T1eb342 Def: 25/10/16
29/12/17@ 3:26pm	Informed Grace, we are pending estimate from repairer. LS 63500, 3 days CRed \$ 11843.69, 27%

REF: SMO

ASSIGNMENT

From: _____ Date: 28/12/17

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLR 6336E

at Workshop no: SK Automobik

of 8kaki Bkt Ave 4 # 08-46

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Van No: SLR6336E Yr Regn: 2017 July

Type: ☒ M/Cat ☐ M/Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover

Truck / Trailer or

Make: Lexus RX 200 cc: 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 7428 T/Radio: Insured / Std / NI / NA

Eng No: _____

C.No: JTJBAMCAX02030383

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim ☒ STD A/Rim or

Tyre Size: F: 235/55R20

R: 235/55R20

☒ BS ☐ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm

R/Bal: 06 mm

L/Bal: 06 mm

L/Bal: 06 mm

D.O.A:

D.O.A: 28/12/17

Survey held at: SK

Des. of Damages: Frt / ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

TP Sampo

RECEIVED 28 FEB 2019

Date/Time: File Pass to?

☐

: Preli. Report

1) 28/12 2017

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

V. 13400 S

Photo

Chart

TOTAL

Add Fee:

☐

Site Insp: S

☐

Interview: S

☐

Tech. Insp: S

☐

Weekend: S

Report Format: 7P

Lump Sum / L.B. / S 3500

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17024495/Aqb	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 27-12-2017	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDH 8988H	Veh. Inspected	SLR 6336E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704679/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/12/2017	Inspection Date	28/12/2017
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 27 December, 2017 12:15 PM
To: Julie Johari; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: XIONG; md daud nadzim
Subject: CMTD1704679/NSW - ACCIDENT INVLG SDH8988H & SLR6336E on 22.12.2017
Attachments: ARRANGE SURVEYOR FOR SLR 6336E.PDF; SLR 6336E_GIA REPORT.PDF

Your Reference: SLR6336E

Our Claim Reference: CMTD1704679/NSW

Without

Prejudice

Hi Julie/ Xiong,

We acknowledged receipt of your claim documents.

Please be informed that Shawn Ngo is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SLR6336E.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Julie Johari [mailto:julie@skauto.com.sg]
Sent: Wednesday, December 27, 2017 11:21 AM
To: Claims - Motor Survey
Cc: XIONG; md daud nadzim
Subject: ARRANGE PRI FOR SLR 6336E (YOUR REF: SDH 8988H)

Dear Sir/Madam, 'WITHOUT PREJUDICE'

Kindly arrange surveyor to survey our client vehicle at (URGENT)

8 Kaki Bukit Ave 4

#08-46 Premier@Kaki Bukit

Singapore 415875

Contact Person: Xiong - 8121 0478

Your Insured: SDH 8988H

DOA : 22.12.2017

Place: MCE SLIP ROAD INTO CENTRAL BOULEVARD

Time: 17:45hrs

Best Regards,

Julie 

SK Automobile Pte Ltd (201500047H)

Tel: 6789 5155

Fax: 6783 5155

DID: 9623 4440

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 29 December, 2017 3:26 PM
To: 'Teo, Grace'; assignments
Cc: SUR
Subject: RE: CMTD1704679/NSW - ACCIDENT INVLG SDH8988H & SLR6336E on 22.12.2017

Dear Grace,

Please be informed that we have inspected the vehicle SLR 6336E on 28/12/2017.

We are pending for estimate from repairer.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 27 December, 2017 4:03 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CMTD1704679/NSW - ACCIDENT INVLG SDH8988H & SLR6336E on 22.12.2017

Dear Grace,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 27 December, 2017 12:15 PM
To: Julie Johari <julie@skauto.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: XIONG <xiongskauto@gmail.com>; md daud nadzim <mddaudn731@gmail.com>
Subject: CMTD1704679/NSW - ACCIDENT INVLG SDH8988H & SLR6336E on 22.12.2017

Your Reference: SLR6336E

Our Claim Reference: CMTD1704679/NSW

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6112J
Vehicle Details	
Vehicle No.:	SLR6336E
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS RX200T LUXURY AT S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	8ARW579254
Chassis No.:	JTJBAMCAX02030383
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$56,222.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$73,200.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount:	\$54,900.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027

COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$38,000.00
Total Rebate Amount:	\$92,900.00

The information contained herein is correct as at 26 Dec 2017

OK

~~\$~~ 260000
- 92900

16,7100



**Now from \$204,999 + \$5,000 Service Credits
+ 5-Year Servicing + Immediate Registration**

[BOOK A TEST DRIVE >](#)


Username / Email Add
 password

[» Sign Up New Account](#)
[» Forgot Password](#)

Lexus RX200

Min Price ▾

to

No Max ▾

Depreciation ▾

Vehicle Type ▾

Category ▾

Advanced
Search

Home » New Cars » Lexus RX200 Search Results

Tools & Tips

[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)

Lexus RX200 Search Results (1 vehicles)

Sort by Model (Ascending) ▾

15 ▾ results/page

Car Model	Price	Dealer	Built in	User Rating
Lexus RX Turbo		Borneo Motors	Japan	
 RX200t 2.0 Executive (A)	\$251,800 ▲ \$22,100 /yr ?	• 12.3km/l 234bhp 6-speed (A)		1 User Review Promotion
RX200t 2.0 Luxury (A)	\$269,800 ▲ \$23,300 /yr ?	• 11.9km/l 234bhp 6-speed (A)		Editor's Review
RX200t 2.0 F Sport (A)	\$283,800 ▲ \$24,400 /yr ?	• 11.9km/l 234bhp 6-speed (A)		

Car Model	Price	Dealer	Built in	User Rating
				15 ▾ results/page

Car Tyres



sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

[Compare](#)

MALP17168553 / Alpha Motors Pte Ltd - HQ
ENTRY DATE & TIME: 23/12/2017 11:39
SUBMITTED BY: RONNIE TAN GUAN HIN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/12/2017 11:39
Date Of Accident 22/12/2017 17:45
Exact Location Of Accident MCE SLIP ROAD INTO CENTRAL BLVD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR6336E
Insured/Policyholder
Name Of Registered Owner CHEW ANN PHONG
NRIC No S7326112J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91260875
Alternative Phone No OFFICE-60000000
Vehicle Particulars
Manufacturer LEXUS
Model RX200T-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number VPA/P1963015
Cover Note Number
Driver
Name of Driver CHEW ANN PHONG
NRIC No S7326112J
Date Of Birth 18/07/1973
Occupation INDOOR
Date Of Driving Pass 18/07/2002
Driving Experience 15 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91260875
Fax Number
Contact Number OFFICE-60000000
Email Address NOEMAIL

Address BLK 558 HOUGANG ST 51 #10-376
 Postcode 530558
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Report please refer to sketch plan

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: GET FROM WORKSHOP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDH8986H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver GAN PAY YAP
 NRIC/Passport Number
 Contact Number 98564747
 Address
 Postcode
 Insurance Company Name SOMPO INSURANCE SINGAPORE PTE. LTD.
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim's process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such personal information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agent(s) (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *P. S. S. S. S.*
NHIC/IN No.: *571518076*

SKETCH PLAN



On 22/12/17 @ 1744 hrs, I was travelling on MCE slip road
towards Dochar Rd.

Vehicles in front stopped before the zebra crossing.
I stopped my vehicle too. My vehicle was stationary
when suddenly vehicle B, SDH 8588-H hit into the
rear of my car.

I/We declare the foregoing particulars are true in every respect.

Alfred Jones

Per cyrholder's Signature
Date & Time:

$$A = \begin{pmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1 \end{pmatrix}, \quad B = \begin{pmatrix} 1 & 0 & 0 \\ 0 & 1 & 0 \\ 0 & 0 & 1 \end{pmatrix}$$

W. H. L. G.

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Control Personnel's Signature
Name: Kerr
HHC/TM No.: 57133076

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: SOMPO	DATE	: 26-Dec-17
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLR6336E
ADDRESS	: <i>Xiao Chun</i>	MODEL	: LEXUS RX200
TEL. NO.	:	CHASSIS NO	: <i>JTJBAACA02030383</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>del d</i>	1	\$ 1,445.00	\$ 1,445.00
2	REAR BUMPER LOWER <i>del d</i>	1	\$ 1,025.00	\$ 1,025.00
3	REAR BUMPER REFLECTOR <i>RT could</i>	2	\$ 287.10	\$ 574.20
4	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 458.00	\$ 458.00
5	REAR BUMPER REINFORCEMENT SPONGE <i>could</i>	1	\$ 270.70	\$ 270.70
6	REAR BUMPER UPPER RETAINER <i>re</i>	2	\$ 70.60	\$ 141.20
7	REAR BUMPER SIDE RETAINER <i>re</i>	2	\$ 68.50	\$ 137.00
8	REAR PARKING SENSOR <i>del d</i>	2	\$ 348.00	\$ -696.00
9	TAILGATE <i>2</i>	1	\$ 1,879.00	\$ 1,879.00
10	TAILGATE WEATHERSTRIP <i>AP</i>	1	\$ 194.10	\$ 194.10
11	TAILGATE STOPPER <i>m</i>	2	\$ 32.00	\$ 64.00
12	TAILGATE EMBLEM	1	\$ 115.00	\$ 115.00
13	TAILGATE EMBLEM "LEXUS"	1	\$ 107.60	\$ 107.60
14	TAILGATE EMBLEM "RX200"	1	\$ 94.50	\$ 94.50

15	TAILLAMP RH	1	\$ 689.00	\$ 689.00	+
16	REAR WINDSCREEN MOULDING	1	\$ 158.60	\$ 158.60	+
17	REAR END PANEL	1	\$ 715.30	\$ 715.30	+
18	REAR END PANEL TOP GARNISH	1	\$ 611.70	\$ 611.70	+
19	REAR FENDER SIDE INNER TRIM RH	1	\$ 969.10	\$ 969.10	+
20	REAR AMPLIFIER SPEAKER	1	\$ 1,060.80	\$ 1,060.80	+
21	EXHAUST PIPE CHROME	1	\$ 428.00	\$ 428.00	350
22	EXHAUST BRACKET	1	\$ 180.30	\$ 180.30	+
23	EXHAUST PIPE MOUNTING	2	\$ 45.00	\$ 90.00	+

40278
3625.02

TOTAL PRICE \$ 12,104.10
LESS 10% \$ 1,210.41
SUB TOTAL PRICE \$ 10,893.69

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR WINDSCREEN INNER SEAL	1	\$ 125.00	\$ 125.00	+
2	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
3	REAR BUMPER CLIP SET	1	\$ 70.00	\$ 70.00	30
4	TAILGATE INNER TRIM CLIP SET	1	\$ 70.00	\$ 70.00	+
5	END PANEL TOP GARNISH CLIP SET	1	\$ 55.00	\$ 55.00	+
6	END PANEL JOINT SEALANT	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER SIDE INNER TRIM CLIP SET	1	\$ 120.00	\$ 120.00	30

SUB TOTAL PRICE \$ 600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,400.00	300	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,000.00	400	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 150.00	x	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 200.00	60	
5	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	x	
6	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024495/Aqbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 01-03-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDH 8988H	Veh. Inspected	SLR 6336E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704679/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/12/2017

2. Vehicle Particulars & Condition

Make & Model	LEXUS RX200	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTJBAMCAX02030383	Colour	SILVER
Odometer	7428	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm
L/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm
R/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm
L/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/12/2017	Inspection Date	28/12/2017
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6336E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,445.00	1,445.00
1	REAR BUMPER LOWER	DEFORMED	1,025.00	520.00
2	REAR BUMPER REFLECTOR @\$287.10	O/S CRACKED	574.20	287.10
1	REAR BUMPER REINFORCEMENT	BENT	458.00	458.00
1	REAR BUMPER REINFORCEMENT SPONGE	CRACKED	270.70	270.70
2	REAR BUMPER UPPER RETAINER @\$70.60	NOT NECESSARY	141.20	-
2	REAR BUMPER SIDE RETAINER @\$68.50	NECESSARY	137.00	137.00
2	REAR PARKING SENSOR @\$348.00	DAMAGED	696.00	560.00
1	TAILGATE	NOT NECESSARY	1,879.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	194.10	-
2	TAILGATE STOPPER @\$32.00	NOT NECESSARY	64.00	-
1	TAILGATE EMBLEM	NOT NECESSARY	115.00	-
1	TAILGATE EMBLEM "LEXUS"	NOT NECESSARY	107.60	-
1	TAILGATE EMBLEM "RX200"	NOT NECESSARY	94.50	-
1	TAILLAMP RH	NOT NECESSARY	689.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	158.60	-
1	REAR END PANEL	NOT NECESSARY	715.30	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	611.70	-
1	REAR FENDER SIDE INNER TRIM RH	NOT NECESSARY	969.10	-
1	REAR AMPLIFIER SPEAKER	NOT NECESSARY	1,060.80	-
1	EXHAUST PIPE CHROME	BENT	428.00	350.00
1	EXHAUST BRACKET	NOT NECESSARY	180.30	-
2	EXHAUST PIPE MOUNTING @\$45.00	NOT NECESSARY	90.00	-
	LESS 10% DISCOUNT		-1,210.41	-402.78
			10,893.69	3,625.02
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	125.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	70.00	30.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NOT NECESSARY	70.00	-
1	SET END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	55.00	-
1	END PANEL JOINT SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/SMO17024495/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER SIDE INNER TRIM CLIP (SN)	NOT NECESSARY	120.00	-
			600.00	30.00
	LABOUR			
	CUT OFF,REPLACE REAR END PANEL AND FLOOR PANEL STRAIGHTEN,REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.		1,400.00	300.00
	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.		1,000.00	400.00
	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	NOT NECESSARY	150.00	-
	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS,PERFORM DISTANCE SENSORY TESTING.		200.00	60.00
	DISMENTLE AND INSTALL REAR SEATS,SPEAKER BOARD AND SEATS TRIMMING.	NOT NECESSARY	150.00	-
	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION.		80.00	30.00
	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	NOT NECESSARY	100.00	-
	DRILL HOLE TO ENABLE REFIX TAILGATE SPOILER.	NOT NECESSARY	120.00	-
	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	NOT NECESSARY	300.00	-
	APPLY TUFF COATING TREATMENT.	NOT NECESSARY	200.00	-
			3,850.00	790.00
GRAND TOTAL			15,343.69	4,445.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/SMO17024495/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.