

22/03/2002

ASS. REC. BY:

REF: CS/III 17024498 / Uvb n2 Special Instruction:

Surveor: Maruls. ASSIGNMENT (Office)

From (Person): Meifman Adeline Tham of III Date/Time: 26/22017 4:19pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 3958A Insured: SHA 1695m

at Workshop m/s JEC Auto Tel: 6509 6585

of Blk 1 Kaki Bukit Ave 6 #03-11

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 21.12.2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 27/12/2017 Person Contacted: Ahxian Vehicle IN/OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate                     |
|-----------|---|
|           | SKG 3958A - X   |
|           | SHA 1695m - NS / INC16023874 / H1473 n2 DOA: 12.12.16 |
|           |   |
|           |   |
|           |   |
|           |   |

Surveillance/Marcus

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / PR / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SKG 3958A  
 at Workshop m/s: Jec  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 95  
 IDAC Accident Report: 9 Consistent? : Yes or No  
 G/A / PR Seen: 9 Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time Action / Instruction

Dep 15

214 8/266

3/1/18 Confirmed 4/5 @ 3000 with AH Kien. (Red 10,333.27, 2790)

RECEIVED 3 JAN 2018

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2) 3/1- typist

Report Format : merimen

Lump Sum / I.B.I: (\$) 3000

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)  
☐

Survey Fee

Transportation

\$ + RS \$

Phone

Other

TOTAL

350

10

360

Veh No: SKG 3958A Yr Regn: 30/8 12

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyo Lexus 65250 2500

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 108955 T/Radio: Insured / Std / NI / NA

Engl No:

C/No: JTHBF13L105 000269

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 235/50R18

BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 21/1/17

Survey held at

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 27/1/17

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

## Survey Department Check List (Case Handler)

Reference No.: CS/III/17024498/UVB

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

|   |                                       | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No.                         | ✓      |        |        |        |
| C | Customer Code                         |        |        |        |        |
| N | Assign From                           |        |        |        |        |
| C | Assign Date                           | ✓      |        |        |        |
| C | Veh No (Inspected)                    | ✓      |        |        |        |
| C | Veh No (Insured)                      | ✓      |        |        |        |
| C | D.O.A                                 | ✓      |        |        |        |
| C | Policy No                             | ✓      |        |        |        |
| C | Claim No                              | ✓      |        |        |        |
| C | Insurance Authorisation (CA /REV/REP) |        |        |        |        |
| C | Report Type                           | ✓      |        |        |        |
| C | Weekend Charges                       |        |        |        |        |
| N | Survey held at/Repairer               | ✓      |        |        |        |
| C | Excess                                |        |        |        |        |

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

|   |                        |   |  |  |  |
|---|------------------------|---|--|--|--|
| C | Vehicle No             | ✓ |  |  |  |
| C | Regn Month/Year        | ✓ |  |  |  |
| N | Vehicle Type           | ✓ |  |  |  |
| N | Make & Model           | ✓ |  |  |  |
| C | Engine Capacity. (C.C) | ✓ |  |  |  |
| N | Colour                 | ✓ |  |  |  |
| C | Odometer. (Sp.Reading) | ✓ |  |  |  |
| C | Chassis No             | ✓ |  |  |  |
| N | General Condition      | ✓ |  |  |  |
| N | Steering               | ✓ |  |  |  |
| N | Brake                  | ✓ |  |  |  |
| N | Modification (Modi)    | ✓ |  |  |  |
| C | Tyre Size              | ✓ |  |  |  |
| N | Tyre Make              | ✓ |  |  |  |
| C | Tyre Balance           | ✓ |  |  |  |
| C | Date of Inspection     | ✓ |  |  |  |
| N | Survey held            | ✓ |  |  |  |
| N | Des.of Damages         | ✓ |  |  |  |

**(2) System - (Views/Merimen)**

|   |                                      |   |  |  |  |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ |  |  |  |
|---|--------------------------------------|---|--|--|--|

**(3) Workshop Estimate/Assignment Form**

|   |   |   |  |  |  |
|---|---|---|--|--|--|
| N | ALL Parts condition                           | ✓ |  |  |  |
| C | Market Value for OD cases                     |   |  |  |  |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) |   |  |  |  |
| C | Days of repair                                | ✓ |  |  |  |
| C | Finalised Amount                              | ✓ |  |  |  |
| C | Re-inspection Cases to Finalize within 5 Days |   |  |  |  |

**(4) System - (Views/Merimen)**

|   |                         |   |  |  |  |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ |  |  |  |
|---|-------------------------|---|--|--|--|

Check By: VERON 3/1/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III17024498/Uvb

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 27-12-2017



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | SHA 1695M    | Veh. Inspected | SKG 3958A  |
| Policy No.   |              | Coverage (\$)  | 0.00       |
| Claim No.    |              | Excess (\$)    | 0.00       |
| Assign From  | ADELINE THAM | Assign Date    | 26/12/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 21/12/2017  | Inspection Date | 27/12/2017 |
| Survey held at | JEC AUTOMOTIVE<br>1 KAKI BUKIT AVENUE 6<br>#02-11 AUTOBAY<br>SINGAPORE 417883 |                 |            |

## 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

**Catherine Chong (LKK Auto)**

---

**From:** Adeline Tham <adelinetham@iii.com.sg> on behalf of Motor Claim - III  
<motorclaim@iii.com.sg>  
**Sent:** Tuesday, 26 December, 2017 4:19 PM  
**To:** bonnie kwok  
**Cc:** Admin A; 'SUR'; 'LKK - Assignments'  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKG3958A (Accident involving SKG3958A and SHA1695M on 21.12.2017)

Dear Sir,

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO : SKG3958A

III INSURED VEHICLE NO. : SHA1695M

DATE OF LOSS : 21.12.2017

We acknowledge receipt of your letter dated 26.12.2017.

Our insured has reported the above accident to us.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

-You have agreed to the appointment of our surveyor.

Therefore, we have appointed our surveyor LKK Auto Consultants Pte Ltd to conduct the pre-repair survey.

This claim is handled by Ms Priya

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**  
**\*\*Surveyor kindly upload this assignment to Merimen.**

**Thank You.**

Best Regards,

Adeline Tham  
Motor Claims Department  
India International Insurance Pte Ltd  
64 Cecil Street #05 IOB Building  
Singapore 049711

**From:** bonnie kwok [mailto:litigation@bonniekwok.com]  
**Sent:** Tuesday, 26 December, 2017 2:28 PM  
**To:** Motor Claim - III  
**Subject:** Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKG3958A (Accident involving SKG3958A and SHA1695M on 21.12.2017)

Dear Gabriel,

Our client agree to

• Adrin Ling of LKK Auto Consultants Pte Ltd as SJE.

Regards,  
June

On 22 December 2017 at 15:06, Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
**India International Insurance Pte Ltd**  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination



of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

**BONNIE KWOK LLC**

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                          |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars      |                          |
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 7390F                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SKG3958A                 |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 29 Dec 2017              |
| Vehicle Make:                  | TOYOTA                   |
| Vehicle Model:                 | LEXUS GS250 F SPORT AUTO |
| Primary Colour:                | Black                    |
| Manufacturing Year:            | 2012                     |
| Engine No.:                    | 4GR0805813               |
| Chassis No.:                   | JTHBF1BL105000269        |
| Maximum Power Output:          | 154.0 kW (206 bhp)       |
| Open Market Value:             | \$57,428.00              |
| Original Registration Date:    | 30 Aug 2012              |
| First Registration Date:       | 30 Aug 2012              |
| Transfer Count:                | 0                        |
| Actual ARF Paid:               | \$57,428.00 28714        |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 29 Aug 2022              |
| PARF Rebate Amount:            | \$40,199.00              |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 29 Aug 2022              |
| COE Category:                  | E - Open Category        |

|                             |                    |
|-----------------------------|--------------------|
| COE Period(Years):          | 10                 |
| QP Paid:                    | \$93,990.00        |
| COE Rebate Amount:          | \$41,067.00        |
| <b>Total Rebate Amount:</b> | <b>\$81,266.00</b> |

The information contained herein is correct as at 27 Dec 2017

OK

MSME17166310 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 22/12/2017 16:31  
SUBMITTED BY: Pei Ying

JEC  
JUNE

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 22/12/2017 16:31  
Date Of Accident 21/12/2017 13:30  
Exact Location Of Accident KARMAT ROAD  
Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SKG3958A  
**Insured/Policyholder**  
Name Of Registered Owner KWEK SIOK LIN ANGELINE GERMAINE  
NRIC No S7707390F  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-94578175  
Alternative Phone No OFFICE-94578175

**Vehicle Particulars**

Manufacturer LEXUS  
Model GS250  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number P27565065DMA  
Cover Note Number

**Driver**

Name of Driver KWEK SIOK LIN ANGELINE GERMAINE  
NRIC No S7707390F  
Date Of Birth 15/03/1977  
Occupation INDOOR  
Date Of Driving Pass 09/03/2005  
Driving Experience 12 YEARS AND 9 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-94578175  
Fax Number  
Contact Number OFFICE-94578175  
Email Address NOEMAIL

Address BLK 637 BEDOK RESERVOIR ROAD #16-37  
 Postcode 410637  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

MY CAR WAS STATIONARY BEHIND THE STOP LINE AT KARMAT ROAD'S EXIT. THE TAXI BEHIND, A BLUE COMFORT (SHA1695M) KNOCKED MY CAR FROM BEHIND.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHA1695M  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category TAXI  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1


## SKETCH PLAN


## IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


My car was stationary behind the stop line at Kramat Road's exit. The taxi, a blue comfort, SHA 1695 M knocked my car from behind.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

(BASIC SketchPlan Form, 5/2)

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# JEC AUTO SERVICE

1 Kaki Bukit Avenue 6 #02-11 Autobay, Singapore 417883

H/P : 9232 7457

Fax : 6509 6584

Email : jecautoservice@yahoo.com.sg

Vehicle No. : SKG 3958A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Model: Lexus GS250F

Date:

| Qty | List Price   |
|-----|--|
| 1   | Rear Bumper <i>we/changed</i>                      |
| 1   | Rear Bumper Sponge <i>70.1</i>                     |
| 1   | Rear Bumper Reinforcement <i>70.1</i>              |
| 2   | Rear Bumper Side Retainers-R/L @\$95.50 <i>msd</i> |
| 2   | Rear Bumper Reflector @\$68.55 <i>msd</i>          |
| 1   | Rear Bumper Lower Spoiler <i>n</i>                 |
| 2   | Rear Bumper Bold Cover @\$18.50 <i>11</i>          |
| 2   | Rear Bumper PDC Sensor @\$381.30 <i>switch 1/5</i> |
| 1   | Rear Bumper PDC Sensor Wire Harness <i>11</i>      |
| 10  | Rear Bumper Clip @\$4.50 <i>new</i>                |
| 2   | Rear Tail Lamps- R/L @\$637.80 <i>msc</i>          |
| 1   | Rear Boot Inner Trim <i>11</i>                     |
| 1   | Rear End Panel <i>n</i>                            |
| 1   | Rear End Panel Garnish <i>11</i>                   |
| 3   | Rear End Panel Garnish Clip @\$4.50 <i>11</i>      |
| 2   | Rear Exhaust @\$1082.80 <i>11</i>                  |
| 2   | Rear Exhaust chrome @\$182.60 <i>msd</i>           |

Less 10%

*252*

Subtotal

| Price                   |
|-------------------------|
| \$ 930.60               |
| \$ 181.60               |
| \$ 655.20               |
| \$ 191.00 <i>12C</i>    |
| \$ 137.10 <i>12C</i>    |
| \$ 678.50 <i>2</i>      |
| \$ 37.00 <i>2</i>       |
| \$ 762.60 <i>20C</i>    |
| \$ 281.60 <i>X</i>      |
| \$ 45.00 <i>✓</i>       |
| \$ 1,275.60 <i>72C</i>  |
| \$ 189.65 <i>2</i>      |
| \$ 720.60 <i>2</i>      |
| \$ 395.50 <i>2</i>      |
| \$ 13.50 <i>2</i>       |
| \$ 2,165.60 <i>2</i>    |
| \$ 365.20 <i>12C</i>    |
| \$ 9,025.85             |
| (902.59) <i>3178.15</i> |
| 8123.27 <i>2383.61</i>  |

## Labour Charges:

|  |                        |
|--|------------------------|
| To Checking Rear Electrical Wiring                         | \$ 180.00 <i>20</i>    |
| To Remove, Replace And Reset Bumper PDC Sensor             | \$ 220.00 <i>50</i>    |
| To Remove, Refix R/interior Trims To Assit Repair          | \$ 250.00 <i>60</i>    |
| To Remove and Replace Exhaust                              | \$ 11 250.00 <i>2</i>  |
| To Respray Undercoating                                    | \$ 11 250.00 <i>2</i>  |
| To Diagnose, Erase Fault Memory After Repair               | \$ 11 450.00 <i>2</i>  |
| To Respray Painting and etc                                | \$ 1,800.00 <i>600</i> |
| Panel Beating, Cut, Weld, Remove and Replacing Above Parts | \$ 1,800.00 <i>650</i> |
| Subtotal   | \$ 5,200.00            |

ESTIMATE PARTS AND LABOUR GRAND TOTAL

13,323.27



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III17024498/UVBN2

Date: 08/01/2018

**REFERENCE**

|                       |                                       |                      |          |
|-----------------------|---------------------------------------|----------------------|----------|
| Handling Insurer:     | India International Insurance Pte Ltd | Policy No:           |          |
| Claimant Vehicle No : | SKG3958A                              | Insured Vehicle No : | SHA1695M |
| Date of Loss:         | 21/12/2017                            | Nature of Claim:     | TP       |
|                       |                                       | Claim No:            | N/A      |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SKG3958A                     | Engine No:  | 4GR0805813        |
| Make & Model:               | LEXUS GS250, 2.5 (A)         | Chassis No: | JTHBF1BL105000269 |
| Reg. Date:                  | 30/08/2012 (Man. Year: 2012) | Odometer:   | 109955 km         |
| Colour:                     | Black                        |             |                   |
| Engine Capacity:            | 2500 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 235/50R18     | Rear Tyre Size:  | 235/50R18     |
| Front Left Side:  | Goodyear 7 mm | Rear Left Side:  | Goodyear 7 mm |
| Front Right Side: | Goodyear 7 mm | Rear Right Side: | Goodyear 7 mm |

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

|  | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--|------------------|-----------------|------------------|--------------|
| Parts                                    | 8,123.26         | 2,383.61        | 5,739.65         | 70.66        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 5,200.00         | 1,380.00        | 3,820.00         | 73.46        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>13,323.26</b> | <b>3,763.61</b> | <b>9,559.65</b>  | <b>71.75</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>3,000.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                 | <b>13,323.26</b> | <b>3,000.00</b> | <b>10,323.26</b> | <b>77.48</b> |

**INSPECTION**

|                     |                          |   |
|---------------------|--------------------------|---|
| Date of Assignment: | 26/12/2017               |   |
| Date Inspected:     | 27/12/2017 Inspected At: | Jec Automotive (HQ)<br>1 KAKI BUKIT AVENUE 6, #02-11<br>AUTOBAY<br>Singapore 417883 |

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 08 Jan 2018)  |
| <b>Parts:</b> 143  | LEXUS GS250 2.5 (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SKG3958A) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition       | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------------|-----------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                         | Deformed/Warped | 930.60 FL   | *930.60 FL |
| 2   | 1   |          | *REAR BUMPER SPONGE                  | Torn            | 181.60 FL   | *181.60 FL |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT           | Dented          | 655.20 FL   | *655.20 FL |
| 4   | 1   |          | *REAR BUMPER SIDE RETAINERS-R/L      | N/s Bent        | 191.00 FL   | *95.50 FL  |
| 5   | 1   |          | *REAR BUMPER REFLECTOR               | N/s Scratched   | 137.10 FL   | *68.55 FL  |
| 6   | 1   |          | *REAR BUMPER LOWER SPOILER           | Repair          | 678.50 FL   | *- FL      |
| 7   | 2   |          | *REAR BUMPER BOLD COVER              | Not Necessary   | 37.00 FL    | *- FL      |
| 8   | 1   |          | *REAR BUMPER PDC SENSOR              | N/s Shorted     | 762.60 FL   | *381.30 FL |
| 9   | 1   |          | *REAR BUMPER PDC SENSOR WIRE HARNESS | Not Necessary   | 281.60 FL   | *- FL      |
| 10  | 10  |          | *REAR BUMPER CLIP                    | Necessary       | 45.00 FL    | *45.00 FL  |
| 11  | 1   |          | *REAR TAIL LAMPS-R/L                 | N/s Cracked     | 1,275.60 FL | *637.80 FL |
| 12  | 1   |          | *REAR BOOT INNER TRIM                | Not Necessary   | 189.65 FL   | *- FL      |
| 13  | 1   |          | *REAR END PANEL                      | Repair          | 720.60 FL   | *- FL      |
| 14  | 1   |          | *REAR END PANEL GARNISH              | Not Necessary   | 395.50 FL   | *- FL      |
| 15  | 3   |          | *REAR END PANEL GARNISH CLIP         | Not Necessary   | 13.50 FL    | *- FL      |
| 16  | 2   |          | *REAR EXHAUST                        | Not Necessary   | 2,165.60 FL | *- FL      |
| 17  | 1   |          | *REAR EXHAUST CHROME                 | N/s Scratched   | 365.20 FL   | *182.60 FL |

F=Franchise part. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>9,025.85</b> | <b>3,178.15</b> |
| <b>- List Item Discount on L Items 10.00/25.00% (S\$)</b> | <b>902.59</b>   | <b>794.54</b>   |
| <b>Total Parts (S\$)</b>                                  | <b>8,123.26</b> | <b>2,383.61</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | TO CHECKING REAR ELECTRICAL WIRING                      | New      | 180.00          | 20.00           |
| 2                              | TO REMOVE,REPLACE AND RESET BUMPER PDC SENSOR           | New      | 220.00          | 50.00           |
| 3                              | TO REMOVE,REFIX R/INTERIOR TRIMS TO ASSIST REPAIR       | New      | 250.00          | 60.00           |
| 4                              | TO REMOVE AND REPLACE EXHAUST                           | New      | 250.00          | -               |
| 5                              | TO RESPRAY UNDERCOATING                                 | New      | 250.00          | -               |
| 6                              | TO DIAGNOSE,ERASE FAULT MEMORY AFTER REPAIR             | New      | 450.00          | -               |
| 7                              | TO RESPRAY PAINTING AND ETC                             | New      | 1,800.00        | 600.00          |
| 8                              | PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS | New      | 1,800.00        | 650.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>5,200.00</b> | <b>1,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >