

TEL: 6841 0055 FAX: 6841 6315





NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC17024525/K1vbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	09-01-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJE 5477E	Veh. Ir	nspected	SHC 2598T	
	Policy No.	5087675899	Cover	age (\$)	0.00	
	Claim No.	MT/0974708-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	22/12/2017	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2010	
	Chassis No.	KMHET41VMAA798027	Colou	r	BLUE	
	Odometer	54541	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MAXXI	S	7 mm	
	L/H Front Tyre	215/60 R16	MAXXI	S	7 mm	
	R/H Rear Tyre	215/60 R16	MAXXI		7 mm	
	L/H Rear Tyre	215/60 R16	MAXXI	S	7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	21/12/2017	Insped	tion Date	22/12/2017	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		4 Working Days		