MCD617169871 / ComfortDelGro Engineering Pte Ltd - Loyang ENTRY DATE & TIME: 27/12/2017 13:31 SUBMITTED BY: Catherine Por Moy Juan

#### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	27/12/2017 13:31
Date Of Accident	27/12/2017 09:00
Exact Location Of Accident	DRIVEWAY BESIDE SERANGOON AVE 2
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHA3709U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-15072701MFSH
Cover Note Number	
Driver	
Name of Driver	SEE-THO KWOK WENG
NRIC No	S0031115D
Date Of Birth	05/09/1953
Occupation	OUTDOOR
Date Of Driving Pass	15/01/1974
Driving Experience	43 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	

NOEMAIL

Address

207A #10-938 PUNGGOL PLACE

Postcode

821207

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SKA3749T

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

LIM TONG TECK

NRIC/Passport Number

S8020818I

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

LEFT SIDE

No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1



### SHA 3709 U

### ACCIDENT STATEMENT

Recorded by Alex Lim

This morning (27/12/2017), I travelled on the carpark driveway after exiting Serangoon Avenue 2. I was then on the way to pick up a female passenger who earlier had booked my taxi.

As seen in the video footage, while I drove normally on the driveway towards the destination, it was car B(SKA 3749T) that caused the accident amid moving out from the exit of the multi-storey carpark at Blk 238A without stopping at the exit point.

There was a stop line at the carpark exit.

In the accident, I found the front portion of my taxi was damaged while the whole left side to car B sustained dents.

I took photos at the scene and also exchanged particulars with the driver of car B.

No report of injury.

I affirmed the above-statement is true

and correct.

Driver name : See-Tho Kwok Weng

NRIC NO : S 0031115D

Date: 27/12/2017