Surveyor: Faisal | REF: 24538 | eb3 | 25412

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 9961H

at Workshop m/s Allswell

of 25, DEFULANG 9

Insured: AIG/up

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJV 9961H Yr Regn: 2010 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: TOYOTA COROLLA ALTIS 1.6A cc 1598

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading 218641 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053ZEE106168905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or KAPSEN

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	14/12/17	D.O.I.	09/02/18

Survey held at ALLSWELL

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or NO FRG

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) _____ ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: ___$ + RS___SI

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ : Tech. Invs ($ _____) ☐ : Weekend ($ _____)

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: ($ _____)