

22/07/2012

ASS. REC. BY:

REF: CS/EG17024589/T19d3ⁿ² Special Instruction:

Survisor:

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EG1 Date/Time: 27/12/17 @ 5:13pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 1282A Insured: YK 341L

at Workshop m/s Cycle & Carriage Kia Tel: 6568 4501

of 209 Pandan Gardens

Policy No: Claim No: DSMFH1702744

Sum Insured: Excess:

Make of Veh:
(Client's Record)

D.O.A. 22/11/2017

CA / REV / REP. / REV 24 HRS

'up

02/01/2017 @ after 9am

H.O.D. Endorsement:

Date/Time: 11:23am @ 28/12/17

Person Contacted: Mr. Tay

Vehicle IN OUT

Date/Time Action/Instruction (✓) Estimate

SKV1282A-CC4/AIG16012516/Aya3

D.O.A: 04/07/2016

YK341L-X

04/1/18 @ 8:10pm revised to Pei Li by email.

Signature

Taufik

REP: EGI

ASSIGNMENT

From: _____ Date: 02/01/17

Estimated Cost: _____

OD / ☒ PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKV1282A
at Workshop m/s: Cycle & Carriage Kia
of: 209 Pandan Gardens

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

After 9am

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wpr'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV1282A Yr Regn: 2015 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Forte K3 d.c. 1591

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 85593 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C.No: KNA F241 / M#5471033

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brakes: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 02/01/18 @ 1230

Survey held at: C&C Pandan Groh

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12054, 3 days. E-mail to Larry.
(led to 3173, 61%)

Date/Time File Pass to? ☐ : Preli. Report

05/3 turned ☐ : Final Report

Date/Time File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

8-PM-SI

Phone

Others

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Report Format: Tr

Lump Sum / J.B.I: (\$ 2054)

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17024589/qd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 28-12-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YK 341L	Veh. Inspected	SKV 1282A
Policy No.		Coverage (\$)	0.00
Claim No.	DSMFH1702744	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/11/2017	Inspection Date
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMFH1702744

Date: 04th January 2018

Our Ref: CS/EG117024589/T1qd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKV 1282A


We thank you for the instruction on 27/12/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/01/2018 at the premises of M/s CYCLE & CARRIAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,227.00</u>
Revised Estimate Amount	: S\$ <u>2,288.00</u>
"Check" Items Amount	: S\$ <u>869.00</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

Taufikh
Automotive Assessor

Survey Department Check List (Case Handler)

Reference No.: CEG/1704589/TLad3
Policy Type: OD / TP / TP RES / TL / EVA

SKV1282A

Case Handler

Typist

Admin (Nurph): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	<input checked="" type="checkbox"/>			
C Customer Code	<input checked="" type="checkbox"/>			
N Assign From	<input checked="" type="checkbox"/>			
C Assign Date	<input checked="" type="checkbox"/>			
C Veh No (Inspected)	<input checked="" type="checkbox"/>			
C Veh No (Insured)	<input checked="" type="checkbox"/>			
C D.O.A	<input checked="" type="checkbox"/>			
C Policy No	<input checked="" type="checkbox"/>			
C Claim No	<input checked="" type="checkbox"/>			
C Insurance Authorisation (CA /REV/REP)	<input checked="" type="checkbox"/>			
C Report Type	<input checked="" type="checkbox"/>			
C Weekend Charges	<input checked="" type="checkbox"/>			
N Survey held at/Repairer	<input checked="" type="checkbox"/>			
C Excess	<input checked="" type="checkbox"/>			

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	<input checked="" type="checkbox"/>			
C Regn Month/Year	<input checked="" type="checkbox"/>			
N Vehicle Type	<input checked="" type="checkbox"/>			
N Make & Model	<input checked="" type="checkbox"/>			
C Engine Capacity. (C.C)	<input checked="" type="checkbox"/>			
N Colour	<input checked="" type="checkbox"/>			
C Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>			
C Chassis No	<input checked="" type="checkbox"/>			
N General Condition	<input checked="" type="checkbox"/>			
N Steering	<input checked="" type="checkbox"/>			
N Brake	<input checked="" type="checkbox"/>			
N Modification (Modi)	<input checked="" type="checkbox"/>			
C Tyre Size	<input checked="" type="checkbox"/>			
N Tyre Make	<input checked="" type="checkbox"/>			
C Tyre Balance	<input checked="" type="checkbox"/>			
C Date of Inspection	<input checked="" type="checkbox"/>			
N Survey held	<input checked="" type="checkbox"/>			
N Des.of Damages	<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>			
--	-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	<input checked="" type="checkbox"/>			
C Market Value for OD cases	<input checked="" type="checkbox"/>			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)	<input checked="" type="checkbox"/>			
C Days of repair	<input checked="" type="checkbox"/>			
C Finalised Amount	<input checked="" type="checkbox"/>			
C Re-inspection Cases to Finalize within 5 Days	<input checked="" type="checkbox"/>			

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	<input checked="" type="checkbox"/>			
---------------------------	-------------------------------------	--	--	--

Check By: Ch 05/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 27 December, 2017 5:13 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YK341L / TP : SKV1282A/LKK / DOA : 22/11/2017 (DSMFH1702744)
Attachments: YK341L - SAS.pdf; SKV1282A - SAS.pdf; SKV1282A - PRS FORM.pdf; SKV1282A - ESTIMATE.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE KIA PTE LTD**.

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : TAY JIAN YE @ 6568 4515

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 30.11.2017
Our Reference: DSMFH1702744/RH/pl
Your Reference: SKV 1282A

To: CYCLE & CARRIAGE KIA PTE LTD

Sent via Fax ☐
or
Email jianye.tay@cyclecarriage.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKV 1282A
Insured's Vehicle: YK 341L
Date Of Accident: 22.11.2017


We acknowledge receipt of your request for PRS on: 29.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OIC is Rohaini</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:


Workshop use only:

Assessor attended workshop on:

Date: 02 Jan 18
Time: After 9am
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.


Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 4 January, 2018 5:10 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); assignments
Cc: SUR
Subject: RE: YK341L / TP : SKV1282A/LKK / DOA : 22/11/2017 (DSMFH1702744)
Attachments: CSEGI17024589T1qd3.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SKV 1282A.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 28 December, 2017 2:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments
<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YK341L / TP : SKV1282A/LKK / DOA : 22/11/2017 (DSMFH1702744)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 02/01/2018.

"Wishes you a Happy New Year 2018"

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 27 December, 2017 5:13 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YK341L / TP : SKV1282A/LKK / DOA : 22/11/2017 (DSMFH1702744)

Dear Catherine,


Accident Photo



Accident Photo




Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8480470C



Name:
TAN SHWU YONG



Race
CHINESE
Date of birth
28-02-1984
Country/Place of birth
MALAYSIA

Sex
F

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8480470C

Name:
TAN SHWU YONG



Birth Date: 28 Feb 1984
Issue Date: 07 Jul 2015

FOR C&C USE ONLY



002448085K



5327090



NRIC No. S8480470C



Date of Issue
10-07-2014

FOR C&C USE ONLY

Address

APT BLK 271B JURONG WEST STREET 24
#13-44
SINGAPORE 642271

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B
Class 3

Motorcycles \leq 200 cc

Motor Cars \leq 3000kg with \leq 7 passengers, exclusive
of the driver; and other motor vehicles \leq 2500kg


EFFECTIVE DATE

30 Jan 2010

30 Jan 2010


FOR C&C USE ONLY

NP 428A



Licence No: S8480470C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8480470C



Name
TAN SHWU YONG

FOR C&C USE ONLY

Race
CHINESE

Sex
F

Date of birth
28-02-1984

Country/Place of birth
MALAYSIA



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8480470C

Name:
TAN SHWU YONG

FOR C&C USE ONLY

Birth Date: 28 Feb 1984

Issue Date: 07 Jul 2015



002448085K



5327090



NRIC No. S8480470C



FOR C&C USE ONLY

Date of Issue
10-07-2014

Address


APT BLK 271B JURONG WEST STREET 24
#13-44
SINGAPORE 642271

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles \leq 200 cc	30 Jan 2010
Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg	30 Jan 2010

FOR C&C USE ONLY

NP 428A



Licence No: S8480470C



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DEONG BAN SOON	Cust No/Name /MR DEONG BAN SOON
BLK 271B JURONG WEST ST 24	Reg No/Reg Date SKV1282A / 31/08/201
#13-44	Date In/Mileage / 0
642271	Chassis No KNAFZ41MF5471033
Contact No Mobile: 97294963	Engine No G4FGFH784347
	Make/Model KIA/FORTE K3 1.6 A SX AAC PREMIUM
	Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	29/11/2017/ 11:36		465 / Tay Jian Ye	18848

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER AND REPAIR END PANEL				550 1650.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER AND END PANEL				420 1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY TO APPLY ANTI CORROSION ON AFFECTED PORTION				nn x 80.00
M SUNDRY SUNDRIES				20 50.00
M STAY-RR BUMPER LH	1.00	75.00	00.00	75.00
M STAY-RR BUMPER RH	1.00	75.00	00.00	75.00
M BEAM-RR BUMPER	1.00	360.00	00.00	360.00
M BRACKET-RR BEAM LWR MTG	2.00	5.00	00.00	10.00
M BRACKET-RR BEAM LWR,CTR	1.00	5.00	00.00	5.00
M COVER-RR BUMPER	1.00	768.00	00.00	768.00
M BRACKET-RR BUMPER SIDE MTG,LH	1.00	33.00	00.00	33.00
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	33.00	00.00	33.00
M COVER-RR BUMPER,UPR	1.00	234.00	00.00	234.00
M ULTRASONIC SENSOR ASSY-FBWS	1.00	172.00	00.00	172.00
M ULTRASONIC SENSOR ASSY-FBWS	1.00	172.00	00.00	172.00

SURVEYOR NAME: Tanjim 97495745SURVEYOR SIGNATURE: [Signature]DATE: 02/01/17 @ 1230REMARKS: Renewing by paint 'wp'
surp (w/ant-rain) 3days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Confirm & accepted by
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

7% GST on **Nett** 5,227.00
365.89

Total Payable 5,592.89

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DEONG BAN SOON	Cust No/Name /MR DEONG BAN SOON
BLK 271B JURONG WEST ST 24	Reg No/Reg Date SKV1282A / 31/08/2015
#13-44	Date In/Mileage 02/01/2018/ 55593
642271	Chassis/Package KNAFZ411MF5471033 /FS314K3
Contact No Mobile: 97294963	Engine No G4FGFH784347
02/01/	Make/Model KIA/FORTE K3 1.6 A SX AAC PREMIUM
	Colour/Trim SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/01/2018/ 15:25	TLT	884 / Lauro Songcuan	18848

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER				550.00 ✓
E PNT98000 SPRAY PAINT REAR BUMPER				420.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X COVER-RR BUMPER ✓	1.00	768.00	00.00	768.00 ✓
X BRACKET-RR BUMPER SIDE MTG,LH ✓	1.00	33.00	00.00	33.00 ✓
X BRACKET-RR BUMPER SIDE MTG,RH ✓	1.00	33.00	00.00	33.00 ✓
Z TEXT TP ERGO DOA: 22/11/2017 SURVEYOR: TAUFILH LKK 02.01.17				

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	834.00	Nett	2,054.00
Labour	1,200.00	7% GST on	143.78
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	2,054.00	Total Payable	2,197.78

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK
Taufikh

VEHICLE NO : SKV 1282 A

MODEL : KIA/FORTE K3 1.6 A SX

WIP : 18848

Material	:	\$	<u>834.00</u>
Labour	:	\$	<u>1,220.00</u>
Sub-Total	:	\$	<u>2,054.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>2,054.00</u>
GST 7%	:	\$	<u>143.78</u>
Grand Total	:	\$	<u>2,197.78</u>
Finalise By/Date : <u>Lanny ON 26/01/18</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS

* TP vehicle no: YK341 L (ERGO)

* GIA search fee \$ 2.00

* Claim loss of RENTAL.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17024589/T1qd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 06-03-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YK 341L	Veh. Inspected	SKV 1282A	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMFH1702744/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE K3	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAFZ411MF5471033	Colour	WHITE	
Odometer	55593	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2017	Inspection Date	02/01/2018	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 1282A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	75.00	-
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	75.00	-
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	360.00	-
2	BRACKET-RR BEAM LWR MTG (SN)	NOT NECESSARY	10.00	-
1	BRACKET-RR BEAM LWR CTR (SN)	NOT NECESSARY	5.00	-
1	COVER-RR BUMPER (SN)	DEFORMED	768.00	768.00
1	BRACKET-RR BUMPER SIDE MTG,LH (SN)	NECESSARY	33.00	33.00
1	BRACKET-RR BUMPER SIDE MTG,RH (SN)	NECESSARY	33.00	33.00
1	COVER-RR BUMPER,UPR (SN)	NOT NECESSARY	234.00	-
1	ULTRASONIC SENSOR ASSY-FBWS (SN)	NOT NECESSARY	172.00	-
1	ULTRASONIC SENSOR ASSY-FBWS (SN)	NOT NECESSARY	172.00	-
			1,987.00	854.00
<u>LABOUR</u>				
	TO RENEW REAR BUMPER AND REPAIR END PANEL.		1,650.00	550.00
	PAINT WORK SPRAY REAR BUMPER AND END PANEL.		1,260.00	420.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	TO APPLY ANTI COROSSION ON AFFECTED PORTION.	NOT NECESSARY	80.00	-
			3,240.00	1,200.00
GRAND TOTAL			5,227.00	2,054.00
RECOMMENDED COST OF REPAIRS				2,054.00

Report Ref No. CS/EGI17024589/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.