

INS. CASE OWNER:

CC 4 ASM 4608, AUB 9/1 LKK: IDAC

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 22/11/18

After call ltr to OI: 22/11/18 - no on

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L6

S\$

4,000.00

(6 days)

Reduction:

70 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

11c

Repair Cost:

(21/11/18)

S\$

4,280.00

Loss of Rental (LOR):

S\$

-

(1 days)

Loss of Use (LOU):

S\$

4,000.00

x 6

days

Loss of Income (LOI):

S\$

-

(15 x days)

LOI only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

5.35

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

4,765.35

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4,765.35

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$380.00

REFERENCE NUMBER	
CCA / 10017024608 / AUB3	
DATE / TIME	ACTIONS / REMARKS
19/01/18	- AXA APPROVED WARRANTY @ 01/9 & 4.5K (AU N)
21/01/18	- SEND 1st OFFER TO TP.
21/01/18	- TP REQUESTED OFFER. PROPOSED FOR \$4,925.55.
21/01/18	- RESOLV WARRANTY
26/01/18	- AXA REQUESTED IMPROVED OFFER TO \$4,765.55. WARRANTY ON @ \$60/DAY.
	- SEND 2nd OFFER TO TP.
27-02-18	TO MONITOR REPLY FROM TP ON OUR IMPROVED OFFER.
21/01/18	- REQUESTED BY TP ACCEPTED OFFER.
	- ALL DONE IN ORDER.
	- TO CLOSE.

(2/2)

REF:

ASSIGNMENT

24/06/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SI6 1728Y Yr Regn: 2008 JuneType: ☒ M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante cc 1591Colour: Grey AC Insured / Std / NI / NASp. Reading: 24324 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ~~KMH~~ KMH D441 BR8U S25B6Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 185/65 R15R: 185/65 R15BS / ☒ OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 28/12/17Survey held at: M4 Solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA

U6 @ 4,000.00 (PMD: @ 9,305.36/70%)

MV: 11.2K

PV: 12.2K

Nett: AK

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

2) _____

Transportation: _____

Add Fee: ☐ Site Insp. (\$ _____)

S + RS: \$ _____

☐ Interview (\$ _____)

Photos: _____

☐ Tech. Insp. (\$ _____)

Other: _____

☐ Weekend (\$ _____)

TOTAL: _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM17024608/Ahb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 28-12-2017



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 688L	Veh. Inspected	SJG 1728Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/12/2017	Inspection Date	28/12/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE	DATE	: 26/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJG1728Y		
MODEL	: HYUNDAI AVANTE 1.6A	Vic	
CHASSIS NO		KMHDDU41BR8U525186	
<u>ACCIDENT DETAILS</u>		DATE	: 22-Dec-17
		TIME	: 22:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER Distorted	1	\$ 482.20	\$ 482.20
2	FRONT BUMPER LOWER GRILLE New	1	\$ 167.50	\$ 167.50
3	FRONT BUMPER FOGLAMP GARNISH New	1	\$ 89.20	\$ 89.20
4	FRONT BUMPER SIDE RETAINER New	1	\$ 43.60	\$ 43.60
5	FRONT BUMPER REINFORCEMENT Best	1	\$ 322.20	\$ 322.20
6	FRONT BUMPER SPONGE Cooled	1	\$ 123.00	\$ 123.00
7	FRONT BUMPER UNDER COVER Not on	1	\$ 190.00	\$ 190.00
8	HEAD LAMP LH Cooled	1	\$ 480.00	\$ 480.00
9	HEAD LAMP LOWER BRACKET LH New	1	\$ 89.00	\$ 89.00
10	FRONT FENDER RH Distorted	1	\$ 450.00	\$ 450.00
11	FRONT FENDER EMBLEM 'VVT' RH New	1	\$ 29.60	\$ 29.60
12	FRONT FENDER INNER COWLING Distorted	2	\$ 95.40	\$ 190.80
13	FRONT DOOR LH New	1	\$ 1,055.20	\$ 1,055.20
14	SUPPORT PANEL Cooled	1	\$ 890.00	\$ 890.00
15	FRONT KNUCLE ARM Best	1	\$ 376.40	\$ 376.40
16	FRONT KNUCLE BEARING New	1	\$ 183.90	\$ 183.90
17	FRONT WHEEL HUP Distorted	1	\$ 192.80	\$ 192.80
18	FRONT SHOCK ABSORBER Best	1	\$ 349.60	\$ 349.60

29730

19	FRONT LOWER ARM <i>Best</i>	1	\$ 422.30	\$ <u>422.30</u>	<i>✓</i>
20	FRONT DRIVESHAFT <i>2nd</i>	1	\$ 1,679.80	\$ 1,679.80	<i>x</i>
21	FRONT STEERING RACK AND PINION <i>2nd</i>	1	\$ 1,974.60	\$ 1,974.60	<i>x</i>

4274.40
3419.52

TOTAL PRICE \$ 9,781.70
LESS 20% \$ 1,956.34
SUB TOTAL PRICE \$ 7,825.36

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP(SET) <i>2nd</i>	1	\$ 20.00	\$ 20.00	<i>-</i>
2	FRONT BUMPER LOWER LID <i>cracked</i>	1	\$ 890.00	\$ <u>890.00</u>	<i>600</i>
3	FRONT FENDER SEALANT LH <i>me</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
4	FRONT FENDER COWLING LH <i>clips LH</i> <i>me</i>	1	\$ 20.00	\$ 20.00	<i>-</i>
5	FRONT WHEEL TYRE <i>2nd</i>	1	\$ 450.00	\$ 450.00	<i>x</i>
6	FRONT WHEEL RIM <i>2nd</i>	1	\$ 850.00	\$ <u>850.00</u>	<i>400</i>

1040

TOTAL \$ 2,310.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ <u>1,200.00</u>	<i>700</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ <u>1,200.00</u>	<i>600</i>	
3	WIRING CHECK	\$ <u>60.00</u>	<i>30</i>	
4	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>	
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ <u>320.00</u>	<i>220</i>	
6	TO PRESS FRONT WHEEL BEARING	\$ 80.00	<i>x</i>	
7	FOUR WHEEL ALIGNMENT	\$ <u>100.00</u>	<i>30</i>	
8	TO TRANSFER FRONT DOOR FITTING	\$ 150.00	<i>x</i>	

1580

TOTAL \$3,170.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 10,135.36
TOTAL LABOUR COST \$ 3,170.00
TOTAL REPAIR COST \$ 13,305.36

Adrian G
4/5 28/12/17
0629
told 6089.52
4/5 4K

1. K.A. ...
2. ...
3. ...
4. ...
5. ...
6. ...
7. ...
8. ...
9. ...
10. ...
11. ...
12. ...
13. ...
14. ...
15. ...
16. ...
17. ...
18. ...
19. ...
20. ...
21. ...
22. ...
23. ...
24. ...
25. ...
26. ...
27. ...
28. ...
29. ...
30. ...
31. ...
32. ...
33. ...
34. ...
35. ...
36. ...
37. ...
38. ...
39. ...
40. ...
41. ...
42. ...
43. ...
44. ...
45. ...
46. ...
47. ...
48. ...
49. ...
50. ...
51. ...
52. ...
53. ...
54. ...
55. ...
56. ...
57. ...
58. ...
59. ...
60. ...
61. ...
62. ...
63. ...
64. ...
65. ...
66. ...
67. ...
68. ...
69. ...
70. ...
71. ...
72. ...
73. ...
74. ...
75. ...
76. ...
77. ...
78. ...
79. ...
80. ...
81. ...
82. ...
83. ...
84. ...
85. ...
86. ...
87. ...
88. ...
89. ...
90. ...
91. ...
92. ...
93. ...
94. ...
95. ...
96. ...
97. ...
98. ...
99. ...
100. ...

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7737C
Vehicle Details	
Vehicle No.:	SJG1728Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	G4FC8U457854
Chassis No.:	KMH DU41BR8U525136
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$13,104.00
Original Registration Date:	24 Jun 2008
First Registration Date:	24 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$13,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2018
PARF Rebate Amount:	\$6,552.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,101.00
COE Rebate Amount:	\$689.00
Total Rebate Amount:	\$7,241.00

The information contained herein is correct as at 28 Dec 2017



UP TO
64% OFF*
CAR INSURANCE

Starting from
\$411.69*
Receive \$50
CapitaVouchers*

BUY NOW

T&Cs apply.

income

Username / Email Add

password

f Connect

[Sign Up New Account](#)
[Forgot Password](#)

Avante

Price Range

Depreciation

2008

Vehicle Type

[Home](#)
[Used Cars](#)

Used Car Comparison

— Comparing 3 Vehicles —

Hyundai Avante 1.6A

Hyundai Avante 1.6A

Hyundai Avante 1.6A S


 Use search bar above to set
to compare.

Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

Price	\$10,998	\$10,800	\$11,800	-
Instalment	\$1,559	\$1,531	\$1,397	-
Registration Date	29-May-2008	29-May-2008	12-Jul-2008	-
Manufactured	2008	2008	2008	-
Mileage	130,250 km	-	136,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,591 cc	1,591 cc	1,591 cc	-
Road Tax	\$738 /yr	\$738 /yr	\$738 /yr	-
Power	89.7 kW (120 bhp)	89.7 kW (120 bhp)	89.7 kW (120 bhp)	-
Curb Weight	1,264 kg	1,264 kg	1,264 kg	-
Features	1.6L DOHC VVT Engine, Dual SRS Airbags, ABS, 4 Speed Automatic, Auto Climate Control Aircon, Fog Lamps, Etc.	-	1.6L DOHC CVT Engine, 4 Speed Automatic Transmission, ABS, SRS Airbags.	-
Accessories	Leather Seats, Upgraded Sports Rims, Single Din Audio Player, Reverse Sensors, Solar Films, Etc.	-	Sports Rims, Solar Films, Audio System.	-
Description	Balloon Scheme Available! Low Monthly Instalment Only At \$515! New Road Tax! Tip Top Conditions! Grab It Now! Low Down Payment Of 2k, Easy Approval And Flexible Bank/In House Loan Up To 90%! All Our Quality Pre-Owned Cars Are Selling At The Most Reasonable Price And With A Peace Of Mind! STA/VICOM Are Welcome. View To Appreciate!		Good Condition, Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Details.	
COE	\$15,701	\$14,404	\$6,451	-
OMV	\$13,085	\$13,085	\$13,027	-
ARF	\$13,085	\$14,394	\$11,729	-
Depreciation	-	-	\$11,110 /yr	-
No. of Owners	2	3	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car	PARF Car	PARF Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

Seller	Resolcar Pte Ltd	Breaking Point	Happy Motoring Pte Ltd	-
--------	------------------	----------------	------------------------	---



Re:RE: Re:RE: Re:RE: SEEK MANDATE

Type

 Question

Message

HI LKK, pls offer \$4,765.35. LOU maintain at \$60/- per day as TP veh only 1.6 cc. Thank you.

Reply

AUTHORIZATION TO ACT

I, SUPREME LEASING & LIMOUSINE SERVICES ("the third party claimant")

of 61 UBI AVE > #02-08 AUTOMOBILE MEGAMART S(108898) (address),

owner of SJG 1728Y (vehicle no.) hereby authorize

MG SOLUTION PTE LTD

("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my Vehicle No. SJG 1728Y that was damaged pursuant to the accident which occurred on 22/12/2017 (date) along TAMPINES AVE 1 TOWARDS TAMPINES AVE 4 AFTER JUNCTION OF TAMPINES AVE 10 (location) involving Vehicle No/s SJB 688L

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ day of _____ (month) 20____ (year)



Signed by "the third party claimant"



Signed by "the workshop"

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: SUPREME LEASING & LIMOUSINE SERVICES
CAR/ LORRY/CYCLE: REG NO: SJG 1728Y POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. SJG 1728Y from the repairers,
Messrs MG SOLUTION PTE LTD
And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or
about the 22 day of 12 2017 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:



26/12/2017 PER
27/12/2017
31/01/2018 Sunday
01/01/2018 - TH

Vehicle In - 26/12/2017
Vehicle Out - 01/01/2018
LOU - 10 days x \$80
= \$800



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Bill No. : 188070

Date : 16-March-2018

Vehicle Number : **SJG 1728Y**

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,000.00
BEFORE GST		4,000.00
7% GST		280.00
TOTAL		\$ 4,280.00

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Co's stamp & Authorised Signature





MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 16/03/2018

Your Ref : CC4/ASM17024608/Ahb3 (SJB 688L)

To : AXA INSURANCE SINGAPORE PTE LTD

Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SJG 1728Y & SJB 688L ON 22/12/2017 AT
ALONG TAMPINES AVENUE 1 TOWARDS TAMPINES AVENUE 4 AFTER
JUNCTION OF TAMPINES AVENUE 10.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.188070 @ S\$4,280.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$800.00 (10 Days x S\$80)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

23 JANUARY 2018

CHUNG AI LIT AGNES
1A CANTONMENT ROAD
#29-09
SINGAPORE 085101

Dear Sir/Madam,

OUR REF : CC4/ASM17024608/Ahb3
YOUR REF : SJB 688L
ACCIDENT INVOLVING SJB 688L AND SJG 1728Y ALONG SLIP ROAD GOING INTO
TAMPINES AVE 1 ON 22.12.2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from MG SOLUTION PTE LTD, acting on behalf of the owner of SJG 1728Y against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had collided the Third Party vehicle SJG 1728Y. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Siti Jaafar
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORITY

Name : SUPREME LEASING & LIMOUSINE SERVICES

Address : 61 UBI AVE 2 #02-08 AUTOMOBILE
MEGAMART SINGAPORE 408898

Contact No : _____

TO: AXA INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SJG1728Y AND SJB688L ON 22/12/2017
AT/ALONG TAMPINES AVE 1 TOWARDS TAMPINES AVE 4 AFTER JUNCTION
OF TAMPINES AVE 10.

I/We, SUPREME LEASING & LIMOUSINE SERVICES, am/are the registered owner of
motor car no. SJG1728Y

Please note that I have assigned all compensations monies due to me/us in the above said accident
to **M/S MG SOLUTION PTE LTD.**

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to **M/S MG SOLUTION PTE LTD** and forward your settlement cheque to **M/S MG SOLUTION**
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant

A handwritten signature in black ink.

Witness By



redefining / insurance

CLAIM REF : S7M0060W
INSURED : CHUNG AI LIT AGNES

Provided always that the discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

DISCHARGE VOUCHER

We/I, SUPREME LEASING & LIMOUSINE SERVICES, CO. REG. NO. 53287737C hereby agree to accept the sum of dollars FOUR THOUSAND SEVEN HUNDRED SIXTY FIVE AND CENTS THIRTY FIVE ONLY (\$\$4,765.35) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SJB 688L as a result of an accident along TAMPINES AVENUE 1 on 22/12/2017 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SJG 1728Y.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SJB 688L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SJB 688L.

Dated this 21 day of 01 2019

Claimant's Signature : _____

NRIC no./ Company Stamp : 53287737C

Occupation/ Business : OUTDOOR

Address : 23 KAEI BURST AVE A #02-03 S(415933)

Telephone No. : 6243 1373

Witness's Name : WONG SU HUI

Witness's Signature : _____

Witness's NRIC No. : G1066386K



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

INVOICE No : TI 199021

PB No : 188070

Date : 22-January-2019

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : SJG 1728Y

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,000.00
BEFORE GST		4,000.00
7% GST		280.00
TOTAL		\$ 4,280.00

Cheque should be made payable to MG Solution Pte Ltd



Co's stamp & Authorised Signature



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 23 Dec 2017 / 09:49:23

Receipt Date/Time : 23 Dec 2017 / 09:49:23

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171223-000189

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJB688L				
As at 22 Dec 2017/22:10:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SJB688L Enquiry Fee 20171223094817127502	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	20171223094823508	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK Save as PDF

Vehicle Insurance Particulars Result

Vehicle No.
SJB688L

Incident Date/Time
22 Dec 2017 / 22:10:00

Insurance Company Name
AXA INSURANCE PTE LTD

[Print](#) [OK](#) [Save as PDF](#)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJB 688L (Insd veh)	Model:	TPVD HYUNDAI AVANTE-
	SJG 1728Y (TP veh)		1.6 (A)
Date of Accident:	22/12/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	14,236.74
Final Repair Cost	:	\$	4,280.00
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	5.35

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	4,765.35

Is Third Party Workshop GIA Registered?		☐ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks				

Payment Instruction: Payee's Breakdown		
1)	MG SOLUTION PTE LTD	\$ 4,765.35

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

13/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim

57H0060W

Reference

CCA/ASM17024606/AM0342

Loss Date

22 December 2017

Request Date

21 August 2018

Due Date

Vendor Name

LK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SJG172BY

Make

TPVED HYUNDAI

Model

AVANTE 1.6 (A)

Service Address

1A CANTONMENT ROAD, #015101

Primary Contact/Insured

CHUNG AI LIT AGNES

1A CANTONMENT ROAD, #29-09, 0815101, Singapore

96226388

AGNESCHUNG1306@YAHOO.COM

Claim Handler

ANG Richard

richard.ang@laka.com.sg

Additional Instructions

TP-NON ARC PLS VERIFY WITH TP ON THE ACCUT TIMING-DIFFERENT FB INSRD - 2HRS APART PLS OBTAIN VIDEO P/L (required)

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UNLOADED
LK01Invoice 1 (1).pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown - SGJ 1728V.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019
 LEO.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LUK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LUK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019
 WORKSHOP INVOICE.pdf	Invoice	Receipt	LUK AUTO CONSULTANTS PTE LTD (TP)	13 February 2019
 Email from TP dtd 211118.pdf	Letters and Correspondence	Workshop	LUK AUTO CONSULTANTS PTE LTD (TP)	21 November 2018
 Google Map Location.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	1 October 2018
 LUK REINSPECTION PHOTOS.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	16 June 2018
 MANDATE REQUEST.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	16 June 2018
 LUK INSPECTION PHOTOS.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	16 June 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LUK AUTO CONSULTANTS PTE LTD (TP)	23 May 2018
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LUK AUTO CONSULTANTS PTE LTD (TP)	23 May 2018
 TP ESTIMATE - FINALIZED.pdf	Reports & Statement	Estimate / Quotation	LUK AUTO CONSULTANTS PTE LTD (TP)	1 March 2018
 TP VIDEO FOOTAGE - SGJ1728V.mpeg	Evidence	Video	LUK AUTO CONSULTANTS PTE LTD (TP)	1 March 2018

Vehicle Portal				
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	1 March 2018
 Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKX AUTO CONSULTANTS PTE LTD (TP)	1 March 2018
 SJB68BL INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anmol	27 December 2017
 SSG172BY TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Anmol	27 December 2017
 EMAIL RECEIVED FROM WORKSHOP WITH TP GIA & CO. CLAIMANT.mig	Letters and Correspondence	Others	PATIL Anmol	27 December 2017
 GA260345-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	TEO Kitty	27 December 2017
 SSG172BY TP GIA IRPT.PDF	Reports & Statement	GIA Report	TEO Kitty	27 December 2017
 SJB68BL INSD GIA RPT.PDF	Reports & Statement	GIA Report	TEO Kitty	27 December 2017

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Rating	Parts & Labour	Schedule/Remarks	Summary
Job ID: JOB-2024-0876 Date: 2024-09-15 Location: 123 Main St, Cityville, CA 90210 Technician: Alice Johnson	Year/Make/Model: 2018 Ford Focus SE Vin: 1FADP3HJ8L1A12345 Mileage: 45,000 Driver Name: John Doe	Exterior: Good Interior: Fair Engine: Excellent Transmission: Good	Tax Rate: 8.75% Rating: 4.8	Part Number: PART-FORD-FOCUS-2018-INTAKE-MANIFOLD Labour Hours: 1.5	Notes: Customer reports intermittent stalling at idle. Status: In Progress	Total Cost: \$131.25 Estimate #: EST-2024-0876
Job ID: JOB-2024-0877 Date: 2024-09-15 Location: 456 Oak Ave, Cityville, CA 90210 Technician: Bob Smith	Year/Make/Model: 2020 Toyota Camry LE Vin: 4T1B11HK5L1A67890 Mileage: 60,000 Driver Name: Jane Smith	Exterior: Excellent Interior: Good Engine: Good Transmission: Excellent	Tax Rate: 8.75% Rating: 4.9	Part Number: PART-TOYOTA-CAMRY-2020-OIL-FILTER Labour Hours: 0.8	Notes: Routine oil change and filter replacement. Status: Completed	Total Cost: \$70.00 Estimate #: EST-2024-0877
Job ID: JOB-2024-0878 Date: 2024-09-16 Location: 789 Pine Rd, Cityville, CA 90210 Technician: Charlie Brown	Year/Make/Model: 2015 Honda Civic LX Vin: 1FADP3HJ8L1A12345 Mileage: 75,000 Driver Name: Mike Davis	Exterior: Fair Interior: Fair Engine: Fair Transmission: Fair	Tax Rate: 8.75% Rating: 4.7	Part Number: PART-HONDA-CIVIC-2015-BRAKE-PADS-FRONT Labour Hours: 2.0	Notes: Front brake pads worn down to metal. Status: In Progress	Total Cost: \$175.00 Estimate #: EST-2024-0878
Job ID: JOB-2024-0879 Date: 2024-09-16 Location: 101 Elm St, Cityville, CA 90210 Technician: Diana Prince	Year/Make/Model: 2019 Chevrolet Malibu LT Vin: 1G1ZD5ST5L1A90123 Mileage: 55,000 Driver Name: Liam Wilson	Exterior: Good Interior: Good Engine: Good Transmission: Good	Tax Rate: 8.75% Rating: 4.9	Part Number: PART-CHEVROLET-MALIBU-2019-AIR-FILTER Labour Hours: 0.5	Notes: Regular maintenance check. Status: Completed	Total Cost: \$43.75 Estimate #: EST-2024-0879
Job ID: JOB-2024-0880 Date: 2024-09-17 Location: 202 Maple Dr, Cityville, CA 90210 Technician: Eve Adams	Year/Make/Model: 2017 Nissan Altima S Vin: 1N4AA1AP5L1A45678 Mileage: 80,000 Driver Name: Sophia Garcia	Exterior: Fair Interior: Fair Engine: Fair Transmission: Fair	Tax Rate: 8.75% Rating: 4.6	Part Number: PART-NISSAN-ALTIMA-2017-WATER-PUMP Labour Hours: 2.5	Notes: Water pump leaking coolant. Status: In Progress	Total Cost: \$218.75 Estimate #: EST-2024-0880

EDIT	SER NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR & DAYS	Approve			
	2	SET FRONT BUMPER CLIP	Approve	20	NECESSARY	
	3	FRONT BUMPER LOWER LID	Approve	600	CRACKED	
	4	FRONT FENDER SEALANT LH	Deny	0	NOT NECESSARY	
	5	FRONT FENDER COWLING CLIPS LH	Approve	20	NECESSARY	
	6	FRONT WHEEL TYRE	Deny	0	NOT NECESSARY	
	7	FRONT WHEEL RIM	Approve	400	CUT	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$6,039.52		Claim Amount		\$6,039.52	
CATEGORY	ESTIMATE		REVISED AMOUNT			
Spare Parts	\$3,419.52		\$3,419.52			
Labour	\$1,580.00		\$1,580.00			
Miscellaneous	\$1,040.00		\$1,040.00			