

REF: AXA

ASSIGNMENT

From: _____ Date: 28/12/17

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKN 9866Eat Workshop m/s Insurance Autoof Blk 134 Pasir Ris st 11 # 04-253

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

TP - Non ARC PLS Ensure Consistence & Be
(Policy Condition) Stringent on cor.

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 9866E Yr Regn: 07 12Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw(A)X5

c/c

2P79Colour: Black

A/O:

Insured / Std / NI / NA

Sp. Reading: 255814

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: WBA8V42-0006493011Gen. Cond: (Good) Fair / Poor / BurntSteering: (In order) Jammed / Leaked / Burnt orBrake: (In order) Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F:

R:

235/55R18BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 5 mmL/Bal. 2 mmL/Bal. 5 mmD.O.A. 26/12/17D.O.I. 28/12/17Survey held at ✓Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12 1545 pass to Carterm

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

1)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

S - PS (\$ _____)

Photos _____

Others _____

TOTAL