

22/03/2002

ASS. REC. BY:

REF:

CS3 / III 17024639 / Gb22

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Adeline Tam

of

III

Date/Time:

26.12.2017 351pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 7421X

Insured:

SHC 8645B

at Workshop m/s

Target Auto

Tel:

9228 8881

of

160 Sin Ming Drive #07-7

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21.12.2017

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SKW 7421X - X

SHC 8645B - CS3 / ALH / LUC 13617 / H1243W2

D.O.A: 170714

Dismantle Part: 29.12.2017

REF: II

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Target Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: _____

IDAC Accident Rpt#: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. * / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW 7421 X Yr Regn: 13 Nov 2015
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda verzei C.C. 1496
Colour: red A/C: Insured / Std / NI / NA
Sp. Reading: 52435 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: RU111 05260
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60 R16
R: 11
BS / BMW / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 28-12-17
Survey held at w/s Target Auto 5:30 pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
-------------	----------------------

RECEIVED 2018

Date/Time, File Pass to?

1) 20-01-2018
Date/Time, File Return to?

2)

Report Format : PRS.

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

$$) \quad S \rightarrow RS \dots SI$$

) Photos

1 Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III17024639/Gb		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 28-12-2017		
		Code : III2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 8645B	Veh. Inspected	SKW 7421X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	ADELINE THAM	Assign Date	26/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages on				
5. General Information				
Accident Date	21/12/2017	Inspection Date	28/12/2017	
Survey held at	TARGET AUTO PTE LTD 160 SIN MING DRIVE #07-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Catherine Chong (LKK Auto)

From: Adeline Tham <adelinetham@iii.com.sg> on behalf of Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 26 December, 2017 3:51 PM
To: 'LKK - Assignments'; Admin A
Cc: Daniel Poon & Co.
Subject: RE: Our Ref: DP.10281.17.NS.TAR Your Ref: SHC 8645B

Dear Sir,

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO : SKW7421X

III INSURED VEHICLE NO. : SHC8645B

DATE OF LOSS : 21.12.2017

We acknowledge receipt of your letter dated 26.12.2017.

Our insured has reported the above accident to us.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK Auto Consultants Pte Ltd to conduct the pre-repair survey.

This claim is handled by Priya

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

Adeline Tham
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #05 IOB Building
Singapore 049711

From: Daniel Poon & Co. [mailto:law@dpco.com.sg]
Sent: Tuesday, 26 December, 2017 9:23 AM
To: Motor Claim - III
Subject: RE: Our Ref: DP.10281.17.NS.TAR Your Ref: SHC 8645B

Dear Sir/s,

ACCIDENT ON 21 DECEMBER 2017 INVOLVING SKW 7421X AND SHC 8645B ALONG NORTH BUONA VISTA DRIVE AFTER BIOPOLIS WAY

We refer to your E-mail dated 22 December 2017.

We will not be appointing any of your appointed surveyor as a single joint expert.

Kindly note that in the event that you are not agreeable to our list of appointed surveyor attached with our e-mail dated 22 December 2017, kindly contact the workshop to arrange a pre-repair inspection.

Yours faithfully,

Daniel C. K. Poon
Advocate & Solicitor

DANIEL POON & CO.

Advocates & Solicitors
Commissioners for Oaths
Notary Public

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227 2469
Fax: +65 6225 2579
E-mail: law@dpco.com.sg

Note: We do not accept service of Court documents via email

This email is confidential. If you are not the intended recipient, please inform us and then delete it from your system; you should not copy, disclose, or distribute its contents to anyone nor act in reliance on this email, as this is prohibited and may be unlawful.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Friday, 22 December, 2017 4:23 PM
To: Daniel Poon & Co. <law@dpco.com.sg>
Subject: RE: Our Ref: DP.10281.17.NS.TAR Your Ref: SHC 8645B

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: Daniel Poon & Co. [<mailto:law@dpco.com.sg>]
Sent: 22 December, 2017 4:12 PM

To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: DP.10281.17.NS.TAR Your Ref: SHC 8645B

Dear Sir/s,

ACCIDENT ON 21 DECEMBER 2017 INVOLVING SKW 7421X AND SHC 8645B ALONG NORTH BUONA VISTA DRIVE AFTER BIOPOLIS WAY

We refer to the above matter.

We attach herewith our letter dated 22 December 2017 for your attention and information.

Yours faithfully,

Daniel C. K. Poon
Advocate & Solicitor


DANIEL POON & CO.

Advocates & Solicitors
Commissioners for Oaths
Notary Public

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227 2469
Fax: +65 6225 2579
E-mail: law@dpcos.com.sg

Note: We do not accept service of Court documents via email

This email is confidential. If you are not the intended recipient, please inform us and then delete it from your system; you should not copy, disclose, or distribute its contents to anyone nor act in reliance on this email, as this is prohibited and may be unlawful.



This email has been checked for viruses by Avast antivirus software.
www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by Avast antivirus software.

www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/12/2017 16:37
Date Of Accident	21/12/2017 11:00
Exact Location Of Accident	NORTH BUONA VISTA DRIVE AFT BIOPOLIS WAY LANE 2&3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW7421X
Insured/Policyholder	
Name Of Registered Owner	LEOW BEE HONG
NRIC No	S1628848I
Email Address	KYLIE13@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97927726
Alternative Phone No	OFFICE-97927726
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075459983-02
Cover Note Number	
Driver	
Name of Driver	LEOW BEE HONG
NRIC No	S1628848I
Date Of Birth	17/01/1964
Occupation	INDOOR
Date Of Driving Pass	16/09/1988
Driving Experience	29 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97927726
Fax Number	
Contact Number	OFFICE-97927726
Email Address	KYLIE13@GMAIL.COM

Address	8 LENGKOK MARIAM
Postcode	509111
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8645B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAY YIONG TENG
NRIC/Passport Number	S1371639J
Contact Number	96679861
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time 21/12/17
1908HRS

Driver's Signature


(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature

Name: VINCENT
NRIC/IN No: S197133

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/12/2017 at around 1100HRS, I (SKW7421X) was travelling along line 2 at North Buena Vista Drive. After passing by Bucala Way, I felt an impact from right side of my vehicle & I notice that the taxi (SHC 8645B) from lane 3 change lane into lane 2 & collided into me. The taxi damage was on front left corner.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/12/17
1410HRS

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name VINCENT
NRIC/FIN No.: 5991138

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SKW7421X
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	VEZEL 1.5X CVT
Chassis No. :	RU11105260
Propellant :	Petrol
Engine No. :	L15B4025291
Engine Capacity :	1496 cc
Maximum Power Output :	96.0 kW (128 bhp)
Maximum Laden Weight :	1465 kg
Unladen Weight :	1190 kg
Year Of Manufacture :	2015
Original Registration Date :	13 Nov 2015
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$57,301.00
COE Expiry Date :	12 Nov 2025
Road Tax Expiry Date :	12 Nov 2018
PARF Eligibility Expiry Date :	12 Nov 2025
Inspection Due Date :	12 Nov 2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018 Edit Reg		26 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Co. Reg. No.:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Adjuster:

-

LEOW BEE HONG, ID: S1628848I

SKW7421X

TP

SHC8645B

Target Auto Pte Ltd (Autocity) 160 SIN MING DRIVE, #07-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel:

India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/01/2018]

[Created by adjuster]

Date of Loss:

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

21/12/2017 21:00 - :59

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.



































ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW7421X
[SHC8645B]
TP
LEOW BEE HONG
Dec 21 2017 9:00PM
[-]
Target Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
2	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
3	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
4	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
5	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
6	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
7	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
8	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
9	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
10	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
11	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
12	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
13	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
14	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
15	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
16	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
17	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
18	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
19	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
20	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
21	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
22	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
23	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
24	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
25	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
26	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
27	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
28	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
29	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
30	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
31	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
32	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
33	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
34	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			
35	20/01/18 13:39	General View		Load JPG	<input checked="" type="checkbox"/>			

36	20/01/18 13:39	General View	1	Load JPG	✓
37	20/01/18 13:39	General View	1	Load JPG	✓
38	20/01/18 13:39	General View	1	Load JPG	✓
39	20/01/18 13:39	General View	1	Load JPG	✓
40	20/01/18 13:39	General View	1	Load JPG	✓
41	20/01/18 13:39	General View	1	Load JPG	✓
42	20/01/18 13:39	General View	1	Load JPG	✓
43	20/01/18 13:39	General View	1	Load JPG	✓
44	20/01/18 13:39	General View	1	Load JPG	✓
45	20/01/18 13:39	General View	1	Load JPG	✓
46	20/01/18 13:39	General View	1	Load JPG	✓
47	20/01/18 13:39	General View	1	Load JPG	✓
48	20/01/18 13:39	Odometer Reading	1	Load JPG	✓
49	20/01/18 13:39	Chassis Number	1	Load JPG	✓
50	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
51	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
52	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
53	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
54	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
55	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
56	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
57	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
58	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
59	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
60	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
61	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
62	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
63	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
64	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
65	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
66	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
67	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
68	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
69	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
70	20/01/18 13:40	Photographs of Damaged Parts	1	Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 08:47	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III17024639/GBE2

Date: 24/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKW7421X

Insured Vehicle No : SHC8645B

Date of Loss: 21/12/2017

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW7421X

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4025291

Reg. Date: 13/11/2015 (Man. Year: 2015)

Chassis No: RU11105260

Colour: Red

Odometer: 52435 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 28/12/2017 Inspected At:

Target Auto Pte Ltd (Autocity)
160 SIN MING DRIVE, #07-17 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jan 2018)
Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKW7421X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >