

22/05/2002

ASS. REC. BY:

REF: CS3/AIG17024645/Wd362

PAR &amp; depts

Special Instructions:

SURVIVOR:

Wilson

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time: 12.39pm @ 28/12/17

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FX 6703T

Insured:

SLK 2267J

at Workshop m/s

Asia Motorsports

Tel:

6745 3811

of

568 Geylang Rd

Policy No:

Claim No:

4380939614SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/12/2017

CA / REV / REP. / REV 24 HRS

lwp

29/12/17

H.O.D. Endorsement:

Date/Time:

2.49pm @ 28/12/17

Person Contacted:

Mr. Leo

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction ( X ) Estimate
	FX 6703T-x
	SLK 2267J-x
	Dismantled photo - 3/1/2018

PRG  
Wiken

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To inspect Vehicle No. **FX 6703T**  
 at Workshop mis **Asia Sport**  
 of **568 Ceylang Road**  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Est. of Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 G/A PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **3** days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No. **FX 6703T** 1st Regn **2004 Feb**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make **Honda Wave 125SA** cc **125**  
 Colour **Blue** Insured / Std / Nil / NA  
 Sp Reading **No Available** Radio Insured / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 C No **NF125MD0088774**  
 Gen Cond **Good / Fair / Poor / Burnt**  
 Steering **Inorder / Jammed / Leaked / Burnt or**  
 Brake **Inorder / Jammed / Leaked / Burnt or**  
 Mod: Nil / S/Rim **STD A/Rim or**  
 Tyre Size F: **2.75 / 17**  
 R: **80 / 90 - 17**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Dunlop (F)**  
**Dimensional (R)**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R Bal **4** mm R Bal **2** mm  
 L Bal \_\_\_\_\_ mm L Bal \_\_\_\_\_ mm  
 D O A \_\_\_\_\_  
 Survey held at: **29/12/2017**  
 Des. of Damages **Frt / Rear / O/S / N/S / U/C / Rooftop or**  
 The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

**\* No Power Supply**  
**No Accident Report Given.**  
**11/4 Submit DAR report**

RECEIVED 11 APR 2018

Date/Time File Pass to: ☐ : Preli. Report  
☐ : Final Report

Days Of Repair: **3**  
 Resurvey No. of Trip: **1**

Report Format: **DAR**  
 Lump Sum / I.B.I. / S

Add Fee: ☐ Site Insp / S  
☐ Interview / S  
☐ Tech Insp / S  
☐ Weekend / S

Survey Fee  
 Transportation  
 S + Rd S  
 Phone  
 Fine

180
20
200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE SLK2267J AND FX6703T ON 23/12/2017**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: Thursday, 28 December, 2017 12:39:40 PM  
Attachments:  Fax30F5.tif

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**ASIA MOTORSPORTS SOLUTION PTE LTD**

Specialise in sales of new &amp; reconditioned bikes

Co. Reg. No: 200507766N

---

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: [www.asiamotorsports.com.sg](http://www.asiamotorsports.com.sg)Your Ref:  
Our Ref: FX 6703 T

27 December 2017

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

Dear Sir/Mdm,

**NOTICE OF ACCIDENT: ACCIDENT INVOLVING FX 6703 T & SLK 2267 J ON 23 DECEMBER 2017**

We are instructed to notify you of a road traffic accident on 23 December 2017 at about 3.10 am at BKE towards Bukit Batok(aft. S'pore Turf Club) involving our client's vehicle registration number FX 6703 T and vehicle registration number SLK 2267 J driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **29 December 2017 (Friday), 1630H**, we will be forwarding our proposed list of motor surveyors for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Yours Faithfully,

Asia Motorsports  
6745 3811  
6746 5110 (Fax)  
[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)

---

For Internal Reference

Sent on: 27/12/2017, 1605H

Vehicle No.:

(1) Damaged (2) Damaged (3) Damaged (4) Cracked (5) Cut (6) Scratched  
 (7) Detached (8) Bent (9) Stuck (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## FOR MOTORCYCLE

ACTION:

May 2007

1. Replace (✓) 2. Repair (✓) 3. Check (✓)  
 4. Not Consistent (NC)

## Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	DP	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	WP	SCR	✓
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	NP	✓	
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	SCR	✓	
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CRA	✓	
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip (RH)	SCR	✓	
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever	SCR	✓	
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing (RH)	SCR	✓	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			
		LHS / RHS FM Fairing	SCR	✓	
		RHS Wing Mirror	DM	✓	

Vehicle No.:

FX 6703 J

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake	DP	SCR	✓
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	BT	SCR	✓
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	SCR	✓	
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate	DD	✓	
3076	994192	Side Box			
3077	992927	Rear Box	SCR	✓	
3078	992928	Rear Box Bracket	BT	✓	
3079	991328	Emblem			
1136	990247	Sticker			
		Taillamp	CRA	✓	
		Garnish			

No of Items:

Assessor:

3 Days  
Repairs

4/11/2018

E-FILE

MVA317169935 / VAC - Kaki Bukit  
ENTRY DATE & TIME: 27/12/2017 14:33  
SUBMITTED BY: Nohaini Bte Abdul Majid

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 27/12/2017 14:54**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/12/2017 14:33
Date Of Accident	23/12/2017 03:10
Exact Location Of Accident	BKE TOWARDS BUKIT BATOK (AFT. S'PORE TURF CLUB)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX6703T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VENKATAH RAO S/O SANNASY
NRIC No	S2709648D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81388401
Alternative Phone No	Others-81388401

### Vehicle Particulars

Manufacturer	HONDA
Model	WAVE 125S A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSCN: 71964030 (TP)

Cover Note Number

### Driver

Name of Driver	VENKATAH RAO S/O SANNASY
NRIC No	S2709648D
Date Of Birth	26/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	08/01/1996



4/11/2018

E-FILE

Driving Experience	21 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81388401
Fax Number	
Contact Number	OTHERS-81388401
EMail Address	NOEMAIL
Address	BLK 289F BUKIT BATOK ST 25 #03-126
Postcode	655289
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO POLICE REPORT ATTACHED.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLK2267J
-----------------------------	----------

4/11/2018

E-FILE

Vehicle Make/Model/Colour

TOYOTA PRIUS HYBRID 1.8 CVT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

VENKATAH RAO S/O SANNASY

Approximate Age

Injuries Sustain

LIMB INJURIES, SHOULDER

Injured person in which vehicle?

FX6703T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode



4/11/2018

E-FILE

**Sketch Plan**

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**LAC KAKI BUKIT (VAC)**

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

E-mail: [vac@singnet.com.sg](mailto:vac@singnet.com.sg)

Name:

NRIC/FIN No.:


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

SARASU SHANKARAN

## Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report T/20171223/2021.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

GUMING Sketch Plan Form V2

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackh@singnet.com.sg](mailto:vackh@singnet.com.sg)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

4/11/2018

E-FILE

**Individual Statement**



# SINGAPORE POLICE FORCE



T/20171223/2021

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

1 of 3

Report No. T/20171223/2021

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/12/2017 07:51		Vide Report No.:		Station Diary No.: 31	
<b>Informant's Particulars</b>					
Name of Informant: VENKATAH RAO S/O SANNASY			Address: APT BLK 289F BUKIT BATOK STREET 25 #03-126 SINGAPORE 655289		
ID Type / ID No.: NRIC NO / S2709648D			Contact No.: Home/Office: Mobile: 81388401		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 50	Date of Birth: 26/12/1966	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: SBS TRANSIT BUS CAPTAIN			Driving Licence Information: Class: 2B,3,4A,4 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/12/2017 03:10	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
Bukit Timah Expressway towards Bukit Batok after the Singapore Turf Club				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Moving vehicle (car) to Moving vehicle (motorcycle) (Head to Rear)				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FX6703T	Motorcycle	HONDA	WAVE 125S A	Blue		0
SLK2267J	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	White	Slightly Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

## Individual Statement

**SINGAPORE  
POLICE FORCE**

T/20171223/2021

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

2 of 3

Report No. T/20171223/2021

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FX6703T	MSIG INSURANCE (SINGAPORE) PTE. LTD.	71964030	05/02/2017	04/02/2018

**Brief Details.**

On the 23 December 2017 at about 3.10am, I was riding my motorcycle registration number: FX6703T, along the Bukit Timah Expressway (BKE) towards Bukit Batok after the Singapore Turf Club. This is a one way road, and it is four lane, and I was riding on the third lane from the left. Suddenly a vehicle registration number: SLK 2267J, Toyota, white colour knocked onto the rear of my motorcycle. The impact was hard and I lost control of my motorcycle and fell onto the road lane I was riding.

The said driver, a male Malay stopped and rendered assistance to me. The ambulance and Police arrived and I was conveyed to Khoo Teck Puat Hospital, I sustained injuries relating to contusion and abrasions (right shoulder pain and difficulty in lifting upwards, multiple abrasions over bilateral upper and lower limbs). I received five days medical leave (Period 23 to 27 December 2017). I do not know the extent of damage to my motorcycle as it was towed away after I was conveyed to hospital. The extent of damage to the vehicle registration number: SLK2267J, another pillion rider who had assisted me (name and contact I do not have) had used my phone to take a picture of this vehicle (SLK2267J) damage. This vehicle (SLK 2267J) only the front number plate was damage and was hanging on the vehicle still.

4/11/2018

E-FILE

**Individual Statement**



4/11/2018

E-FILE



**SINGAPORE  
POLICE FORCE**



T/20171223/2021

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

3 of 3





Report No. T/20171223/2021

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / SSI ANDY LUCAS 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/12/2017 07:51
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case: SN 085
Authentication Stamp NP168	 Signature:  Singapore Police Force

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 <a href="#">Edit Reg</a>		28 Dec 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	FX6703T	Date of Loss:	23/12/2017 00:00 - :59 [166 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4380939614SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLK2267J	Policy No. (Claimant):	
		Excess:	
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) No 568 Geylang Road, 389514 Geylang - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Khoo, Kay-Eng - 6419 1026] Kay-Eng.Khoo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 12/04/2018]		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

- AIG\_SG (04/04/2018): NO TP GIA REPORT

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents






































\*FX6703T (4380939614SG)  
[SLK2267J]
























TP

Dec 23 2017 12:00AM

[LCRF Pte Ltd]

Asia Motorsports Solution Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
2	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
3	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
4	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
5	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
6	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
7	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
8	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
9	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
10	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
11	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
12	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
13	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
14	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
15	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
16	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
17	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
18	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
19	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
20	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
21	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
22	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
23	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
24	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
25	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
26	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
27	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
28	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
29	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
30	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
31	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
32	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
33	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
34	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
35	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
36	03/04/18 16:39	General View														Load JPG	<input checked="" type="checkbox"/>			
37	10/04/18 17:20	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/18 17:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 14:49	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17024645/WD3E2

Date: 12/04/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FX6703T

Insured Vehicle No : SLK2267J

Date of Loss: 23/12/2017

Nature of Claim: TP

Claim No: 4380939614SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FX6703T**

Make &amp; Model: HONDA WAVE 125-S, 125cc

Engine No: NF125MDE0088774

Reg. Date: 04/02/2004 (Man. Year: 2003)

Chassis No: NF125MD0088774

Colour: Blue

Odometer: 0 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 2.75/17

Rear Tyre Size: 80/90-17

Front Left Side: Dunlop 4 mm

Rear Left Side: DIAMOND 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 29/12/2017 Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)  
No 568 Geylang Road  
Singapore 389514

Estimated Period of Repair: 3.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Warped / Scratched	0.00 F	*- F
3	1		*FRONT FORK ASSY	Warped	0.00 F	*- F
4	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
5	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
6	1		*HANDLE BAR GRIP (RH)	Scratched	0.00 F	*- F
7	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
8	1		*REAR FAIRING (RH)	Scratched	0.00 F	*- F
9	1		*LHS/RHS FRT FAIRING	Scratched	0.00 F	*- F
10	1		*RHS WING MIRROR	Damaged	0.00 F	*- F
11	1		*FOOT BRAKE	Dented / Scratched	0.00 F	*- F
12	1		*REAR FOOT REST	Bent / Scratched	0.00 F	*- F
13	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
14	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
15	1		*REAR BOX	Scratched	0.00 F	*- F
16	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
17	1		*TAILLAMP GARNISH	Cracked	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >