

22/03/2012

ASS. REC. BY:

REF: CS3/AIG17024649/Wd33*

Special Instructions:

Survivor:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

28/12/17 @ 3:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

F22009E

Insured:

SLH 4184S

at Workshop m/s

MCS Auto

Tel:

629 6 9939

of

1106/1102 Serangoon Rd

Policy No:

Claim No:

388790412386

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up/

29/12/17

H.O.D. Endorsement:

Date/Time:

5:05pm @ 28/12/17

Person Contacted:

Stephanie

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

F22009E-X

SLH 4184S - CS / EGI 17001661 / K/be2

D.O.A : 21/01/2017

Dismantled Photo - 8/1/2018

Simult

PRS


W-16N

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: FZ 2009 E
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured: _____ Excess _____
 (Client's Record)
 Make of Ven _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: _____ Consistent? : Yes or No

GLA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted _____

Vehicle: IN / OUT

Veh No: FZ 2009 E Yr Regn: 6/5/2005
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Yamaha cc: 111
 Colour: Silver AC Insured / Std / NI / NA

Sp. Reading: 53696 T Radio Insured / Std / NI / NA

Eng No _____

C/No: SYW 027776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 70/90-17 m/c
 R: 80/90-17 m/c

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRC (F)
Dunlop (R)

Front R/Bal: 2 mm R/Bal: 3 mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A: 16/12/2017 DOI: 29/12/2017

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

11/4/18 Submit DAR report

RECEIVED 11 APR 2018

Date/Time File Pass to:

☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

1. S - RE _____

2. Petrol

3. Other

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)


☐ Tech Insp (\$)

☐ Weekend (\$)

Report Format: DAR

Lump Sum / I.B.I: (\$)

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLH4184S AND FZ2009E ON 16/12/2017**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: Thursday, 28 December, 2017 3:14:31 PM
Attachments:  171242.pri.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
舉 NOTARY PUBLIC - 公証官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L. LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K
GST Registration No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Our Ref: CL/171242/T/MCS.sg
Your Ref: SLH 4184S

Date: 22 December 2017

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

LCRF Pte Ltd
60 Anson Road
#11-01 Mapletree Anson
Singapore 079914

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FZ 2009E / SLH 4184S ON 16.12.2017 ALONG BUKIT TIMAH ROAD
TOWARDS UPPER BUKIT TIMAH**

We are instructed by **Kwek Say Kow** to notify you of a road traffic accident involving our client's vehicle No. FZ 2009E and vehicle No. SLH 4184S driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.


As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: MCS Auto
1100/1102 Serangoon Road
Singapore 328195

Contact: Stephanie @ 6296 9939

Yours faithfully



cc: clients

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2017 11:46
Date Of Accident	16/12/2017 08:00
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FZ2009E
Insured/Policyholder	
Name Of Registered Owner	KWEK SAY KOW @ LAU CHONG GEOK
NRIC No	S0592142B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96161408
Alternative Phone No	OTHERS-96161408

Vehicle Particulars

Manufacturer	YAMAHA
Model	SUPREME X-1-111CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	A 27794597 TPY
Cover Note Number	06/11/2017-05/11/2018

Driver

Name of Driver	KWEK SAY KOW @ LAU CHONG GEOK
NRIC No	S0592142B
Date Of Birth	11/07/1941
Occupation	INDOOR
Date Of Driving Pass	15/04/1977
Driving Experience	40 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96161408
Fax Number	(LOCAL) +65-96161408
Contact Number	OTHERS-96161408
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	KWEK SAY KOW @ LAU CHONG GEOK
Approximate Age	76
Injuries Sustain	RT LITTLE FINGER FRACTURE, PAIN ON RT HIP & MULTIPLE ABRASIONS
Injured person in which vehicle?	FZ2009E
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



**SINGAPORE
POLICE FORCE**



T/20171219/2073

1 of 3

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

Report No. T/20171219/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/12/2017 14:02	Vide Report No.:	Station Diary No.: 16
Informant's Particulars		
Name of Informant: KWEK SAY KOW	Address: APT BLK 154 ANG MO KIO AVENUE 5 #02-3108 SINGAPORE 560154	
ID Type / ID No.: NRIC NO / S0592142B	Contact No.: Home/Office:	Mobile: 96161408
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 76	Date of Birth: 11/07/1941
Type of Informant: Cyclist		
Race: Chinese	Language:	Institution / School Name:
Occupation: Kitchen Helper	Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/12/2017 08:00	Type of Location:
Location: Along Road 1 BUKIT TIMAH ROAD				
Towards Upper Bukit Timah				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FZ2009E	Motorcycle					0
SLH4184S	Car					0



**SINGAPORE
POLICE FORCE**



T/20171219/2073

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

3 of 3

Report No. T/20171219/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 LIM ZHI CONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Contact No.:

Signature Of Informant:

Date/Time:

19/12/2017 14:02

Classification Of Case:

Authentication Stamp

NP168

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FZ2009E		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	SUPREME X-1		
Chassis No. :	5YW027776		
Propellant :	Petrol		
Engine No. :	5YW027776		
Engine Capacity :	111 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	96 kg		
Year Of Manufacture :	2005		
Original Registration Date :	06 May 2005		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
PQP Paid :	\$2,643.00		
COE Expiry Date :	30 Apr 2020		
Road Tax Expiry Date :	05 May 2018		
Inspection Due Date :	05 Nov 2018		
Intended Transfer Date :	11 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 05 May 2018. You may renew the road tax from 06 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 05 May 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 06 May 2018 to 05 Nov 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	45.00	-	45.00
Total Amount Payable :			70.00
Amount Payable (From 06 May 2018 to 05 May 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2142B
Vehicle Details	
Vehicle No.:	FZ2009E
Vehicle to be Exported:	No
Intended De-registration Date:	11 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	SUPREME X-1
Primary Colour:	Orange
Manufacturing Year:	2005
Engine No.:	5YW027776
Chassis No.:	5YW027776
Maximum Power Output:	-
Open Market Value:	\$1,458.00
Original Registration Date:	06 May 2005
First Registration Date:	06 May 2005
Transfer Count:	2
Actual ARF Paid:	\$219.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2020
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,643.00
COE Rebate Amount:	\$1,085.00
Total Rebate Amount:	\$1,085.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Apr 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0592142B

Name
KWEK SAY KOW @ LAU CHONG
GEOK @ KWEK CHONG GEOK
刘宗玉

Race
CHINESE

Date of Birth
11-07-1941

Sex
M

Country of Birth
SINGAPORE



0757290



NRIC No S0592142B



Blood Group A+ Date of Issue 04-07-1994

Address
APT BKK 15 ANG MO KIO AVENUE 5
#02-3108
SINGAPORE 2056

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S0592142B**
 Name: **KWEK SAY KOW**
 Birth Date: **11 Jul 1941**
 Issue Date: **22 Sep 2003**

1000853345B




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles <= 200 CC	15 Apr 1977
Class 2A Motorcycles between 201 CC and 400 CC	15 Apr 1977
Class 2 Motorcycles > 400 CC	15 Apr 1977
Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	21 Oct 1977

S0592142B S / No. 9000072342

NP 428A

Licence No: S0592142B



FOR MOTORCYCLE

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	SCR/ DD	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp (RH)	CRA ✓		
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip (RH) (LH)	TRN ✓		
3031	995184	Handle Bar Balancer LH	SCR ✓		
3032	992300	Handle Bar Balancer RH	SCR ✓		
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	SCR ✓		
3035	992293	Hand Brake Lever	SCR ✓		
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower (LHS/RHS)	Deformed ✓		
		LHS/ RHS Wing Mirror	SCR ✓		
		Foot Resting RHS	SCR ✓		

Vehicle No: FZ 2009 E

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake	SCR/ BS	✓	
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber	TN ✓		
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	SCR ✓		
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	SCR ✓		
3061	991058	Exhaust Muffler Assy	DD ✓		
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard	SCR ✓		
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	SCR ✓		
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker			
		Rear No. plate	DD ✓		
		Tail lamp Garnish	CRA ✓		

No of Items: _____

Assessor: _____

3 Days Return

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2018 Edit Reg		28 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: -		
Main Claimant:	KWEK SAY KOW		
Vehicle Reg. No.:	FZ2009E	Date of Loss:	16/12/2017 00:00 - :59 [151 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3887904123SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLH4184S	Policy No. (Claimant):	
		Excess:	
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 12/04/2018]		
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)



































- AIG_SG (04/04/2018): TP GIA REPORT

















































ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)




















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FZ2009E (3887904123SG)
[SLH4184S]
TP
KWEK SAY KOW
Dec 16 2017 12:00AM
[LCRF Pte Ltd]
Mcs Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	10/04/18 16:58	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 14:40	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div>Show Remarks To: <input type="checkbox"/> Handling Insurer</div> <div>Note: Remarks are private unless you show it to other parties.</div>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17024649/WD3S2

Date: 20/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FZ2009E

Insured Vehicle No : SLH4184S

Date of Loss: 16/12/2017

Nature of Claim: TP

Claim No: 3887904123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FZ2009E

Make & Model: YAMAHA SUPREME X-1, 111cc

Reg. Date: 06/05/2005 (Man. Year: 2005)

Colour: Silver

Engine Capacity: 111 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 5YW027776

Chassis No: 5YW027776

Odometer: 53696 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size:

80/90-17

Front Left Side: IRC 2 mm

Rear Left Side:

Dunlop 3 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 29/12/2017

Estimated Period of Repair: 3.0 days

Inspected At:

Mcs Auto (HQ)

1100/1102 Serangoon Rd

Singapore 328195

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Scratched / Dented	0.00 F	*- F
2	1		*FRONT HEADLAMP (RH)	Cracked	0.00 F	*- F
3	1		*HANDLE BAR GRIP (RH) (LH)	Torn	0.00 F	*- F
4	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
5	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
6	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
7	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
8	1		*FAIRING LOWER (LHS / RHS)	Deformed	0.00 F	*- F
9	1		*LHS / RHS WING MIRROR	Scratched	0.00 F	*- F
10	1		*FRT FAIRING RHS	Scratched	0.00 F	*- F
11	1		*FOOT BRAKE	Scratched / Bent	0.00 F	*- F
12	1		*KICK STARTER RUBBER	Torn	0.00 F	*- F
13	1		*REAR FOOT REST	Scratched	0.00 F	*- F
14	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
15	1		*EXHAUST MUFFLER ASSY	Dented	0.00 F	*- F
16	1		*REAR FENDER WHEEL GUARD	Scratched	0.00 F	*- F
17	1		*REAR BOX	Scratched	0.00 F	*- F
18	1		*REAR NO. PLATE	Dented	0.00 F	*- F
19	1		*TAILLAMP GARNISH	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)

0.00

0.00

Report was unsubmitted during this print-out.

There are no new miscellaneous items selected.

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >