

Special Instruction:

49: \$ 5450.00

From (Person): Elaine Ng of MSU Date/Time: 09/03/2018
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Constant Appraiser

Workshop: Super modern

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJX 190P Insured: GZ 3085R

at Workshop m/s Super modern Tel: 91525152

of 25 Kaki Bukit Rd 4 #01-26

Policy No: A28604393mkc Claim No: 540052

Sum Insured: Excess:

Make of Veh: D.O.A. 23.12.2017


(Client's Record)

Do Not Finalize

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red S _____ / _____ %; Original 4 days)

Date/Time: 12/02/18 Submit Final Fig 3.3K, 04 days (Red \$ 2150 / 39 %; Original 4 days)

Date/Time	Action/Instruction
	<p> SJX 190P - CCB / A17151106599 / R15G3W2 R2 3085R - X </p> <p>  </p> <p> DEF: 19043015 URGENT </p>

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 13 APR 2018

Para(3) : Nett Value

Market Value :

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add	
Transport	
Photos	
Others	
Total	

Date: _____

1) Date/Time 12/4/18 File Pass to Typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time _____ File Return to _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17024664/Atd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-12-2017	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GZ 3085R	Veh. Inspected	SJX 190P
Policy No.	A28604393MKC	Coverage (\$)	0.00
Claim No.	542452	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	29/12/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/12/2017	Inspection Date	02/01/2018
Survey held at	SUPER MODERN SERVICES 25 KAKI BUKIT ROAD 4 #01-26 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2017		28 Dec 2017 11:40 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JESSICA ART N' CRAFT, Co. Reg. No.: 24187000C		
Main Claimant:	MARTHAS BIN ABU TALIB, ID: S1374625G		
Vehicle Reg. No.:	SJX190P	Date of Loss:	23/12/2017 11:00 - :59
Claim Type:	TP / 542452	Policy/Cover Note No.:	A28604393MKC (TP, Fire & Theft) Coverage: 07/09/2017 - 06/09/2018
Vehicle Reg. No. (Insured):	GZ3085R	Policy No. (Claimant):	
		Excess:	
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4, # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 29/12/2017]		
Driver/Custodian (Insured):	CHENG JING HEAN (), NRIC: S8710321H, Tel: +6583428691		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

22/03/2012

ASS. REC. BY:

REF: CS3/MSG17024664/ Ad3

Special Instructions:

S. No. 102

Adnan

ASSIGNMENT (Office)

Mennen

From (Person):

Elaine Ngu

of

MSIG

Date/Time: 28/12/17 @ 11:40am

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 190P

Insured:

G2 3085R

at Workshop no/s

Super Modern Services

Tel:

91525152/62568830

25

of Kaki Blk Rd 4 # 01-26 Synergy 417000

Policy No:

A28604393MKC

Claim No:

542452

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

02/01/2017 @ After 2pm

H.O.D. Endorsement:

Date/Time:

5:12pm @ 28/12/17

Person Contacted:

Mdm. Teoh

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJX 190P-X

G2 3085R-X

Surveys

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJX190P Yr Regn: 2010 May
 Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Stream cc: 1799
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 156317 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JHMRN68809C200562

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18
 R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 02/01/18

Survey held at: Super ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time _____ Action / Instruction
TP MSIG PRS

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS - \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2017		28 Dec 2017 11:40 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All
CLAIM SUBFOLDER DETAILS								[Created by insurer]
Insured:	JESSICA ART N' CRAFT, Co. Reg. No.: 24187000C							
Main Claimant:	MARTHAS BIN ABU TALIB, ID: S1374625G							
Vehicle Reg. No.:	SJX190P			Date of Loss:	23/12/2017 11:00 - :59			
Claim Type:	TP / 542452			Policy/Cover Note No.:	A28604393MKC (TP, Fire & Theft) Coverage: 07/09/2017 - 06/09/2018			
Vehicle Reg. No. (Insured):	GZ3085R			Policy No. (Claimant):				
				Excess:				
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mel - 6594 2540]							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/12/2017]							
Driver/Custodian (Insured):	CHENG JING HEAN (), NRIC: S8710321H, Tel: +6583428691							
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail
There are no mail for this case.								
ALL ASSOCIATED TASKS								
View All Search Tasks Create New Task Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On Done?
No results.								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2017 12:03
Date Of Accident	23/12/2017 11:00
Exact Location Of Accident	BLK 832 SIMS AVENUE OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX190P
Insured/Policyholder	
Name Of Registered Owner	MARTHAS BIN ABU TALIB
NRIC No	S1374625G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98381664
Alternative Phone No	OTHERS-98381664

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5068914942-02
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	MARTHAS BIN ABU TALIB
NRIC No	S1374625G
Date Of Birth	01/12/1959
Occupation	INDOOR
Date Of Driving Pass	20/09/1984
Driving Experience	33 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98381664
Fax Number	
Contact Number	OTHERS-98381664
EMail Address	NOEMAIL

Address	BLK 838 #04-830 SIMS AVENUE
Postcode	400838
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was reversing out from the carpark lot and as I need to exit at the exit nearby at the rear left, therefore I reversed along the driveway of the carpark. Suddenly, vehicle B reversed to exit the carpark lot. Unable to brake in time, my rear right area of my vehicle A hit into the rear left area of vehicle B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ3085R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	83428691
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report No: MT/

D.O.A: 23-12-2017
Time: 11:00 hrs

Vehicle No: SIX190P

Make / Model: HONDA STREAM

Report Date & Start Time: 23-12-17 / 11:55

Reporting Type: End Time: /

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

23-12-17 / 11:55

Policyholder's Signature / Date & Time

23-12-17 / 11:55


Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 2

SKETCH PLAN



Blk 832 Sims Avenue Open Space Carpark

Vehicle A: SJX190P

Vehicle B: GZ3085R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was reversing out from the carpark lot and as I need to exit at the exit nearby at the rear left, therefore I reversed along the driveway of the carpark. Suddenly, vehicle B reversed to exit the carpark lot. Unable to brake in time, my rear right area of my vehicle A hit into the rear left area of vehicle B.

Declaration

I/We declare the foregoing particulars are true in every respect.

23-12-17 11:55

Policyholder's Signature / Date & Time

23-12-17 11:55

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Marthas Bin Abu Talib
Blk 838 Sims Ave
#04-830
Singapore 400838

Date : 15/01/2018

Reference No : CAS/18-01/013

General Information

Registration No. : SJX 190P
Accident Date : 23/12/2017

Particulars of Damaged Vehicle

Colour	: Black	Make & Model	: Honda Stream 1.8L
Engine Capacity	: 1799 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 156317	Engine No.	: R18A13850561
Chassis No.	: JHMRN68809C200562	Steering	: In Order
Registration Date	: 07/05/2010	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	225/40R18	PIRELLI	90%
L/H Front Tyre	225/40R18	PIRELLI	90%
R/H Rear Tyre	225/40R18	PIRELLI	90%
L/H Rear Tyre	225/40R18	PIRELLI	90%

Inspection

Repairer : Super Modern Services Pte Ltd
25 Kaki Bukit Road 4, #01-26 Synergy@KB, Singapore 417800

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$8,523.92
Revised Amount : \$5,450.00
Less Excess : -
Nett Total : \$5,450.00

Remarks

- (A) Survey was done on 02/01/2018
- (B) Re-survey was done on 09/01/2018
- (C) Re-survey after repair was done on 11/01/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SJX 190P

Our ref : CAS/18-01/013

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1set	Rear windscreen moulding	Necessary	178.50	178.50
2	1pc	Rear tailgate	Dented	1,465.60	1,465.60
3	1pc	Rear tailgate emblem 'Stream'	Necessary	62.50	62.50
4	1pc	Rear tailgate emblem 'RSZ'	Necessary	85.00	85.00
5	1pc	Rear tailgate inner lock <i>Not Nec</i>	Bent	303.20	303.20
6	1pc	Rear tailgate inner trim board	Deformed/Broken	386.50	386.50
7	1pc	Rear tailgate weatherstrip <i>Not Nec</i>	Distorted/Torn	186.60	186.60
3	2pcs	Rear tailgate stopper @ \$18.60	Necessary	37.20	37.20
9	1pc	Rear tailgate outer garnish	Serviceable	235.90	-
10	1pc	Rear bumper	Dented/Broken	1,081.60	1,081.60
11	2pcs	Rear bumper lower bracket @ \$55.90 <i>RH Side</i>	Bent	111.80	111.80
12	2pcs	Rear bumper side retainer @ \$48.50	Necessary	97.00	97.00
13	1pc	Rear end panel <i>Repair</i>	Dented	561.50	561.50
14	1pc	Rear end panel inner member <i>2848.9</i>	Repair	425.00	-
15	1pc	Rear end panel inner trim <i>2778.12</i>	Deformed/Broken	212.60	212.60
16	1pc	Rear exhaust silencer box	Repair	624.40	-
				6,054.90	4,769.60
Less 20%				(1,210.98)	(953.92)
Sub total				4,843.92	3,815.68
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Rear windscreen sealant set	Necessary	100.00	80.00
2	1pc	Rear no plate	Serviceable	30.00	-
3	1set	Reverse sensor (4pcs)	Damaged <i>518</i>	480.00	450.00
4	1set	Rear bumper clip	Necessary	55.00	55.00
5	1set	Rear bumper reflector	Grazed/Broken	88.00	88.00
6	1set	Rear tailgate inner trim board clip	Necessary	45.00	45.00
7	1set	Rear end panel inner trim clip	Necessary	22.00	22.00
Sub total				5,663.92	4,555.68
<u>LABOUR & MISC. CHARGES</u>					
1		To check rear electrical wiring & test for any leakage		80.00	40.00

Constant Appraiser Services

Vehicle No : SJX 190P

Our ref : CAS/18-01/013

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
2		To remove, refix rear windscreen glass		140.00	120.00 ✓
3		To remove, refix reverse sensor		100.00	60.00 ✓ 40
4		To remove, refix interior upholstery to assist repair		120.00	80.00 ✓ 60
5		To respray undercoating		120.00	60.00 ✓ 40
6		To respray painting & etc		1,100.00	1,000.00 ✓ 600
7		To panel beating, remove & replacing		1,100.00	900.00 ✓ 600
8		To remove, refix rear exhaust silencer box	Not Necessary	100.00	-
		Grand total		8,523.92	6,815.68
Commended cost of lump sum repair (To its pre-accident condition)					5,450.00



Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$5,450.00** on a contractual basis. Under normal circumstances, the repair period would be about **4 (Four)** working days.

Yours faithfully,

Constant Appraiser Services



 Lim Yong Tian (Sebastian)
 Licensed Appraiser
 Adv. Dip. In Mechanical Engineering (AUS)
 MSAAA

Total: 4157.12
 1/5: 33K
 04 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Dec 2017		28 Dec 2017 11:40 Edit Adj Rpt	S\$3,300.00 Edit Estimates	S\$3,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JESSICA ART N' CRAFT , Co. Reg. No.: 24187000C								
Main Claimant:	MARTHAS BIN ABU TALIB , ID: S1374625G								
Vehicle Reg. No.:	SJX190P	Date of Loss:	23/12/2017 11:00 - :59 [91 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 542452	Policy/Cover Note No.:	A28604393MKC (TP, Fire & Theft) Coverage: 07/09/2017 - 06/09/2018						
Vehicle Reg. No. (Insured):	GZ3085R	Policy No. (Claimant):							
		Excess:							
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 29/12/2017]								
Driver/Custodian (Insured):	CHENG JING HEAN (), NRIC: S8710321H, Tel: +6583428691								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (05/04/2018): Paper survey report - urgent									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX190P (542452)
[GZ3085R]
TP
MARTHAS BIN ABU TALIB
Dec 23 2017 11:00AM
[JESSICA ART N' CRAFT]
Super Modern Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	28/12/17 11:09	Accident Statement From: SC - Reg. No: GZ3085R, Claimant: JESSICA ART N' CRAFT					Load HTM		
						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
2	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
3	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
4	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
5	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
6	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
7	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
8	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
9	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
10	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
11	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
12	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
13	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
14	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
15	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
16	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
17	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
18	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
19	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
20	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
21	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
22	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
23	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
24	09/03/18 11:42	General View					Load JPG	<input checked="" type="checkbox"/>	
25	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
26	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
27	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
28	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
29	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
30	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
31	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
32	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	
33	09/03/18 11:43	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/03/18 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/03/18 11:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	09/03/18 11:43	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/12/17 11:09	TP GIA Rep -SJJ190P From: SC - Reg. No: GZ3085R, Claimant: JESSICA ART N' CRAFT	 Load PDF	
2	23/02/18 17:18	CONSTANT APPRAISER SERVICES REPORT- SJJ190P.	 Load PDF	
3	23/02/18 17:18	TP SURVYOR PHOTO 1 - SJJ190P	 Load PDF	
4	23/02/18 17:18	TP SURVYOR PHOTO 2 - SJJ190P	 Load PDF	
5	23/02/18 17:18	TP SURVYOR PHOTO 3 - SJJ190P	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17024664/ATD3E2

Date: 13/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28604393MKC

Claimant Vehicle No : SJX190P

Insured Vehicle No : GZ3085R

Date of Loss: 23/12/2017

Nature of Claim: TP

Claim No: 542452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX190P**

Make & Model: HONDA STREAM, 1.8 L RSZ (A)

Engine No: R18A13850561

Reg. Date: 07/05/2010 (Man. Year: 2010)

Chassis No: JHMRN68809C200562

Colour: Black

Odometer: 156317 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,663.92	2,797.12	2,866.80	50.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,360.00	1,500.00	52.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,523.92	4,157.12	4,366.80	51.23
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	8,523.92	3,300.00	5,223.92	61.29
+ GST 7.00/7.00% (S\$)	596.67	231.00	365.67	61.29
Nett Amount (S\$)	9,120.59	3,531.00	5,589.59	61.29

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 02/01/2018 Inspected At:

Super Modern Services Pte Ltd (Kaki Bukit)

Synergy @ KB, Kaki Bukit road 4 , # 01-26
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX190P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR WINDSCREEN MOULDING	Necessary	178.50 FL	*118.50 FL
2	1		*RREAR TAILGATE	Dented	1,465.60 FL	*903.00 FL
3	1		*REAR TAILGATE EMBLEM STREAM	Necessary	62.50 FL	*62.50 FL
4	1		*REAR TAILGATE EMBLEM RSZ	Necessary	85.00 FL	*65.00 FL
5	1		*REAR TAILGATE INNER LOCK	Not Necessary	303.20 FL	*- FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Broken	386.50 FL	*271.50 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	186.60 FL	*- FL
8	2		*REAR TAILGATE STOPPER	Necessary	37.20 FL	*37.20 FL
9	1		*REAR TAILGATE OUTER GARNISH	Serviceable	235.90 FL	*- FL
10	1		*REAR BUMPER	Dented / Broken	1,081.60 FL	*1,081.60 FL
11	1		*REAR BUMPER LOWER BRACKET	O/S Bent	111.80 FL	*55.90 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	97.00 FL	*97.00 FL
13	1		*REAR END PANEL	Repair	561.50 FL	*- FL
14	1		*REAR END PANEL INNER MEMBER	Repair	425.00 FL	*- FL
15	1		*REAR END PANEL INNER TRIM	Deformed / Broken	212.60 FL	*156.70 FL
16	1		*REAR EXHAUST SILENCER BOX	Repair	624.40 FL	*- FL
17	1		*SET REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
18	1		*REAR NO PLATE	Serviceable	30.00 FS	*- FS
19	1		*SET REVERSE SENSOR (4 PCS)	Damaged	480.00 FS	*300.00 FS
20	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*30.00 FS
21	1		*SET REAR BUMPER REFLECTOR	Grazed / Broken	88.00 FS	*88.00 FS
22	1		*SET REAR TAILGATE INNER TRIM BOARD CLIP	Necessary	45.00 FS	*30.00 FS
23	1		*SET REAR END PANEL INNER TRIM CLIP	Necessary	22.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,874.90** **3,366.90**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 1,210.98 569.78

Total Parts (\$\$) 5,663.92 2,797.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING & TEST FOR ANY LEAKAGE	New	80.00	0.00
2	TO REMOVE, REFIX REAR WINDSCREEN GLASS	New	140.00	120.00
3	TO REMOVE, REFIX REVERSE SENSOR	New	100.00	40.00
4	TO REMOVE, REFIX INTERIOR UPHOLSTERY TO ASSIST REPAIR	New	120.00	60.00
5	TO RESPRAY UNDERCOATING	New	120.00	40.00
6	TO RESPRAY PAINTING & ETC	New	1,100.00	500.00
7	TO PANEL BEATING, REMOVE & REPLACING	New	1,100.00	600.00
8	TO REMOVE, REFIX REAR EXHAUST SILENCER BOX	New	100.00	0.00
Gross Labour Cost (\$\$)			2,860.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >