



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 SUZUKI SX4 1.6 HB AT (SJQ9963D)

Date of Loss

24 December 2017

Time of Loss

2.25

Loss Description

SJQ9963D C/W JKK792

Comment

Workshop Details

Total Rebate Amount

4546

Nett Loss Amount

\$7,454.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

29/04/2018



Days of work completion *

41



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJQ9963D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

04/06/2009



Mileage

343718

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

SAFUAN B ZAINAL

CATEGORY Make

POLICY INFORMAT... SUZUKI

ASSESSMENT INFO... SUZUKI

CATEGORY Model

POLICY INFORMAT... SX4 1.6 HB AT

ASSESSMENT INFO... SX4 1.6HB AT

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JSAGYA21S00205726

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 29 April 1968

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 49

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JSAGYA21S00205726

CATEGORY Engine No

POLICY INFORMAT... M16A1463646

ASSESSMENT INFO... M16A1463646

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1586

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 12000

FNOL INFORMATI... 17

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2001

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... BLK 323 WOODLANDS ST 32 #04-149,
730323, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S6816285H

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

19/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/60R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

205/60R16

Front left side

YOKOHAMA5mm

Rear left side

YOKOHAMA5mm

Front right side

YOKOHAMA5mm

Rear right side

YOKOHAMA5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT FENDER - LH			Repair	0	0	0	0	0	Deny
		2	1			FRONT FENDER VVT WORDING - LH			Serviceable	0	0	0	0	0	Deny
		3	1			FRONT FENDER LAMP - LH			Serviceable	0	0	0	0	0	Deny
		4	1			FRONT FENDER COWLING - LH			Damaged	49				49	Reviewing
		5	10			FRONT FENDER COWLING CLIPS - LH			Serviceable	0	0	0	0	0	Deny
		6	1			FRONT FENDER OUTER WHEEL ARCH GARNISH - LH			Damaged	166				166	Reviewing
		7	1			FRONT BUMPER			Deformed	670				670	Reviewing
		8	10			FRONT BUMPER CLIPS			Necessary	1.5				15	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		9	1			FRONT BUMPER SIDE HOLDER - LH			Bent	15				15	Reviewing
		10	1			FRONT BUMPER SIDE HOLDER - RH			Serviceable	0	0	0	0	0	Deny
		11	1			FRONT TYRE RIM - LH			Repair	0	0	0	0	0	Deny
		12	1			FRONT TYRE RIM, SMALL HUP CAP - LH			Serviceable	0	0	0	0	0	Deny
		13	1			HEAD LAMP UNIT - LH			Damaged	315				315	Reviewing
		14	1			HEAD LAMP LOWER RETAINER - LH			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	400	0	0	Reviewing		
		2		TO RESPRAY PAINT ON ACCIDENT PORTIONS	360	0	0	Reviewing		
		3		TO CHECK WIRING	20	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FRONT NUMBER PLATE WITH CASING	Reviewing	35	NECESSARY	
		2	FRONT BUMPER OUTER WHEEL ARCH GARNISH - LH	Reviewing	40	(TORN) SUPPLEMENTARY 26/02/2018	
		3	DAYS OF REPAIR : 4 DAYS	Reviewing			
		4	FRONT NUMBER PLATE	Reviewing	60	NECESSARY	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount \$1,745.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,230.00	\$780.00
Spare Parts	\$2,054.00	\$1,230.00
Miscellaneous	\$35.00	\$135.00
Excess	-\$400.00	-\$400.00