

22/03/2002

ASS. REC. BY:

REF: CS3/MSG17024712/TI d3et

Special Instruction:

Survivor:

Menmen

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSIG Date/Time: 29/12/17 @ 3.24pm

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLK 7659D Insured: SKD 1036P

at Workshop m/s Kok Wang Car Grooming Tel: 9183 9633

of 1, Soon Lee Street #06-40

Policy No: B27214085 SMP Claim No: 542784

Sum Insured: Excess:

Make of Veh: D.O.A. 27/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 02/01/2017

H.O.D. Endorsement:

Date/Time: 4.11pm @ 29/12/17 Person Contacted: Mr. KOK Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLK 7659D-X
	SKD 1036P-CS/MSG1702475/Dgb
	Dismantle Part: 03012018

D.O.A: 27/12/2017

Signature: Tan Kah

REF: MS16

ASSIGNMENT

Cat 2018 March

From:

Date:

02/01/2017

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLK7659D

at Workshop m/s

Kok Wong Car Grooming

of 1, Soon Lee Street #06-40

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS 1 up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK7659D

Yr Regn:

31 2008

March

Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish 1.8A

1794

Colour:

Grey

A/O:

Insured / Std / NI / NA

So. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C.No:

ZNE100399107

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

02/01/18 EC1120

Survey held at

Kok Wang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Repair Estimate : S\$ 6600 - 8500

[Signature]

9/4/2018

RECEIVED 11 APR 2018

Date/Time File Pass to?



Preli. Report

1. 10042018



Final Report

Date/Time File Return to?

2.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:



Site Insp

\$



Interview

\$



Tech. Insp

\$



Re-survey

\$

Photos

Costs

Report Format:

PRS.

Lump Sum / I.B.I.:

120

50

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		29 Dec 2017 15:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GTA ELECTRONICS PTE LTD, Co. Reg. No.: 200303728M		
Main Claimant:	Lay Auto Leasing Pte Ltd, Co. Reg. No.: 201310521C		
Vehicle Reg. No.:	SLK7659D	Date of Loss:	27/12/2017 10:00 - :59
Claim Type:	TP / 542784	Policy/Cover Note No.:	B27214085SMP (Comprehensive) Coverage: 28/10/2017 - 27/10/2018
Vehicle Reg. No. (Insured):	SKD1036P	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/12/2017]		
Driver/Custodian (Insured):	ONG AH KOON (), NRIC: S13672361, Tel: +6591727481		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





883 North Bridge Road
#18-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY.SLK7659D.17.KWC.wp(Lh)

Your Ref : Your Insured vehicle **SKD 1036P**

28 December 2017

GTA ELECTRONICS PTE LTD
c/o Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807



By Fax : 68277809 / 6643 1349


Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLK 7659D & SKD 106P ON 27.12.2017 @ 10:50HRS ALONG PIE TOWARDS EUNOS LINK

We are instructed by M/S LAY AUTO LEASING PTE LTD to notify you of a road traffic accident on 27.12.2017 @ 10:50hrs along PIE towards Eunos Link involving our client's customer's vehicle registration number SLK 7659D and vehicle registration number SKD 106P driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah LLC
Enc

cc: M/s. Kok Wang Car Grooming
1 Soon Lee Street #06 -- 40 Pioneer Centre (S) 627605
Mr. Kok (9183 9633)
By fax 6694 4864

MS1317199953 / STA INSPECTION PTE LTD - Boon Lay
ENTRY DATE & TIME: 27/12/2017 15:26
SUBMITTED BY: GON WEE LING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/12/2017 15:26
Date Of Accident 27/12/2017 10:50
Exact Location Of Accident PIE TOWARDS EUNOS LINK - EXIT- 9
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK7659D
Insured/Policyholder
Name Of Registered Owner LAY AUTO LEASING PTE LTD
Co Reg No 201310521C
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-83832594
Alternative Phone No OFFICE-64625828

Vehicle Particulars

Manufacturer TOYOTA
Model WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number 5088404545-01
Cover Note Number

Driver

Name of Driver MUHAMMAD NABIL SYAZWAN BIN SARBINI
NRIC No S9512129B
Date Of Birth 05/04/1995
Occupation OUTDOOR
Date Of Driving Pass 23/08/2013
Driving Experience 4 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83832594
Fax Number
Contact Number OFFICE-83832594
Email Address NOEMAIL

Address BLK 662 CHOA CHU KANG CRESCENT #18-273
 Postcode 660662
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKD1036P
 Vehicle Make/Model/Colour BMW 730 AUTO - BLACK COLOR
 Details Of Properties FRONT PORTION DAMAGED
 Vehicle Category PRIVATE CAR
 Name of Driver ONG AH KOON
 NRIC/Passport Number S13672361
 Contact Number 91727481
 Address NA
 Postcode NA
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD NABIL SYAZWAN BIN SARBINI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

REFER REPORT

SLK7659D

YES

NO

BLK 662 CHOA CHU KANG CRESCENT #18-273

680662

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/12/2017
12:35 HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At approximately 1050 HRS, I it was my turn to filter into Europa Link after the zebra crossing. I stopped at the give-way sign as I saw traffic coming from Eunos Road, therefore giving way to the main traffic flow (coming from Eunos Road). As I glanced to my rear-view mirror, I saw the driver of the black car at that time looking at the main traffic coming from Eunos Road & white and entering fast into my direction. Within a few seconds, the car rear-ended my rear bumper and caused my vehicle to surge into the nearest lane after the give-way sign marked on the road. My body slammed against my seat ~~while~~ while my head slammed against the head rest of my seat. The impact was caused to my mobile phone docked on the phone holder to drop as well.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

27/12/2017
1235 HRS

Reporting Centre Personnel's Signature
Name:
NRIC/PN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2017		29 Dec 2017 15:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:		GTA ELECTRONICS PTE LTD, Co. Reg. No.: 200303728M		[Created by insurer]	
Main Claimant:		Lay Auto Leasing Pte Ltd, Co. Reg. No.: 201310521C			
Vehicle Reg. No.:		SLK7659D	Date of Loss:	27/12/2017 10:00 - :59 [116 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:		TP / 542784	Policy/Cover Note No.:	B27214085SMP (Comprehensive) Coverage: 28/10/2017 - 27/10/2018	
Vehicle Reg. No. (Insured):		SKD1036P	Policy No. (Claimant):		
			Excess:	S\$750.00	
Repairer:		Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:			
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 30/12/2017]			
Driver/Custodian (Insured):		ONG AH KOON (), NRIC: S13672361, Tel: +6591727481			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)



































ALL ASSOCIATED TASKS



Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Documents

***SLK7659D (542784)**
[SKD1036P]
TP
Lay Auto Leasing Pte Ltd
Dec 27 2017 10:00AM
[GTA ELECTRONICS PTE LTD]
Kok Wang Car Grooming

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/12/17 15:14	Accident Statement <small>From: OD - Reg. No: SKD1036P, Claimant: GTA ELECTRONICS PTE LTD</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/04/18 09:26	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	10/04/18 15:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	10/04/18 15:01	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/12/17 15:14	TP request for PRI	Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1	
2	29/12/17 15:14	SLK7659D E FILE REPORT.	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17024712/T1D3E2

Date: 11/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B27214085SMP

Claimant Vehicle No : SLK7659D

Insured Vehicle No :

SKD1036P

Date of Loss: 27/12/2017

Nature of Claim:

TP

Claim No: 542784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK7659D

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: HIDDEN

Reg. Date: 31/03/2008 (Man. Year: 2008)

Chassis No: ZNE100399107

Colour: Grey

Odometer: 0 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/12/2017

Date Inspected: 02/01/2018 Inspected At:

Kok Wang Car Grooming (HQ)
1 SOON LEE STREET #06-40 PIONEER
CENTRE
Singapore 627605

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,600.00 - \$8,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 11 Apr 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK7659D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >