

ASS. REC. BY:

REF: cs/MSG17024723/Tird3

Special Instruction:

Survivor

Menmen

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

29/12/17 @ 4:39pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGW 8757T

Insured:

SKM 7695A

at Workshop m/s

TC Autoclinic

Tel:

67038511

of

25 Jeng Kee Rd 159097

Policy No:

29025734TMP

Claim No:

543386

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/12/17

CA / REV / REP. / REV 24 HRS

'up'

03/01/17 @ 10am-11am
owner waiting

Date/Time:

4:43pm @ 29/12/17

Person Contacted:

Kalvin

Vehicle IN (OUT)

Date/Time	Action/Instruction
	(✓) Estimate
	SGW 8757 T-X
	SKM 7695A -X
12/1/18	sent poli through menmen
	Confirm \$4606.78, 6 days
	Red: 4378.38, 491.

Synopsis *Tafher*

REF: *msth*

ASSIGNMENT

From: _____ Date: *03.01.2018*

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SHW 8757T*
at Workshop n/s: *TC Autoclinic*
of: *25 Leng Kee Road*

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	

Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SGW8757T* Yr Reg: *2017 July*

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Nissan Pulsar 1.2* CC: *1197*

Colour: *Grey* A/C: Insured / Std / NI / NA

So. Reading: *2172* T. Radio: Insured / Std / NI / NA

Eng No: _____

C.No: *VSKDDAC1340103974*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/50R17*

R: *1 1*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Continental*

Front

Rear

R/Bal: *6* mm R/Bal: *8* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A. _____ D.O.I: *3/1/18 @ 1115*

Survey held at: *TC Leng Kee*

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

94606.78, *6 days*
waiting for before part parts

RECEIVED 12 APR 2018

Date/Time File Pass to: ☐ Prel. Report

typist ☒ Final Report

Date/Time File Return to: _____

Days Of Repair: *6*

Resurvey No. of Trip: *1*

Survey Fee

Transporter

_____ S - R - C -

Phone

Add Fee: ☐ Site Insp: \$

☐ Inter. Insp: \$

☐ Tech. Insp: \$

☐ Lab. Insp: \$

Report Format: *TP*
Lump Sum / I.B. \$: *4606.78*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024723/T1rd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 29-12-2017

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 7695A	Veh. Inspected	SGW 8757T
Policy No.	29025734TMP	Coverage (\$)	0.00
Claim No.	543386	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	29/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/12/2017	Inspection Date
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		29 Dec 2017 16:39 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ANDERSSON ROLF NIKLAS, ID: S7183579J		
Main Claimant:	GOH TECK CHUAN, ID: S6905864G		
Vehicle Reg. No.:	SGW8757T	Date of Loss:	22/12/2017 00:00 - :59
Claim Type:	TP / 543386	Policy/Cover Note No.:	29025734TMP Coverage: 22/09/2017 - 21/09/2018
Vehicle Reg. No. (Insured):	SKM7695A	Policy No. (Claimant):	
		Excess:	
Repairer:	TC AutoClinic Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel: 67038511		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/12/2017]		
Adj Asg. Remarks:	Pls survey the vehicle on 3/01/18 at 10am at TC Autoclinic, 25 Leng Kee Rd		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Hasrianah Binte Hassan

From: Woon Choo Kwok
Sent: Wednesday, 27 December, 2017 4:53 PM
To: Christina Wong; Monica Chung; Hasrianah Binte Hassan
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: Accident Involving SGW8757T & SKM7695A On 22/12/17
Attachments: SGW8757T GIA Report.PDF; Estimate Before Survey.pdf

Dear MC & HAS,

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Wednesday, December 27, 2017 4:33 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: Accident Involving SGW8757T & SKM7695A On 22/12/17

From: Shawn Chua / TCAC [<mailto:shawnychua@tanchong.com>]
Sent: Wednesday, December 27, 2017 1:14 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Kelvin Heng / TC AUTO CLINIC <kelvinheng@tanchong.com>
Subject: Accident Involving SGW8757T & SKM7695A On 22/12/17

Dear Sir/Madam,

Our customer holds your insured driver, **SKM7695A** liable for the accident on **22/12/17** and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, **SGW8757T**.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by **29/12/17**. Otherwise our customer will proceed in a manner that he deems fit.

Please let me know when I can arrange a survey with my customer.

Attached herewith the **GIA Report** and **estimate of repair cost** for **SGW8757T**.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKM7695A	Accident Date	: 22/12/2017
TP Vehicle No	: SGW8757T	Assignment Date	: 29/12/2017
Make	: NISSAN PULSAR	Est. Duration of Repair	: 6.00
Date of Inspection	: 03/01/2018		
Inspection At	: TC AUTOCLINIC PTE LTD (LENG KEE) 25 LENG KEE ROAD SINGAPORE 159097		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,762.60
Revised Amount	:S\$	4,113.88
Check Items (Estimated)	:S\$	2,890.80
Total	:S\$	7,004.68

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 13:44
Date Of Accident	22/12/2017 20:30
Exact Location Of Accident	TAMPINES ST 45 TURNING INTO BLK 497
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW8757T
Insured/Policyholder	
Name Of Registered Owner	GOH TECK CHUAN
NRIC No	S6905864G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96693324
Alternative Phone No	OTHERS-96693324

Vehicle Particulars

Manufacturer	NISSAN
Model	PULSAR-1.2 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700032438
Cover Note Number	25/07/2017 - 24/07/2018

Driver

Name of Driver	LIM AI YEE
NRIC No	S7005463I
Date Of Birth	20/02/1970
Occupation	INDOOR
Date Of Driving Pass	10/04/1993
Driving Experience	24 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97345768
Fax Number	
Contact Number	
EEmail Address	AIYEE.LIM@GMAIL.COM

Address	24 JALAN MASTULI
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to attached sketch plan. 1 driver & 2 passengers.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM7695A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TONY SANDBERG
NRIC/Passport Number	S6964286A
Contact Number	91728064
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

A - SGW 8757 T

B - SKM 7695 A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at Tampines Street 45 while I was waiting to turn into car park entrance of Blk 497, a vehicle came knocked onto the left side of my car while it was stationary. My mother in the front passenger seat & my aun in the right side of the passenger seat.
The driver claimed that due to the wet road, he skidded after applying brake.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Authorization Letter

I, Goh Teck Chuan, S6905864G hereby authorise
Lim Ai Yee, S70054632 to make a report on my behalf.



CERTIFICATE OF INSURANCE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Goh Teck Chuan
 Period of Insurance : 25 Jul 2017 To 24 Jul 2018
 Engine No. : HRA2427433A
 Chassis No. : VSKDDAC13U0103974

Vehicle No. : SGW6757T
 Policy No. : 1700032438
 Endorsement No. :
 Issued Date : 11 Aug 2017

ABOUT THE COVER

Make/Model : NISSAN Pulsar 1.2
 Engine Capacity/Tonnage : 1,197.00 CC
 Driver Restriction : NA

Sum Insured :
 Off Peak Car : No

Market Value :
 First Year of Registration : 2017
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with written permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specific age condition.

You have to pay an additional sum of \$0.000 as "Young and/or Inexperienced Driver Excess" ("YIDP") if You are or Your authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (10 days) 1500cc - 1000cc

* Limitations rendered operative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 156) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

Goh Teck Chuan - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No. 1, Sveli Lek Yang Road Singapore 628059 62622212
2. Autostar Industrial Add: 18 Ubi Road 4 Singapore 408623 64908686
3. TC AutoClinic Add: 25 Leng Fae Road Singapore 109087 67006511 67006512 67006513
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 596223 64640291 64640292 64640293
5. Tan Chong Motor Sales Add: 17 Lorong 8 Teo Payoh Singapore 319254 63570753 63570754

For other Approved Reporting Centres/Autonomous Repairers, please contact our 24-hour accident emergency hotline at +65 9328 9200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 156), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1988 (Malaysia).

0500610318

TAN CHONG CREDIT PTE LTD-GBL
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 596223 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Prile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

0500610318

97345768

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 241/IC/TCAC/CCR/2017
DATE : 26-DEC-2017

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 62232181
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : GOH TECK CHUAN
ADDRESS : 24 JALAN MASTULI

TELEPHONE NO : 97345768

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700032438
VEHICLE NO : SGWB757T
MODEL CODE : DRLARDZC13UEAB-F-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016
ENGINE NO : HRA2427433A
CHASSIS NO : VSKDDAC13U0103974
MILEAGE : 6840 KM
DATE IN : 26/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 22/12/2017

Tan Jiah 97495749
- WP

Resurvey before paint.

03/01/18 @ 1115.

6 days.


15/1/18

sur@hkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts photo are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SQWB757T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RC1	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00 ✓	
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00 ✓	
3 RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00 ✓	
4 ZZ/001	RENEW REAR BUMPER ASSY, BACKDOOR ASSY, EMBLEMS, PANEL AND REPAIRS END PANEL. ²⁵⁰	1250.00 ^{750.}	
5 ZZ/002	RESPRAY REAR BUMPER ASSY, BACKDOOR ASSY, END PANEL. ^{200.}	800.00 ^{600.}	
6 ZZ/003	TRANSFER BACKDOOR MECHANISM TO FACILITATE REPAIR	120.00 ✓	
7 ZZ/004	REMOVE AND INSTALL SEAT CARPET TO FACILITATES REPAIRS	250.00 ✓	
8 ZZ/005	RENEW TAILGATE GLASS TO FACILITATE REPAIR	180.00 ✓	
9 ZZ/006	INSTALL SOLAR FILM ON TAILGATE GLASS	144.00 ✓	
10 ZZ/007	QC, RETUNE & CONSULT CHECK		
11 ZZ/008	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00 ^{3Xnn}	
TOTAL LABOUR CHARGES		3159.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGWB757T

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	REAR UPPER PANEL	09110-3ZLMA	800.30	Xnn		
2	REVERSE SENSOR	SENSOR-TE9140			180.00	des
3	TAILGATE GLASS	90300-3ZLOA	759.50	Xnn		
4	PULSAR EMBLEM	90891-3GFD8	87.00	ne		
5	NISSAN EMBLEM	90890-3ZLQA	59.70	nn		
6	STAY ASSY-BACK DOOR RH	90450-3ZL1A	448.80	Xnn		
7	STAY ASSY-BACK DOOR LH	90451-3ZL1A	448.80	Xnn		
8	FINISHER ASSY-BACK DOOR	90810-3ZLBA	221.20	xnn		
9	TAILGATE	K0100-3ZLAA	1115.80	bt		
10	WEATHERSTRIP	90830-3ZLDC	156.50	Xnn		
11	BOARD ASSY -LUGGAGE FLOOR	84906-3ZL1A	887.30	Xnn		
12	PLATE LUGGAGE	84992-3ZLOA	149.30	Xnn		
13	REINFORCEMENT	H5030-3ZLMA	486.40	bt		
14	LEFT ENERGY ABSORBER	85093-3ZLOA	154.60	? der		
15	RIGHT ENERGY ABSORBER	85092-3ZLOA	154.60	xnn		
16	RIGHT BUMPER BRACKET	85226-3ZLOA	59.30	xnn		
17	LEFT BUMPER BRACKET	85227-3ZLOA	59.30	Xnn		
18	REAR BUMPER	H5022-3ZLMH	731.10	der		
SUB TOTAL			6779.50	0.00	180.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1355.90	0.00	0.00	
GRAND TOTAL			5423.60	0.00	180.00	
OVERALL TOTAL			5603.60			

LEGEND: REMARKS(OK) = APPROVED. REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGWB757T

TOTAL LABOUR CHARGES	3159.00
TOTAL SPARE PARTS CHARGES	5603.60
GRAND TOTAL	8762.60 * 8985.16

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 241/IC/TCAC/CCR/2017
DATE : 26-DEC-2017

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 62232181
FAX : 62257402
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : GOH TECK CHUAN
ADDRESS : 24 JALAN MASTULI

TELEPHONE NO : 5(537751)
: 97345768

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700032438
VEHICLE NO : SGWB757T
MODEL CODE : DRLAR0ZC13UEAB-F-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016
ENGINE NO : HRA2427433A
CHASSIS NO : VSKDDAC13U0103974
MILEAGE : 6840 KM
DATE IN : 26/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 22/12/2017

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGWB757T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	120.00
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
4 ZZ/001	RENEW REAR BUMPER ASSY, TAILGATE, EMBLEMS REPAIR REAR UPPER PANEL	1250.00	750.00
5 ZZ/002	RESPRAY REAR BUMPER ASSY, BACKDOOR ASSY, END PANEL	800.00	600.00
6 ZZ/003	TRANSFER BACKDOOR MECHANISM TO FACILITATE REPAIR	120.00	120.00
7 ZZ/004	REMOVE AND INSTALL SEAT CARPET TO FACILITATES REPAIRS	250.00	250.00
8 ZZ/005	RENEW TAILGATE GLASS TO FACILITATE REPAIR	180.00	180.00
9 ZZ/006	INSTALL SOLAR FILM ON TAILGATE GLASS	144.00	144.00
10 ZZ/007	QC, RETUNE & CONSULT CHECK		
11 ZZ/008	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	.00
	TOTAL LABOUR CHARGES	3159.00	2339.00
	ADDITIONAL DISCOUNT(5.00%)		116.95
	FINAL LABOUR CHARGES		2222.05

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGW8757T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 LEFT REINFORCEMENT STAY (SUPPLEMENTARY)	H5211-3ZLMA	278.20		b7✓	OK
✓ 2 STAY ASSY-BACK DOOR RH	90450-3ZL1A	448.80			X
✓ 3 PULSAR EMBLEM	90891-3GF08	87.00			OK
✓ 4 NISSAN EMBLEM	90890-3ZL0A	59.70			OK
5 REINFORCEMENT (SUPPLEMENTARY)	H5030-3ZLMA	485.40		b7✓	OK
✓ 6 REAR UPPER PANEL	G9110-3ZLMA	800.30			X
✓ 7 REVERSE SENSOR	SENSOR-TE5140			180.00	OK
✓ 8 TAILGATE GLASS	90300-3ZL0A	759.50			X
✓ 9 STAY ASSY-BACK DOOR LH	90451-3ZL1A	448.80			X
✓ 10 FINISHER ASSY-BACK DOOR	90810-3ZL8A	221.20			X
✓ 11 TAILGATE	X0100-3ZLAA	1115.80			OK
✓ 12 WEATHERSTRIP	90830-3ZLOC	156.50			X
✓ 13 BOARD ASSY -LUGGAGE FLOOR	84906-3ZL1A	887.30			X
✓ 14 PLATE LUGGAGE	84992-3ZL0A	149.30			X
✓ 15 LEFT ENERGY ABSORBER (SUPPLEMENTARY)	85093-3ZL0A	154.60			OK
✓ 16 RIGHT ENERGY ABSORBER	85092-3ZL0A	154.60			X
✓ 17 RIGHT BUMPER BRACKET	85226-3ZL0A	59.30			X
✓ 18 LEFT BUMPER BRACKET	85227-3ZL0A	59.30			X
✓ 19 REAR BUMPER	H5022-3ZLMH	731.10			OK
SUB TOTAL		2912.80	0.00	180.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		582.56	0.00	0.00	
GRAND TOTAL		2330.24	0.00	180.00	
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-5.00%)		116.51	0.00	9.00	
OVERALL TOTAL		2384.73			

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

> MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SQWB757T

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST
				S/NETT REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGWB7571

NETT ITEM	2912.80
LESS 20.00%	-582.56
NETT AMOUNT	2330.24
ADDITIONAL DISCOUNT(5.00%)	-116.51
FINAL AMOUNT	2213.73

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	180.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	180.00
ADDITIONAL DISCOUNT(5.00%)	-9.00
FINAL AMOUNT	171.00

TOTAL LABOUR CHARGES	2222.05
TOTAL SPARE PARTS CHARGES	2384.73

TOTAL CHARGES	4606.78
ADD 7 % GST	322.47

GRAND TOTAL	4929.25
-------------	---------

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		29 Dec 2017 16:39 Edit Adj Rpt	S\$4,606.78 Edit Estimates	S\$4,606.78 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ANDERSSON ROLF NIKLAS , ID: S7183579J									
Main Claimant: GOH TECK CHUAN , ID: S6905864G									
Vehicle Reg. No.: SGW8757T		Date of Loss: 22/12/2017 00:00 - :59 [4 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 543386		Policy/Cover Note No.: 29025734TMP Coverage: 22/09/2017 - 21/09/2018							
Vehicle Reg. No. (Insured): SKM7695A		Policy No. (Claimant):							
		Excess:							
Repairer: TC AutoClinic Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel: 67038511									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/01/2018]									
Adj Asg. Remarks: Pls survey the vehicle on 3/01/18 at 10am at TC Autoclinic, 25 Leng Kee Rd									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGW8757T (543386)
[SKM7695A]
TP
GOH TECK CHUAN
Dec 22 2017 12:00AM
[ANDERSSON ROLF NIKLAS]
TC AutoClinic Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/01/18 15:23	Accident Statement From: SC - Reg. No: SKM7695A, Claimant: ANDERSSON ROLF NIKLAS		 Load HTM	

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/01/18 10:36	Adjuster Immediate Advice		 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/01/18 10:40	General View		 Load JPG	☒
2	12/01/18 10:40	General View		 Load JPG	☒
3	12/01/18 10:40	General View		 Load JPG	☒
4	12/01/18 10:40	General View		 Load JPG	☒
5	12/01/18 10:40	General View		 Load JPG	☒
6	12/01/18 10:40	General View		 Load JPG	☒
7	12/01/18 10:40	General View		 Load JPG	☒
8	12/01/18 10:40	General View		 Load JPG	☒
9	12/01/18 10:40	General View		 Load JPG	☒
10	12/01/18 10:40	General View		 Load JPG	☒
11	12/01/18 10:40	General View		 Load JPG	☒
12	12/01/18 10:40	General View		 Load JPG	☒
13	12/01/18 10:40	General View		 Load JPG	☒
14	12/01/18 10:40	General View		 Load JPG	☒
15	12/01/18 10:40	General View		 Load JPG	☒
16	12/01/18 10:40	General View		 Load JPG	☒
17	12/01/18 10:40	General View		 Load JPG	☒
18	12/01/18 10:40	General View		 Load JPG	☒
19	12/01/18 10:40	General View		 Load JPG	☒
20	12/01/18 10:40	General View		 Load JPG	☒
21	12/01/18 10:40	General View		 Load JPG	☒
22	12/01/18 10:40	General View		 Load JPG	☒
23	12/01/18 10:40	General View		 Load JPG	☒
24	12/01/18 10:40	General View		 Load JPG	☒
25	12/01/18 10:40	General View		 Load JPG	☒
26	12/01/18 10:40	General View		 Load JPG	☒
27	12/01/18 10:40	General View		 Load JPG	☒
28	12/01/18 10:40	General View		 Load JPG	☒
29	12/01/18 10:40	General View		 Load JPG	☒
30	12/04/18 09:56	Reinspection Photo		 Load JPG	☒
31	12/04/18 09:56	Reinspection Photo		 Load JPG	☒
32	12/04/18 09:56	Reinspection Photo		 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	12/04/18 09:56	Reinspection Photo	Load JPG	☒
34	12/04/18 09:56	Reinspection Photo	Load JPG	☒
35	12/04/18 09:56	Reinspection Photo	Load JPG	☒
36	12/04/18 09:56	Reinspection Photo	Load JPG	☒
37	12/04/18 09:56	Reinspection Photo	Load JPG	☒
38	12/04/18 09:56	Reinspection Photo	Load JPG	☒
39	12/04/18 09:56	Reinspection Photo	Load JPG	☒
40	12/04/18 09:56	Reinspection Photo	Load JPG	☒
41	12/04/18 09:56	Reinspection Photo	Load JPG	☒
42	12/04/18 09:56	Reinspection Photo	Load JPG	☒
43	12/04/18 09:56	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/12/17 15:20	Email frm TP - PRI	Load PDF	
2	29/12/17 15:26	Estimate	Load PDF	
3	29/12/17 15:27	SGW8757T GIA Report	Load PDF	
4	12/01/18 15:23	TP GIA Rep - SGW8757T. From: SC - Reg. No: SKM7685A, Claimant: ANDERSSON ROLF NIKLAS	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/04/18 09:04	SUPPLEMENTARY PART	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024723/T1RD3Q2

Date: 16/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29025734TMP

Claimant Vehicle No: SGW8757T

Insured Vehicle No: SKM7695A

Date of Loss: 22/12/2017

Nature of Claim: TP

Claim No: 543386

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGW8757T

Make & Model: NISSAN PULSAR, 1.2 L DIG-T (A)

Engine No: HRA2427433A

Reg. Date: 25/07/2017 (Man. Year: 2017)

Chassis No: VSKDDAC13U0103974

Colour: Grey

Odometer: 7172 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size: 205/50 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,826.16	2,384.73	3,441.43	59.07
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	3,159.00	2,222.05	936.95	29.66
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,985.16	4,606.78	4,378.38	48.73
+ GST 7.00/7.00% (S\$)	628.96	322.47	306.49	48.73
Nett Amount (S\$)	9,614.12	4,929.25	4,684.87	48.73

INSPECTION

Date of Assignment: 29/12/2017

Date Inspected: 03/01/2018 Inspected At:

TC AutoClinic Pte Ltd (Leng Kee)

25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Apr 2018)

Parts: N/A NISSAN PULSAR 1.2 L DIG-T (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGW8757T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER PANEL	Not Necessary	800.30 FN	*- FN
2	1		*REVERSE SENSOR	Distorted	180.00 FS	*171.00 FS
3	1		*TAILGATE GLASS	Not Necessary	759.50 FN	*- FN
4	1		*PULSAR EMBLEM	Necessary	87.00 FN	*87.00 FN
5	1		*NISSAN EMBLEM	Necessary	59.70 FN	*59.70 FN
6	1		*STAY ASSY -BACK DOOR RH	Not Necessary	448.80 FN	*- FN
7	1		*STAY ASSY -BACK DOOR LH	Not Necessary	448.80 FN	*- FN
8	1		*FINISHER ASSY -BACK DOOR	Not Necessary	221.20 FN	*- FN
9	1		*TAILGATE	Bent	1,115.80 FN	*1,115.80 FN
10	1		*WEATHERSTRIP	Not Necessary	156.50 FN	*- FN
11	1		*BOARD ASSY -LUGGAGE FLOOR	Not Necessary	887.30 FN	*- FN
12	1		*PLATE LUGGAGE	Not Necessary	149.30 FN	*- FN
13	1		*REINFORCEMENT	Bent	486.40 FN	*486.40 FN
14	1		*LEFT ENERGY ABSORBER	Deformed	154.60 FN	*154.60 FN
15	1		*RIGHT ENERGY ABSORBER	Not Necessary	154.60 FN	*- FN
16	1		*RIGHT BUMPER BRACKET	Not Necessary	59.30 FN	*- FN
17	1		*LEFT BUMPER BRACKET	Not Necessary	59.30 FN	*- FN
18	1		*REAR BUMPER	Deformed	731.10 FN	*731.10 FN
19	1		*LEFT REINFORCEMENT STAY	Bent	278.20 FN	*278.20 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,237.70	3,083.80
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	1,411.54	582.56
- Add. Disc. on L,N Items 0.00/5.00% (\$\$)	0.00	116.51
Total Parts (\$\$)	5,826.16	2,384.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REVERSE CAMERA ,FINISHER MOUNTING ,ALIGNMENT ,SETTING & FUNCTION TEST	New	120.00	120.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
3	REPLACE REVERSE SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
4	RENEW REAR BUMPER ASSY ,BACKDOOR ASSY ,EMBLEMS ,PANEL AND REPAIRS END PANEL	New	1,250.00	750.00
5	RESPRAY REAR BUMPER ASSY ,BACKDOOR ASSY ,END PANEL	New	800.00	600.00
6	TRANSFER BACKDOOR MECHANISM TO FACILITATE REPAIR	New	120.00	120.00
7	REMOVE AND INSTALL SEAT CARPET TO FACILITATES REPAIRS	New	250.00	250.00
8	RENEW TAILGATE GLASS TO FACILITATE REPAIR	New	180.00	180.00
9	INSTALL SOLAR FILM ON TAILGATE GLASS	New	144.00	144.00
10	WASH & VACUUM ,POLISH & WAX.SHINE ALL TYRES	New	120.00	0.00
Gross Labour Cost (\$\$)			3,159.00	2,339.00
- 0.00/5.00% Labour Discount (\$\$)			0.00	116.95
Gross Labour after Discount (\$\$)			3,159.00	2,222.05

Report was unsubmitted during this print-out.

< END OF ESTIMATES >