

SURVEY REQUEST ON 03/01/2018
AFTER 1000 HRS.
Tayeb

ERGO

Date: 26.12.2017
Our Reference: DSMPC1703041/SE/pl
Your Reference: SLS 9489Y

Sent via Fax

or

Email

sayedinah@motorimage.net

To: **MOTOR IMAGE ENTERPRISES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: **SLS 9489Y**
Insured's Vehicle: **SJE 9364X**
Date Of Accident: **19.12.2017**


We acknowledge receipt of your request for PRS on: **26.12.2017**

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

| | | | |
|-----|--|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd | LKK | LKK Auto Consultants Pte Ltd |
| IAS | Infiniti Appraisal Service | PS | Priority Services |
| JPK | JP Knights Pte Ltd | VAC | Vicom Ltd |
| | | | |

| | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy. |
| <input type="checkbox"/> | Your request for inspection does not have your client's GIA report, kindly forward a copy. |
| <input type="checkbox"/> | We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate. |
| <input type="checkbox"/> | Our Insured's driver has not reported the accident to us to date. |
| <input checked="" type="checkbox"/> | Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OIC - STEVE LIM |

| | | | | |
|--------------|---|--------|-----------|---------------------------|
| Prepared by: |  | Pei Li | 6829 9194 | claims@ergo.com.sg |
| Signature: | | | | FAX : 6829 9247 |

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

| |
|--|
| |
|--|

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0553/2017
DATE : 22-DEC-2107

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : JOSHUA NATHAN
ADDRESS : BLK 288C BUKIT BATOK STREET 25
#10-26
S(652288)
TELEPHONE NO : 9835 2932

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1
VEHICLE NO : SLS9489Y
MODEL CODE : GT3BKGC
MODEL/YEAR : SUBARU XV 1.6I-S AWD CVT
ENGINE NO : FB16YB21176
CHASSIS NO : JF1GT3KC5JG020103
MILEAGE : 1 KM
DATE IN : 22/12/2107
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/12/2017

Print Date : 22/12/2017
Print Time : 11:00:54

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLS9489Y

| S/NO | JOB CODE | NATURE OF JOB | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|---|-------------------|---------------------------|
| 1 | TPCLAIM | CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) | | |
| 2 | ZZ/001 | TO CONDUCT TP CLAIM ERGO LOCATION JUNC OF JURONG EAST1 & JURONG TOWN HALL DATE 19/12/2017 TIME:0920 | | |
| 3 | ZZ/002 | REPLACE/REFIX REAR BUMPER, PANEL, TAILGATE | 1680.00 | |
| 4 | ZZ/003 | RESPRAY REAR BUMPER, PANEL, TAILGATE | 1260.00 | |
| 5 | ZZ/004 | TRANSFER (BOOTLID) MECHANISM | 150.00 | |
| 6 | ZZ/005 | REMOVE & INSTALL (FRT/REAR)WINDSCREEN | 300.00 | |
| 7 | ZZ/006 | TO CONDUCT (FRT / REAR) LIGHTNING TEST | 50.00 | |
| 8 | ZZ/007 | TO SUPPLY & INSTALL REVERSE SENSOR - 2EYES | 300.00 | |
| 9 | ZZ/008 | TO SUPPLY & INSTALL (PER SIDE) TINTED FILM | 145.00 | |
| 10 | ZZ/009 | SUNDRIES | 100.00 | |
| TOTAL LABOUR CHARGES | | | 3985.00 | |

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLS9489Y

| | | DAMAGED PARTS & PRICES | | | |
|-----------------------------|-----------------------------|--------------------------|---------|------|----------------|
| S/NO | PARTS DESCRIPTION | PARTS NUMBER | NETT | LIST | S/NETT |
| | | | | | S/LIST REMARKS |
| 1 | GASKET | 44011SG000 | 7.20 | | |
| 2 | EXH PIPE ASSY R | 44200FL110 | 527.58 | | |
| 3 | MUFFLER ASSY W16 | 44300FL020 | 720.00 | | |
| 4 | SKIRT COMPL R 5D | 52401FL0209P | 288.00 | | |
| 5 | BUMPER FACE R XV | 57704FL250 | 401.00 | | |
| 6 | BRKT SD R XV RH | 57707FL400 | 12.10 | | |
| 7 | BRKT SD R XV LH | 57707FL410 | 12.10 | | |
| 8 | BEAM COMPL R EU | USE FL0409P 57711FL0419P | 202.90 | | |
| 9 | COVER HOOK R XV | 57731FL570NN | 6.50 | | |
| 10 | LENS & BODY COMPLRRH | 84913AL120 | 129.60 | | |
| 11 | LENS & BODY COMPLRLH REFLEX | 84913AL140 | 64.20 | | |
| SUB TOTAL | | | 2371.18 | 0.00 | 0.00 |
| LESS DISCOUNT (NETT-20 %) | | | 474.24 | 0.00 | 0.00 |
| GRAND TOTAL | | | 1896.94 | 0.00 | 0.00 |
| OVERALL TOTAL | | | 1896.94 | | |

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLS9489Y

TOTAL LABOUR CHARGES 3985.00
TOTAL SPARE PARTS CHARGES 1896.94

GRAND TOTAL 5881.94 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.