

2/03/2017

ASS. REG. BY:

REF: CS/PCI18000031 /Tb 521

Special Instruction:

Surveyor: Taufelch.

ASSIGNMENT (Office)

From (Person): Eteerlee CWS of First Capital Insurance

Date/Time: 2/1/2018 - 245pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBF 490 M

Insured: SHA 4348 X

at Workshop m/s Hug chin (2000) Trading Motor Service Center

Tel: 68966619/0

of 50 Bukit Batok Street 23 #02-02 Midview Building

Policy No:

Claim No: 018000059 MF8H

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 27/2/2017

CA / REV / REP. / REV 24 HRS

3/1/2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle-IN/OUT

Date/Time	Action/Instruction () Estimate
10/2/2017	SHA 4348 X - NS/INC17002150/H1VH3m DOA: 02/02/2017
	Dismantle Part: 04-01-2018
	After repair: 11-01-2018

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS3/FCI18000031/T1b	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-01-2018	
		Code : FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 4348X	Veh. Inspected	FBF 490M
Policy No.		Coverage (\$)	0.00
Claim No.	D18000059MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	02/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/12/2017	Inspection Date	03/01/2018
Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

MOTOR SURVEY ASSIGNMENT

Date	28-12-2017	Our Ref No. D18000059MFSH
Accident Date	27-12-2017	Claim Type. Third Party
Insured Vehicle	SHA4348X	Third Party Vehicle. FBF490M
Survey Location	50 BUKIT BATOK STREET 23 #02-02 MIDVIEW BUILDING	
Contact Person.	MR LIM W KOON	
Contact No.	68966619/0	Fax No. 62678616
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Mr Lim 3/1/2018
Veh In.

Cc : Workshop	HUA CHIN (2000)TRADING MOTOR SERVICE CENTRE	Attention. NIL
Cc : TP Solicitor	MAHADI ABU BAKAR & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232456)



PRI Documents



Close



PRI Header Details

Claim No	D18000059MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & MA PARTNER RIDER
Workshop Name	HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE (Contact Person : MR. LIM W KOON)	Survey Location & Contact Details	50 BUKIT BATOK STREET 23 #02-02 MIDVIEW Mobile: 0 , Phone: 68966619 , Fax: 6267861 EmailId: MAB_LAW06@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4348X	TP Vehicle No	FBF49C
PRI Recieved Date	28-12-2017 10:04:25 PM	Surveyor Appointed Date	02-01-2018 02:46:21 PM	Surveyor Accept Date	27-01-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	27-01-2018	Upload Survey Report *:	<input type="text"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks


**SINGAPORE
POLICE FORCE**


T/20171227/2108

1 of 3

Police Station, Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20171227/2108

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/12/2017 16:28		Vide Report No.:		Station Diary No.: 71	
Informant's Particulars					
Name of Informant: CHUA BOON HOW			Address: APT BLK 421 BUKIT BATOK WEST AVENUE 2 #09-171 SINGAPORE 650421		
ID Type / ID No.: NRIC NO / S81648681			Contact No.: Home/Office: Mobile: 93632002		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 36	Date of Birth: 07/09/1981	Type of Informant: Rider		
Race: Chinese			Language: Malay		Institution / School Name:
Occupation: Chef			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 27/12/2017 15:15	Type of Location: Straight Road
Location: Along Road 1 ROCHESTER PARK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF490M	Motorcycle	YAMAHA	FZ1-N	White	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBF490M	NTUC Income Insurance Co-Operative Limited	5075457069-01	07/01/2017	06/01/2018



**SINGAPORE
POLICE FORCE**



T/20171227/2108

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

2 of 3

Report No. T/20171227/2108

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider:			
Name	CHUA BOON HOW	ID No.	S8164868I
Related Vehicle	FBF490M (Motorcycle)	Contact No.	93632002
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/12/2017 at about 1515hrs, I was riding my motorbike, registration number FBF490M, along Rochester Park. Suddenly, a door from the rear right passenger seat, of a blue taxi, swing open. I could not stop in time. As such, the door hit on to me. The driver and passenger alighted from the taxi and look at me. They did not assist me. The driver went back to his taxi and left the scene.



**SINGAPORE
POLICE FORCE**



T/20171227/2108

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3

Report No. T/20171227/2108

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D/
Staff Sgt NOORHIDAYAT BIN WAHID

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
27/12/2017 16:28

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt ESTHER CHONG
Contact No.: 65476368

Classification Of Case:

Authentication Stamp
NP168

SINGAPORE
POLICE FORCE

SN 40

SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4868I
Vehicle Details	
Vehicle No.:	FBF490M
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jan 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZ1-N
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	N513E052861
Chassis No.:	JYARN16H000000380
Maximum Power Output:	-
Open Market Value:	\$10,176.00
Original Registration Date:	07 Jan 2011
First Registration Date:	07 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$1,527.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2021
COE Category:	D - Motorcycle

COE Period(Years):	10
QP Paid:	\$1,503.00
COE Rebate Amount:	\$442.00
Total Rebate Amount:	\$442.00

The information contained herein is correct as at 27 Jan 2018

OK



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI18000031/T1bs2	
36 ROBINSON ROAD		Date: 01-02-2018	
#16-01 CITY HOUSESINGAPORE 068877		Code: FCI2	
			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 4348X	Veh. Inspected	FBF 490M
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D18000059MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	02/01/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA FZ1-N	c.c	998
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JYARN16H000000380	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	190/55 R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55 R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information			
Accident Date	27/12/2017	Inspect Date / Time	03/01/2018 (12:50 PM)
Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/FCI18000031/T1bs2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.