

DAR & days.

1204570

APP REC BY

REF CS3/AIG18000042/M1632

Special Instruction

Signature

Ma

ASSIGNMENT (Office)

Mr/Ms/Mr/Ms

chin Lee Ying

AIG

Date/Turn: 02012018

Estimate No.

Bill to

OD (TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDX 5533Y

Insured SUY 240X

at Workshop: Motronic Motor Works Pte Ltd

Tel:

of Sin Ming Auto City, 160 Sin Ming Drive SC 575722

Policy No.

Claim No.

Sum Insured

Excess:

Make of Veh.

(Client's Record)

DOA 29/22017

CA / REV / REP. / REV 24 HRS

3/1/2018

H.O.D. Endorsement

Date/Turn

2/1

Person Contacted

Ray

Vehicle (IN) OUT

Date/Turn

Action/Instruction

Estimate

24092014 SDX 5533Y - CC3/AIG14012708/Rgbq2 DOA: 26/06/2014

After repair: 10-01-2018

REF:

ATG

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days: Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SDX 55331 Yr Regn: FEB 2012Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: LAND ROVER cc: 392Colour: RED A/C: Insured / Std / NI / NASp. Reading: 100694 T. Radio: Insured / Std / NI / NA

Eng. No: _____

C/No: SALFA2AA3CH283048Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / 2 Rim / STD A/Rim orTyre Size: F: 235/60/R18 m/c

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm R/Bal: 8 mmL/Bal: 8 mm L/Bal: 8 mmD.O.A: 21/12/2017 D.O.I: 03/01/2018 CSurvey held at: motronic 4:48 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OS Body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 09 MAR 2018

Date/Time / File Pass to?

09/03/2018



: Preli. Report



: Final Report

Date/Time / File Return to?

2

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

3-45-15

Phone

Diary

Add Fee:



Site Insp. / \$



Interview / \$



Tech Insp. / \$



Overhead / \$

Report Format: PRS

Lump Sum / I.B.I: / \$



Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

| (1) Office Assign Form | | Y-Date | N-Date | Y-Date | N-Date |
|------------------------|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | ✓ | | | |
| N | Assign From | ✓ | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | | | | |
| C | Claim No | | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

| (1) Assignment Form | | Y-Date | N-Date | Y-Date | N-Date |
|---------------------|------------------------|--------|--------|--------|--------|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|--|--|--|--|
| N | ALL Parts condition | | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | | | | |
| C | Finalised Amount | | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|--|--|--|--|
| C | Resurvey photo Uploaded | | | | |
|---|-------------------------|--|--|--|--|

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---------------------------|---------------------------|------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CS3/AIG18000042/M1b | | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 02-01-2018 | |  |
| | | Code : AIG | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SLU 240X | Veh. Inspected | SDX 5533Y | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | CHIN LEE YING | Assign Date | 02/01/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 29/12/2017 | Inspection Date | 04/01/2018 | |
| Survey held at | 160 SIN MING DRIVE #08-06 | | | |
| Repairer | MOTRONIC MOTOR WORKS | | | |
| 5a. Remarks | | | | |
| | | | | |

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLU240X AND SDX5533Y ON 29/12/2017**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: Tuesday, 2 January, 2018 3:00:22 PM
Attachments:  PRS 1 - SDX 5533Y.PDF  PRS 2 - SDX 5533Y.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SLU 240X SLU 240X
Our Ref : SDX 5533Y/MM/jp/ms
Date : 2 January 2018

DID: 3152 0985
Email: jiapei@ksegp.com

AIG Asia Pacific Insurance Pte Ltd

By Fax 6415 3727 & Email

Dear Sirs,

DATE OF ACCIDENT: 29 December 2017
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your fax of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/no. | Name of Surveyor | Company Name |
|-------|------------------|------------------------------------|
| 1 | William Ng | Allied Auto Appraisal |
| 2 | Lee Kok Weng | Lee Automobile Appraisers Services |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Motronic Motor Works Pte Ltd
Sin Ming Auto City
160 Sin Min Drive
Singapore 575722
Contact Person/HP/Tel : Mr. Ray Ng / Tel: 9662 9356

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

f JP

Your Ref : SLU 240X
Cur Ref : SDX 5533Y/RV/jp/ms
Date : 2 January 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (party by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------------|
| Date Of Report | 30/12/2017 12:36 |
| Date Of Accident | 29/12/2017 23:00 |
| Exact Location Of Accident | MCNAIR ROAD TOWARDS BALESTIER ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------|
| Vehicle Registration Number | SDX5533Y |
| Insured/Policyholder | |
| Name Of Registered Owner | SIEW NAI PEN |
| NRIC No | S0214524C |
| Email Address | SIEWNAIPEN@PENTEC.COM.SG |
| Mobile Phone No | (LOCAL) +65-98366828 |
| Alternative Phone No | OFFICE-98366828 |

Vehicle Particulars

| | |
|--|---|
| Manufacturer | LAND ROVER |
| Model | FREELANDER 2 LF 3.2L (A) ABS A/B G/D SR |
| Exact Purpose for which vehicle was being used at time of accident | |

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5085408194-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|--------------------------|
| Name of Driver | SIEW NAI PEN |
| NRIC No | S0214524C |
| Date Of Birth | 20/04/1953 |
| Occupation | INDOOR |
| Date Of Driving Pass | 03/12/1991 |
| Driving Experience | 26 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98366828 |
| Fax Number | |
| Contact Number | OFFICE-98366828 |
| Email Address | SIEWNAIPEN@PENTEC.COM.SG |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

30 Dec 2017 10:25am


Driver's Signature
(If driver is not the policyholder)

30 Dec 2017 10:25am
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BOX 5533Y DAR Right Side

- 1.) RHF Fender x 1 Painted
- 2.) RHF Fender lower garnish x 1 distorted
- 3.) RHF Fender air vent outer cover x 1 cut
- 4.) RHF wheel rim x 1 rep scratched LR 2001-
- 5.) RHF door x 1 Painted
- 6.) RHF door lower garnish x 1 cut
- 7.) RHR door x 1 rep
- 8.) Rear bumper x 1 rep
- 9.) RHR wheel rim x 1 rep scratched LR 2001-
- 10.) RHR door lower garnish x 1 cut.

| | |
|-------------------|----------------------------|
| Pr Panel Painting | ₹1200/- ₹1000/- |
| Spry Painting | ₹1000/- |
| R/R RHF door | ₹60/- |
| R/R Trng cont | ₹40/- |

5 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|--|--|------------|---|
| Main | 03 Jan 2018 Edit Reg | | 02 Jan 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|---|------------------------|----------------------------|
| Insured: | S K NAIR CHAUFFEUR SERVICES, Co. Reg. No.: 53371006E | | |
| Main Claimant: | SIEW NAI PEN, ID: S0214524C | | |
| Vehicle Reg. No.: | SDX5533Y | Date of Loss: | 29/12/2017 23:00 - :59 |
| Claim Type: | TP / 8862803246SG | Policy/Cover Note No.: | 1700080110 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SLU240X | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Motronic Motor Works (HQ) BLK 17 SIN MING IND. EST. SEC. A #01-69, 575675 Sin Ming - Tel: 6454 8418 / 9820 9599 | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 06/02/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (29/01/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SDX5533Y (8862803246SG)**
[SLU240X]
TP
SIEW NAI PEN
Dec 29 2017 11:00PM
[S K NAIR CHAUFFEUR SERVICES]
Motronic Motor Works

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

| Assessment Reports | | | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--------------|-------------------------------------|
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 29/01/18 09:54 | Accident Statement <small>From:OD - Reg. No: SLU240X, Claimant: S K NAIR CHAUFFEUR SERVICES</small> | Load HTM | |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 27/01/18 13:29 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 27/01/18 13:29 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 27/01/18 13:29 | General View | Load JPG | <input checked="" type="checkbox"/> |

| | | | | | |
|----|----------------|-------------------|---|----------|---|
| 31 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 32 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 33 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 34 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 35 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 36 | 27/01/18 13:29 | General View | i | Load JPG | ✓ |
| 37 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 38 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 39 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 40 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 41 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 42 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 43 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 44 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 45 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 46 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 47 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 48 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 49 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 50 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 51 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 52 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 53 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 54 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 55 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 56 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |
| 57 | 27/01/18 13:31 | Photo After Spray | i | Load JPG | ✓ |

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18000042/M1BS2
 Date: 12/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700080110

Claimant Vehicle No: SDX5533Y

Insured Vehicle No: SLU240X

Date of Loss: 29/12/2017

Nature of Claim: TP Claim No: 8862803246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDX5533Y

Make & Model: LAND ROVER FREELANDER 2 HSE, 3.2 (A)

Engine No: B6324S11101107305

Reg. Date: 29/02/2012 (Man. Year: 2011)

Chassis No: SALFA2AA3CH283048

Colour: Red

Odometer: 100654 km

Engine Capacity: 3192 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18

Rear Tyre Size: 235/60R18

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 02/01/2018

SIN MING AUTO CITY, 160 SIN MING DRIVE
SINGAPORE 575722

Date Inspected: 03/01/2018 Inspected At:

Repairer: Motronic Motor Works (HQ)
BLK 17 SIN MING IND. EST. SEC. A #01-69
Singapore 575675

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|--|-----------|---------------------------|------------------|
| 1 | 1 | | *RHF FENDER | Dented | 0.00 F | *- F |
| 2 | 1 | | *RHF FENDER LOWER GARNISH | Distorted | 0.00 F | *- F |
| 3 | 1 | | *RHF FENDER AIR VENT OUTER COVER | Cut | 0.00 F | *- F |
| 4 | 1 | | *RHF WHEEL RIM (LOCAL REPAIR @ \$200.00) | Repair | 0.00 F | *- F |
| 5 | 1 | | *RHF DOOR | Dented | 0.00 F | *- F |
| 6 | 1 | | *RHF DOOR LOWER GARNISH | Cut | 0.00 F | *- F |
| 7 | 1 | | *RHR DOOR | Repair | 0.00 F | *- F |
| 8 | 1 | | *REAR BUMPER | Repair | 0.00 F | *- F |
| 9 | 1 | | *RHR WHEEL RIM (LOCAL REPAIR @ \$200.00) | Repair | 0.00 F | *- F |
| 10 | 1 | | *RHR DOOR LOWER GARNISH | Cut | 0.00 F | *- F |
| F=Franchise part. | | | | | | |
| | | | | | Total Parts (\$\$) | 0.00 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >