



PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18000048/M1be2		
8 SHENTON WAY #24-01		Date: 08-02-2018		
AXA TOWERSINGAPORE 068811				
ATTN : RUTH CHUA		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 4940E	Veh. Inspected	SJT 9576Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	S7M0068F	Excess (\$)	0.00	
Assign From	RUTH CHUA	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDGJ20W905001193	Colour	PEARL WHITE	
Odometer	178958 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	CONTINENTAL	7 mm	
L/H Front Tyre	195/65 R15	CONTINENTAL	7 mm	
R/H Rear Tyre	195/65 R15	CONTINENTAL	7 mm	
L/H Rear Tyre	195/65 R15	CONTINENTAL	7 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information				
Accident Date	28/12/2017	Inspect Date / Time	03/01/2018 (04:25 PM)	
Survey held at	160 SIN MING DRIVE #07-18			
Repairer	A T PERFORMANCE			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18000048/M1be2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.