



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD TOYOTA WISH (SJT9576Y)

Date of Loss

December 28, 2017

Time of Loss

8.00

Loss Description

XD4940E (INSD) C/W SJT9576Y (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

02/18/2018



Days of work completion *

51

« Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
SJT9576Y

Registration State
SINGAPORE

Mileage
178958

Purchase Date
mm/dd/yyyy

Registration Date *
11/11/2009

Age of Vehicle
8

CATEGORY Manufacturing Year

POLICY INFORMATION

ASSESSMENT INFORMATION
2009

CATEGORY Make

POLICY INFORMATION TPVD TOYOTA

ASSESSMENT INFORMATION
TOYOTA

POLICY INFORMATION

WISH

ASSESSMENT INFORMATION

WISH 2.0 AUTO

CATEGORY

Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Chassis No

POLICY INFORMATION

ASSESSMENT INFORMATION

JTDGJ20W905001193

CATEGORY

Engine No

POLICY INFORMATION

ASSESSMENT INFORMATION

3ZRA397441

CATEGORY

Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION

1987

CATEGORY

Sum Insured

POLICY INFORMATION

CATEGORY

Market Value

POLICY INFORMATION

ASSESSMENT INFORMATION

0

Driver Details

CATEGORY

Driver Name

FNOL INFORMATION

SJT9576Y LIM KIM HUN

POST SURVEY INFORMATION

CATEGORY

Date of Birth

FNOL INFORMATION

December 4, 1978

POST SURVEY INFORMATION

mm/dd/yyyy



CATEGORY

Age

FNOL INFORMATION

39

POST SURVEY INFORMATION

CATEGORY

Occupation

FNOL INFORMATION

Unknown

POST SURVEY INFORMATION

CATEGORY

Education Qualification

FNOL INFORMATION

Other

POST SURVEY INFORMATION





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

01/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

195/65R15

Front left side

CONTINENTAL7mm

Front right side

CONTINENTAL7mm

Spare wheel

Rear Tyre Size

195/65R15



LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18000048/M1be2		
8 SHENTON WAY #24-01		Date: 08-02-2018		
AXA TOWERSINGAPORE 068811				
ATTN: RUTH CHUA		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 4940E	Veh. Inspected	SJT 9576Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	S7M0068F	Excess (\$)	0.00	
Assign From	RUTH CHUA	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDGJ20W905001193	Colour	PEARL WHITE	
Odometer	178958 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	CONTINENTAL	7 mm	
L/H Front Tyre	195/65 R15	CONTINENTAL	7 mm	
R/H Rear Tyre	195/65 R15	CONTINENTAL	7 mm	
L/H Rear Tyre	195/65 R15	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information				
Accident Date	28/12/2017	Inspect Date / Time	03/01/2018 (04:25 PM)	
Survey held at	160 SIN MING DRIVE #07-18			
Repairer	A T PERFORMANCE			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18000048/M1be2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

