

ASS. REC. BY:

REF:

CS/msh18000120/mlrbe2

Special instruction:

SURVEYOR:

Ma

ASSIGNMENT (Office)

From (Person):

Pearllyn Kang

of

msh

Date/Time:

03/01/2018 2:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJC 177

Insured:

at Workshop m/s

CP Motors.

Tel:

8201 8103

of

Blk 34 Sin Ming Drive #01-126

Policy No:

A29009135QMY

Claim No:

Sum Insured:

Excess:

\$950.00

Make of Veh:

(Client's Record)

D.O.A.

01.01.2018

CA

REV

/ REP.

/ REV

24 HRS

160 Sin Ming Drive #05-05

Malah

H.O.D. Endorsement:

6594 2560

Date/Time:

03/01/2018 3:45pm

Person Contacted:

Thomas.

Vehicle

IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	check tyres & brake and steering wheels. SJC 177 - 03/AXA 11074223/Rhdcl DCA: 04111
4/1/18	Sent prob through menimen
	Repaier. not agree to sign the disagreement cost plus letter
8/1/18	Milah inform to offer repaier \$20k, repaier asking for \$20k.
	Resent IA through menimen.

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s CP MR PIL.

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: ~~\$82K~~ \$85K (advice fromIDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No adhamGIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No 4/1/18

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJC 17T. Yr Regn: SEP 2011.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI. A5 CABRIOLET 1984Colour: Black A.O: Insured / Std / NI / NASp. Reading: 124568 T. Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAN 2228 F0BN 024375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/25/19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or AIR

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 01/01/2018 D.O.I. 31/12/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S BODY

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1/18 Agreement between ms16 & Thomas, L/S \$21K (bfr GST).  
 Authorise repair; Inform Thomas to proceed

Confirm L/S \$21K (before excess \$950), 12 days  
 Red: \$23,457.78, 52%.

REF: 1234567890

Date/Time. File Pass to?

☐ : Preli. ReportDays Of Repair: 121) typical☒ : Final ReportResurvey No. of Trip: 1

Survey Fee

Transportation

Date/Time File Return to?

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Tech. Insp \$☐ : Weekend \$

Photos

Chem

TOTAL

Report Format : ODLump Sum / I.B.I: (\$) 21K

450

10

460



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000120/M1rb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-01-2018



Code : MSG

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJC 17T
Policy No. A29009135QMY	Coverage (\$)	0.00
Claim No.	Excess (\$)	950.00
Assign From MERIMEN (PEARLLYN KANG)	Assign Date	03/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Engine No. HIDDEN	Accident Date 01/01/2018	Inspection Date 03/01/2018
	Survey held at 160 SIN MING DRIVE #05-05	
	Repairer CP MOTORS PTE LTD	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2018		03 Jan 2018 14:23 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS**

Insured:

TEO WEIXIAN, ID: S8520574I, Tel: +6585550555, Email: CLUB\_17@LIVE.COM

Vehicle Reg. No.:

SJC17T

Date of Loss:

01/01/2018 05:00 - :59

Claim Type:

OD

Policy/Cover Note No.:

A29009135QMY (Comprehensive)  
Coverage: 27/09/2017 - 26/09/2018

Excess:

S\$950.00

Repairer:

CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE, 575708 Sin Ming - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/01/2018]

Driver/Custodian:

TEO WEIXIAN (32 / Male), NRIC: S8520574I, Tel: +6585550555

Adj Asg. Remarks:

Please revert and arrange to survey the vehicle by today. To inform the surveyor to check brake system, tyres conditions and also the steering wheel system if they are in efficient conditions. Please check market value, rebates and net value to determine if it is economical to repair. Thank you.

**ASSOCIATED MAIL RECEIVED**

View All

Compose Case Mail

- MSIG\_SG (03/01/2018): Cancellation of Assignment: SJC17T

**ALL ASSOCIATED TASKS**

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 04 Jan 2018

## Preliminary Advice

Vehicle No	: SJC17T	Accident Date	: 01/01/2018
Make	: AUDI A5	Policy No.	: A29009135QMY
Assignment Date	: 03/01/2018	Excess	: S\$950.00
Date of Inspection	: 03/01/2018	Est. Duration of Repair	: 12.00
Inspection At	: CP MOTORS PTE LTD (HQ) BLK 34 #01-126, SIN MING DRIVE SINGAPORE 575708		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,457.78
Revised Amount	:S\$	19,431.43
Check Items (Estimated)	:S\$	16,407.64
Total	:S\$	35,839.07

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	62,802.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,198.00

### Remarks

( X ) Tyres : Serviceable condition

Brakes : In Order condition

Steering Wheels : In Order condition

Pending repair cost from repairer.

Pending "Disagreement To Adopt "Cost-Plus" Repair by Workshop" from repairer.

( ) The above survey was conducted on a 'without prejudice' basis.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 08 Jan 2018

**Preliminary Advice**

Vehicle No	: SJC17T	Accident Date	: 01/01/2018
Make	: AUDI A5	Policy No.	: A29009135QMY
Assignment Date	: 03/01/2018	Excess	: S\$950.00
Date of Inspection	: 03/01/2018	Est. Duration of Repair	: 12.00
Inspection At	: CP MOTORS PTE LTD (HQ) BLK 34 #01-126, SIN MING DRIVE SINGAPORE 575708		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,457.78
Revised Amount	:S\$	19,431.43
Check Items (Estimated)	:S\$	16,407.64
Total	:S\$	35,839.07

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	62,802.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,198.00

**Remarks**

( X ) Repairer unable to repair at \$20,000.00. Repairer asking for \$30,000.00.

Tyres : Serviceable condition

Brakes : In Order condition

Steering Wheels : In Order condition

Pending "Disagreement To Adopt "Cost-Plus" Repair by Workshop" from repairer.

( ) The above survey was conducted on a 'without prejudice' basis.

## Print Received Message

This mail is associated with :

**\*SJC17T (543664)**

OD

Jan 1 2018 5:00AM

[TEO WEIXIAN]

CP Motors Pte Ltd

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 09/01/2018 16:12 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$21000.00) - SJC17T - Claim Handler: Pearllyn Kang Yen Lin

Approved:21000.00:AUTHORIZE AT LUMP SUM NOT MORE THAN \$21,0000.

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Tuesday, January 09, 2018 4:50 PM  
**To:** 'Thomas'  
**Cc:** SUR  
**Subject:** RE: SJC 17T MSIG OD DOA : 01.01.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJC 17T (excess \$950/-)**. Please note that repair cost **L/S not more than \$21K**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Thomas [[mailto:thomas\\_tan26@hotmail.com](mailto:thomas_tan26@hotmail.com)]  
**Sent:** Tuesday, January 09, 2018 4:42 PM  
**To:** Janice Lee (LKKAUTO) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)>  
**Subject:** Re: SJC 17T MSIG OD DOA : 01.01.2018

Dear Janice,

Attached is the form.

Best Regards

Thomas Tan

CP Motors Pte Ltd

160 Sin Ming Drive

Sin Ming Auto City #05-05

Singapore 575722

[thomas\\_tan26@hotmail.com](mailto:thomas_tan26@hotmail.com)

HP: +65 8201 8103 Fax: +65 6459 5357





MSIG

Vehicle No

SJC 177

Date of Accident

01/01/2018

Date of Survey

**DISAGREEMENT TO ADOPT "COST-PLUS" REPAIR BY WORKSHOP  
(OWN DAMAGE CLAIM)**

I, Thomas Tan (workshop's Service Advisor),  
hereby confirm that CP Motors Pte Ltd (name of Workshop)  
is not agreeable to adopt "Cost-Plus" basis for the settlement of the own  
damage claim for vehicle number SJC 177.

Surveyor

Workshop's Service Advisor

Signature

Signature

Name

Name

Date/Time

Date/Time

Reason for not signing this form by Workshop's Service Advisor, if applicable  
(To be completed by Surveyor):

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807  
Tel: (65) 6827 7888 Fax: (65) 6827 7800 www.msig.com.sg  
Co. Reg. No. 200412212G

A Member of **MS&AD** INSURANCE GROUP

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0574I

### Vehicle Details

Vehicle No.:	SJC17T
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 CABRIOLET 2.0 TFSI QUATTRO
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CDN218953
Chassis No.:	WAUZZZ8F0BN024375
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$57,334.00
Original Registration Date:	27 Sep 2011
First Registration Date:	27 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$57,334.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2021
PARF Rebate Amount:	\$37,267.00

### Intended COE Rebate Details

COE Expiry Date:	26 Sep 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$68,501.00
COE Rebate Amount:	\$25,535.00
<b>Total Rebate Amount:</b>	<b>\$62,802.00</b>

The information contained herein is correct as at 04 Jan 2018

OK

# ANNOUNCING

as sgCarMart Premium Dealer for the 4<sup>th</sup> Consecutive Year

**BENEFIT AUTO**

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal 2008 Toyota Vios 1.5A



\$2500 Downpayment Monthly  
From \$580 Onwards. Lowest  
3.68%P.A@Gv Cars Financing.  
GV Credit Pte Ltd StarAd

**HIN LUNG AUTO**  
Ho Bee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars  
30 years after sale



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

2 vehicles

Audi A5 cabriolet 2.0

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Audi A5 cabriolet 2.0</b>		Any	Any	<b>2011</b>	Any	Any	Any	<b>Available</b>
	<b>Audi A5 Cabriolet 2.0A TFSI Quattro</b>		<b>\$86,800</b>	<b>\$17,770 /yr</b>	<b>14-Apr-2011</b>	<b>1,984 cc</b>	<b>120,000 km</b>	<b>Sports</b>	<b>Available</b>
The Most Elegant And Practical Cabriolet At An Affordable Price Tag. Black With Brown Leather Interior, Regularly Groomed, Agent Maintained Excellent Condition, View To Believe. Call Now For Inquiries									
Posted: 25-Nov-2017 Tags: 2011 Audi A5, 2011 Audi A5, Audi A5, Audi A5, Audi, A5, A5, Used Audi									
	<b>Audi A5 Cabriolet 2.0A TFSI Quattro</b>		<b>\$79,000</b>	<b>\$15,220 /yr</b>	<b>27-Apr-2011</b>	<b>1,984 cc</b>	<b>79,000 km</b>	<b>Sports</b>	<b>Available</b>
Flawless A5 Cabriolet With Loads Of Upgrades! Approved Supersprint Catback Exhaust, Upper And Lower K&N Filter, RS Front Grille, Strut Bars, Ap Front And Rear BBK, BBS Wheels, CF GT Wing, Reverse Cam,...									
Posted: 03-Nov-2017 Tags: 2011 Audi A5, 2011 Audi A5, Audi A5, Audi A5, Audi, A5, A5, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A5 cabriolet 2.0, Audi A5 cabriolet 2.0 Singapore, used Audi A5 cabriolet 2.0 Singapore, used Audi A5 cabriolet 2.0, used vehicles Singapore or even buy used Audi A5 cabriolet 2.0 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/01/2018 17:50
Date Of Accident	01/01/2018 05:00
Exact Location Of Accident	KEPPEL ROAD TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC17T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO WEIXIAN
NRIC No	S85205741
Email Address	CLUB_17@LIVE.COM
Mobile Phone No	(LOCAL) +65-85550555
Alternative Phone No	OFFICE-61001755

### Vehicle Particulars

Manufacturer	AUDI
Model	A5-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29009135QMY
Cover Note Number	

### Driver

Name of Driver	TEO WEIXIAN
NRIC No	S85205741
Date Of Birth	25/07/1985
Occupation	INDOOR
Date Of Driving Pass	20/10/2004
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85550555
Fax Number	
Contact Number	OFFICE-61001755
Email Address	CLUB_17@LIVE.COM

Address	3 HARTLEY GROVE
Postcode	457872
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:



# CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City  
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd  
160 Sin Ming Drive #05-05  
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000079

Date : 02/01/2018

Vehicle Num. : SJC17T

Make/Model : Audi A5 2.0 TFSI Cabriolet-2011

Chassis/Eng# : WAUZZZ8F0BN024375

Accident Date : 01/01/2018

Claim No. :

Reference : O/D Claim MSIG

Policy No. : A29009135 QMY

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- |     |       |                              |  |  |
|-----|-------|------------------------------|--|--|
| 1.  | 1 pc  | Left Front Fender            |  |  |
| 2.  | 1 pc  | Left Front Door              |  |  |
| 3.  | 1 pc  | Left Front Door Outer Handle |  |  |
| 4.  | 1 pc  | Left Wing Mirror             |  |  |
| 5.  | 1 pc  | Left Wing Mirror Cover       |  |  |
| 6.  | 1 pc  | Left Wing Mirror Glass       |  |  |
| 7.  | 1 pc  | Left Wing Mirror Signal Lamp |  |  |
| 8.  | 1 pc  | Left Rear Fender             |  |  |
| 9.  | 1 pc  | Rear Bumper                  |  |  |
| 10. | 8 pcs | Rear Bumper Clip             |  |  |
| 11. | 1 pc  | Left Front Knuckle Arm       |  |  |
| 12. | 1 pc  | Left Front Wheel Bearing     |  |  |
| 13. | 1 pc  | Left Front Wheel Oil Seal    |  |  |
| 14. | 1 pc  | Left Front Lower Arm         |  |  |
| 15. | 1 pc  | Left Front Thrust Arm        |  |  |
| 16. | 2 pcs | Front Absorber               |  |  |
| 17. | 1 pc  | Steering Rack                |  |  |
| 18. | 1 pc  | Left Rear Knuckle Arm        |  |  |
| 19. | 1 pc  | Left rear wheel bearing      |  |  |
| 20. | 1 pc  | Left Rear Lower Arm          |  |  |
| 21. | 1 pc  | Left Rear Thrust Arm         |  |  |
| 22. | 2 pcs | Sport's Rim                  |  |  |

## LIST ITEMS :

List TotalS\$ :

10.00% Discount S\$ :

dt	1,107.60	
dt	2,677.60	
dt	309.83	
dt	1,470.83	
dt	457.99	
dt	1,450.83	
dt	197.90	
dt	3,906.70	
dt	1,899.80	
dt	80.00	
dt	1,500.87	bt
dt	999.30	bt
dt	98.90	bt
dt	889.70	bt
dt	1,209.30	bt
dt	3,401.94	bt
dt	5,997.60	bt
dt	1,517.67	bt
dt	999.30	bt
dt	1,500.87	bt
dt	1,297.00	bt
dt	3,960.00	bt
dt	36,931.53	
dt	3,693.15	
dt	33,238.38	

CONTINUE / ...



# CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City  
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd  
160 Sin Ming Drive #05-05  
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000079

Date : 02/01/2018

Vehicle Num. : SJC17T

Make/Model : Audi A5 2.0 TFSI Cabriolet-2011

Chassis/Eng# : WAUZZZ8F0BN024375

Accident Date : 01/01/2018

Claim No. :

Reference : O/D Claim MSIG

Policy No. : A29009135 QMY

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	2 pcs	SPECIAL NETT ITEMS : Tyres Pirelli 255/35R19	<i>cut</i> <del>380.00</del>	760.00
		Special Nett Total S\$ :		760.00
		LABOUR :		
		Rebuild Door Mechanism		<del>100.00</del> 80
		Remove left fender inner garnish, seats & upholstery		<del>300.00</del> 200
		Remove/Refix Front/Rear Undercarriage		<del>800.00</del> 540
		Programming, Coding & Resetting		<del>500.00</del> 250
		4 Wheel Alignment ( Computerise )		<del>100.00</del> 80
		To Install Parking Sensor To New Bumper		<del>100.00</del> 60
		To straighten left front door pillar, left rocker panel, cut out left rear fender include welding & replacement of parts.		1600
		Spray paint on left front fender, front bumper, left door left rear fender, left rocker panel, rear bumper.		1400
		Labour Total S\$ :		5,900.00

E. & O.E.

Total S\$ : 39,898.38

4445778

for CP MOTORS PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Revert -  
P/P Repair  
Before paint photo  
LKK Auto  
cost 110%  
to change list to cost price.  
EXCESS \$4950  
22/1/18*

*10/1/18*

# CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City

Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd  
160 Sin Ming Drive #05-05  
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

## Supplementary Estimate : ES000080

Date : 02/01/2018

Vehicle Num. : SJC17T

Make/Model : Audi A5 2.0 TFSI Cabriolet-2011



Chassis/Eng# : WAUZZZ8F0BN024375

Accident Date : 01/01/2018

Claim No. :

Reference : O/D Claim

Policy No. : A29009135 QMY

S/N	Quantity	Particular	Unit Price	Amount S\$
<hr/>				
		LIST ITEMS :		
1.	1 pc	Rear Axle		4,868.00
2.	1 pc	Left Rear Fender Dust Cover		198.00
		List TotalS\$ :		5,066.00
		10.00% Discount S\$ :		506.60
				<hr/>
				4,559.40

E. & O.E.

Total S\$ : 4,559.40

  
for CP MOTORS PTE LTD

License: SJC17T  
 Year: 10  
 Date: 10.1.18 11:57

## Audi 2009-16 A5/S5 4X4 Cabrio 1BA 1BE 1BD

## Front : Left

Actual	Before	Specified Range
-2°43'	-2°46'	-1°28' -0°42'
4°07'	4°07'	
0°15'	0°22'	0°03' 0°17'
6°31'	6°34'	
3°48'	3°48'	
		-2°19' -1°19'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

## Front : Right

Actual	Before	Specified Range
-0°58'	-0°59'	-1°28' -0°42'
3°51'	3°51'	
0°00'	0°00'	0°03' 0°17'
4°21'	4°21'	
3°23'	3°23'	
		-2°19' -1°19'

## Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
-1°45'	-1°47'	-0°30' 0°30'
0°16'	0°16'	
2°10'	2°13'	
0°16'	0°21'	0°06' 0°34'

## Rear : Left

Actual	Before	Specified Range
-2°07'	-2°07'	-1°45' -0°55'
-0°01'	-0°02'	0°05' 0°15'

Camber  
 Toe

## Rear : Right

Actual	Before	Specified Range
-1°12'	-1°13'	-1°45' -0°55'
-0°02'	-0°02'	0°05' 0°15'

## Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
-0°54'	-0°54'	-0°30' 0°30'
-0°03'	-0°03'	0°10' 0°30'
0°04'	0°00'	-0°10' 0°10'

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2018		03 Jan 2018 14:23 <a href="#">Edit Adj Rpt</a>	<b>S\$21,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$21,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by Insurer]		
Insured:	TEO WEIXIAN, ID: S8520574I, Tel: +6585550555, Email: CLUB_17@LIVE.COM					
Vehicle Reg. No.:	SJC17T	Date of Loss:	01/01/2018 05:00 - :59			
Claim Type:	OD / 543664	Policy/Cover Note No.:	A29009135QMY (Comprehensive) Coverage: 27/09/2017 - 26/09/2018			
		Excess:	S\$950.00			
Repairer:	CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE, 575708 Sin Ming - Tel:					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 02/02/2018]					
Driver/Custodian:	TEO WEIXIAN (32 / Male), NRIC: S8520574I, Tel: +6585550555					
Adj Asg. Remarks:	Please revert and arrange to survey the vehicle by today. To inform the surveyor to check brake system, tyres conditions and also the steering wheel system if they are in efficient conditions. Please check market value, rebates and net value to determine if it is economical to repair. Thank you.					

ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>MSIG_SG (09/01/2018): Alert - Adj Mandate Approved (S\$21000.00) - SJC17T - Claim Handler: Pearllyn Kan...</li> <li>MSIG_SG (08/01/2018): Alert - Adj Mandate Approved (S\$19431.43) - SJC17T - Claim Handler: Pearllyn Kan...</li> <li>MSIG_SG (03/01/2018): Cancellation of Assignment: SJC17T</li> </ul>			

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*SJC17T (543664)

OD

Jan 1 2018 5:00AM

[TEO WEIXIAN]

CP Motors Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View** [View in Browser](#)

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print	
1	02/01/18 20:05	Accident Statement	1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	04/01/18 19:18	Adjuster Immediate Advice	1	Load HTM		
2	08/01/18 15:47	Adjuster Immediate Advice	1	Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print	
1	02/01/18 20:03	Identification Card [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
2	02/01/18 20:03	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
3	02/01/18 20:03	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
4	02/01/18 20:03	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
5	02/01/18 20:03	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
6	02/01/18 20:04	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
7	02/01/18 20:04	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
8	02/01/18 20:04	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
2	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
3	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
4	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
5	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
6	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
7	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
8	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
9	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
10	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
11	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
12	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
13	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
14	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
15	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
16	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
17	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
18	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	
19	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>	

20	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	04/01/18 14:41	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	19/03/18 11:31	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/01/18 14:19	PARF/COE rebate details	1	Load PDF	
2	03/01/18 14:21	Estimate repair bill	1	Load PDF	
3	03/01/18 14:21	Email from repairer to arrange for survey	1	Load PDF	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	02/01/18 20:03	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 13:51	Workshop estimate	1	Load PDF	
2	09/01/18 16:55	SHC 17T Disagreement Cost-Plus Letter	1	Load PDF	
3	20/03/18 09:22	Supplementary	1	Load PDF	

## Linked Accident Report Documents

View 

<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print

1	02/01/18 20:05	Accident Statement	1	Load HTM	
<b>Photos/Images</b>			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	02/01/18 20:03	Identification Card	1	Load JPG	<input checked="" type="checkbox"/>
2	02/01/18 20:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	02/01/18 20:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	02/01/18 20:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	02/01/18 20:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	02/01/18 20:04	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	02/01/18 20:04	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	02/01/18 20:04	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	02/01/18 20:03	Sketch Plan	1	Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 540px; margin: 5px 0;"></div> <div style="text-align: right; margin-right: 10px;"> <span>^</span>  <span>v</span> </div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18000120/M1RBE2

Date: 20/03/2018

REFERENCE

Insured/Claimant:	TEO WEIXIAN	Policy No:	A29009135QMY	
Date of Loss:	01/01/2018	Nature of Claim:	OD	Claim No: 543664

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJC17T</b>	Engine No:	CDN218953
Make & Model:	AUDI A5, 2.0 (A)	Chassis No:	WAUZZZ8F0BN024375
Reg. Date:	27/09/2011 (Man. Year: 2011)	Odometer:	124568 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35 R19	Rear Tyre Size:	225/35 R19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	38,557.78	24,599.19	13,958.59	36.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,900.00	4,210.00	1,690.00	28.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,457.78</b>	<b>28,809.19</b>	<b>15,648.59</b>	<b>35.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>21,000.00</b>		
- Excess (S\$)	950.00	950.00	0.00	0.00
<b>(S\$)</b>	<b>43,507.78</b>	<b>20,050.00</b>	<b>23,457.78</b>	<b>53.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,045.54</b>	<b>1,403.50</b>	<b>1,642.04</b>	<b>53.92</b>
<b>Nett Amount (S\$)</b>	<b>46,553.32</b>	<b>21,453.50</b>	<b>25,099.82</b>	<b>53.92</b>

INSPECTION

Date of Assignment: 03/01/2018

Date Inspected: 03/01/2018 Inspected At:

CP Motors Pte Ltd (HQ)  
BLK 34 #01-126, SIN MING DRIVE  
Singapore 575708

Estimated Period of Repair: 12.0 days



**Adjuster:** MA CHIN FOOK

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 20 Mar 2018)  
**Parts:** M1-COUPE      AUDI A5 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SJC17T)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT FRONT FENDER	Dented	1,107.60 FL	*1,107.60 FL
2	1		*LEFT FRONT DOOR	Dented	2,677.60 FL	*2,677.60 FL
3	1		*LEFT FRONT DOOR OUTER HANDLE	Cut	309.83 FL	*309.83 FL
4	1		*LEFT WING MIRROR	Cracked	1,470.83 FL	*1,470.83 FL
5	1		*LEFT WING MIRROR COVER	Cracked	457.99 FL	*457.99 FL
6	1		*LEFT WING MIRROR GLASS	Cracked	1,450.83 FL	*1,450.83 FL
7	1		*LEFT WING MIRROR SIGNAL LAMP	Cracked	197.90 FL	*197.90 FL
8	1		*LEFT REAR FENDER	Dented	3,906.70 FL	*3,906.70 FL
9	1		*REAR BUMPER	Deformed	1,899.80 FL	*1,899.80 FL
10	8		*REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
11	1		*LEFT FRONT KNUCKLE ARM	Bent	1,500.87 FL	*1,500.87 FL
12	1		*LEFT FRONT WHEEL BEARING	Bent	999.30 FL	*999.30 FL
13	1		*LEFT FRONT WHEEL OIL SEAL	Necessary	98.90 FL	*98.90 FL
14	1		*LEFT FRONT LOWER ARM	Bent	889.70 FL	*889.70 FL
15	1		*LEFT FRONT THRUST ARM	Bent	1,209.30 FL	*1,209.30 FL
16	2		*FRONT ABSORBER	Serviceable	3,401.94 FL	*- FL
17	1		*STEERING RACK	Serviceable	5,997.60 FL	*- FL
18	1		*LEFT REAR KNUCKLE ARM	Bent	1,517.67 FL	*1,517.67 FL
19	1		*LEFT REAR WHEEL BEARING	Bent	999.30 FL	*999.30 FL
20	1		*LEFT REAR LOWER ARM	Bent	1,500.87 FL	*1,500.87 FL
21	1		*LEFT REAR THRUST ARM	Bent	1,297.00 FL	*1,297.00 FL
22	2		*SPORTS RIM	Cut	3,960.00 FL	*2,916.00 FL
23	2		*TYRES PIRELLI 255/35 R19	Cut	760.00 FS	*760.00 FS
24	1		*REAR AXLE	Serviceable	4,868.00 FL	*- FL
25	1		*LEFT REAR FENDER DUST COVER	Serviceable	198.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>42,757.53</b>	<b>27,247.99</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>4,199.75</b>	<b>2,648.80</b>
<b>Total Parts (\$\$)</b>	<b>38,557.78</b>	<b>24,599.19</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REBUILD DOOR MECHANISM	New	100.00	80.00
2	REMOVE LEFT FENDER INNER GARNISH, SEATS & UPHOLSTERY	New	300.00	200.00
3	REMOVE / REFIX FRONT / REAR UNDERCARRIAGE	New	800.00	540.00
4	PROGRAMMING, CODING & RESETTNG	New	500.00	250.00
5	4 WHEEL ALIGNMENT (COMPUTERISE)	New	100.00	80.00
6	TO INSTALL PARKING SENSOR TO NEW BUMPER	New	100.00	60.00
7	TO STRAIGHTEN LEFT FRONT DOOR PILLAR, LEFT ROCKER PANEL, CUT OUT LEFT REAR FENDER INCLUDE WELDING & REPLACEMENT OF PARTS	New	2,200.00	1,600.00
8	SPRAY PAINT ON LEFT FRONT FENDER, FRONT BUMPER, LEFT DOOR LEFT REAR FENDER, LEFT ROCKER PANEL, REAR BUMPER	New	1,800.00	1,400.00
Gross Labour Cost (\$\$)			<b>5,900.00</b>	<b>4,210.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >