

ASS. REC. BY:

REF:

CS/MSG18000164/Rttb02

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

merimen

From (Person):

Clara Milah Yeo

of

MSI(1)

Date/Time: 03/01/2018 4:38 pm

Estimated Cost:

Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJQ 881R

Insured:

at Workshop m/s

Performance

Tel:

9116 5779

of

303 Alexander Rd

Policy No:

B27464797 SMP

Claim No:

543815

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

D.O.A.

27/02/07

(Client's Record)

CA / (REY) / REP. / REV 24 HRS

04/01/2018 @ 10am

H.O.D. Endorsement:

Date/Time:

03/01/2018 4:58pm

Person Contacted:

Gary

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJQ 881R - X
5/1-	Refer via merimen
5/1-@11:30am	authorise repair ng chen haw
5/1 @11:55am	Inform gary authorise repair via email
	Part by Part \$7729.65 (Red: 2316.55 !23%)

Form

REF:

27824

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJQ 881R
 at Workshop m/s: PERFORMANCE
 of 803 ALEXANDRA RD
 Insured: MSH/00
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: 1000
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

GARY

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 107K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJQ 881R Yr Regn: 2013 Jan
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W X3 XDRIVE 20i ABS 1997
 Colour: WHITE A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 69287 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAW X320 X00B 26614
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: 245/50R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/12/17 D.O.I. 04/01/18
 Survey held at: PERFORMANCE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 APR 2018

Date/Time, File Pass to? ☐ : Prel. Report

1) 20/4 Typst ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation: 300

Photos:

Others:

TOTAL

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format :

Lump Sum / I.E. (\$) 7729.65

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18000164/R1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 03-01-2018	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SJQ 881R	
Policy No.	B27464297SMP	Coverage (\$)	0.00	
Claim No.	543815	Excess (\$)	1,000.00	
Assign From	MERIMEN (CLARA MILAH)	Assign Date	03/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/12/2017	Inspection Date	04/01/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		03 Jan 2018 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		MAI JU-LE @ MO JU-LI, ID: S2552782H, Tel: +6597548196, Email: JULE.MAI2@GMAIL.COM							
Vehicle Reg. No.:		SJQ881R		Date of Loss: 27/12/2017 14:00 - :59					
Claim Type:		OD / 543815		Policy/Cover Note No.: B27464297SMP (Comprehensive) Coverage: 31/01/2017 - 30/01/2018					
		Excess:		S\$1,000.00					
Repairer:		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/01/2018]							
Driver/Custodian:		MAI JU-LE @ MO JU-LI (55 / Female), NRIC: S2552782H, Tel: +6597548196							
Adj Asg. Remarks:		Request for survey on 04/01/2018 @ 10am Please revert. Thanks.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SJQ881R (543815)**

OD

Dec 27 2017 2:00PM

[MAI JU-LE @ MO JU-LI]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 05/01/2018 11:13 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7254.30) - SJQ881R - Claim Handler: Clara Milah Yeo

Approved:7254.30.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 5 January, 2018 11:55 AM
To: Gary Poh Chai Hoon
Cc: Inthiran Thurasamy; SUR
Subject: SJQ 881R OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJQ 881R (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2017 17:19
Date Of Accident	27/12/2017 14:45
Exact Location Of Accident	MEDIACORP B2 CARPARK LOT D
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ881R
Insured/Policyholder	
Name Of Registered Owner	MAI JU-LE @ MO JU-LI
NRIC No	S2552782H
Email Address	JULE.MAI2@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97548196
Alternative Phone No	OFFICE-97548196

Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27464297SMP
Cover Note Number	

Driver

Name of Driver	MAI JU-LE @ MO JU-LI
NRIC No	S2552782H
Date Of Birth	15/04/1962
Occupation	INDOOR
Date Of Driving Pass	10/10/2007
Driving Experience	10 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97548196
Fax Number	
Contact Number	OFFICE-97548196
EMail Address	JULE.MAI2@GMAIL.COM

Address	41 HUME AVENUE #03-12
Postcode	598738
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA874X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALWIYAH BINTE MOHD SIZ
NRIC/Passport Number	S7621172H
Contact Number	96606343
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time


[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

GARY HOON
Performance Network Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119971

Witnessed by Reporting Centre Personnel

Sketch Plan




Sketch Plan Pg. 2


Describe Circumstances of the Accident


On 27/12/17 Afternoon 1444 Hrs I was driving Back
to Medion Car Park Basement 2
While turn left to the road, One Car from
the Carpark lot drive towards my car and
hit the bottom of the ^{left} front door and
fender cause dented.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time

 27/12/17
Driver's Signature (if driver is not the policyholder) / Date
& Time

27/12/17 1645

GARY PUICHAH HOON
Performance Motors Limited
303 Alexandra Road
Sino Darby Performance Centre
Singapore 159111

Witnessed by Reporting Centre
Personnel

Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

138 Robinson Road #07-09

The Corporate Office

Singapore 068906

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No: MPML 17170113 Vehicle Registration No: 978 881 R

Name(as shown in NRIC): MAI JU-LI @ MAI JU-LI

(*Vehicle Driver/Vehicle Owner) (*Please delete as appropriate)

NRIC/Passport No: 425527824

Address: _____

Contact (Tel): _____ (H/P): 97548196

(Email): _____

Date Of Accident: 27/12/17 Time Of Accident: 14:45

Place Of Accident: MEDIA CORP B2 CAR PARK LOT 30

Insurance Company: MGIC

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:-

From 3rd Party claim Revert to Own
claim



SIGNATURE OF VEHICLE OWNER/DRIVER
DATE:

31/1/18

0900

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 058807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

SIME MOTOR PRIVATE**RENEWAL CERTIFICATE**

Policy Number	Period of Insurance	Place of Issue
B 27464297 SMP	31/01/2017 to 30/01/2018	SINGAPORE
Name and Address of Insured		Date of Issue
Mai Ju-Le @Mo Ju-Li 41 Hume Avenue #03-12 Singapore 598738		18/01/2017
		Account Number
		212165
Premium	GST	Total Due
SGD1,325.88	SGD92.81	SGD1,418.69

RISK NUMBER 1**SIME MOTOR PRIVATE****OCCUPATION**

Director

FINANCIAL INTEREST

United Overseas Bank Limited
 as Hire Purchase Owners

SCOPE OF COVER Comprehensive**INTEREST INSURED**

REGISTRATION NO. SJQ881R
 MAKE/MODEL BMW X3 XDrive 20I
 ENGINE NUMBER B6050307N20B20A
 CHASSIS NUMBER WBAWX320X00B26614
 YEAR OF MFG 2012
 CAPACITY 1997 C.C.
 SEATING CAPACITY 5 (INCL. DRIVER)
 WINDSCREEN UNLIMITED

SUM INSURED
 INCL. COE/PARF YES
 OFF-PEAK CAR NO
 NO CLAIM DISCOUNT 50.00% (or F/D)
 GOOD DRIVER'S
 DISCOUNT SGD69.78
 NCD PROTECTOR COVERED
 EXCESS SGD1,000
 ANNUAL PREMIUM SGD1,325.88

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit,
 rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Mai Ju-Le @Mo Ju-Li

IDENTITY CARD NO. S2552782H



Name

MAI JU-LE
@MO JU-LI

麥如麗

Race

CHINESE

Date of birth

15-04-1962

Country/Place of birth

CHINA



Sex

F

S2552782H



Service Number S2552782H

MAI JU-LE

Birth Date: 15 Apr 1962

Issue Date: 10 Oct 2007



001535311J

5730419



NRIC No. S2552782H

Date of issue

18-04-2017

Address

41 HUME AVENUE
#03-12
SINGAPORE 598738

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals =< 2500kg 10 Oct 2007



Licence No: S2552782H

NP 428A

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2782H
Vehicle Details	
Vehicle No.:	SJQ881R
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X3 XDRIVE20I ABS 4WD SR HID DSC NAV
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B6050307N20B20A
Chassis No.:	WBAWX320X00B26614
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,026.00
Original Registration Date:	31 Jan 2013
First Registration Date:	31 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$40,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2023
PARF Rebate Amount:	\$30,019.00
Intended COE Rebate Details	

COE Expiry Date:	30 Jan 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$97,000.00
COE Rebate Amount:	\$45,730.00
Total Rebate Amount:	\$75,749.00

The information contained herein is correct as at 04 Jan 2018

OK

107,000
75,749

31,251
//

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

28 DEC 2017

Estimate No. : b1 45307
Date Estimated : 27/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Mai Ju-Le @ Mo Ju-Li
41 Hume Avenue
#03-12

Singapore 598738

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ881R	0B26614	31/01/2013	X3 xDrive20i	0

DESCRIPTION

To replace left front fender, left front door and side skirt
& attachment include knocking cause by the accident

Painting left front fender, left front door.

To carry out body cavity preservation.
(Per panel).

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

Sundries.

VALUE

✓ 2125 3,400.00

✓ 1996 2,218.00

✓ 200 238.00

✓ 451 531.00

80 150.00

Total Labour 1: 6,535.00

DESCRIPTION

FRT LH FENDER
FRT LH DOOR
LH RR DOOR UPPER BRACKET
RH UPPER REAR DOOR HINGE
FRONT DOOR BRAKE
CHANNEL COVER EXTERIOR DOOR FRT LH
PRESSURE LIP SEAL FRT LH
FRT SECT. FRT LH WHEELHOUSING COVER
COVER F/REAR WHEELHOUSING FRT LH
LH DOOR SILL COVER (SCHWARZ)
FRT LH WHEEL ARCH COVER

QTY	PRIC
1	765.70
1	1,387.40
1	55.75
1	55.75
1	80.80
1	84.30
1	12.50
1	129.65
1	129.65
1	214.80
1	179.20

VALUE

✓ 765.70

✓ 1,387.40

55.75

55.75

80.80

84.30

12.50

129.65

129.65

214.80

✓ 179.20

Total Parts : 3,095.50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45307
Date Estimated : 27/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJQ881R	0B26614	31/01/2013	X3 xDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims QP / 3rd Party / Uninsured Losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/01/18 @ 1000 Excess \$ 1000

Surveyor's Name Ratan Sign _____

Surveyor's Tel 90010068 Authorised Yes / No C

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SUR YES / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 6 days

Resurvey 64 part

[Signature]
8/1/18

REVIEW

10046.20

Labour 1	:	6,535.00
Parts	:	3,095.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	674.14
Grand Total	:	10,304.64

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45307
Date Estimated : 27/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Mai Ju-Le @ Mo Ju-Li
41 Hume Avenue
#03-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 598738

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SJQ881R	0B26614	31/01/2013	X3 xDrive20i	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	
To replace front LH door and attachments, front LH fender and attachments include knocking out dents caused by the accident			2125.00		2,125.00	
To spray paint front LH fender and front LH door			1996.00		1,996.00	
To carry out body cavity preservation. (Per panel).			200.00		200.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)			451.00		451.00	
# To conduct checks on all doors and boot lid central locking system for proper function			150.00		150.00	
Sundries			80.00		80.00	(LA)

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	765.70	1.00		765.70
FRT LH DOOR	1,387.40	1.00		1,387.40
# MODEL LETTERING X DRIVE 20i *	91.55	1.00		91.55 (A)
# DOOR WEATHERSTRIP FRT *	160.65	1.00		160.65
COVER F/REAR WHEELHOUSING FRT LH	129.65	1.00		129.65
# EXPANDING RIVET *	1.35	10.00		13.50 (A)
FRT LH WHEEL ARCH COVER	179.20	1.00		179.20

SUPPLEMENTARY ITEMS

Total Labour :	5,002.00
Total Parts :	2,727.65
Total Labour & Parts :	7,729.65
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	6,729.65
GST @7%:	471.08
Grand Total :	7,200.73

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45307
Date Estimated : 27/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Mai Ju-Le @ Mo Ju-Li
41 Hume Avenue
#03-12

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 598738

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJQ881R	0B26614	31/01/2013	X3 xDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To conduct checks on all doors and boot lid central locking system for proper function

150.00

150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# MODEL LETTERING X DRIVE 20i *	91.55	1.00		91.55
# DOOR WEATHERSTRIP FRT *	160.65	1.00		160.65
# EXPANDING RIVET *	1.35	10.00		13.50

Total Labour :	150.00
Total Parts :	265.70
Total Labour & Parts :	415.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18000164/R1TBN2

Date: 20/04/2018

REFERENCE

Insured/Claimant: MAI JU-LE @ MO JU-LI
Date of Loss: 27/12/2017

Policy No: B27464297SMP
Nature of Claim: OD

Claim No: 543815

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJQ881R
Make & Model: BMW X3, 2.0 xDrive20i (A)
Reg. Date: 31/01/2013 (Man. Year: 2012)
Colour: White
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$107,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: B6050307N20B20A
Chassis No: WBAWX320X00B26614
Odometer: 69287 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,511.20	2,807.65	703.55	20.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,535.00	4,922.00	1,613.00	24.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,046.20	7,729.65	2,316.55	23.06
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	9,046.20	6,729.65	2,316.55	25.61
+ GST 7.00/7.00% (S\$)	633.23	471.08	162.15	25.61
Nett Amount (S\$)	9,679.43	7,200.73	2,478.70	25.61

INSPECTION

Date of Assignment: 03/01/2018

Date Inspected: 04/01/2018 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
Parts:	M1-SUV	BMW X3 2.0 xDrive20i (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ881R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Bent	765.70 FS	*765.70 FS
2	1		*FRT LH DOOR	Bent	1,387.40 FS	*1,387.40 FS
3	1		*LH RR DOOR UPPER BRACKET	Serviceable	55.75 FS	*- FS
4	1		*RR UPPER REAR DOOR HINGE	Serviceable	55.75 FS	*- FS
5	1		*FRONT DOOR BRAKE	Serviceable	80.80 FS	*- FS
6	1		*CHANNEL COVER EXTERIOR DOOR FRT LH	Serviceable	84.30 FS	*- FS
7	1		*PRESSURE LIP SEAL FRT LH	Serviceable	12.50 FS	*- FS
8	1		*FRT SECT FRT LH WHEELHOUSING COVER	Cut	129.65 FS	*129.65 FS
9	1		*COVER F/REAR WHEELHOUSING FRT LH	Serviceable	129.65 FS	*- FS
10	1		*LH DOOR SILL COVER (SCHWARZ)	Serviceable	214.80 FS	*- FS
11	1		*FRT LH WHEEL ARCH COVER	Deformed	179.20 FS	*179.20 FS
12	1		*MODEL LETTERING X DRIVE 20i	Necessary	91.55 FS	*91.55 FS
13	1		*DOOR WEATHERSTRIP FRT	Necessary	160.65 FS	*160.65 FS
14	10		*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
15	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
					Total Parts (\$\$)	3,511.20 2,807.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE LEFT FRONT FENDER,LEFT FRONT DOOR AND SIDE SKIRT & ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	3,400.00	2,125.00
2	PAINTING LEFT FRONT FENDER,LEFT FRONT DOOR	New	2,218.00	1,996.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	236.00	200.00
4	TO TRANSFER LOCK MECHNAISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
5	TO CONDUCT CHECKS ON ALL DOORS AND BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	150.00	150.00
Gross Labour Cost (\$\$)			6,535.00	4,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >