

ASS. REC. BY:

REF: CS/SMD18000171/Krbn2 Special Instruction:

Surveyor:

Kenneth

## ASSIGNMENT (Office)

From (Person):

Irene

of

SMD

Date/Time: 03/01/2018 4:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 1444K

Insured:

SFF 8023D

at Workshop m/s

Lim Yew Boo

Tel:

9685 2332

of

Blk 10 Sin Ming

Rd #01-10

Policy No:

Claim No:

CMD1704673 / AGL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/22018

(Client's Record)

05-01-2018 @ 11:30am

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

03/01/2018 4:49pm

Person Contacted:

Serene

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SLS 1444K - X

SFF 8023D - X

Berneth confirmed \$2925.00. 3 days

Red: \$1917.00, 40%.

REP: SMO

## ASSIGNMENT

SLS 444K Page 08 17

From: Date: 5/1/18

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLS 444K

at Workshop m/s Lim Yew Boon

of Blk 10, Sin Ming Rd # 01-10

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

11:30 am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

8/1 File pass to Carham, car not ready

RECEIVED 05 MAY 2018

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota CHR

C.C.

1787

Colour:

Black

A/C Insured / Std / NI / NA

Sp. Reading

0239

T. Radio: Insured / Std / NI / NA

Eng/No

ZYX10

2054198

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

18/12/17

D.O.I.

5/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

by: hph

Date/Time File Return to?



Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + P + S

Photo:

Other:

Add Fee:



\$

\$

\$

\$

Report Format:

TP

Lump Sum / I.B.I. \$

2925.00

250



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18000171/Krb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 03-01-2018



Code : SMO

## Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SFF 8023D	Veh. Inspected	SLS 444K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD1704673/AGC	Excess (\$)	0.00
	Assign From	IRENE	Assign Date	03/01/2018

## Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

## Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

## Description of Damages

4.

## General Information

5.	Accident Date	18/12/2017	Inspection Date
	Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.	

## Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## Catherine Chong (LKK Auto)

---

**From:** Henry, Irene James <irene.henry@sompo.com.sg>  
**Sent:** Wednesday, 3 January, 2018 4:21 PM  
**To:** assignments; Admin-D (LKKAuto)  
**Subject:** FW: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017  
**Attachments:** 444 - sompo.pdf

Our Reference: CMTD1704673/AGC

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLS444K).

Please refer to the email correspondence below.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Serene LIM [mailto:serene@autocare.com.sg]  
**Sent:** Wednesday, 3 January, 2018 4:10 PM  
**To:** Henry, Irene James <irene.henry@sompo.com.sg>  
**Cc:** Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>  
**Subject:** Re: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Hi Irene Henry

We arrange for surveyor first, kindly arrange LKK to contact us for the survey

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: [serene@autocare.com.sg](mailto:serene@autocare.com.sg)

**From:** Henry, Irene James  
**Sent:** Wednesday, January 03, 2018 1:07 PM  
**To:** Serene LIM  
**Cc:** Chan, Shu Hui Agnes  
**Subject:** RE: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Without Prejudice

Hi Serene,

We have still yet to receive our insured's report, thus unable to revert.

You may advise your client to seek other alternatives or please let us know should you still intend for us to conduct the motor survey on a "without prejudice" basis.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Serene LIM [<mailto:serene@autocare.com.sg>]  
**Sent:** Wednesday, 3 January, 2018 11:24 AM  
**To:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Cc:** Chan, Shu Hui Agnes <[agnes.chan@sompo.com.sg](mailto:agnes.chan@sompo.com.sg)>  
**Subject:** Re: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Hi All

Any update?

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: [serene@autocare.com.sg](mailto:serene@autocare.com.sg)

**From:** Henry, Irene James  
**Sent:** Tuesday, December 26, 2017 5:24 PM  
**To:** Serene LIM  
**Cc:** Chan, Shu Hui Agnes  
**Subject:** RE: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Our Reference: CMTD1704673/AGC

WITHOUT PREJUDICE

Hi Serene,

We refer to the above matter.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Serene LIM [<mailto:serene@autocare.com.sg>]

**Sent:** Tuesday, 26 December, 2017 4:35 PM

**To:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Cc:** Chan, Shu Hui Agnes <[agnes.chan@sompo.com.sg](mailto:agnes.chan@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

**Subject:** Re: CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Hi Agnes

Can confirm liability?

Thank you & Regards

Serene LIM

Lim Yew Boo Spray Paint Co

Tel: +65 64545011 | Fax: +65 64593724 | Hp: +65 96852332

E-mail: [serene@autocare.com.sg](mailto:serene@autocare.com.sg)

**From:** Teo, Grace  
**Sent:** Tuesday, December 26, 2017 4:19 PM  
**To:** Serene LIM  
**Cc:** Chan, Shu Hui Agnes ; Henry, Irene James  
**Subject:** CMTD1704673/AGC - Accident invlg SFF8023D & SLS444K on 18.12.2017

Your Reference: SLS444K  
Our Reference: CMTD1704673/AGC

Without Prejudice

Date: 26<sup>th</sup> December 2017

**Attention:**  
**M/S LIM YEW BOO SPRAY PAINT CO**

**Accident invlg SFF8023D & SLS444K on 18.12.2017**

Dear Serene,

We refer to your Notice of Accident dated 26/12/2017.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey			
	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.



Yours faithfully,

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Serene LIM [<mailto:serene@autocare.com.sg>]

**Sent:** Tuesday, December 26, 2017 11:01 AM

**To:** Claims - Motor Survey

**Subject:** Fw: SLS444K & SFF8023D ALONG TPY LOR 6 TWD BRADDELL RD ON 18/12/2017

re-sent

**From:** Serene LIM

**Sent:** Saturday, December 23, 2017 4:29 PM

**To:** Tenet PRI Survey

**Subject:** SLS444K & SFF8023D ALONG TPY LOR 6 TWD BRADDELL RD ON 18/12/2017

To : Motor Claims Dept (Arrangement of Surveyor Unit)

**RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**  
**ACCIDENT INVOLVING SLS444K & SFF8023D ALONG TPY LOR 6 TWD BRADDELL RD ON 18/12/2017**

We are the repairer for Mdm Lee Poh Leng the owner of vehicle no. SLS444K

Please be informed that the said vehicle can be inspected at the following venue:

Lim Yew Boo Spray Paint Co

Blk 10 Sin Ming Industrial Estate #01-10 Singapore 575645

Tel: 64534177 Fax: 64593724 Email: [serene@autocare.com.sg](mailto:serene@autocare.com.sg)

Contact Person: Serene Lim Hp : +65 96852332

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)



VEHICLE ( NOT IN OR-IN ) WORKSHOP

PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS CASE

I/ We enclosed herewith a copy of our client **SAS Statement** for your reference. Looking forward to your kind assistance and co-operative in this matter.

Please note that if you fail to conduct the pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you

Regards  
Serene LIM  
Lim Yew Boo Spray Paint Co  
Direct : +65 64545011  
Mobile : +65 96852332

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 19/12/2017 17:13  
Date Of Accident 18/12/2017 18:25  
Exact Location Of Accident TOA PAYOH LOR 6 TWRDS BRADDELL RD  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS444K  
**Insured/Policyholder**  
Name Of Registered Owner LEE POH LENG  
NRIC No S7612242C  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-96944044  
Alternative Phone No OTHERS-NOPHONE

### Vehicle Particulars

Manufacturer TOYOTA  
Model CHR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
PRIVATE CAR

Vehicle Category

### Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number D17MTPV01012173  
Cover Note Number

### Driver

Name of Driver LEE POH LENG  
NRIC No S7612242C  
Date Of Birth 25/04/1976  
Occupation OUTDOOR  
Date Of Driving Pass 21/04/1995  
Driving Experience 22 YEARS AND 7 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-96944044  
Fax Number  
Contact Number  
Email Address OTHERS-NOPHONE  
NOEMAIL

Address 9 ALEXANDRA VIEW #08-11  
Postcode 158742  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2

### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHED THIRD PARTY CLAIM AT LIM YEW BOO SPRAY PAINT CO

### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFF8023D  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver HO SIEW LOONG  
NRIC/Passport Number S7025662B  
Contact Number 93652819  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

### Details of Witness

Name  
Phone Number  
Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations/laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 19 Dec 2017  
4.51 pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Exiting Toa Payoh Lorong 6, merging onto Braddell Road.  
 Approaching Braddell Road, I slowed down to a stop at five-way lines,  
 as there is a vehicle on Braddell Road.  
 The car behind me SFF8023D did not stop, and collided onto me.

My car is "Car A"  
 The other car is "CAR B"

Please email report to [limyewboo@singnet.singnet.com.sg](mailto:limyewboo@singnet.singnet.com.sg)

My preferred workshop is Lim Yew Boo Spray Paint Co.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 19 Dec 2017  
 4.51 pm

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



# LIM YEW BOO SPRAY PAINT CO. *Kr*

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645  
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721  
 Tel: 6453 4177 Fax: 6459 3724  
 Email: limyewboo@singnet.com.sg  
 Company Reg. No. : 200514/00L

SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE #05-01/06  
 SINGAPORE LAND TOWER SINGAPORE 048623

Attention : Motor Claim Department  
 Contact : 64616555 Fax No. : 6

Estimate : TP18/014

Date : 22/03/2018  
 Vehicle Num. : SLS 444K  
 Make/Model : TOYOTA C-HR HYBRID-2017  
 Chassis/Eng# : ZYX102054194/2ZR8143762  
 Accident Date : 18/12/2017  
 Claim No. :  
 Reference : LYB/SLS444/SOMPO/tp/sy  
 Policy No. :

*Not Authorized*  
*1-B.1*  
*Put away B&Pain*  
*\$ 2925.00*

*3 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

## LIST ITEMS :

- |    |   |                           |
|----|---|---------------------------|
| 1. | 1 | REAR BUMPER <i>700.00</i> |
| 2. | 2 | REAR BUMPER BRACKET       |
| 3. | 2 | REAR BUMPER RETAINER      |

List TotalS\$ :  
 25.00% Discount S\$ :

<i>Ad/LA</i>	1,536.00 ✓
45.00 <i>Sm</i>	90.00 X
55.00 <i>Sm</i>	110.00 X
	1,736.00
	434.00
	1,302.00

## SPECIAL NETT ITEMS :

- |    |   |                                 |
|----|---|---------------------------------|
| 1. | 1 | REAR BUMPER LIP SPOILER         |
| 2. | 1 | REAR BUMPER LIP SPOILER SEALANT |
| 3. | 1 | REAR REVERSE SENSOR             |
| 4. | 2 | REAR REVERSE SENSOR HOUSING     |

Special Nett Total S\$ :

<i>Ad</i>	1,260.00 ✓
<i>Sm</i>	80.00 X
<i>Sm</i>	250.00 X
55.00 <i>Ad</i>	110.00 X
	1,700.00

## LABOUR :

TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS  
 TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS  
 TO SPRAY ON NANO COATING PORTION

<i>nn</i>	120.00 X
<i>50d</i>	120.00
<i>25d</i>	500.00

TO REPAIR,ALGN ON AFFECTED TAILGATE & PANEL & LABOUR TO  
 REPLACE ABOVE PARTS.

<i>35d</i>	500.00
------------	--------

CONTINUE / ...

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

All cheques should be crossed and made payable to  
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.





# LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645  
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721  
Tel: 6453 4177 Fax: 6459 3724  
Email: limyewboo@singnet.com.sg  
Company Reg. No. : 200514/001.

SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE #05-01/06  
SINGAPORE LAND TOWER SINGAPORE 048623

Attention : Motor Claim Department  
Contact : 64616555 Fax No. : 6

Estimate : TP18/014

Date : 22/03/2018  
Vehicle Num. : SLS 444K  
Make/Model : TOYOTA C-HR HYBRID-2017  
Chassis/Eng# : ZYX102054194/2ZR8143762  
Accident Date : 18/12/2017  
Claim No. :  
Reference : LYB/SLS444/SOMPO/tp/sy  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY,PRIMER TO SPRAY ON REAR BUMPER,SENSOR, AFFECTED TAILGATE USING 2K PAINTS.		600.00
		Labour Total S\$ :		1,840.00

E. & O.E.

Total S\$ :

4,842.00

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to  
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.

# ARTDESHINE

DETAILING CONCEPTS SPECIALISTS

@artdeshinedetailingcentre  
@artdeshineworld  
@artdeshinetc  
@artdesshine

SPC Toa Payoh  
180 Lor 6 Toa Payoh  
Singapore 319381  
Tel: +65 9029 0720 (Victor)  
Email: sales@artdesshine.com.sg  
www.artdesshine.sg

## INVOICE

Bill To  
Company: -  
Address: -

Attention:  
Contact:

Invoice No: 20180303-T05

Invoice Date: 9/3/2018

Payment Term: Cash

Currency: SGD

VEHICLE DETAILS	JOB DESCRIPTION	DATE COMPLETED	AMOUNT
Toyota C-HR SLS444K	Ayicon Single Session (Standard) 1. Stage 1/2 polishing *Rear Bumper & Tailgate 2. Ayicon coating - 2 layers	9 Mar	500.00

Sub Total	500.00
Discount	
Total Amt	500.00
Deposit	
Balance Due	

E. & O.E.

TOTAL AMOUNT OF:

FOR ARTDESHINE



All cheques crossed and made payable to ARTDESHINE

FOR BANK TT

Account Payee: ARTDESHINE  
Bank Name: UNITED OVERSEAS BANK LIMITED

CUSTOMER/ENTITY/COMPANY SIGNATURE/STAMP

Bank Code: 7375  
Branch Code: 035  
Account No: 383 303 073 0

# ARTDESHINE

## DETAILING CONCEPTS SPECIALISTS



@artdeshinedetailingcentre  
@artdeshineworld  
@artdeshinelp



@artdeshine

SPC Toa Payoh  
180 Lor 6 Toa Payoh  
Singapore 319381  
Tel: +65 9029 0720 (Victor)  
Email: sales@artdeshine.com.sg  
www.artdeshine.sg

### INVOICE

Bill To  
Company: -  
Address: -

Attention: -  
Contact: -

Invoice No.: 20171005-T4

Invoice Date: 09/10/2017

Payment Term: Cash

Currency: SGD

#### VEHICLE DETAILS

#### JOB DESCRIPTION

#### DATE COMPLETED

#### AMOUNT

Toyota CHR  
SLS444K

Ayicon Single Session  
1. Stage 1/2 polishing  
2. Ayicon coating - 2 layers  
3. Interior detailing/conditioning  
4. Wheel/Window/Trims coating  
5. Engine bay detailing

9 Oct 17

450.00

CHR Exclusive

E. & O.E.

TOTAL AMOUNT OF :

FOR ARTDESHINE



All cheques crossed and made payable to ARTDESHINE

FOR BANK TT

Account Payee: ARTDESHINE  
Bank Name: UNITED OVERSEAS BANK LIMITED

Sub Total	450.00
Discount	90.00
Total Amt	360.00
Deposit	
Balance Due	

CUSTOMER/ENTITY/COMPANY SIGNATURE/STAMP

Bank Code: 7375  
Branch Code: 035  
Account No: 363 303 072 0



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18000171/Krbn2

50 RAFFLES PLACE  
#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 03-05-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFF 8023D	Veh. Inspected	SLS 444K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704673/AGC	Excess (\$)	0.00
Assign From	IRENE	Assign Date	03/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102054194	Colour	METALLIC BLACK
Odometer	6239	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	9 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	9 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	9 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	9 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	18/12/2017	Inspection Date	05/01/2018
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 444K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED / CUT	1,536.00	700.00
2	REAR BUMPER BRACKET @\$45.00	SERVICEABLE	90.00	-
2	REAR BUMPER RETAINER @\$55.00	SERVICEABLE	110.00	-
	LESS 25% DISCOUNT		-434.00	-175.00
			1,302.00	525.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER LIP SPOILER (SN)	DENTED	1,260.00	1,260.00
1	REAR BUMPER LIP SPOILER SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
2	REAR REVERSE SENSOR HOUSING @\$55.00 (SN)	SERVICEABLE	110.00	-
			1,700.00	1,300.00
<b><u>LABOUR</u></b>				
	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.	NOT NECESSARY	120.00	-
	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS.		120.00	50.00
	TO SPRAY ON NANO COATING PORTION.		500.00	250.00
	TO REPAIR, ALIGN ON AFFECTED TAILGATE & PANEL & LABOUR TO REPLACE ABOVE PARTS.		500.00	350.00
	TO PUTTY, PRIMER TO SPRAY ON REAR BUMPER SENSOR, AFFECTED TAILGATE USING 2K PAINTS.		600.00	450.00
			1,840.00	1,100.00
<b>GRAND TOTAL</b>			<b>4,842.00</b>	<b>2,925.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,925.00</b>

Report Ref No. CS/SMO18000171/Krbn2

KSC

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.