

22/02/2012

ASS. REC. BY:

REF: CS/CT18000216/Kqb 9-1

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Jawyn Tay

of

CTL

Date/Time:

04/01/2018 9:31am

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GRC 4566T

Insured:

6Y 5470D

at Workshop m/s

Complete vms

Tel:

6455 0012

of

176 Gin ming Drive 403-14

Policy No:

DMCVSN3092611700

Claim No:

SNM18000015CD2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/2/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Li Hui

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GRC 4566T - x

6Y 5470D - NM/RSC1100964/12

Den: 28013011

21/02/18 8:13/1c

19/14 21/02/18 8:15 500 Carbur no loc. (Ref & 72488.33, 59%)

Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Complete

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 84311

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

11 Mr pass to Catherine

RECEIVED 19 APR 2010

Date/Time, File Pass to?

1) 19/4/2010

Date/Time, File Return to?

2) _____

☐ : Prell. Report☐ : Final ReportDays Of Repair: 21Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$Survey Fee: 770

Transportation

\$ - RS. \$1

Photos

Others

TOTAL

Veh No: GBC 4566T Yr Regn: 07, 12Type: M.Car / M.Cycle / Bus / Van / Corry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Cabrio c.c. 2953Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 301556 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TN13C 2F24. E08 50364Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: B-5 185/75R15R: Yoko 155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 3 mmL/Bal: 3 mmD.O.A. 28/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or8/11

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal: 3 3 mmL/Bal: 3 3 mmD.O.I. 3/1/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000216/Kqb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 5470D	Veh. Inspected	GBC 4566T
Policy No.	DMCVSN3092611700	Coverage (\$)	0.00
Claim No.	SNM18D00015C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/12/2017	Inspection Date	04/01/2018
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		04 Jan 2018 09:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	EZ MOBILE LAUNDERETTE PTE LTD		
Main Claimant:	WOH HUP (PTE) LTD		
Vehicle Reg. No.:	GBC4566T	Date of Loss:	28/12/2017 00:00 - :59
Claim Type:	TP / SNM18D00015C02	Policy/Cover Note No.:	DMCVSN3092611700 (Comprehensive) Coverage: 04/12/2017 - 03/12/2018
Vehicle Reg. No. (Insured):	GY5470D	Policy No. (Claimant):	
		Excess:	\$40.00
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/01/2018]		
Adj Asg. Remarks:	1) REQUESTED FOR KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS. OUR INSURED HAS YET TO REPORT THE ACCIDENT.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0021M

Vehicle Details

Vehicle No.: GBC4566T

Vehicle to be Exported: Yes

Intended De-registration
Date: 29 Dec 2017

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS
2DR 2WD TURBO

Primary Colour: Silver

Manufacturing Year: 2011

Engine No.: ZD30298329K

Chassis No.: JN15C2F24Z0850364

Maximum Power Output: -

Open Market Value: \$34,386.00

Original Registration Date: 31 Jul 2012

First Registration Date: 31 Jul 2012

Transfer Count: 0

Actual ARF Paid: \$1,720.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jul 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$58,553.00

COE Rebate Amount: \$26,852.00

Total Rebate Amount: \$26,852.00

The information contained herein is correct as at 29 Dec 2017

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

July 2014 Toyota Dyna At \$67K.



1st Lady Driver, Accident Free.
Under Agent Maintenance. Mileage
80,000km Done.
Direct Owner StarAd



Browse by Category

Sort by Date Posted

6 vehicles

Nissan Cabstar

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh
------	-------	-------	--------------	----------	---------	---------	-----

Search Selection	Nissan Cabstar	Any	Any	2012	Any	Any	
------------------	----------------	-----	-----	------	-----	-----	--



Nissan Cabstar

\$42,800

\$9,070 /yr

24-Sep-2012

2,953 cc

-

1

Fuel Type: Diesel

10 Feet Lorry With Box, 2 Sliding Doors For Easy Loading/unloading. Excellent Condition, New Paintwork. In-house Loan Available, High Tra Now For Viewing! Pricing Negotiable!

ABWIN (1994) Pte Ltd

Posted: 29-Dec-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Cabstar, Used Nissan



Nissan Cabstar

\$40,800

\$8,740 /yr

04-Sep-2012

2,953 cc

-

1

Fuel Type: Diesel

One Owner Only, Low Mileage, High Loan Available, Low Interest Rate, Call Now And Check Location Before Drop By.

ABWIN Bus Pte Ltd

Posted: 26-Dec-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Cabstar, Used Nissan



Nissan Cabstar

\$39,800

\$8,570 /yr

27-Aug-2012

2,953 cc

-

1

Fuel Type: Diesel

Cheapest In Town, 1 Owner, Low Miles, No Need Repair, Regular Servicing Done, Price Negotiable, High Loan With Lowest Interest Rate Av High Trade In, Call Now!

ABWIN Bus Pte Ltd

Posted: 21-Dec-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Cabstar, Used Nissan



Nissan Cabstar

\$41,800

\$8,850 /yr

24-Sep-2012

2,953 cc

-

1

Fuel Type: Diesel

Barely Hard To Find Box With Partition! Partition Can Be Taken It Out Too! Its 5 Doors! Can Segregate Your Items For Delivery And Tidiness! House Loan Available! Faster Call Us Now For More De...

ABWIN (1994) Pte Ltd

Posted: 21-Dec-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Cabstar, Used Nissan

Car Buying

Car Selling

Car Aftermarket

Buying & Uns

Car Ownership

On The Move

Lifestyle

E



Nissan Cabstar

\$41,800

\$8,600 /yr

14-Nov-2012

2,953 cc

-

1

Fuel Type: Diesel

1 Owner! Comes With Checkered Plate And Movable Canopy! No Major Repairs Needed! High Loan Available! No Obligations! Call Now To E

Posted: 10-Nov-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Cabstar, Used Nissan

**Nissan Cabstar****\$47,800****\$10,740 /yr****18-Jun-2012****2,953 cc****1****Fuel Type:** Diesel

Power Tailgate! Door Step Viewing Available. High Loan Available, Full In House Loan Available. Call Now! Cheapest In Market.

ABWIN (1994) Pte Ltd

Posted: 08-Nov-2017

Tags: 2012 Nissan Cabstar, 2012 Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Nissan Cabstar, Cabstar, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh 1
------	-------	-------	--------------	----------	---------	---------	-------

For old advertisements, view [Expired ads](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Nissan Cabstar Singapore, used Nissan Cabstar Singapore, used Nissan Cabstar, used vehicles Singapore or even buy used Nissan Cabstar Singapore. We have new car dealers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore, sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance is made that the information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

© 2004-2018 sgCarMart. All rights reserved.

- Terms of
- Privacy P
- Personal

[Compare](#)

SGCARMART
APP DOWNLOAD

23

Car Make or Model

Search


**WatchBox
Asia**

 The Leap
Pre-Owned
Source


Username / Email Add

password



Connect

or Sign Up with Email

or Sign Up with Email

Cabstar

Price Range



Depreciation



2012



Vehicle Type



Home » Used Cars » ABWIN (1994) Pte Ltd » Nissan Cabstar

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Rental

 For Private &
Commercial Vehicles
Rental From
\$50/Day

1st
 Estate Agent

Nissan Cabstar

Overview

Financial

Accessories

Similar

Research

Photos

Map

ABWIN 詢

ONE-STOP
 ANY FINANCE SOLUTIONS


Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$47,800**Depreciation** \$10,700 /yr

Note: Includes 4.0% on-road depreciation

Reg Date 18-Jun-2012

(4yrs 5mths 18days COE left)

Manufactured 2011**Mileage** -**Transmission** Manual**Engine Cap** 2,953 cc**Curb Weight** 2,160 kg**Fuel type** Diesel
Features New Paintwork, Just Serviced, Excellent Condition,
Pristine Condition Tailgate Vehicle, Excellent For
Loading/Unloading Heavy Goods.
Accessories -
Description Power Tailgate! Door Step Viewing Available. High Loan
Available, Full In House Loan Available, Call Now!
Cheapest In Market.
COE \$57,589**OMV** \$34,386**ARF** \$1,720**Dereg Value** \$25,718 as of today (change)**No. of Owners** 2**Type of Veh** Truck**Category** -**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 08-Nov-2017 | Last updated on: 18-Dec-2017

 Tags: Nissan Cabstar, Nissan Cabstar 2012 Nissan Cabstar, 2012 Nissan Cabstar,
Nissan, Cabstar, Cabstar, Used Nissan


Seller's Information

Company ABWIN (1994) Pte Ltd
 • 06466 1111
 • 166 employees | 192 vehicles
 available
Address 20 Kaki Bukit Road 2
Contact Person(s) Nicholas 81389955
 Cj Yeo 83337446
 Egg 93896679
 Eugene 90927943

Financing Payment

www.sgcarMart.com

Transfer Fee \$25**Payment** \$4,780 (change)

Maximum 90% Loan

Interest \$934

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/12/2017 18:02
Date Of Accident	28/12/2017 12:15
Exact Location Of Accident	JUNCTION OF CLEMENTI ROAD AND ULU PANDAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4566T
Insured/Policyholder	
Name Of Registered Owner	WOH HUP (PRIVATE) LIMITED
Co Reg No	NA
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97102194

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW006046-R02
Cover Note Number	

Driver

Name of Driver	AZHAR BIN AWANG
NRIC No	S7031720F
Date Of Birth	27/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	09/10/1998
Driving Experience	19 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97102194
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 63 CIRCUIT ROAD #02-271 SINGAPORE
Postcode	370063
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY5470D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLD4469S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name AZHAR BIN AWANG
Approximate Age
Injuries Sustain REFER POLICE REPORT
Injured person in which vehicle? GBC4566T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the insurer's discretion and the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transmit such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Alva Road, Rd

Veh A : GBC4566T
Veh B : GY 5470D
Veh C : SLD4469S

Clomenti Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/12/2017 13:53		Vide Report No.: D/20171228/0056		Station Diary No.: 57	
Informant's Particulars					
Name of Informant: AZHAR BIN AWANG			Address: APT BLK 63 CIRCUIT ROAD #02-271 SINGAPORE 370063		
ID Type / ID No.: NRIC NO / S7031720F			Contact No.: Home/Office: Mobile: 97102194		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 27/09/1970	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B,2A,3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/12/2017 12:15	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 CLEMENTI ROAD ULU PANDAN ROAD Junction of Clementi Road and Ulu Pandan Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC4566T	Lorry				Slightly Damaged	0
GY5470D	Van				Seriously Damaged	0
SLD4469S	Car				Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

CONTINUATION OF REPORT

Driver			
Name	AZHAR BIN AWANG	ID No.	S7031720F
Related Vehicle	NIL	Contact No.	97102194
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/12/2017 at about 1215hrs I was driving along Clementi Rd on the third lane from the right. There was a car (SLD4469S) in-front of me slowing down as such I applied brakes to slow down as well. Suddenly, I felt a large impact from the back and I blacked out. When I woke up I saw my windscreen was cracked and my coffee was spilled all over. I was unsure of what was happening and I got off my vehicle and was approached by the car driver in front of me. He asked if I was ok but I was still in shock due to the impact. I then realized that I was hit by a van (GY5470D) from the rear. I was suffering from chest pain and giddiness and I could not understand what the van driver was mumbling about. I then went to the side to rest and did not find out exactly what happened.

I was then conveyed by ambulance to NUH A&E and I did not manage to take down any particulars. My friend assisted me to take photos of the scene and the damages of the vehicles. Police from land division and traffic police attended to the scene. I am unsure if there is anymore injured parties. I was discharged on 29/12/2017 at about 12pm and was given MC of 8 days from 28/12/2017 to 04/01/2018.



**SINGAPORE
POLICE FORCE**



T/20171229/2049

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 3

Report No. T/20171229/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 JACKSON KOH TIAN LIN <i>Tay Kah Jun</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 29/12/2017 13:53
Officer In Charge Of Case: TP / GIT / Contact No.:	Classification Of Case: SNJ70 <i>[Signature]</i>
Authentication Stamp NP168	



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

WOH HUP (PTE) LTD
217 UPPER BUKIT TIMAH RD, WOH HUP BUILDING
SINGAPORE 588185

Attention : THE OWNER
Contact : 63858585 81831482

Estimate : ES006237

Date : 29/12/2017

Vehicle Num. : GBC4566T

Make/Model : NISSAN CABSTAR 3.0-2011

Chassis/Eng# : JN1SC2F24Z0850364/ZD30298329K

Accident Date : 28/12/2017

Claim No. _____

Reference

Policy No

Not Noted
11 Aug 813,000
Henry A. L. L. L.
2100

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAIL GATE		1,688.40
2.	3	TAIL GATE HINGE	138.60	415.80
3.	1	TAIL GATE SIDE BRACKET R/H		35.00
4.	1	REAR NUMBER PLATE BRACKET		125.00
5.	1	REVERSE SOUND RELAY		188.00
6.	2	SPARE TIRE CARRIAGE SUPPORT BRACKET	245.00	490.00
7.	2	REAR END PANEL SUPPORT MOUNTING	153.00	306.00
8.	1	REAR EXHAUST SILENCER BOX BRACKET		126.00
9.	2	REAR EXHAUST SILENCER BOX RUBBER RING	40.00	80.00
10.	1	CHASSIS FRAME REAR MEMBER		983.00
11.	1	REAR FLOOR PANEL LAST MEMBER		572.50
12.	1	REAR EXHAUST BOX BRACKET		142.30
13.	1	CENTRE EXHAUST PIPE		953.00
14.	1	REAR FENDER MUDFLAP R/H		65.40
15.	1	SIDE PANEL BOARD R/H		2,915.10
16.	6	REAR FLOOR PANEL MOUNTING	112.00	672.00
17.	2	PETROL TANK BRACKET	112.00	224.00
18.	1	FRONT DOOR R/H		1,923.40
19.	1	FRONT CORNER PANEL R/H		568.00
20.	2	FRONT MIRROR STAND COVER	152.00	304.00
21.	1	FRONT WIPER MOTOR		325.00
22.	2	FRONT WIPER ARM	53.00	106.00
23.	2	FRONT WIPER BLADE	29.00	58.00
24.	1	FRONT APRON PANEL		490.10
25.	1	FRONT PANEL		1,740.00
26.	1	CABSTAR EMBLEM		66.30
27.	1	RADIATOR GRILLE		526.00
28.	1	GRILLE LOGO		79.00
29.	6	RADIATOR GRILLE CLIP	5.30	31.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before any painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary cost(s) must be surveyed and is subject to final approval from Insurance Company

CONTINUE /



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

WOH HUP (PTE) LTD
217 UPPER BUKIT TIMAH RD, WOH HUP BUILDING
SINGAPORE 588185

Attention : THE OWNER
Contact : 63858585 81831482

Estimate : ES006237

Date : 29/12/2017
Vehicle Num : GBC4566T
Make/Model : NISSAN CABSTAR 3.0-2011
Chassis/Eng# : JN1SC2F24Z0850364/ZD30298329K
Accident Date : 28/12/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
30	2	HEADLAMP BRACKET	152.00	304.00
31	1	FRONT BUMPER	CM	951.90
32	1	FRONT BUMPER REINFORCEMENT	R	432.00
33	2	FRONT BUMPER BRACKET	R	773.20
34	1	FRONT CROSS MEMBER BRACKET	R	233.00
35	1	FRONT DASHBOARD	CM	1,123.00
36	1	DASHBOARD LOWER PART R/H	Sm	321.00
37	1	DASHBOARD CENTRE COVER	Sm	125.00
38	1	STEERING WHEEL	Sm	555.00
39	1	STEERING SHAFT ASSY	R	632.00
40	1	FRONT DOOR PILLAR R/H	R	1,264.90
41	2	ENGINE MOUNTING	Sm	348.60
42	1	RADIATOR FAN BLADE	CM	265.00
43	1	RADIATOR FAN CLUTCH	Sm	385.00
44	1	REAR PILLAR R/H	R	556.00
List Total S\$:				24,468.70
30.00% Discount S\$:				7,340.61
				17,128.09
NETT ITEMS :				
1	2	TAIL GATE SAFETY LOCK	125.30	250.60
2	2	TAIL GATE RUBBER STOPPER	42.00	84.00
3	2	TAIL LAMP	Ar	453.40
4	2	TAIL LAMP BRACKET	168.80	337.60
5	1	REAR NUMBER PLATE LAMP	Ar	51.90
6	1	SPARE TIRE CARRIAGE SET	Ar	299.20
7	1	REAR END PANEL	Ar	468.00
8	1	REAR EXHAUST SILENCER BOX	Ar	668.20
9	1	REAR FENDER R/H	R	168.60

CONTINUE /



COMPLETE VMS PTE LTD - The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

WOH HUP (PTE) LTD
217 UPPER BUKIT TIMAH RD, WOH HUP BUILDING
SINGAPORE 588185

Attention : THE OWNER
Contact 63858585 81831482

Estimate : ES006237

Date : 29/12/2017
Vehicle Num : GBC4566T
Make/Model : NISSAN CABSTAR 3.0-2011
Chassis/Eng# : JN1SC2F24Z0850364/ZD30298329K
Accident Date : 28/12/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

10.	1	FRONT EXHAUST SILENCER BOX	By 833.00	✓
11.	1	REAR LEAF SPRING REAR MOUNTING R/H	By 186.00	✓
12.	2	FRONT DOOR HINGE R/H	155.30 R 310.60	X
13.	1	FRONT W/SCREEN GLASS	CPA 1,037.00	✓
14.	2	FRONT W/SCREEN GLASS MOULDING	ME 140.00	✓
15.	2	FRONT WIPER NOZZLE	CPA 28.40	✓
16.	2	HEADLAMP	CPA 629.30	✓
17.	1	AIR CON DISCHARGE HOSE	By 280.00	✓
18.	1	AIR CON LIQUID PIPE	By 198.70	✓
19.	1	AIR CON COOLING COIL	By 645.10	✓
20.	1	AIR CON BLOWER MOTOR	CPA 720.00	✓
21.	1	REAR VIEW MIRROR	By 176.00	✓
22.	1	RADIATOR ASSY	By 850.30	✓
Nett Total S\$:			9,613.60	
10.00% Discount S\$:			961.36	
			8,652.24	

SPECIAL NETT ITEMS				
1.	1	TAIL GATE INNER ALUMINIUM PLATE	By 680.00	✓
2.	1	70 KM/H STICKER	By 15.00	✓
3.	1	13 PAX STICKER	By 15.00	✓
4.	1	REAR FLOOR PANEL TOP PLATE	R 1,800.00	✓
5.	1	REVERSE SENSOR	By 280.00	2000
6.	1	REAR NUMBER PLATE	By 25.00	2011
7.	2	SPARE TIRE RIM	Ref 155.00	310.00
8.	1	SPARE TIRE (FRONT)	By 195.00	600
9.	1	SPARE TIRE (REAR)	By 165.00	✓
10.	1	REAR STEEL STAND	By 280.00	✓
11.	1	SIDE RAILING R/H	By 255.00	✓

CONTINUE / ...



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

WOH HUP (PTE) LTD
217 UPPER BUKIT TIMAH RD, WOH HUP BUILDING
SINGAPORE 588185

Attention : THE OWNER
Contact : 63858585 81831482

Estimate : ES006237

Date : 29/12/2017
Vehicle Num : GBC4566T
Make/Model : NISSAN CABSTAR 3.0-2011
Chassis/Eng# : JN1SC2F24Z0850364/ZD30298329K
Accident Date : 28/12/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

12.	1	FRONT W/SCREEN SEALANT	65.00	
13.	1	FRONT NUMBER PLATE	25.00	
14.	1	DOOR COMPANY STICKER R/H	45.00	
15.	1	ERP BRACKET	28.00	
Special Nett Total S\$:				4,183.00

LABOUR :

TOW VEHICLE ON KING ROLLER	120	150.00
REMOVE FRONT W/SCREEN GLASS	120	180.00
REMOVE FRONT DASHBOARD ASSY	250	380.00
TRANSFER R/H FRONT DOOR COMPONENTS TO NEW DOOR	150	150.00
RUST PROOFING TREATMENT	150	250.00
SPRAY PAINT FRONT & REAR DAMAGED AREA	1400	1,800.00
CHANGE TAIL LAMP AND CHECK LIGHTING	40	65.00
CHANGE AIRCON BLOWER MOTOR, COOLING COIL, DISCHARGE HOSE, LIQUID PIPE, REFILL AIRCON GAS	120	280.00
REMOVE STAY SHAFT ASSY CLUTCH / BRAKE PEDAL		250.00
TO CUT OFF FRONT PANEL, FRONT DOOR PILLAR, FRONT SUPPORT BRACKET, KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME	nn	1,800.00
REMOVE EXHAUST REAR SILENCER BOX, CENTRE PIPE COVER, FRONT SILENCER BOX		120.00
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR FLOOR PANEL, REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	2200	2,600.00

Labour Total S\$:

8,025.00

SingDollars : Thirty-Seven Thousand Nine Hundred Eighty-Eight & Cents Thirty-Three Only

Total S\$: 37,988.33

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		04 Jan 2018 09:31 Edit Adj Rpt	S\$15,500.00 Edit Estimates	S\$15,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	EZ MOBILE LAUNDERETTE PTE LTD , Co. Reg. No.: -								
Main Claimant:	WOH HUP (PTE) LTD								
Vehicle Reg. No.:	GBC4566T	Date of Loss:	28/12/2017 00:00 - :59 [64 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D00015C02	Policy/Cover Note No.:	DMCVSN3092611700 (Comprehensive) Coverage: 04/12/2017 - 03/12/2018						
Vehicle Reg. No. (Insured):	GY5470D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/01/2018]								
Adj Asg. Remarks:	1) REQUESTED FOR KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS. OUR INSURED HAS YET TO REPORT THE ACCIDENT.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC4566T (SNM18D00015C02)
 [GY5470D]
 TP
 WOH HUP (PTE) LTD
 Dec 28 2017 12:00AM
 [EZ MOBILE LAUNDERETTE PTE LTD]
 COMPLETE VMS PTE LTD

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 13:05	General View	 Load JPG	☒
2	19/04/18 13:06	General View	 Load JPG	☒
3	19/04/18 13:06	General View	 Load JPG	☒
4	19/04/18 13:06	General View	 Load JPG	☒
5	19/04/18 13:06	General View	 Load JPG	☒
6	19/04/18 13:06	General View	 Load JPG	☒
7	19/04/18 13:06	General View	 Load JPG	☒
8	19/04/18 13:06	General View	 Load JPG	☒
9	19/04/18 13:06	General View	 Load JPG	☒
10	19/04/18 13:06	General View	 Load JPG	☒
11	19/04/18 13:06	General View	 Load JPG	☒
12	19/04/18 13:06	General View	 Load JPG	☒
13	19/04/18 13:06	General View	 Load JPG	☒
14	19/04/18 13:06	General View	 Load JPG	☒
15	19/04/18 13:06	General View	 Load JPG	☒
16	19/04/18 13:06	General View	 Load JPG	☒
17	19/04/18 13:06	General View	 Load JPG	☒
18	19/04/18 13:06	General View	 Load JPG	☒
19	19/04/18 13:06	General View	 Load JPG	☒
20	19/04/18 13:06	General View	 Load JPG	☒
21	19/04/18 13:06	General View	 Load JPG	☒
22	19/04/18 13:06	General View	 Load JPG	☒
23	19/04/18 13:06	General View	 Load JPG	☒
24	19/04/18 13:06	General View	 Load JPG	☒
25	19/04/18 13:06	General View	 Load JPG	☒
26	19/04/18 13:06	General View	 Load JPG	☒
27	19/04/18 13:06	General View	 Load JPG	☒
28	19/04/18 13:06	General View	 Load JPG	☒
29	19/04/18 13:06	General View	 Load JPG	☒
30	19/04/18 13:06	General View	 Load JPG	☒
31	19/04/18 13:06	General View	 Load JPG	☒
32	19/04/18 13:06	General View	 Load JPG	☒
33	19/04/18 13:06	General View	 Load JPG	☒
34	19/04/18 13:06	General View	 Load JPG	☒
35	19/04/18 13:06	General View	 Load JPG	☒
36	19/04/18 13:06	General View	 Load JPG	☒
37	19/04/18 13:06	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/04/18 13:06	General View	 Load JPG	☒
39	19/04/18 13:06	Odometer Reading	 Load JPG	☒
40	19/04/18 13:06	Chassis Number	 Load JPG	☒
41	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
42	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
43	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
44	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
45	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
46	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
47	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
48	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
49	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
50	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
51	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
52	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
53	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
54	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
55	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
56	19/04/18 13:10	Reinspection Photo	 Load JPG	☒
57	19/04/18 13:10	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118000216/KQBQ2

Date: 24/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3092611700

Claimant Vehicle
No: GBC4566TInsured Vehicle
No: GY5470D

Date of Loss: 28/12/2017

Nature of Claim: TP

Claim
No: SNM18D00015C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC4566T

Make & Model: NISSAN CABSTAR, 2.0 (M)

Engine No: ZD30298329K

Reg. Date: 31/07/2012 (Man. Year: 2011)

Chassis No: JN1SC2F24Z0850364

Colour: Silver

Odometer: 301556 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75 R15

Rear Tyre Size: 155R12X8 (D)

Front Left Side: Bridgestone 3 mm

Rear Left Side: Yokohama 3/3 mm

Front Right Side: Bridgestone 3 mm

Rear Right Side: Yokohama 3/3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,963.33	22,170.61	7,792.72	26.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,025.00	4,660.00	3,365.00	41.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,988.33	26,830.61	11,157.72	29.37
Approved Total (Overridden) (S\$)		15,500.00		
(S\$)	37,988.33	15,500.00	22,488.33	59.20
+ GST 7.00/7.00% (S\$)	2,659.18	1,085.00	1,574.18	59.20
Nett Amount (S\$)	40,647.51	16,585.00	24,062.51	59.20

INSPECTION

Date of Assignment: 04/01/2018

Date Inspected: 03/01/2018 Inspected At:

COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721

Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Apr 2018)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4566T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE	Bent	1,688.40 FL	*1,688.40 FL
2	3	*TAIL GATE HINGE	Distorted / Bent	415.80 FL	*415.80 FL
3	1	*TAIL GATE SIDE BRACKET R/H	Bent	35.00 FL	*35.00 FL
4	1	*REAR NUMBER PLATE BRACKET	Distorted	125.00 FL	*125.00 FL
5	1	*REVERSE SOUND RELAY	Missing	188.00 FL	*188.00 FL
6	2	*SPARE TIRE CARRIAGE SUPPORT BRACKET	Bent	490.00 FL	*490.00 FL
7	2	*REAR END PANEL SUPPORT MOUNTING	Serviceable	306.00 FL	*- FL
8	1	*REAR EXHAUST SILENCER BOX BRACKET	Necessary	126.00 FL	*126.00 FL
9	2	*REAR EXHAUST SILENCER BOX RUBBER RING	Torn	80.00 FL	*80.00 FL
10	1	*CHASSIS FRAME REAR MEMBER	Bent	983.00 FL	*983.00 FL
11	1	*REAR FLOOR PANEL LAST MEMBER	Repair	572.50 FL	*- FL
12	1	*REAR EXHAUST BOX BRACKET	Bent	142.30 FL	*142.30 FL
13	1	*CENTRE EXHAUST PIPE	Bent	953.00 FL	*953.00 FL
14	1	*REAR FENDER MUDFLAP R/H	Cracked	65.40 FL	*65.40 FL
15	1	*SIDE PANEL BOARD R/H	Bent	2,915.10 FL	*2,915.10 FL
16	6	*REAR FLOOR PANEL MOUNTING	Serviceable	672.00 FL	*- FL
17	2	*PETROL TANK BRACKET	Repair	224.00 FL	*- FL
18	1	*FRONT DOOR R/H	Buckled	1,923.40 FL	*1,923.40 FL
19	1	*FRONT CORNER PANEL R/H	Bent	568.00 FL	*568.00 FL
20	2	*FRONT MIRROR STAND COVER	Missing	304.00 FL	*304.00 FL
21	1	*FRONT WIPER MOTOR	Serviceable	325.00 FL	*- FL
22	2	*FRONT WIPER ARM	Serviceable	106.00 FL	*- FL
23	2	*FRONT WIPER BLADE	Cut	58.00 FL	*58.00 FL
24	1	*FRONT APRON PANEL	Bent	490.10 FL	*490.10 FL
25	1	*FRONT PANEL	Bent	1,740.00 FL	*1,740.00 FL
26	1	*CABSTAR EMBLEM	Necessary	66.30 FL	*66.30 FL
27	1	*RADIATOR GRILLE	Cracked	526.00 FL	*526.00 FL
28	1	*GRILLE LOGO	Necessary	79.00 FL	*79.00 FL
29	6	*RADIATOR GRILLE CLIP	Necessary	31.80 FL	*31.80 FL
30	2	*HEADLAMP BRACKET	Repair	304.00 FL	*- FL
31	1	*FRONT BUMPER	Cracked	951.90 FL	*951.90 FL
32	1	*FRONT BUMPER REINFORCEMENT	Repair	432.00 FL	*- FL
33	2	*FRONT BUMPER BRACKET	Repair	773.20 FL	*- FL
34	1	*FRONT CROSS MEMBER BRACKET	Repair	233.00 FL	*- FL
35	1	*FRONT DASHBOARD	Cracked	1,123.00 FL	*1,123.00 FL
36	1	*DASHBOARD LOWER PART R/H	Serviceable	321.00 FL	*- FL
37	1	*DASHBOARD CENTRE COVER	Serviceable	125.00 FL	*- FL
38	1	*STEERING WHEEL	Serviceable	555.00 FL	*- FL
39	1	*STEERING SHAFT ASSY	Bent	632.00 FL	*632.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT DOOR PILLAR R/H	Repair	1,264.90 FL	*- FL
41	2		*ENGINE MOUNTING	Serviceable	348.60 FL	*- FL
42	1		*RADIATOR FAN BLADE	Cracked	265.00 FL	*265.00 FL
43	1		*RADIATOR FAN CLUTCH	Serviceable	385.00 FL	*- FL
44	1		*REAR PILLAR R/H	Bent	556.00 FL	*556.00 FL
45	2		*TAIL GATE SAFETY LOCK	Distorted	250.60 FN	*250.60 FN
46	2		*TAIL GATE RUBBER STOPPER	Missing	84.00 FN	*84.00 FN
47	2		*TAIL LAMP	Broken	453.40 FN	*453.40 FN
48	2		*TAIL LAMP BRACKET	Bent	337.60 FN	*337.60 FN
49	1		*REAR NUMBER PLATE LAMP	Buckled	51.90 FN	*51.90 FN
50	1		*SET SPARE TIRE CARRIAGE	Bent	299.20 FN	*299.20 FN
51	1		*REAR END PANEL	Bent	468.00 FN	*468.00 FN
52	1		*REAR EXHAUST SILENCER BOX	Bent	668.20 FN	*668.20 FN
53	1		*REAR FENDER R/H	Repair	168.60 FN	*- FN
54	1		*FRONT EXHAUST SILENCER BOX	Bent	833.00 FN	*833.00 FN
55	1		*REAR LEAF SPRING REAR MOUNTING R/H	Serviceable	186.00 FN	*- FN
56	2		*FRONT DOR HINGE R/H	Repair	310.60 FN	*- FN
57	1		*FRONT W/SCREEN GLASS	Cracked	1,037.00 FN	*1,037.00 FN
58	2		*FRONT W/SCREEN GLASS MOULDING	Necessary	280.00 FN	*280.00 FN
59	2		*FRONT WIPER NOZZLE	Cracked	56.80 FN	*56.80 FN
60	2		*HEADLAMP	Cracked	1,258.60 FN	*1,258.60 FN
61	1		*AIR CON DISCHARGE HOSE	Bent	280.00 FN	*280.00 FN
62	1		*AIR CON LIQUID PIPE	Dented	198.70 FN	*198.70 FN
63	1		*AIR CON COOLING COIL	Cracked	645.10 FN	*645.10 FN
64	1		*AIR CON BLOWER MOTOR	Cracked	720.00 FN	*720.00 FN
65	1		*REAR VIEW MIRROR	Missing	176.00 FN	*176.00 FN
66	1		*RADIATOR ASSY	Punctured	850.30 FN	*850.30 FN
67	1		*TAIL GATE INNER ALUMINIUM PLATE	Buckled	680.00 FS	*680.00 FS
68	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
69	1		*13 PAX STICKER	Necessary	15.00 FS	*15.00 FS
70	1		*REAR FLOOR PANEL TOP PLATE	Repair	1,800.00 FS	*- FS
71	1		*REVERSE SENSOR	Missing	280.00 FS	*200.00 FS
72	1		*REAR NUMBER PLATE	Bent	25.00 FS	*20.00 FS
73	2		*SPARE TIRE RIM	Dented (1 PCS ONLY)	310.00 FS	*155.00 FS
74	1		*SPARE TIRE (FRONT) (60%)	Cut	195.00 FS	*117.00 FS
75	1		*SPARE TIRE (REAR)	Serviceable	165.00 FS	*- FS
76	1		*REAR STEEL STAND	Bent	280.00 FS	*280.00 FS
77	1		*SIDE RAILING R/H	Bent	255.00 FS	*255.00 FS
78	1		*FRONT W/SCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
79	1		*FRONT NUMBER PLATE	Dented	25.00 FS	*25.00 FS
80	1		*DOOR COMPANY STICKER R/H	Necessary	45.00 FS	*25.00 FS
81	1		*ERP BRACKET	Necessary	28.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	38,265.30	28,321.90
- List Item Discount on L Items 30.00/30.00% (\$)	7,340.61	5,256.45
- Nett Item Discount on N Items 10.00/10.00% (\$)	961.36	894.84
Total Parts (\$)	29,963.33	22,170.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOW VEHICLE ON KING ROLLER	New	150.00	120.00
2	REMOVE FRONT W/SCREEN GLASS	New	180.00	120.00
3	REMOVE FRONT DASHBOARD ASSY	New	380.00	250.00
4	TRANSFER R/H FRONT DOOR COMPONENTS TO NEW DOOR	New	150.00	60.00
5	RUST PROOFING TREATMENT	New	250.00	150.00
6	SPRAY PAINT FRONT & REAR DAMAGED AREA	New	1,800.00	1,400.00
7	CHANGE TAIL LAMP AND CHECK LIGHTING	New	65.00	40.00
8	CHANGE AIRCON BLOWER MOTOR ,COOLING COIL ,DISCHARGE HOSE ,LIQUID PIPE,REFILL AIRCON GAS	New	280.00	120.00
9	REMOVE STAY SHAFT ASSY CLUTCH /BRAKE PEDAL	New	250.00	100.00
10	TO CUT OFF FRONT PANEL ,FRONT DOOR PILLAR ,FRONT SUPPORT BRACKET ,KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME	New	1,800.00	0.00
11	REMOVE EXHAUST REAR SILENCER BOX ,CENTRE PIPE COVER ,FRONT SILENCER BOX	New	120.00	100.00
12	TO CUT OFF REAR END PANEL,KNOCK AND STRAIGHTEN REAR FLOOR PANEL ,REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	New	2,600.00	2,200.00
Gross Labour Cost (\$\$)			8,025.00	4,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >