

Our Ref : T 0118 / SHC3839S /CL(st)
 Your Ref: _____
 Date : 16-Jan-18

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Flr
 Singapore 508969

Mainline +65 6383 6280
 Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408649

Senoko
 24 Senoko Loop
 Singapore 758156

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

Yishun
 501 Yishun Industrial Park A
 Singapore 768732

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Buliding
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC3839S YOUR INSURED SLQ5148T
 AND OTHER _____ ON 01.01.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHC3839S which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SLQ5148T we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 3,905.50
2	<u>4</u> days Loss of Rental @ \$ 125.00 per day	\$ 500.00
3	Survey Report Fees <i>(Surveyed by M/s LKK)</i>	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
Sub Total :		\$ 4,412.99

HIRER'S CLAIM

7	<u>4</u> days Loss of Income @ \$ 80.00 per days	\$ 320.00
Total Claims :		\$ 4,732.99

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 6 pcs.
 b) LTA search slip/s of : SLQ5148T
 c) GIA / Police report/s of : SHC3839S
 d) Letter of authority from owner / hirer / operator
 () Photograph/s of Accident Scene () Certificate of Insurance
 () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 8 January 2018 1:58 PM
To: 'Insurance LCR SG'
Subject: ACCIDENT INVOLVING SLQ 5148T(AIG) & SHC 3839S ON 01/01/2018 (13:05HOURS) ALONG TAMPINES STREET 83

Your Ref: **SLQ 5148T**
Our Ref: CC3/LCR18000235/K1jb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLQ 5148T(AIG) & SHC 3839S ON 01/01/2018 (13:05HOURS) ALONG TAMPINES STREET 83

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SHC 3839S against your insurance policy.

Based on the information on hand, we are of the opinion that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****i 40 SHC3839S , SLQ5148T
TAMPINES ST 83(TWDS AVE 5) X BLK 835 CAR PARK EXIT****ON 01-Jan-18 13:05**

I / We

WANG SEE JUI(Hirer) NRIC No.: **S1582309G**

and/or

(Relief) NRIC No.:

Taxi Number

SHC3839S

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

02-Jan-2018

Name of Hirer

WANG SEE JUI

Hirer NRIC

S1582309G

Signature :



Address

**830 TAMPINES STREET 82 #01-29
520830**

Contact No.

84011938

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,435.00 (Global Sum) for vehicle no. SHC 3839S that was damaged pursuant to the accident which occurred on 01/01/2018 (date) along TAMPINES STREET 83 (location) involving vehicle no/s SLO 5148T. This is pursuant to the inspection conducted on 03/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SHC 3839S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 3839S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of 01 FEB 2018 (month) 20 (year)



Signed by appointed surveyor


CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:-
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

GST REG. NO. M2-8921817-3

TAX INVOICE

8010004
AIG ASIA PACIFIC INSURANCE PTE LTD
#08-16 78 SHENTON WAY.CHARTIS BUILD
SINGAPORE 079120
CONTACT NO: 64193000 3225094

VEHICLE NO
SHC3839S
MAKE
HYUNDAI
MODEL
I-40
DATE OF REG
31.12.2014
CHASSIS CODE
KMHLB41UMFU062662

INV. NO/DATE
91351169 12.01.2018
JOB NO.
305103025
ODOMETER READING

JOB TYPE

Description : 3P 01.01.2018

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt		3,650.00
Add GST @ 7.000 %		255.50
Total Invoice amount		3,905.50

Issued by : CHEWBEELENG 12.01.2018 10:28:35
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

1) WHILST TAKING ALL REASONABLE PRECAUTIONS, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR DAMAGE TO OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND KEPT AT OWNERS' RISK.
2) CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM DELIVERY NOTIFY IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO BE IN GOOD ORDER.
3) INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND PAYABLE TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT OR AFTER 30 DAYS FROM THE DATE OF DELIVERY OF GOODS.
4) PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DAMAGES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM OUR CUSTOMERS, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.

Our Ref: CT18010012

Date: 11 January 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 01/01/2018 @ 13:05 hrs
ALONG TAMPINES ST 83(TWDS AVE 5) X BLK 835 CAR PARK
EXIT
INVOLVING SLQ5148T

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3839S** (the "Taxi"). The Taxi was hired to **WANG SEE JUI IC NO S1582309G** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

SHC 38395

MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
	FROM	TO					FROM	TO
	6600		01/01/2018	V.A.	255333	192	0650	1338
		12 Noon	01/1/18	Accident	WANG SEE JUI		1330	
			04/1/18	repair	V. W			1400
169	1653	2323						
277	0600	1757						
172	1916	0340						
182	0715	1800						
141	1128	0303						
264	0615	1748						
228	1818	0215						
440	0615	2320						

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLQ5148T	01 Jan 2018 / 13:05:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

SUC 38395