

ASS. REC. BY:

REF:

08/EG118000261 /Ribbez

Special Instructions:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time 04/01/2018 2037pm

Estimated Cost: Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 2119E Insured: YN 469261

at Workshop m/s Cycle & Carriage Automotive Tel: 6568 4501

of 209 Pandan Garden

Policy No: Claim No: YN 469261 /SE/pl

Sum Insured: Excess:

Make of Veh: D.O.A. 02-01-2018

(Client's Record)

05.01.2018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 04/01/2018 236pm Person Contacted: Jian Ye Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 2119E - x
	YN 469261 - x
10/1/18	Recd file from Catherine
10/1/18	Email preli revised to Pei Li

REP: **Faru**

REF: **EG1**

4597k

ASSIGNMENT

From: _____ Date: **05/01/2018**

Estimated Cost: _____

OD: **(C) TP / WS / TP RES / OD RES / EVA / INV / MV**

To inspect Vehicle No: **SLF 2119 E**

at Workshop no: **Cycle & Carriage Automotive**

of: **209 Pandan Garden**

Insured: _____


Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record) **Jian Ye**

Make of Veh: _____



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **'DS'**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Gen No: **SLF 2119E** Yr Reg: **2016 JAK**

Type: **(C) M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or: _____

Make: **MTSUBISHI ATTARAGE (L2)** 1193

Colour: **WHITE** A/C Insured / Std / NI / NA

So. Reading: **110030** T. Radio: Insured / Std / NI / NA

Eng No: _____

C No: **MMBSTA13HH00781**

Gen. Cond: Good / **(C) Fair** / Poor / Burnt

Steering: **(C) In order** / Jammed / Leaked / Burnt or

Brake: **(C) In order** / Jammed / Leaked / Burnt or

Modl: Nil / **(C) Rim** / STD A/Rim or

Tyre Size: F: **185/55 R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **ROADSTONE**

Front: _____ Rear: _____

R. Bal. **5** mm R. Bal. **5** mm

L. Bal. **5** mm L. Bal. **5** mm

D.O.A. **02/04/17** D.O.I. **05/01/18**

Survey held at **C8C (CPW)**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NO / FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action Instruction

24/1/18 Final fig \$ 5658 confirmed by email (Ref 1354, 1990)

24/1/2018

RECEIVED 23 JAN 2018

Date/Time File Pass to: ☐ Preli. Report

☐ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

___ \$ + P.O. ___

Printed

Checked

TOTAL

Date/Time File Return to:

24/1- typist

Report Format:

Lump Sum: **187.5**

TP 5658 k

Add Fee: ☐ Site Insp: **5**

☐ Inter. insp: **5**

☐ Tech. insp: **5**

☐ Test and: **5**

250

250

Survey Department Check List (Case Handler)

Reference No.: CS/ EFT/ 18000261/ R/V
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (**)**: Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (**)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Veron 24/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18000261/R1vb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 04-01-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4692G	Veh. Inspected	SLF 2119E
Policy No.		Coverage (\$)	0.00
Claim No.	YN4692G/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/01/2018	Inspection Date	05/01/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 10 January, 2018 2:16 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: YN4692G / TP : SLF2119E/LKK / DOA : 02/01/2018
Attachments: PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLF 2119E
Date of survey: 5/1/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 4 January, 2018 2:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: YN4692G / TP : SLF2119E/LKK / DOA : 02/01/2018

Dear Pei Li,

Thank you for the assignment.

'WISHES YOU A HAPPY NEW YEAR 2018'

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 4 January, 2018 2:03 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : YN4692G / TP : SLF2119E/LKK / DOA : 02/01/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE AUTOMOTIVE PTE LTD**.

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : TAY JIAN YE @ 6568 4501

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YN4692G/SE/pl
Our ref: CS/EGI18000261/R1vb

Date: 10/1/2018

The Motor Claims Department
M/s ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLF 2119E


We thank you for your instruction on 4/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/1/2018 at the premises of M/s CYCLE & CARRIAGE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,012.00
Revised Estimate Amount	: S\$5,677.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 4 January, 2018 2:03 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YN4692G / TP : SLF2119E/LKK / DOA : 02/01/2018
Attachments: YN4692G - SAS.pdf; SLF2119E - SAS.pdf; SLF2119E - ESTIMATE.pdf; SLF2119E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **CYCLE & CARRIAGE AUTOMOTIVE PTE LTD**,

ADDRESS : 209 PANDAN GARDENS
SINGAPORE 609339

PERSON TO CONTACT : TAY JIAN YE @ 6568 4501

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 04.01.2018
Our Reference: YN 4692G/SE/pl
Your Reference: SLF 2119E

Sent via Fax

or

Email

jianye.tay@cyclecarriage.com.sg

To: CYCLE & CARRIAGE AUTOMOTIVE P/L

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLF 2119E
Insured's Vehicle: YN 4692G
Date Of Accident: 02.01.2018

We acknowledge receipt of your request for PRS on: 03.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK.

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd


☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.

☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.

☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.

☐ Our Insured's driver has not reported the accident to us to date.

☒ Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OIC - SIT1

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:


Date: 04-1-18

Time: 15:00

Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.


Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2018 13:33
Date Of Accident	02/01/2018 19:30
Exact Location Of Accident	WOODLANDS RD TOWARDS MANDAI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF2119E
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	UBER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995056
Cover Note Number	

Driver

Name of Driver	KALAIARASAN S/O RETNAM
NRIC No	S7107031Z
Date Of Birth	22/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	10/04/1991
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 3
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 4
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN4692G
 Vehicle Make/Model/Colour MITSUBISHI/WHITE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver THOZHAN RAJASEEKAR

NRIC/Passport Number	G8336225T
Contact Number	91964827
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along woodlands Road towards Marsden Road. I was in the right turning lane and the lorry was in the left lane. Suddenly came into my lane and hit left side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name /Lion City Rentals Pte Ltd Reg No/Reg Date SLF2119E / 18/08/201 Date In/Mileage / 0 Chassis No MMBSTA13AH001781 Engine No 3A92UDH3880 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	03/01/2018/ 14:40		465 / Tay Jian Ye	19230

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT BUMPER , FRT LH FENDER, REPAIR LH FRT DOOR				✓ 1375 2200.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER , FRT LH FENDER, FRT LH DOOR				✓ 1260 1680.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION				✓ 40 80.00
M SUNDRY SUNDRIES				✓ 20 50.00
M FACE,FR BUMPER	1.00	696.00	00.00	TOP 696.00
M BRACKET,FR BUMPER,LH	1.00	13.00	00.00	13.00
M CLIP,FR BUMPER	10.00	3.00	00.00	30.00
M HEADLAMP ASSY,LH	1.00	654.00	00.00	654.00
M FENDER,FR LH	1.00	458.00	00.00	458.00
M SHIELD,FR WHEELHOUSE,LH	1.00	97.00	00.00	97.00
M CLIP,FR BUMPER (Rear side)	15.00	3.00	00.00	45.00
M MIRROR ASSY,DOOR,LH	1.00	632.00	00.00	632.00
M COVER,DOOR MIRROR,OTR LH	1.00	127.00	00.00	127.00

SURVEYOR NAME: Rashid - Hq 700101018SURVEYOR SIGNATURE: [Signature]DATE: 05/01/18 @ 1410REMARKS: 5 days
Resurvey 6x point

Confirm & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: [Signature]Date: 7/1/18

Nett 7,012.00

GST 490.84

Total Payable

7,502.84

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 January 2018 3:20 PM
To: 'Lauro Araos Songcuan Jr'; Rasul (LKKAUTO); SUR
Cc: Yusof Bin Hashim; Loi Ai Ting; Tay Jian Ye
Subject: RE: SLF2119E (MIT) - FINALISE

Dear Larry,

Confirm finalized amount of **\$5,658.00** before Gst for SLF2119E

No of days: 5 days

Final invoice and all supporting documents sent to ERGO Insurance

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr [mailto:lauro.songcuan@cyclecarriage.com.sg]
Sent: Wednesday, 24 January 2018 2:49 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: SLF2119E (MIT) - FINALISE

Dear Rasul,

Pls. refer to attached files and photos.

Kindly confirm finalized amount of **\$ 5,658.00** before Gst for SLF2119E.

Thank you so much.

Best regards,
Larry Songcuan
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any

views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



LKK
Rasul

VEHICLE NO : SLF2119 E

MODEL : MT/ATRAGE 1.2 CVT

WIP : 19230

Material	: \$	<u>2,733.00</u>
Labour	: \$	<u>2,925.00</u>
Sub-Total	: \$	<u>5,658.00</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>—</u>
Total	: \$	<u>5,658.00</u>
GST 7%	: \$	<u>396.06</u>
Grand Total	: \$	<u>6,054.06</u>
Finalise By/Date : <u>Larry on 24/01/18</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 days (wk. end)
= 7 days

* TP vehicle no: YN4692G (ERGO)

* GIA search fee \$200

* claim loss of use.

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLF2119E / 18/08/2016
#11-01 Mapletree Anson	Date In/Mileage 06/01/2018/ 110030
Singapore 079914	Chassis/Package MMBSTA13AHH001781
Contact No Mobile: 67420984	Engine No 3A92UDH3880
05/01/	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	24/01/2018/ 13:48	TLT	884 / Lauro Songcuan	19230

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

E PNT88000				1375.00
RENEW FRONT BUMPER , FRONT LH FENDER, REPAIR LH FRONT DOOR				
E PNT98000				1260.00
SPRAY PAINT FRONT BUMPER , FRONT LH FENDER, FRONT LH DOOR				
A 54900099				30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				
A 10028901				200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				
M SUNDRY				40.00
APPLY ANTI CORROSION ON AFFECTED PORTION				
M SUNDRY				20.00
SUNDRIES				
X FACE,FR BUMPER	1.00	696.00	00.00	696.00
X BRACKET,FR BUMPER,LH	1.00	13.00	00.00	13.00
X CLIP,FR BUMPER	10.00	3.00	00.00	30.00
X HEADLAMP ASSY,LH	1.00	654.00	00.00	654.00
X FENDER,FR LH	1.00	458.00	00.00	458.00
X SHIELD,FR WHEELHOUSE,LH	1.00	97.00	00.00	97.00
X CLIP,FR BUMPER	15.00	3.00	00.00	45.00
X MIRROR ASSY,DOOR,LH	1.00	632.00	00.00	632.00
X COVER,DOOR MIRROR,OTR LH	1.00	108.00	00.00	108.00
Z TEXT				
TP ERGO				
DOA: 02.01.2018				
SURVEYOR: RASUL 05.01.18				
5 DAYS REPAIR DAY				

Guarantee your warranty, maintain with Cycle & Carriage.

Parts	2,733.00	Nett	5,658.00
Labour	2,865.00	7% GST on	396.06
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,054.06
Sundry/Others	60.00		
Total(w/o GST)	5,658.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18000261/R1vbe2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 29-01-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4692G	Veh. Inspected	SLF 2119E
Policy No.		Coverage (\$)	0.00
Claim No.	YN4692G/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBSTA13AHH001781	Colour	WHITE
Odometer	110030	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R15	ROADSTONE	5 mm
L/H Front Tyre	185/55 R15	ROADSTONE	5 mm
R/H Rear Tyre	185/55 R15	ROADSTONE	5 mm
L/H Rear Tyre	185/55 R15	ROADSTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2018	Inspection Date	05/01/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2119E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	FACE, FR BUMPER (SN)	TORN	696.00	696.00
1	BRACKET, FR BUMPER, LH (SN)	NECESSARY	13.00	13.00
10	CLIP, FR BUMPER @\$3.00 (SN)	NECESSARY	30.00	30.00
1	HEADLAMP ASSY, LH (SN)	CRACKED	654.00	654.00
1	FENDER, FR LH (SN)	BENT	458.00	458.00
1	SHIELD, FR WHEELHOUSE, LH (SN)	DEFORMED	97.00	97.00
15	CLIP, FR BUMPER (FENDER SIDE) @\$3.00 (SN)	NECESSARY	45.00	45.00
1	MIRROR ASSY, DOOR, LH (SN)	MISSING	632.00	632.00
1	COVER, DOOR MIRROR, OTR LH (SN)	MISSING	127.00	108.00
			2,802.00	2,753.00
LABOUR				
TO RENEW FRT BUMPER, FRT LH FENDER, REPAIR LH FRT DOOR.			2,200.00	1,375.00
PAINT WORK SPRAY FRT BUMPER, FRT LH FENDER, FRT LH DOOR.			1,680.00	1,260.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.			50.00	30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
TO APPLY ANTI COROSSION ON AFFECTED PORTION.			80.00	40.00
			4,210.00	2,905.00
GRAND TOTAL			7,012.00	5,658.00

RECOMMENDED COST OF REPAIRS			5,658.00
------------------------------------	--	--	-----------------

Report Ref No. CS/EGI18000261/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.