

ASS. REC. BY:

REF: CS/MSG/17014843 / <sup>52</sup> range  
Special Instruction: Paper Survey

ASSIGNMENT (Office)

Surveyor

From (Person):

Elaine Ng

of

MSB

Date/Time: 04012018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SBY 33558

Insured:

FBI 3190C

at Workshop no/s

3H Auto

Yee Auto

Tel:

6589 3944

of

81k 1 sin ming

Ind Est

# 0113

Policy No:

MSD / VMS / 16-351035 -A

Claim No:

MSC/V/17-001174

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30072017

CA / REV / REP. / REV 24 HRS WP

10/8/2017 11-12pm

Owner Driving

H.O.D. Endorsement

Date/Time:

01082017 3:15pm

Person Contacted:

Junia

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SBY 33558 - X
	FBI 3190C - X
	Change wksp to Yee Auto
9.1.2018	Submit P/P \$1710, 3 days
	Red: \$4311.40, 72h

URGENT

09/01/2018 - To submit P/P 1710 - with 3 days of gr.

- No parts allowed. Only labour. Hence P/P submission.
- LKK surveyed on 10/08/2017 @ 181116 km. About 10 days after accident. Independent survey surveyed on 19/09/2017 @ 181906 km mileage. Vehicle travelled 790 km from LKK survey to independent survey. u/c unlikely to be damaged from accident.
- Furthermore, TP reported that vehicle was stationary when impact. So u/c unlikely to be exposed to torsional stress.

RECEIVED 09 JAN 2018

- Impact by motorcycle.
- Although u/c and rims were replaced. I am not allowing as <sup>any</sup> damage to u/c may not be related to this accident.






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17014843/M1vb-1		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 04-01-2018		
		Code : MSG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBL 3190C	Veh. Inspected	SBY 8855S	
Policy No.	MSD/VMS/16-351035-CA	Coverage (\$)	0.00	
Claim No.	MSC/V/17-001174	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	04/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/07/2017	Inspection Date	04/01/2018	
Survey held at	YEE AUTO SERVICE BLK 15, #01-107 SIN MING INDUSTRIAL ESTATE SINGAPORE 575673			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2017		01 Aug 2017 14:34 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b> IMRAN BIN ABDUL HAMID, ID: S6806776F, Tel: +6582563387									
<b>Main Claimant:</b> GAN KHENG SIONG, ID: S1686422F									
<b>Vehicle Reg. No.:</b> SBY8855S									
<b>Date of Loss:</b> 30/07/2017 00:00 - :59									
<b>Claim Type:</b> TP / MSC/V/17-001174									
<b>Policy/Cover Note No.:</b> MSD/VMS/16-351035-CA (TP, Fire & Theft) Coverage: 06/09/2016 - 05/09/2017									
<b>Vehicle Reg. No. (Insured):</b> FBL3190C									
<b>Policy No. (Claimant):</b>									
<b>Excess:</b>									
<b>Repairer:</b> Yee Auto Service (HQ) 160 Sin Ming Drive #02-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64575768									
<b>Handling Insurer:</b> MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 08/01/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (04/01/2018): Report Send Back Alerts - SBY8855S (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/07/2017 17:44
Date Of Accident	30/07/2017 15:55
Exact Location Of Accident	ALONG JIN EUNOS TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBY8855S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GAN KHENG SIONG
NRIC No	S1686422F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92336677
Alternative Phone No	OFFICE-92336677

### Vehicle Particulars

Manufacturer	MAZDA
Model	EVO 10-2.0 GSR (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1873492
Cover Note Number	

### Driver

Name of Driver	GAN KHENG SIONG
NRIC No	S1686422F
Date Of Birth	28/01/1965
Occupation	INDOOR
Date Of Driving Pass	29/05/1986
Driving Experience	31 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92336677
Fax Number	
Contact Number	OFFICE-92336677
Email Address	NOEMAIL

Address	BLK 132 GEYLANG EAST AVE 1 #03-239
Postcode	380132
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO STATEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL3190C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	IMRAN BIN ABDUL HAMID
NRIC/Passport Number	S6806776F
Contact Number	87831735
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	



# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan

JIN EUNUS ROAD

(A) 800 80000  
(B) 800 80000

# Common Statement

☐ Owner  
☐ Driver

## ACCIDENT STATEMENT

Date of Accident

Time

Location of Accident

30-07-2017 16:55pm ALONG JIN EUNDS TOWARDS PIE

### INSURED/ POLICY HOLDER (VEHICLE A)

Vehicle Registration Number

Name of Policyholder

NRIC/ FIN/ Passport/ ROC (If Policyholder is company)

Address

Contact Number

Occupation

SBV8855  
GAN KYONG SONG  
S1686221E

BK132 GEYLANG EAST AVE 1 #01-239 (S 380132)  
Tel 92336677

1. NOOK

### VEHICLE PARTICULARS (VEHICLE A)

Vehicle Make / Model

Type of Vehicle

Exact Purpose for which vehicle was being used at the time of accident

Are you claiming under your own insurance policy?

Vehicle category

☒ Sedan ☐ MPV, CRV, Van, Lorry, Bus ☐ Motorcycle, Others

PRIVATE USE

☐ Yes

☒ Private

☐ No

☐ Commercial

Remarks

☐ Third party

☐ Motorcycle

### INSURANCE COMPANY (VEHICLE A)

Name of Insurance Company

Type of Policy

Fleet Policy

Policy Number

AXA

☒ Comprehensive

☐ Yes

☐ No

☐ TP Fire & Theft

☐ No

☐ Third party

VPA/P1873V92

### DRIVER

Name of Driver

NRIC/ FIN/ Passport

Date of Birth

Occupation

Driving Pass Date

Gender

Contact Number

Address

Email Address

Was driver an employee of the Insured's Company?

If No, relationship of Driver with the Insured

Vehicle Number of Drivers Own Vehicle (if applicable)

Insurance of Drivers Own Vehicle (if applicable)

### GENERAL INFORMATION OF THE ACCIDENT

Type of Collision (E.g. Chain Collision/ Head-On, etc)

Weather Conditions

Road Surface

Damage Area

28-01-1965

11/06/02

29-05-1986

☒ Male

☐ Female

Tel 92336677

BK132 GEYLANG EAST AVE 1 #01-239 (S 380132)

☐ Yes

☒ No

OWNER

01

☒ TP

☐ Clear

☐ Wet

☐ Dry

☐ Others

☐ Others

☐ Yes

☐ Yes

☐ Yes

☐ Yes

☐ Yes

☐ Yes

☐ Yes

☐ Yes

☐ Yes

### OTHER INFORMATION

Was there any foreign vehicle(s) involved?

Was anybody injured in the accident? (Including Witness)

Was any other vehicle(s) or property damaged?

Was there any camera video footage (in car)?

### DETAILS OF POLICE ACTION

Was the accident reported to the Police?

If Yes, please state which police station & Report No.

Was notice of intended Prosecution given?

(Yes, against whom)



# Common Statement

OWN VEHICLE REGISTRATION NUMBER \_\_\_\_\_

## DETAILS OF OTHER VEHICLES OR PROPERTY DAMAGED

Other Vehicle or Property 1 (VEHICLE B)

Vehicle Registration Number

FBL 3190C

Vehicle Make/ Model/ Colour

Details of Properties (if Other Party is not a Vehicle)

Damage Area

Name of Driver

IMRAN BIN ABDUL HAMID

NRIC/ FIN/ Passport

S6806776F

Contact Number / Email Address

87831725

Address

Name of Insurance Company

Other Vehicle or Property 2

Vehicle Registration Number

Vehicle Make/ Model/ Colour

Details of Properties (if Other Party is not a Vehicle)

Damage Area

Name of Driver

NRIC/ FIN/ Passport

Contact Number / Email Address

Address

Name of Insurance Company

## DETAILS OF WITNESS

Name

Phone / Email Address

Address

NRIC/ FIN/ Passport

## DETAILS OF INJURED PERSON 1

Name

NRIC/ FIN/ Passport

Address

Approximate Age

Injuries Sustained

If Vehicle Occupants, state in which vehicle?

Were Seat Belts Worn?

☐ Yes

☐ No

Was Injured conveyed to hospital by ambulance?

☐ Yes

☐ No

## DETAILS OF INJURED PERSON 2

Name

NRIC/ FIN/ Passport

Address

Approximate Age

Injuries Sustained

If Vehicle Occupants, state in which vehicle?

Were Seat Belts Worn?

☐ Yes

☐ No

Was Injured conveyed to Hospital by Ambulance?

☐ Yes

☐ No

## Declaration

I/We declare that the above particulars & information provided above are true in every aspect

Signature of Policy Holder  
(Company Officer / Representative)

Date & Time

Signature of Driver / Date & Time  
(If Driver is not the Policy Holder)

Date & Time


## Individual Statement

### Describe Circumstances of the Accident

我駕駛在 JN Zones, 於正在停紅灯車輕  
在去 PIC, 當灯3正要行走就听到后面有撞到的  
感觉

### Declaration

I/We declare the foregoing particulars are true in every respect

  
Policyholder's Signature Date &  
Time

Driver's Signature (If driver is not the policyholder) Date  
& Time

  
Witnessed by Reporting Centre  
At & Other

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6422F
Vehicle Details	
Vehicle No.:	SBY8855S
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	EVO 10 GSR 2.0 M
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4B11AY6462
Chassis No.:	CZ4A0001093
Maximum Power Output:	206.0 kW (276 bhp)
Open Market Value:	\$28,468.00
Original Registration Date:	19 Dec 2008
First Registration Date:	19 Dec 2008
Transfer Count:	3
Actual ARF Paid:	\$28,468.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2018
PARF Rebate Amount:	\$14,234.00
Intended COE Rebate Details	

COE Expiry Date:	18 Dec 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$14,001.00
COE Rebate Amount:	\$1,321.00
<b>Total Rebate Amount:</b>	<b>\$15,555.00</b>

The information contained herein is correct as at 05 Jan 2018

OK

# PREMIER APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To :	Mr. Gan Kheng Siong	Our Ref. :	PT1709004-L
	c/o 160 Sin Ming Drive	Policy No. :	
	#02-17 Sin Ming Autocity	Claim No. :	
	Singapore 575722	Sum Insured :	
		Excess :	T/P Claim
		Date :	28th Sep 2017

Assigned By :	Mr. Gan Kheng Siong
Date of Assignment :	19th Sep 2017
Date of Accident :	30th July 2017
Date of Inspection :	19th Sep 2017
Name of Workshop :	Yee Auto Service
Place of Inspection :	160 Sin Ming Drive #02-17 Sin Ming Autocity
	Singapore 575722

Follow up inspections were also conducted.

### PARTICULARS OF VEHICLE

Registration No. :	SBY 8855 S	Odometer/km :	181906
Make/Model :	Mit. Lancer Evo 10 GSR 2.0M	Chassis No. :	CZ4A0001093
Type Of Body :	4 Door Saloon	Engine No. :	4B11AY6462
Year of Manuf./Regn. :	2008	Engine Cap. :	1997 cc
Colour :	Pearl Blue	Carrying Cap. :	4 Passengers

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake :	Serviceable	Body Work :	Good	Market Value :	N/A
Footbrake :	Serviceable	Paint Work :	Good	Scrap Value :	-
Steering :	Serviceable	Modifications :	None	Others :	-

### CONDITION OF TYRES

	Size	N/s - Tread Depth/Make	O/s - Tread Depth/Make
Front Tread :	265/35 - R18	5mm - Yokohama	5mm - Yokohama
Rear Tread (inner) :			
Rear Tread (outer) :	265/35 - R18	5mm - Yokohama	5mm - Yokohama

The above represent an estimated remaining life of the tyre treads in mm.

### POINT OF IMPACT/GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on the n/s rear portion.

The n/s rear fender, n/s rear door were dented. The rear bumper was chafed. The n/s rear wheel rim was dented/grazed. A computer wheel alignment check revealed that the n/s rear suspension has been misaligned as the result of the sustained impact.

For details of damages please refer to our schedule attached.

### REMARKS :

This survey was conducted strictly without prejudice.

*This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.*

# PREMIER APPRAISER SERVICES

Our Ref: PT1709004-L

Vehicle No: SBY 8855 S

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
NETT ITEMS:				
1	n/s taillamp	serviceable	S\$ 495.00	S\$ -
1	n/s rear fender	dented - repair	926.00	-
1	rear windscreen mldg	not required	188.00	-
1	n/s rear susp shock absorber	serviceable	680.00	-
1	n/s rear susp knuckle arm	damaged	888.00	888.00 NH
1	n/s rear susp lower arm	damaged	650.00	650.00 NH
1	n/s rear wheel bearings	damaged	480.00	480.00 NH
*1	n/s rear susp control arm	damaged	560.00	560.00 NH
*1	n/s rear susp toe control arm	damaged	468.00	468.00 NH
			S\$ 5,335.00	S\$ 3,046.00
		LESS 0%	-	10% 304.60
			5,335.00	2,741.40
S/NETT ITEMS:				
1	rear windscreen sealant	necessary	60.00	60.00 NH
1	n/s rear tyre	serviceable	500.00	-
1	n/s rear sport rim 18" - ENKEI - Japan	damaged	1,500.00	1,500.00 LR 300/-
	TOTAL S/PARTS		S\$ 7,395.00	S\$ 4,301.40
To remove/refit interior trims & garnish to assist repairs. (luggage & fender inner trims)			300.00	80.00 ✓
To remove/refit rear windscreen to assist repairs.			250.00	-
Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts. (S\$280.00 * 1.5 days)			1,500.00	420.00 ✓
To dismantle/replace damaged n/s rear suspension parts.			350.00	250.00 NH
To check & adjust wheel alignment & steering geometry. (before & after)			150.00	150.00 120/-
To check wiring functions.			80.00	30.00 NH
To putty, apply primer & spray-paint the affected areas. (n/s rear door, n/s rear fender & rear bumper)			1,400.00	750.00 ✓
To apply rust-proofing on repaired/replaced panels.			160.00	40.00 ✓
	TOTAL		S\$ 11,585.00	S\$ 6,021.40
* supplementary parts.				

Note: The repairer has agreed to undertake the repairs at our adjusted amount of S\$ 6,021.40 corresponding to supply of parts, labour and spray  
The estimated period of repairs is SIX ( 6 ) days.  
Pursuant to your instruction we have not authorised repairs on your behalf.

PREMIER APPRAISER SERVICES

LESLIE K C LIM CAE (UK), MIMI (UK)  
MSAAA, Automotive Appraiser  
Dip.MTM. Automotive Engineer



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jul 2017		01 Aug 2017 14:34 <a href="#">Edit Adj Rpt</a>	<b>S\$1,710.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,710.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured: <b>IMRAN BIN ABDUL HAMID</b> , ID: S6806776F, Tel: +6582563387									
Main Claimant: <b>GAN KHENG SIONG</b> , ID: S1686422F									
Vehicle Reg. No.: <b>SBY8855S</b>		Date of Loss: 30/07/2017 00:00 - :59							
Claim Type: <b>TP / MSC/V/17-001174</b>		Policy/Cover Note No.: MSD/VMS/16-351035-CA (TP, Fire & Theft) Coverage: 06/09/2016 - 05/09/2017							
Vehicle Reg. No. (Insured): <b>FBL3190C</b>		Policy No. (Claimant): Excess:							
Repairer: <b>Yee Auto Service (HQ)</b> 160 Sin Ming Drive #02-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64575768									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Elaine Ngu Siau Mei</b> - 6594 2540]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MA CHIN FOOK</b> ] ... [Final Rpt due 08/01/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (04/01/2018): Report Send Back Alerts - SBY8855S (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SBY8855S (MSC/V/17-001174)  
[FBL3190C]  
TP  
GAN KHENG SIONG  
Jul 30 2017 12:00AM  
[IMRAN BIN ABDUL HAMID]  
Yee Auto Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	14/08/17 11:21	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
2	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
3	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/08/17 18:30	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/08/17 18:32	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	01/08/17 13:56	MSIG Insurance (Singapore) Pte. Ltd. (HQ) SBY8855S GIA RPT	Load PDF	
2	18/08/17 11:19	Email to TP Lawyer on SJE - request for workshop details	Load PDF	
3	18/08/17 13:10	PRI Details	Load PDF	
4	03/11/17 16:31	TPD SBY8855S GIA REPORT	Load PDF	
5	03/11/17 16:31	PREMIER APPPAISER SERVICES REPORT - SBY8855S	Load PDF	

No	Relabel/Reorder		Thumbnail	Print
1	09/01/18 17:05	LKK Auto Consultants Pte Ltd (HQ) PRS INVOICE	Load PDF	

## Documents Checklist

[Reset](#)
[Save](#)
[Print](#)

**DOCUMENTS CHECKLIST**

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

---

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17014843/M1VBS2-1

Date: 09/01/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/16-351035-CA
Claimant Vehicle No :	SBY8855S	Insured Vehicle No :	FBL3190C
Date of Loss:	30/07/2017	Nature of Claim:	TP
		Claim No:	MSCN/17-001174

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SBY8855S	Engine No:	4B11AY6462
Make & Model:	MITSUBISHI EVO 10, 2.0 GSR (M)	Chassis No:	CZ4A0001093
Reg. Date:	19/12/2008 (Man. Year: 2008)	Odometer:	181116 km
Colour:	Blue		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	265/35R18	Rear Tyre Size:	265/35R18
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,395.00	300.00	7,095.00	95.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	1,410.00	2,780.00	66.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,585.00</b>	<b>1,710.00</b>	<b>9,875.00</b>	<b>85.24</b>

## INSPECTION

Date of Assignment:	01/08/2017	
Date Inspected:	10/08/2017 Inspected At:	Blk 1 Sin Ming Ind Est #01-115 Repairer: YEE AUTO SERVICE BLK 15, #01-107 SIN MING INDUSTRIAL ESTATE SINGAPORE 575673
Estimated Period of Repair:	3.0 days	

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2018)
<b>Parts:</b> 143	mitsubishi EVO 10 2.0 GSR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBY8855S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S TAILLAMP	Serviceable	495.00 F	*- FN
2	1		*N/S REAR FENDER	Repair	926.00 F	*- FN
3	1		*REAR WINDSCREEN MLDG	Not Required	188.00 F	*- FN
4	1		*N/S REAR SUSP SHOCK ABSORBER	Serviceable	680.00 F	*- FN
5	1		*N/S REAR SUSP KNUCKLE ARM	Not Necessary	888.00 F	*- FN
6	1		*N/S REAR SUSP LOWER ARM	Not Necessary	650.00 F	*- FN
7	1		*N/S REAR WHEEL BEARINGS	Not Necessary	480.00 F	*- FN
8	1		*N/S REAR SUSP CONTROL ARM	Not Necessary	560.00 F	*- FN
9	1		*N/S REAR SUSP TOE CONTROL ARM	Not Necessary	468.00 F	*- FN
10	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
11	1		*N/S REAR TYRE	Serviceable	500.00 FS	*- FS
12	1		*N/S REAR SPORT RIM 18 - ENKEI - JAPAN (LOCAL REPAIR)	Damaged	1,500.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,395.00</b>	<b>300.00</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>7,395.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE / REFIT INTERIOR TRIMS & GARNISH TO ASSIST REPAIRS. (LUGGAGE & FENDER INNER TRIMS)	New	300.00	80.00
2	TO REMOVE / REFIT REAR WINDSCREEN TO ASSIST REPAIRS.	New	250.00	0.00
3	LABOUR CHARGES TO REPAIR, PANEL BEAT AND STRAIGHTEN DAMAGED PARTS AND REPLACE THE ABOVE-MENTIONED PARTS.	New	1,500.00	420.00
4	TO DISMANTLE / REPLACE DAMAGED N/S REAR SUSPENSION PARTS.	New	350.00	0.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT & STEERING GEOMETRY. (BEFORE & AFTER)	New	150.00	120.00
6	TO CHECK WIRING FUNCTIONS.	New	80.00	0.00
7	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS. (N/S REAR DOOR, N/S REAR FENDER & REAR BUMPER)	New	1,400.00	750.00
8	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.	New	160.00	40.00
Gross Labour Cost (S\$)			<b>4,190.00</b>	<b>1,410.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;