

REF: NS / INC 18000299 / Sub 2

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
at Workshop m/s _____
of _____

Insured: GBC 6078Y

Policy No. BD607550911-04 D51017-041018

Claims No. MT/0976087-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 5518K Yr Regn: 25/7/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SsangYong Rodius C.C. 2696

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 475058 T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: KPTV 0131FSCPO68735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R16C
R: U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Max Miller

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/1/18 D.O.I. 4/1/18

Survey held at SMRT

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

SHB 5518K - P03/MS617007057/3/1/18 DA-170217 TAX/01/18/2009
GBC 6078Y X Ukr
NTUC

11/1/18 Sebastian Confirmed LS \$500 (Ref 1866-50, 7870)

RECEIVED 15 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 15/1-typist

Report Format :

Lump Sum / I.B.I. (\$) 500/2

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

160
35
195

Survey Department Check List (Case Handler)

Reference No. : NS/INC18000399/Svb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Y. Lion 12/11/18
 Case Handler Date

*C: Critical *N: Non-Critical



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000299/Svb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 05-01-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 6078Y	Veh. Inspected	SHB 5518K	
Policy No.	5060755094-04	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/01/2018	Inspection Date	04/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Monday, 15 January 2018 1:21 PM
To: Veron Chen (LKKAUTO)
Subject: RE: REQUEST FOR CLAIM NUMBER

Hi,

Claims created.

With Regards

Junainah

Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 15 January 2018 10:48
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0976087-002	SMRT TAXIS PTE LTD	SHB 5518K	GBC 6078Y
2	MT/0975954-002	SMRT TAXIS PTE LTD	SHB 695P	SLL 3671N

D.O.A	Time of Accident	Estimate	Tentative repair cost
2/1/2018	11:30	\$2,366.50	\$500.00
28/12/2017	21:40	\$8,598.00	\$2,700.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5060755094-04	KANNAN MARINE FOODS PTE LTD	200810678H	GCV	Comprehensive	GBC6078Y	GBC6078Y	05/10/2017	04/10/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB5518K

Vehicle to be Exported: No

Intended De-registration Date: 05 Jan 2018

Vehicle Make: SSANGYONG

Vehicle Model: RODIUS AUTO TAXI

Primary Colour: Beige

Manufacturing Year: 2011

Engine No.: 66592622546436

Chassis No.: KPTV0B1FSCP066735

Maximum Power Output: 121.0 kW (162 bhp)

Open Market Value: \$21,115.00

Original Registration Date: 25 Jul 2012

First Registration Date: 25 Jul 2012

Transfer Count: 0

Actual ARF Paid: \$21,115.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Jul 2020

PARF Rebate Amount: \$14,780.00

Intended COE Rebate Details

COE Expiry Date: 24 Jul 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$48,176.00

COE Rebate Amount: \$15,362.00

Total Rebate Amount: \$30,142.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2018 11:08
Date Of Accident	02/01/2018 11:30
Exact Location Of Accident	SYED ALWI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5518K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	SSANGYONG
Model	RODIUS SV270-2.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	JEFFREY TEO XIANG MING
NRIC No	S1510614Z
Date Of Birth	06/06/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/02/2002
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	22 MARSILING DRIVE 12 12-101
Postcode	730022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY TAXI WAS PARKED STATIONARY INSIDE THE PARKING LOT WHEN THE VEHICLE GBC6078Y WHILE REVERSING WANTED TO PARK INTO THE LOT WHICH IN FRONT OF MINE AND IT'S REAR PORTION HAD COLLIDED ONTO THE FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC6078Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

3/1/2018

3/1/2018

SKETCH PLAN

B - GBC 6078Y
A - SHR 5518K

500 ALUMI RAMP

5'

6'

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

NTUC G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5518K
Ref. No : TAX/01/18/2009
Reg. Date : 25/07/2012
Vehicle Type : TAXI
Make : SSANGYONG
Model : RODIUS-SV270
Name of Driver : JEFFREY TEO XIANG MING
Type of Accident : OTHERS
Date / Time of Accident : 02/01/2018 11:30:00 AM
Accident Reported Date / Time : 03/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093899
Special Instruction to ARC, if any :
GBC6078Y
Prepared Date : 03/01/2018 11:29:20 AM



Sebastian
4/1/18.
- Lump Sum Repair.
- Photo After Paint.
90036121
sebastian.yeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


8/1/18

Chassis No : KPTV0B1FSCP066735

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 473.00	0.00
Total Material Charges	: 1,019.16	1,019.16
Other Charges	: 140.00	0.00
TOTAL	: 1,970.16	0.00
Lum Sum Total	: 1,950.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days.
Arc / Surveyor Sing Off Date	: 03/01/2018 04:09:06 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/01/2018 04:08:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	473.00	0.00 200
Total Spray Painting & Panel Beating	473.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✕
TO WASH AND VACUUM	60.00	0.00 ✕
Total Other Costs	140.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7871A21 000	FRONT		FRT BUMPER ASSY	1	1,187.50	10.00	1,068.75	Replace	Replace <i>R</i>	No
79450210 10	FRONT		GRILLE ASSY- RADIATOR	1	228.00	10.00	205.20	Replace	Replace <i>✓ cut</i>	No
TOTAL MATERIALS								1,273.95	1,273.95	
TOTAL MATERIALS(Discounted)								1,019.16	1,019.16	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									


6-1-18/12:23
6-1-18/16:23

4-1-18/16:23

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5518K
Ref. No : TAX/01/18/2009
Reg. Date : 25/07/2012
Vehicle Type : TAXI
Make : SSANGYONG
Model : RODIUS-SV270
Name of Driver : JEFFREY TEO XIANG MING
Type of Accident : OTHERS
Date / Time of Accident : 02/01/2018 11:30:00 AM
Accident Reported Date / Time : 03/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093899
Special Instruction to ARC, if any :



GBC6078Y - NTUC IDAC 45
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121
LUMPSUM REPAIR

Prepared Date : 03/01/2018 11:29:20 AM

QC 6/1/18 13:20 PMS

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

n

Date

6-1-18

2nd witness

Date

Vehicle to Wega Date In: 5/1	Towing: _____
Time In: 11:00	Driver: DAT
Wega Job No: 01/0013	
Vehicle sent to SMRT Date In: 6-1-2018	Towing: _____
Time In: 11:00	Driver: _____
Received by (SMRT): _____	

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KPTV0B1FSCP066735

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	200.00
Total Spray Painting Charges	: 473.00	200.00
Total Material Charges	: 205.20	205.20
Other Charges	: 140.00	-105.20
TOTAL	: 1,156.20 2366.50	500.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 03/01/2018 04:09:06 AM	04/01/2018 03:39:21 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/01/2018 04:08:23 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-801-0208

Invoice No :

Quotation Date : 8/1

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	200.00 /
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	473.00	200.00 /
Total Spray Painting & Panel Beating	473.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-105.20
Total Other Costs	140.00	-105.20

2366.90

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7871A21000	FRONT		FRT BUMPER ASSY	1	1,187.50	100.00	0.00	Replace	Repair	No <i>R</i>
7945021010	FRONT		GRILLE ASSY-RADIATOR	1	228.00	10.00	205.20	Replace	Replace	No <i>ay</i>
TOTAL MATERIALS							205.20	205.20		
TOTAL MATERIALS(Discounted)							205.20	205.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

205.20 /
+ 200.00 /
+ 200.00 /

605.20 /
- 20%

484.16 /

US \$500/-

Sebastian
11/1/18


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No. 52983356E GST Reg. No. 20-0405911-H

Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18000299/Svbe2	
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 18-01-2018	
		Code: INC4	
1. Policy Particulars : THIRD PARTY CLAIM			
Insured Veh.	GBC 6078Y	Veh. Inspected	SHB 5518K
Policy No.	5060755094-04	Coverage (\$)	0.00
Claim No.	MT/0976087-002	Excess (\$)	0.00
Assign From		Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model	SSANGYONG RODIUS	c.c	2696
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KPTV0B1FSCP066735	Colour	WHITE
Odometer	475058	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/65 R16C	MAXMILER	6 mm
L/H Front Tyre	215/65 R16C	MAXMILER	6 mm
R/H Rear Tyre	215/65 R16C	MAXMILER	6 mm
L/H Rear Tyre	215/65 R16C	MAXMILER	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/01/2018	Inspection Date	04/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5518K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GRILLE ASSY-RADIATOR (DISC 10%)	CUT TO REPAIR	228.00	205.20
1	FRT BUMPER ASSY		1,187.50	-
			1,415.50	205.20
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.	NOT NECESSARY	418.00	200.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		473.00	200.00
	TO WASH AND VACUUM.		60.00	-
			951.00	400.00
GRAND TOTAL			2,366.50	605.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			500.00
---	--	--	---------------

Report Ref No. NS/INC18000299/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.