

22/03/2012

ASS. REC. BY:

REF: CS/MSG18000303/K1rd3n2 Special Instruction:

SUPERVISOR
Menmen

Kalvin

ASSIGNMENT (Office)

From (Person): Katherine Wong of MSG Date/Time: 4/01/2018 @ 4:33pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 4237S Insured: GBA 9563D

at Workshop m/s Comfort Delgro (L) Tel: 6214 8300

of 59 Layang Drive

Policy No: A288 4591MKC Claim No: 543529

Sum Insured: Excess:

Make of Veh: D.O.A. 02/01/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 8:20am @ 5/01/2017 Person Contacted: Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 4237S - NS / INC12024847 / H7vp D.O.A: 22/12/2012
	GBA 9563D - CS / LAW16011600 / A1bn2 D.O.A: 17/04/2015
	Sent preli through menmen

MSIG

ASSIGNMENT

SHD 42375

24 May 2012

Date 05/01/2018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SHD 42375

and Vehicle make Comfort Delgro

59 Loyang Drive

Insured

Policy No

Claims No

Sum Insured

Excess

Clients Record

Make of Van

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value

DAC Accident Report Consistent? Yes or No

GA / PR Seen Consistent? Yes or No

Est Repairs days Reso: Yes or No

Lift Sur % 3 Val: Yes or No

CA / REV / REP / 24 HRS 'wop'

Vehicle IN / OUT

Date Person Contacted

Veh No

Type M/Gar / M/Cycle / Bus / Van / Lorry / T6 / Prime Mover

Truck / Trailer or

Make

Hyundai Sonata

1991

Color

Blue

Ins Used / Std / NI / NA

St Reading

336757

TP Reso / Ins / Rad / Std / NI / NA

Eng No

ONo

1CMHET41RMCA825011

Gen Cond Good / Poor / Burnt

Steering Inc / Jammed / Leaked / Burnt or

Brake Inc / Jammed / Leaked / Burnt or

Mod Nil / S/Rim / STD / Dam or

Tyre Size

R

215 / 60 R16

R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PR / SUM

TOYO / YOKO or

Wst / Lke

Front

Rear

R.Bal

7

mm

R.Bal

7

mm

L.Bal

7

mm

L.Bal

7

mm

D.O.A

2/1/8

D.O.A

5/1/8

Survey held at

(PhE (17 ans))

Des of Damages: Frt / Rear / OS / NS / U/C / Roof top or

Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date Time

Action / Instruction

11/1/8

Condina / up \$3050 / 3 Rpt
Red is \$2078.62, 41%

4/5

RECEIVED 11 JAN 2018

Site Time / Rpt Recd



Prell. Report

typist



Final Report

Site Time / Rpt Recd

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transport

Labour

Tools

Other

Add Fee:



Site Fee



Travel



Technic



Access

Report Recd

tp

Summ Sum

3050

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2018		04 Jan 2018 16:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	COOLSERVE AIR-CONDITION ENGINEERING, Co. Reg. No.: 52812588E		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD4237S	Date of Loss:	02/01/2018 07:00 - :59
Claim Type:	TP / 543529	Policy/Cover Note No.:	A28845915MKC (Comprehensive) Coverage: 02/11/2017 - 01/11/2018
Vehicle Reg. No. (Insured):	GBA9563D	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2018]		
Driver/Custodian (Insured):	Kwan Tak Fook (), NRIC: G6680823N		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18000303/K1rd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 05-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 9563D		Veh. Inspected	SHD 4237S
Policy No.	A2884591MKC		Coverage (\$)	0.00
Claim No.	543529		Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)		Assign Date	05/01/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/01/2018		Inspection Date	05/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 11 Jan 2018

Preliminary Advice

Insured Vehicle No	: GBA9563D	Accident Date	: 02/01/2018
TP Vehicle No	: SHD4237S	Assignment Date	: 04/01/2018
Make	: MERCEDES-BENZ VITO	Est. Duration of Repair	: 3.00
Date of Inspection	: 05/01/2018		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,128.62
Revised Amount	:S\$	3,795.46
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,795.46

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 15:19
Date Of Accident	02/01/2018 06:40
Exact Location Of Accident	KG.AMPAT TWDS UPP PAYA LEBAR B4 BURN RD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4237S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	TAN LIEN CHAI
NRIC No	S1448467A
Date Of Birth	09/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	03/08/1978
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	TANLIENCHAI@GMAIL.COM

Address	46 #13-18 LAKESIDE DRIVE
Postcode	648324
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA9563D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KWAN TAK FOOK
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 25th 2018 (a) OF 40 km. I VEH A
was driving along Eg. Airport towards upp. Alberta.
B-4 Burn Rd. vehicle intent slow down and stop
I veh. A also slow down and stop. Suddenly Veh
B from rear hit Veh A Rear. At the point of
accident I veh. A ferry one female passenger
was ok went veh. A care her.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION INC.
CO REG NO 199003210

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 19930821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

255 Bras Basah Road Singapore 570701

Mainline + 65 6383 8280 Facsimile + 65 6260 9785

Workshops

29 Loyang Drive Singapore 508985

353 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609288

922 Raffles Road Singapore 509841

24 Serangoon Loop Singapore 758156

7 Bungei Kadu Way Singapore 728791

6 Delu Avenue 1 Singapore 539537

Date/Time: 02.01.2018 16:13

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305103027

COMER
IS COMFORT TRANSPORTATION PTE LTD
COMER NO 7010045
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO: SHD4237S	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 02.01.2018 09:25
YR OF MANU 24.05.2012	TARGET DATE
CHASSIS CODE KMHET41VMCA825011	COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 02.01.2018
NATURE: 3P 02.01.18

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHD4237S

LIMITS

Vehicle No.:

SHD4237S

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4237S

DATE 3/1/2018

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid — <i>sent</i>			\$ 1,349.50
	Boot Lid Rubber <i>X sur</i>			\$ 110.90
	Boot Lid Lock Upper <i>X sur</i>			\$ 132.10
	Boot Lid Lock Lower <i>X sur</i>			\$ 30.30
	Boot Lid Sonata Plate — <i>rec</i>			\$ 43.60
	Boot Lid Hyundai Plate — <i>rec</i>			\$ 24.20
	Boot Lid 'H' Emblem — <i>rec</i>			\$ 26.10
	Boot Lid CRDI Plate — <i>rec</i>			\$ 22.70
	Rear Bumper — <i>detached</i>			\$ 578.40
	Rear Bumper Reinforcement <i>2/ rec</i>			\$ 483.30
	Rear Bumper Clip — <i>rec</i>			\$ 22.00
	Rear Bumper Sponge <i>2/ for</i>			\$ 137.40
	Rear Bumper Under Cover <i>X sur</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X repair</i>	\$	38.00	\$ 76.00
	Rear Panel <i>X repair</i>			\$ 391.80
	Rear Panel Garnish <i>X sur</i>			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker — <i>rec</i>			\$ 30.00
	Boot Lid Advertisement Logo — <i>rec</i>			\$ 100.00
	Rear No. Plate <i>X sur</i>			\$ 25.00
	Rear Bumper Reverse Sensor — <i>should</i>			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH) — <i>rec</i>	\$	100.00	\$ 200.00
				\$ 490.70
	Labour Charge			
	Panel Beating			\$ 850.00 <i>600</i>
	Spray Painting Charge			\$ 600.00 <i>540</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
				\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,128.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirm
- Third party survey is only for third party's benefit
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305103027

Date : 09/01/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHD4237S

Date of Accident : 02-Jan-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG --- GBA9563D

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$3,050.00

Final Lumpsum Repair cost \$3,050.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 11/1/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: REAR BUMPER REINFORCEMENT & SPONGE - REPLACED

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000303/K1RD3N2

Date: 15/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28845915MKC
Claimant Vehicle No :	SHD4237S	Insured Vehicle No :	GBA9563D
Date of Loss:	02/01/2018	Nature of Claim:	TP
		Claim No:	543529

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4237S	Engine No:	D4EAA893415
Make & Model:	HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Chassis No:	KMHET41VMCA825011
Reg. Date:	24/05/2012 (Man. Year: 2012)	Odometer:	338753 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,458.62	2,615.46	843.16	24.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,180.00	490.00	29.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,128.62	3,795.46	1,333.16	25.99
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,128.62	3,050.00	2,078.62	40.53
+ GST 7.00/7.00% (S\$)	359.00	213.50	145.50	40.53
Nett Amount (S\$)	5,487.62	3,263.50	2,224.12	40.53

INSPECTION

Date of Assignment:	04/01/2018	
Date Inspected:	05/01/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2018)
Parts:	143	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4237S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,349.50 FL	*1,349.50 FL
2	1		*BOOT LID RUBBER	Serviceable	110.90 FL	*- FL
3	1		*BOOT LID LOCK UPPER	Serviceable	132.10 FL	*- FL
4	1		*BOOT LID LOCK LOWER	Serviceable	30.30 FL	*- FL
5	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
6	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
7	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
8	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
9	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
11	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
13	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*- FL
14	2		*REAR BUMPER PROTECTOR (LH/RH)	Repair	76.00 FL	*- FL
15	1		*REAR PANEL	Repair	391.80 FL	*- FL
16	1		*REAR PANEL GARNISH	Serviceable	95.80 FL	*- FL
17	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
18	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
19	1		*REAR NO PLATE	Serviceable	25.00 FS	*- FS
20	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
21	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
					Sub Total (\$\$)	4,200.60 3,152.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	741.98 537.44
					Total Parts (\$\$)	3,458.62 2,615.46

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	600.00
2	SPRAY PAINTING CHARGE	New	600.00	540.00
3	WIRING CHARGE	New	50.00	-
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
Gross Labour Cost (S\$)			1,670.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >