



Your Ref: C0422877

Date: 22nd February 2018

Our Ref: CS3/AXA17004190/R1qbs2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Ernest Tay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKE 9192M
INSURED VEHICLE: SFV 180B
ACCIDENT DATE: 24/02/2017**

We thank you for your instruction on 05/01/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKE 9192M from M/s Constant Appraiser Services.
- b) Final Repair Bill of SKE 9192M from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SKE 9192M.
- d) Colour damaged vehicle photographs of SKE 9192M.

Pre-Repair Inspection Date : 02/03/2017 at M/s Twincar Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKE 9192M
Make & Model	: Kia Optima 2.0 A
Year of Registration	: 2012
Chassis Number	: KNAGN411MC5214778
Engine Capacity	: 1998 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.