

1200/1000
ASS. REC. BY: REF: 02/MSG18000319 /Kvb
Survivor Kenneth
From (Person): Kathary Wong MSH MSH Date/Time: 03012018 8:45am

Estimated Cost: _____ Bill to: _____
OD / TP / WS / TP RES / OD RES / EVA / EV / MV / CS
To Inspect Vehicle No: SJD 5419D Insured: SJC 9883A
at Workshop m/s: Loh Heng Tel: 6453 2737
of 176 Sin Ming Drive #03-08
Policy No: 28888306TMP Claim No: 545754
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 31.12.2017
(Client's Record)
CA / REV / REP. / REV 24 HRS 'wpi' H.O.D. Endorsement: _____
Date/Time: 03012018 11:20am Person Contacted: Danny Vehicle: EXPLOUT
Date/Time: _____ Action/Instruction (✓) Estimate: _____
SJD 5419D x

REF: *MSG* ✓

Kenneth

STO 54190 Yr Recn: 03, 08

Veh No: 550 34190 Yr Recn: 03, 00

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes 5200 cc 1796

Colour A/C: Insured / Std / NI / NA

So Reading 2.85627 T/Radio: Insured / Std / NI / NA

End No:

C/Nb: WDB 2113612-B 111122

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD-A/Rlm or

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

Front _____ Rear _____

R/Sol. 5 mm R/Sol. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 31/1/12 D.O.I. 5/1/12

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

177 A/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/1	File pass to Cushman, not ready Not reporting, to other carb-in-dies.
24/4/18	Submit uneconomical TIL
25/4/18	Submit preli revised by merimen, vehicle TIL

RECEIVED 07 11 2006 432

☐ : Prel. Report
☐ : Final Report

Days Of Repair

Resurvey No. of Trip:

Survey Fee

DateTime: The Return to:

typist

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Transportation

1

Others

Report Earnist:

Lump Sum / L.B.T. / S.

2004



ANNOUNCING Hamilton Autohub Pte Ltd as sgCarMart Premium Dealer 2018

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2008, Honda Fit 1.3, \$9500. Owner Direct Sell.



Cheapest In The Market.
Direct Owner - StarAd



[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category

Sort by Date Posted

8 vehicles

mercedes e200

Advanced Search

Image	Name	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh
	Search Selection	mercedes e200	Any	Any	2008	Any	Any	
	Mercedes-Benz E-Class E200K Avantgarde		\$35,800	\$17,180 /yr	13-Aug-2008	1,796 cc	91,570 km	Li
Low Usage. Low Depreciation. Well Maintained Interior And Exterior. Smooth Engine And Transmission. Viewing Is Strictly By Appointment Please Call Our Friendly Sales Staff For A Viewing.								
Posted: 03-Jan-2018			Tags: 2008 Mercedes-Benz E200K, 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, E200K, Used Mercedes-Benz					
	Mercedes-Benz E-Class E200K Avantgarde		\$36,000	\$11,790 /yr	26-Nov-2008	1,796 cc	137,000 km	Li
1 Owner Only! Well Maintained! Quiet Engine And Smooth Transmission! View To Believe, Trade In Welcome, Flexible Loan/Insurance Avail. Us Now For An Appointment To View And Test Drive.								
Posted: 02-Jan-2018			Tags: 2008 Mercedes-Benz E200K, 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, E200K, Used Mercedes-Benz					
	Mercedes-Benz E-Class E200K		\$37,800	\$14,630 /yr	31-Oct-2008	1,796 cc	170,030 km	Li
Super Luxurious Drive With Very Impressive Condition! Best In Market! No Maintenance Upkeep Costing At All! Cheaper Than Rental! Own / Drive Away Immediately! Contact/SMS Our Friendly Sales Exec...								
Posted: 30-Dec-2017			Tags: 2008 Mercedes-Benz E200K, 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, E200K, Used Mercedes-Benz					
	Mercedes-Benz E-Class E200K		\$38,800	\$13,220 /yr	29-Dec-2008	1,796 cc		Li
From C&C Unit, Very Well Maintained! Perfect For Short Term Use Or Coe Renewal, Test Drive To Believe! Original Condition! Nice Interior & Body Paint Work, Consignment By Owner, Loan And Trade In...								
Posted: 18-Dec-2017			Tags: 2008 Mercedes-Benz E200K, 2008 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz E200K, E200K, Used Mercedes-Benz					

Car Buying

Car Selling

Car Aftermarket



Car Ownership

On The Move

Lifestyle



Mercedes-Benz E-Class E200 **\$32,000** **\$16,850 /yr** **17-Dec-2008** **1,796 cc** **167,000 km** **Li**

Good For Drive, Extremely Careful Owner!

Posted: 11-Dec-2017 Tags: 2008 Mercedes-Benz E200, 2008 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz E200, E200, Used Mercedes-Benz

Mercedes-Benz E-Class E200K Avantgarde (New 10-yr COE) **\$87,800** **\$8,780 /yr** **27-Feb-2008** **1,796 cc** **176,000 km** **Li**

C&C Unit, Regularly Serviced By Owner. Low Mileage, PARF \$28014, Body \$2800, 5 Years COE Renewal \$62,800 With Depreciation \$1046/h Than Car Rental, We Assist New Exterior Paintwork At \$800 On...

COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,670.00
COE Rebate Amount:	\$362.00
Total Rebate Amount:	\$21,232.00

The information contained herein is correct as at 08 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 16:03
Date Of Accident	31/12/2017 13:00
Exact Location Of Accident	CHIN SWEE TUNNEL ENTRANCE TO CTE TWDS SLE/TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD5419D
Insured/Policyholder	
Name Of Registered Owner	COMMUNICATION SERVICES PTE LTD
Co Reg No	197201203W
Email Address	MICHELLE.GOH@COMMSERV.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63728100

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 K A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MC003371
Cover Note Number	

Driver

Name of Driver	GOH KHENG RONG DEREK
NRIC No	S9733740C
Date Of Birth	29/09/1997
Occupation	INDOOR
Date Of Driving Pass	14/12/2015
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97656383
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 437 ANG MO KIO AVE 10 #20-1365
Postcode	560437
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR (AFTER RAIN)
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: MICHELLE GOH SIEW KIN
	GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC9883A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report ~~promptly~~ the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurers to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and this copy of the report will for a fee be made available upon application by interested parties.
7. By the signers of this report to the insurers, you hereby consent to the archiving of this report at the expense and in copies of the report being made available to interested parties.
8. **Consent under the Personal Data Protection Act (PDPA)**
I, undersigned, acknowledge, agree and consent that:
 - (a) My report, my witness and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this report and any other personal information provided by me as personal data/personal information ("Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Attorney General of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the mailing of correspondence, notices, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as the external cover of envelopes/leaf packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service provider or agent (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information(s) collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 2 Jan 2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA: 31/12/2017. 1.00p.m Chin Swee Tunnel (Bani) CTE tunnel
bicycle SLE/TPR. Weather condition: Roads were wet but it
was not raining.

I was driving into the tunnel behind the car that
caused the accident when he overtook a truck instant
at the back going into the tunnel. He was travelling out
about 70-80km/h when he lost control and skidded.
He hit the walls of the tunnel on both sides. The
truck stopped in time and managed to move out of
the way of the car. I came to a stop to see what
the car would do but the truck blocked my view. The
car went off their skid mark was facing the traffic but
after the truck moved out of the way, the car accelerated
and he smashed into the front left of my car.

No injuries noted ~~Attached~~ Attached Video of accident scene.

Veh A: STD5419D (victim)

Veh B: 95C 9883A

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Reporting Officer's Signature

Date & Time: 2 Jan 2018


Driver's Signature
(If driver is not the policyholder)




Reporting Officer's Signature
Name:
Unit/Station:

Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 16:03
Date Of Accident	31/12/2017 13:00
Exact Location Of Accident	CHIN SWEE TUNNEL ENTRANCE TO CTE TWDS SLE/TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD5419D
Insured/Policyholder	
Name Of Registered Owner	COMMUNICATION SERVICES PTE LTD
Co Reg No	197201203W
Email Address	MICHELLE.GOH@COMMSERV.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63728100

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 K A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MC003371
Cover Note Number	

Driver

Name of Driver	GOH KHENG RONG DEREK
NRIC No	S9733740C
Date Of Birth	29/09/1997
Occupation	INDOOR
Date Of Driving Pass	14/12/2015
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97656383
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 437 ANG MO KIO AVE 10 #20-1365
Postcode	560437
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR (AFTER RAIN)
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: MICHELLE GOH SIEW KIN
	GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SJC9883A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available interested parties.
8. Consent under the Personal Data Protection Act (PDPA)
I, the undersigned, acknowledge, agree and consent that:
(a) My insurer, my solicitor and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (hereby and any other personal information provided by me as) personal data by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Ministry of Justice of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claim (including the handling of correspondence, documents, invoices, reports or notices to me, which must involve disclosure of certain personal data about me to bring about delivery of the same as well as the external mail or envelopes and postages) and/or;
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
(e) the information so collected under (d) above may be shared / disclosed:
(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulation, laws or court orders.


Policyholder's Signature
Date & Time: 2 Jan 2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA: 31/12/2017, 1:00 p.m. Collin Swee Tunnel 'Pinn'. CDE family
towards SLE/TPR. Weather condition: Roads were wet but it
was not raining.

I was driving into the tunnel behind the car that
caused the accident when he overtook a truck instant
at the head going into the tunnel. He was travelling at
about 70-80 km/h when he lost control and skidded.
He hit the walls of the tunnel on both sides. The
truck stopped in time and managed to move out of
the way of the car. I came to a stop to see what
the car would do but the truck blocked my view. The
car was if that skid back was facing the truck but
after the truck moved out of the way, the car accelerated
and he smashed into the front left of my car.

No injuries noted ~~attached~~ Attached Video of accident scene.

Veh A: SJD5419D (victim)

Veh B: SJC 9883A

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Police Officer's Signature
Date & Time: 2 Jan 2018

 
Driver's Signature
(If driver is not the police officer)



 
Reporting Centre Personnel's Signature
Name:
Date: 2 Jan 2018

LOH HENG

Automotive Repair Services
Accident Insurance Claims

08-01-2018

MSIG Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : I Quotation
SJD5419D Mercedes

*Not Authorised
T/less*

S/N	Description	Amount (\$)
	Parts Replacement	
	Bonnet <i>B₁</i>	\$ 1,265.00 ✓
	Bonnet grille	\$ 342.00 ?
	Bonnet grille chrome	\$ 319.00 ?
	Bonnet catch	\$ <i>R</i> 132.00 X
	Top panel	\$ <i>B₁</i> 739.00 ✓
	Bonnet insulator	\$ <i>B₁</i> 268.00 ✓
	Headlamp left <i>B₂</i>	\$ 1,287.00 ✓
	Left side signal lamp	\$ <i>2</i> 84.00 X
	Horn	\$ <i>B₁</i> 198.00 X
	Headlamp moulding right <i>n/i</i>	\$ 129.00 —
	Front mudguard left <i>B₂</i>	\$ 792.00 —
	Front bumper <i>C/M</i>	\$ 928.00 —
	Front bumper reinforcement <i>B₁</i>	\$ 671.00 —
	Front bumper pad <i>C/M</i>	\$ 306.00 —
	Front bumper spine <i>C/M</i>	\$ 183.00 —
	Front bumper chrome center	\$ <i>n/a</i> 198.00 —
	No plate <i>B₁</i>	\$ 75.00 X
	bonnet lock <i>R</i>	\$ 187.00 X
	Radiator cowl	\$ 358.00 ?
	Radiator	\$ 845.00 ?
	Air con fan motor	\$ 472.00 ?
	Air con fan motor cover	\$ 236.00 ?
	Air con fan motor bracket	\$ 128.00 ?
	Air con condenser	\$ 893.00 ?
		\$ 11,035.00
	less 10%	\$ 9,931.50
	Labour Charges	
	Remove and replace front damage parts, cut and reweld front support panel mudguard etc.	\$ 1,600.00 <i>Joe</i>

LOH Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to Block 176 #03-08 Sin Ming Autocare
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by the insurer
- Is subject to final approval from insurer

Acknowledged by Repairer:

Signature:

Date:

Sin Ming Drive

Singapore 575721

Tel: 64532237 / 64530797

Fax: 64556334

LOH HENG

Automotive Repair Services
Accident Insurance Claims

Remove rear upholstery to facilitate repair	NV	\$ 100.00
Remove air con condenser, vacuum and refill air		\$ 180.00
Towing to workshop		\$ 60.00
To putty and respray on front damage area		\$ 1,300.00
Total:		\$ 13,171.50

X

100%

✓

100%

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2018		05 Jan 2018 08:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KANNIAPPAN SELVAKUMARAN , ID: S0147401D, Tel: +6590694832, Email: NOEMAIL									
Main Claimant: COMMUNICATION SERVICES PTE LTD , Co. Reg. No.: 197201203W									
Vehicle Reg. No.:	SJD5419D	Date of Loss:	31/12/2017 12:00 - :59 [117 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 543754	Policy/Cover Note No.:	28888306TMP (Comprehensive) Coverage: 08/03/2017 - 07/03/2018						
Vehicle Reg. No. (Insured):	SJC9883A	Policy No. (Claimant):							
		Excess:							
Repairer:	Loh Heng (HQ) 176 Sin Ming Drive, #03-08 Sin Ming Auto Care, 575721 Sin Ming - Tel: 64532237								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/02/2018]								
Driver/Custodian (Insured):	KANNIAPPAN SELVAKUMARAN (66 / Male), NRIC: S0147401D, Tel: +6590694832								
Adj Asg. Remarks:	please assign Mr Kenneth Kong to survey. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD5419D (543754)
[SJC9883A]
TP
COMMUNICATION SERVICES PTE LTD
Dec 31 2017 12:00PM
[KANNIAPPAN SELVAKUMARAN]
Loh Heng

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/01/18 12:18	Video - Accident From: SC - Reg. No: SJC9883A, Claimant: KANNIAPPAN SELVAKUMARAN		Load MP4	

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/01/18 14:00	Accident Statement From: SC - Reg. No: SJC9883A, Claimant: KANNIAPPAN SELVAKUMARAN		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/18 13:25	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/01/18 11:25	General View		Load JPG	☒
2	08/01/18 11:25	General View		Load JPG	☒
3	08/01/18 11:25	General View		Load JPG	☒
4	08/01/18 11:25	General View		Load JPG	☒
5	08/01/18 11:25	General View		Load JPG	☒
6	08/01/18 11:25	General View		Load JPG	☒
7	08/01/18 11:25	General View		Load JPG	☒
8	08/01/18 11:25	General View		Load JPG	☒
9	08/01/18 11:25	General View		Load JPG	☒
10	08/01/18 11:25	General View		Load JPG	☒
11	08/01/18 11:25	General View		Load JPG	☒
12	08/01/18 11:25	General View		Load JPG	☒
13	08/01/18 11:25	General View		Load JPG	☒
14	08/01/18 11:25	General View		Load JPG	☒
15	08/01/18 11:25	General View		Load JPG	☒
16	08/01/18 11:25	General View		Load JPG	☒

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/01/18 14:00	SJD5419D E-FILE REPORT From: SC - Reg. No: SJC9883A, Claimant: KANNIAPPAN SELVAKUMARAN		Load PDF	
2	04/01/18 14:01	TP PRI request		Load PDF	
3	04/01/18 17:38	TP agreed on common SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000319/KVBQ2

Date: 25/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28888306TMP

Claimant Vehicle No: SJD5419D

Insured Vehicle No: SJC9883A

Date of Loss: 31/12/2017

Nature of Claim: TP

Claim No: 543754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD5419D

Make & Model: MERCEDES-BENZ E200K, 1.8 (A)

Engine No: 27195630865866

Reg. Date: 26/03/2008 (Man. Year: 2007)

Chassis No: WDB2110412B111682

Colour: Metallic Grey

Odometer: 285427 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17

Rear Tyre Size: 245/45 R17

Front Left Side: Continental 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,931.50	5,848.20	4,083.30	41.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,960.00	1,280.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,171.50	7,808.20	5,363.30	40.72
Approved Total (Overridden) (S\$)		0.00		
Nett Amount (S\$)	13,171.50	0.00	13,171.50	100.00

INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 05/01/2018 Inspected At:

Loh Heng (HQ)

176 Sin Ming Drive, #03-08 Sin Ming Auto Care

Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$23,500.00
OMV : \$41,741.00
PARF Rebate (1) : \$20,870.00
Quota Premium Paid : \$18,670.00
COE Rebate (2) : \$362.00
Total Rebate (1) + (2) = : \$21,232.00

The total amount incurred will be Market Value \$23,500.00 minus Total Rebate \$21,232.00 = \$2,268.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$3,233.70 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts: 143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJD5419D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,265.00 FL	*1,265.00 FL
2	1		*BONNET GRILLE	*Check	342.00 FL	*- FL
3	1		*BONNET GRILLE CHROME	*Check	319.00 FL	*- FL
4	1		*BONNET CATCH	Repair	132.00 FL	*- FL
5	1		*TOP PANEL	Bent	739.00 FL	*739.00 FL
6	1		*BONNET INSULATOR	Serviceable	268.00 FL	*- FL
7	1		*HEADLAMP LEFT	Broken	1,287.00 FL	*1,287.00 FL
8	1		*LEFT SIDE SIGNAL LAMP	Serviceable	84.00 FL	*- FL
9	1		*HORN	Serviceable	198.00 FL	*- FL
10	1		*HEADLAMP MOULDING RIGHT	Missing	129.00 FL	*129.00 FL
11	1		*FRONT MUDGUARD LEFT	Buckled	792.00 FL	*792.00 FL
12	1		*FRONT BUMPER	Cracked	928.00 FL	*928.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	671.00 FL	*671.00 FL
14	1		*FRONT BUMPER PAD	Cracked	306.00 FL	*306.00 FL
15	1		*FRONT BUMPER SPONE	Cracked	183.00 FL	*183.00 FL
16	1		*FRONT BUMPER CHROME CENTER	Necessary	198.00 FL	*198.00 FL
17	1		*NO PLATE	Serviceable	75.00 FL	*- FL
18	1		*BONNET LOCK	Repair	187.00 FL	*- FL
19	1		*RADIATOR COWLING	*Check	358.00 FL	*- FL
20	1		*RADIATOR	*Check	845.00 FL	*- FL
21	1		*AIR CON FAN MOTOR	*Check	472.00 FL	*- FL
22	1		*AIR CON FAN MOTOR COVER	*Check	236.00 FL	*- FL
23	1		*AIR CON FAN MOTOR BRAKET	*Check	128.00 FL	*- FL
24	1		*AIR CON CONDENSER	*Check	893.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,035.00	6,498.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,103.50	649.80

Total Parts (\$\$)	9,931.50	5,848.20
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REPLACE FRONT DAMAGE PARTS ,CUT AND REWELD FRONT SUPPORT PANEL MUDGUARD ETC	New	1,600.00	800.00
2	REMOVE REAR UPHOLSTERY TO FACILITATE REPAIR	New	100.00	0.00
3	REMOVE AIR CON CONDENCER,VACUUM AND REFILL AIR	New	180.00	100.00
4	TOWING TO WORKSHOP	New	60.00	60.00
5	TO PUTTY AND RESPRAY ON FRONT DAMAGE AREA	New	1,300.00	1,000.00
Gross Labour Cost (\$\$)			3,240.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >