

CASE OWNER:

Benne

CC 6 / AIG18000325 / UKS 352

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MARCUS

DOI:

05/01/18

Date / Time:

05/01/18

Registered in Merimen:

05/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBC 5624C

Claim No.:

038683689056

Name of Insured:

STUE PTE LTD & /OR DHL EXPRESS
(SINGAPORE) PTE LTD

Policy No.:

Insured Tel No.:

HP: 9726 7251

Make / Model:

MERCEDES-BENZ 3600I/3665

Excess Sec II :SS

D.O.A: 29/12/17

Place of Accident:

12 CHANGI SOUTH ST 2 (DHL AIR
EXPRESS CENTRE)

Is driver the owner?

(YES ☒ NO ☐)

Nature of Accident:

If NO, Driver Name / Age:

JUSRIANDI BIN MODAKIR

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9677 6458

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SJH 4475B



INSRS:

WSP: Focus Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	7 11012018
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	() days Reduction: %
		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:
Repair Cost: (WURST)	SS 1,819.00	
Loss of Rental (LOR):	SS 500.00	(5 days) x \$100.00
Loss of Use (LOU):	SS -	(\$ x days)
Loss of Income (LOI):	SS -	(\$ x days)
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)
GIA/LTA Search	SS 7.45	
Medical:	SS -	
Disbursement:	SS -	(e.g. Tow/ Independent)
Total Cost	SS -	
Total:	SS 2,326.45	Global Sum SS: 2,320.00
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 2,320.00	Name 1: Focus Auto Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT
01/02/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18000325/Uks3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 5624C	Veh. Inspected	SJH 4475B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/12/2017	Inspection Date	05/01/2018	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 6419 3000 FAX: 6835 7416
ATTN: Motor Claim Department
Your Ref No: SJH4475B
Claim Type: Third Party
Accident Date: 29-12-2017
TP Veh Reg No: GBC5624C

Estimate No: EST0000556
Date: 10 Jan 2018
Policy No: DMHCSN16846241600
Veh Reg No: SJH4475B
Make/Model: HONDA FIT
Chassis No: GE61076741
Engine No: L13A4085847
Reg. Date: 07-08-2008

Estimate Repair Cost to Vehicle No :SJH4475B

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
HONDA FIT 1.3A				
List Price				
1 Front Bumper	523.20	1 PC	523.20	α
2 Front Bumper Side Retainer	18.60	1 PC	18.60	α
3 Front Fender LH	352.20	1 PC	352.20	α
4 Front Fender Dust Cover LH	67.40	1 PC	67.40	α
5 Front Fender Dust Cover Clipse	5.50	6 PC	33.00	α
6 Front Door LH	722.20	1 PC	722.20	α
7 Front Door Check LH	58.00	1 PC	58.00	α
8 Front Hinges (Lower & Top)	52.00	2 PC	104.00	α
			1,878.60	1226.8
	Less 20%		375.72	981.44
				1,502.88
Labour				
9 Panel Beating	850.00	1 PC	850.00	400
10 Check Wiring	60.00	1 PC	60.00	30
11 To Alignment	50.00	1 PC	50.00	α
12 Rust Proofing	60.00	1 PC	60.00	α
13 To Remove & Replace Door Assy	80.00	1 PC	80.00	60
14 To Spray Painting	750.00	1 PC	750.00	600
			1,850.00	1,850.00
			Total	SS 3,352.88

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED FIFTY TWO AND CENTS EIGHTY EIGHT

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
Tel: 66349695
AUTHORISED SIGNATURE

Not Authorised
n/s \$1700
3 day.
The ph. After rep.

2131.44

Zaini (LKK Auto)

From: Focus Auto <focus.autopteltd@yahoo.com.sg>
Sent: Monday, 29 January 2018 10:01 AM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: Re: Your Ref: GBC5624C Our Ref: SJH4475B_DOA: 29/12/2017 ALONG DHL AIR EXPRESS CENTRE WAREHOUSE GROUND FLOOR AT ABOUT 1400 HOURS *** LKK REF - CC6/AIG18000325/Uks3

Follow Up Flag: Follow up
Flag Status: Completed

Dear Zaini,

Thanks for your email.

We agreed to the offer \$2,320.00 (all-in) as stated.

Please enclose us the DV

Thank You

Best Regards
Laura

Focus Auto Pte Ltd
No. 1 Kaki Bukit Avenue 6
#02-50 AutoBay Singapore 417883
Tel: 6886 9097 Fax: 6481 9095

On Monday, 29 January 2018, 9:25, Zaini (LKK Auto) <Zaini@lkkauto.com> wrote:

WITHOUT PREJUDICE

Your Ref: SJH4475B
Our Ref: CC6/AIG18000325/Uks3

Dear Laura,

ACCIDENT INVOLVING GBC 5624C & SJH 4475B ON 29/12/2017

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 2,320.00(all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jan 2018 Edit Reg		05 Jan 2018 00:00 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	STVE PTE LTD &/OR DHL EXPRESS, Co. Reg. No.: 198703585C, Tel: +6597267251		
Main Claimant:	PAYLESS AUTOFLEET RENTAL, Co. Reg. No.: 53039146E		
Vehicle Reg. No.:	SJH4475B	Date of Loss:	29/12/2017 00:00 - :59
Claim Type:	TP / 0386836880SG	Policy/Cover Note No.:	(Third Party Only)
Vehicle Reg. No. (Insured):	GBC5624C	Policy No. (Claimant):	DMHCSN16846241600
		Excess:	
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/01/2018]		
Driver/Custodian (Insured):	JUSRIANDI BIN MODAKIR (), NRIC: S7726929J		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (05/01/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJH4475B (0386836880SG)**
[GBC5624C]
TP
PAYLESS AUTOFLEET RENTAL
Dec 29 2017 12:00AM
[STVE PTE LTD &/OR DHL EXPRESS]
Focus Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/18 12:52	Odometer Reading	 Load JPG	☒
2	06/01/18 12:52	General View	 Load JPG	☒
3	06/01/18 12:52	Chassis Number	 Load JPG	☒
4	06/01/18 12:52	General View	 Load JPG	☒
5	06/01/18 12:52	General View	 Load JPG	☒
6	06/01/18 12:52	General View	 Load JPG	☒
7	06/01/18 12:52	General View	 Load JPG	☒
8	06/01/18 12:52	General View	 Load JPG	☒
9	06/01/18 12:52	General View	 Load JPG	☒
10	06/01/18 12:52	General View	 Load JPG	☒
11	06/01/18 12:52	General View	 Load JPG	☒
12	06/01/18 12:52	General View	 Load JPG	☒
13	06/01/18 12:52	General View	 Load JPG	☒
14	06/01/18 12:52	General View	 Load JPG	☒
15	06/01/18 12:52	General View	 Load JPG	☒
16	06/01/18 12:52	General View	 Load JPG	☒
17	06/01/18 12:52	General View	 Load JPG	☒
18	06/01/18 12:52	General View	 Load JPG	☒
19	06/01/18 12:52	General View	 Load JPG	☒
20	06/01/18 12:52	General View	 Load JPG	☒
21	06/01/18 12:52	General View	 Load JPG	☒
22	06/01/18 12:52	General View	 Load JPG	☒
23	06/01/18 12:52	General View	 Load JPG	☒
24	06/01/18 12:52	General View	 Load JPG	☒
25	06/01/18 12:52	General View	 Load JPG	☒
26	06/01/18 12:52	General View	 Load JPG	☒
27	06/01/18 12:52	General View	 Load JPG	☒
28	06/01/18 12:52	General View	 Load JPG	☒
29	06/01/18 12:52	General View	 Load JPG	☒
30	06/01/18 12:52	General View	 Load JPG	☒

31	06/01/18 12:52	General View	1	Load JPG	✓
32	06/01/18 12:52	General View	1	Load JPG	✓
33	06/01/18 12:52	General View	1	Load JPG	✓
34	06/01/18 12:52	General View	1	Load JPG	✓
35	19/01/18 08:30	Reinspection Photo	1	Load JPG	✓
36	19/01/18 08:30	Reinspection Photo	1	Load JPG	✓
37	19/01/18 08:30	Reinspection Photo	1	Load JPG	✓

Documentation

1 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/18 09:09	TP GIA REPORT	1	Load PDF	
2	30/01/18 16:11	TP ESTIMATE - MARKED.	1	Load PDF	
3	06/02/18 09:27	AUTHORISATION TO ACT	1	Load PDF	
4	06/02/18 09:27	LETTER TO OI	1	Load PDF	
5	06/02/18 09:27	LTA SEARCH	1	Load PDF	
6	06/02/18 09:27	RELEASE VOUCHER	1	Load PDF	
7	06/02/18 09:27	RENTAL RECEIPT	1	Load PDF	
8	06/02/18 09:27	WORKSHOP INVOICE	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/01/18 16:07	OI GIA report	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBC5624C (Insd veh)	Model:	HONDA FIT 1.3 G (A)
	SJH4475B (TP veh)		
Date of Accident:	29/12/2017		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No
Repair Estimate	:	\$			3,587.58
Final Repair Cost	:	\$			2,320.00
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$			5 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$			2,320.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :			Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :			BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)			Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Focus Auto Pte Ltd	:	\$ 2,320.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

06 Feb
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18000325/UKS3S2
Date: 06/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJH4475B

Insured Vehicle No : GBC5624C

Date of Loss: 29/12/2017

Nature of Claim: TP Claim No: 0386836880SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH4475B	Engine No:	L13A4085847
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61076741
Reg. Date:	07/08/2008 (Man. Year: 2008)	Odometer:	156209 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,502.88	981.44	521.44	34.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,150.00	700.00	37.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,352.88	2,131.44	1,221.44	36.43
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	3,352.88	1,700.00	1,652.88	49.30
+ GST 7.00/7.00% (S\$)	234.70	119.00	115.70	49.30
Nett Amount (S\$)	3,587.58	1,819.00	1,768.58	49.30
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,326.45		
Global Sum Settlement (S\$)		2,320.00		

INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 05/01/2018

Estimated Period of Repair: 3.0 days

Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48 Autobay
Singapore 417883

Adjuster: MARCUS CHUA

Manager: Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	523.20 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	18.60 FL	*- FL
3	1		*FRONT FENDER LH	Dented	352.20 FL	*352.20 FL
4	1		*FRONT FENDER DUST COVER LH	Deformed / Torn	67.40 FL	*67.40 FL
5	6		*FRONT FENDER DUST COVER CLIPSE	Necessary	33.00 FL	*33.00 FL
6	1		*FRONT DOOR LH	Badly Dented	722.20 FL	*722.20 FL
7	1		*FRONT DOOR CHECK LH	Not Necessary	58.00 FL	*- FL
8	1		*FRONT HINGES (LOWER & TOP)	Top Bent	104.00 FL	*52.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	1,878.60	1,226.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	375.72	245.36
Total Parts (\$\$)	1,502.88	981.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	850.00	400.00
2	CHECK WIRING.	New	60.00	30.00
3	TO ALIGNMENT.	New	50.00	0.00
4	RUST PROOFING.	New	60.00	60.00
5	TO REMOVE & REPLACE DOOR ASSY.	New	80.00	60.00
6	TO SPRAY PAINTING.	New	750.00	600.00
Gross Labour Cost (S\$)			1,850.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >