

INSURANCE

INS. CASE OWNER:

MAHA/PRIMA

CC6 / III18000331 / Ahs3

LKK

IDAC

Surveyor:

ADRIAN

DOI:

02/01/18

Date / Time:

02/01/18

Registered in Merimen:

05/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 4335C

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A: 28/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: HENG KOK KUANH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

HCT1720981

Policy No.:

HCOH0015

Make / Model:

HYUNDAI I40

Place of Accident:

RALESTIER RD

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

% Final? Yes / No

STR 5830A



INSRS:

WSP: mg solution

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

05/01/18 (u.c)

\* NO ESTIMATE

\* CLAIM EACH OTHER

\* video footage is taken by Admin.

\* BOTH CLAIMING EACH OTHER. AFTER

HANDLED THE OTHER CASE (OTI)

25/01/18

FILE REOPENED. OI REPORTED HE WAS

LEFT. ENDED. TP REPORTED OI WADENAI

GUARDED IN STOPPED.

GETT LIABILITY IN OI COV POSTAGE.

OI COV IN WADENAI. V DENG/VIC/SHB4335C

NO TP COV.

TP COV IN. V DENG/VIC/STR 5830A

01/02/18

III AGREED RESTOR.

02/02/18

PERSONALISED TP COV TO III TO

RESTORED LIABILITY.

III WADENAI RESTOR. BUNK TO TP

PRELIMINARY ADVICE

Date/Time:

Sent By:

RESTOR.

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

7,100.00 (6 days) Reduction:

A3

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

—

(

days)

Loss of Use (LOU):

S\$

—

(5

x days)

Loss of Income (LOI):

S\$

—

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

—

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/Independent)

Legal Cost:

S\$

—

Total:

S\$

Global Sum S\$:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

RECEIVED 23 FEB 2018

REF:

## ASSIGNMENT

29/06/09

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJR5830A . Yr Regn: 2009 Jne

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato Forte cc 1591Colour: white A/C Insured / Std / NI / NASp. Reading: 152809 T/Radio Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAFH221385087.213Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. \_\_\_\_\_ D.O.I. 02/01/18Survey held at: MG SolatingDes. of Damages: Fr Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 111

L/G \$7,100.00

CASH: \$5,381.14 (A3%)

MV: 19K

PV: 9K

Nett: 10K.

Date/Time File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Tech. Insp: \$☐ Weekend: \$

Photo: \_\_\_\_\_

Other: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III18000331/Ahs3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 05-01-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SHB 4335C | Veh. Inspected | SJR 5830A  |
| Policy No.   |           | Coverage (\$)  | 0.00       |
| Claim No.    |           | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 05/01/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## 5. General Information

|                |                                                                                                                    |                 |            |
|----------------|--------------------------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 28/12/2017                                                                                                         | Inspection Date | 02/01/2018 |
| Survey held at | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

|                                           |                                 |          |              |
|-------------------------------------------|---------------------------------|----------|--------------|
| TO                                        | : INDIA INTERNATIONAL INSURANCE | DATE     | : 30/12/2017 |
| ATTENTION                                 | : MOTOR CLAIMS DEPT             | JOB TYPE | : T/P CLAIM  |
| ESTIMATE REPORT                           | :                               |          |              |
| <u>VEHICLE DETAILS</u>                    |                                 |          |              |
| VEHICLE NO                                | : SJR5830Z                      |          |              |
| MODEL                                     | : KIA CERATO FORTE 1.6A         |          |              |
| CHASSIS NO                                |                                 |          |              |
| <u>ACCIDENT DETAILS</u>                   |                                 | DATE     | : 28-Dec-17  |
|                                           |                                 | TIME     | : 14:30HRS   |
| THIRD PARTY REQUESTOR / CONTACT : JACK LI |                                 |          |              |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                 | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------------|-----|-----------------|------------------|
| 1   | BONNET <i>Painted</i>                       | 1   | \$ 788.00       | \$ 788.00        |
| 2   | BONNET RUBBER <i>Kit</i>                    | 1   | \$ 92.00        | \$ 92.00         |
| 3   | BONNET HINGE <i>Best</i>                    | 2   | \$ 55.00        | \$ 110.00        |
| 4   | BONNET LOCK <i>Painted</i>                  | 1   | \$ 130.00       | \$ 130.00        |
| 5   | BONNET LOCK CATCH <i>Ne n</i>               | 1   | \$ 80.00        | \$ 80.00         |
| 6   | FRONT BUMPER <i>Painted</i>                 | 1   | \$ 512.00       | \$ 512.00        |
| 7   | FRONT BUMPER SIDE RETAINER <i>ne</i>        | 2   | \$ 58.00        | \$ 116.00        |
| 8   | FRONT BUMPER LOWER GRILLE <i>Painted</i>    | 1   | \$ 120.00       | \$ 120.00        |
| 9   | FRONT BUMPER FOG LAMP <i>the ne</i>         | 2   | \$ 207.00       | \$ 414.00        |
| 10  | FRONT BUMPER FOG LAMP GARNISH <i>the ne</i> | 2   | \$ 98.00        | \$ 196.00        |
| 11  | FRONT BUMPER REINFORCEMENT <i>Best</i>      | 1   | \$ 328.00       | \$ 328.00        |
| 12  | FRONT BUMPER SPONGE <i>Painted</i>          | 1   | \$ 120.00       | \$ 120.00        |
| 13  | CENTRE GRILLE <i>Painted</i>                | 1   | \$ 238.00       | \$ 238.00        |
| 14  | CENTRE GRILLE CHROME <i>Painted</i>         | 1   | \$ 238.00       | \$ 238.00        |
| 15  | FRONT FENDER <i>Kit Buckled</i>             | 2   | \$ 537.50       | \$ 1,075.00      |
| 16  | FRONT FENDER INNER COWLING <i>the ne</i>    | 2   | \$ 139.60       | \$ 279.20        |
| 17  | HEADLAMP <i>Painted</i>                     | 2   | \$ 468.00       | \$ 936.00        |
| 18  | HEADLAMP LOWER BRACKET <i>the ne</i>        | 2   | \$ 55.00        | \$ 110.00        |

|    |                                     |   |           |           |   |
|----|-------------------------------------|---|-----------|-----------|---|
| 19 | AIR FILTER BOX <i>new</i>           | 1 | \$ 420.00 | \$ 420.00 | + |
| 20 | AIR FILTER DUCT <i>new</i>          | 1 | \$ 247.00 | \$ 247.00 | — |
| 21 | FRONT SUPPORT PANEL <i>restored</i> | 1 | \$ 688.20 | \$ 688.20 | — |
| 22 | HORN <i>new</i>                     | 2 | \$ 59.00  | \$ 118.00 | + |
| 23 | WIPER WASHER TANK <i>new</i>        | 1 | \$ 103.00 | \$ 103.00 | + |
| 24 | FRONT AIRCON CONDENSER <i>Best</i>  | 1 | \$ 822.00 | \$ 822.00 | ✓ |
| 25 | RADIATOR <i>Best</i>                | 1 | \$ 755.30 | \$ 755.30 | ✓ |
| 26 | RADIATOR SPARE TANK <i>new</i>      | 1 | \$ 98.00  | \$ 98.00  | + |
| 27 | RADIATOR FAN BLADE <i>new</i>       | 1 | \$ 79.90  | \$ 79.90  | + |
| 28 | RADIATOR FAN MOTOR <i>new - 2yd</i> | 1 | \$ 316.00 | \$ 316.00 | ✓ |
| 29 | RADIATOR FAN COWLING <i>new</i>     | 1 | \$ 105.00 | \$ 105.00 | ✓ |

7086

6377.40

TOTAL PRICE \$ 8,434.60

LESS 10% \$ 843.46

SUB TOTAL PRICE \$ 7,591.14

## SPECIAL NETT ITEMS

| S/N | DESCRIPTION                                | QTY | UNIT S/NETT | TOTAL S/NETT         |
|-----|--------------------------------------------|-----|-------------|----------------------|
| 1   | FRONT NUMBER PLATE <i>new</i>              | 1   | \$ 50.00    | \$ 50.00             |
| 2   | BONNET SEALANT <i>new</i>                  | 1   | \$ 80.00    | \$ 80.00             |
| 3   | FRONT BUMPER CLIP <i>new</i>               | 1   | \$ 20.00    | \$ 20.00             |
| 4   | FRONT BUMPER LID <i>new</i>                | 1   | \$ 850.00   | \$ <del>850.00</del> |
| 5   | CENTRE GRILLE LOGO <i>new</i>              | 1   | \$ 90.00    | \$ <del>90.00</del>  |
| 6   | CENTRE GRILLE STICKER <i>new</i>           | 1   | \$ 220.00   | \$ <del>220.00</del> |
| 7   | FRONT FENDER INNER COWLING CLIP <i>new</i> | 1   | \$ 20.00    | \$ 20.00             |
| 8   | RADIATOR COOLANT <i>new</i>                | 1   | \$ 80.00    | \$ <del>80.00</del>  |

790

TOTAL \$ 1,410.00

## CLAIM DETAILS: LABOUR AND SPRAY PAINTING ( FRONT )

|   |                                                     |                        |     |  |
|---|-----------------------------------------------------|------------------------|-----|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS          | \$ <del>1,600.00</del> | 800 |  |
| 2 | TO SPRAY PAINT AFFECTED AREA                        | \$ <del>1,400.00</del> | 800 |  |
| 3 | TUFF COAT                                           | \$ <del>150.00</del>   | 40  |  |
| 4 | WIRING CHECK                                        | \$ <del>50.00</del>    | 30  |  |
| 5 | REFOCUS HEADLAMP BEAM                               | \$ 80.00               | +   |  |
| 6 | REMOVE AND REFIX AIRCON CONDENSOR                   | \$ <del>120.00</del>   | 60  |  |
| 7 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | \$ <del>80.00</del>    | 60  |  |

1790

TOTAL

\$3,480.00

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 9,001.14

TOTAL LABOUR COST : \$ 3,480.00

TOTAL REPAIR COST : \$ 12,481.14

**APPROVED DETAILS**

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lim  
r/s 02/01/18.  
06 Days.  
Total: 855740  
h/s: 7.1K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                         |
|-------------------------------------|-----------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                         |
| Owner ID Type:                      | Singapore NRIC                          |
| Owner ID:                           | 6882I                                   |
| <b>Vehicle Details</b>              |                                         |
| Vehicle No.:                        | SJR5830A                                |
| Vehicle to be Exported:             | Yes                                     |
| Intended De-registration Date:      | 03 Jan 2018                             |
| Vehicle Make:                       | KIA                                     |
| Vehicle Model:                      | CERATO FORTE 1.6(A) SX ABS D/AB 2WD 4DR |
| Primary Colour:                     | White                                   |
| Manufacturing Year:                 | 2009                                    |
| Engine No.:                         | G4FC9H264236                            |
| Chassis No.:                        | KNAFH221395087213                       |
| Maximum Power Output:               | 92.7 kW (124 bhp)                       |
| Open Market Value:                  | \$14,114.00                             |
| Original Registration Date:         | 29 Jun 2009                             |
| First Registration Date:            | 29 Jun 2009                             |
| Transfer Count:                     | 3                                       |
| Actual ARF Paid:                    | \$14,114.00                             |
| <b>Intended PARF Rebate Details</b> |                                         |
| PARF Eligibility:                   | Yes                                     |
| PARF Eligibility Expiry Date:       | 28 Jun 2019                             |
| PARF Rebate Amount:                 | \$7,762.00                              |
| <b>Intended COE Rebate Details</b>  |                                         |
| COE Expiry Date:                    | 28 Jun 2019                             |
| COE Category:                       | A - Car (1600cc & below)                |
| COE Period(Years):                  | 10                                      |
| QP Paid:                            | \$8,489.00                              |
| COE Rebate Amount:                  | \$1,261.00                              |
| <b>Total Rebate Amount:</b>         | <b>\$9,023.00</b>                       |

The information contained herein is correct as at 03 Jan 2018



Fully Serviced, You Wouldn't Believe The Tip Top Condition Of This Unit Without Viewing It. No Financial Strain As We Provide In House Loans And Lower Financial Services To Meet Your Needs. Attractive...

[Details](#)

Posted: 17-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia



**Kia Cerato Forte 1.6A SX**

**\$18,500**

**\$8,270 /yr**

**18-Jun-2009**

**1,591 cc**

-

**Sedan**

**Available**

Highest Specs "SX" Model Forte 1.6A, Best Choice With Low Depreciation! Reasonable Mileage Done. Confirm No Repairs Needed. Fussy Malay Car Lover Owner. 100% Accident Free. Price Negotiable. Call Now!

Lake View Credit Pte Ltd

Posted: 31-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A**

**\$18,800**

**\$8,130 /yr**

**18-Jun-2009**

**1,591 cc**

**101,000 km**

**Sedan**

**Available**

Quality Preowned With Reasonable Mileage, In Tip Top Condition Interior And Exterior, Fuel Economy And Good Drivability! Call Us To View Today! Cycle & Carriage. Fulco Motor Dealer

Posted: 29-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A**

**\$18,500**

**\$7,920 /yr**

**18-Jun-2009**

**1,591 cc**

-

**Sedan**

**Available**

Vehicle Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA/VICOM/AA/IDAC Evaluation Friendly. Bank And In-House Loan Available. (Viewing Available Daily...

Allmotoring.sg

Posted: 25-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$19,800**

**\$8,800 /yr**

**19-Jun-2009**

**1,591 cc**

-

**Sedan**

**Available**

1 Owner Only! Accident Free! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To View And Discuss.

Posted: 29-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$17,200**

**\$6,840 /yr**

**29-Jun-2009**

**1,591 cc**

**176,000 km**

**Sedan**

**Available**

Very Well Maintained Unit By Fussy Owner. View To Believe It's Condition. All Wear And Tear Had Been Replaced. Rest Assured That This Car Will Serve You Well For The Next 1year 6months Without Any Wor...

Posted: 01-Jan-2018 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$18,800**

**\$7,920 /yr**

**29-Jun-2009**

**1,591 cc**

**145,000 km**

**Sedan**

**Available**

ROAD TAX TILL JUNE 2018! PIONEER DVD PLAYER! Rare White Color Kia Forte! Low Mileage! Black Sports Rims With 4 New Tyres! Very Sporty And Easy To Drive! Come Down Now And See For Yourself Before It's ...

Ka-Hup Vehicles Trading

Posted: 27-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$21,800**

**\$9,950 /yr**

**29-Jun-2009**

**1,591 cc**

-

**Sedan**

**Available**

Deposit \$4,000, Monthly \$900++, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 03-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 2.0A SX**

**\$21,800**

**\$9,330 /yr**

**29-Jun-2009**

**1,998 cc**

-

**Sedan**

**Available**

Well Maintained By 1 Owner. All Wear And Tear Replaced, Zero Repairs Required, New Around The Same Depreciation As A 1.6, Reliable Mid Range Sedan For Your Daily Use, Call Us To View And Feel The Diff...

Dosh Car

Posted: 20-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$20,222**

**\$8,670 /yr**

**30-Jun-2009**

**1,591 cc**

**135,298 km**

**Sedan**

**Available**

(100% Quality Buy!) 1st Owner Unit. Pre Owned From A Family Man, Selling Due To Upgrading. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA/V...

Sincere Motoring Pte Ltd

Posted: 01-Jan-2018 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$19,800**

**\$8,580 /yr**

**30-Jun-2009**

**1,591 cc**

**110,000 km**

**Sedan**

**Available**

1 Owner, Regularly Serviced And Maintained By Previous Owner. Low Mileage Done At 12000km A Year. Stock Condition. Pristine Condition. 100% Accident Free. Call Now For Viewing.

Posted: 31-Dec-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)


**Kia Cerato Forte 1.6A SX**

**\$19,000**

**\$8,030 /yr**

**01-Jul-2009**

**1,591 cc**

-

**Sedan**

**Available**

Lowest In The Market! Only \$3000 Down Payment With In House Loan Available. Free Servicing Package By Authorised Mechanic. No Gimmicks Or Fully Refund. High Quotation Given For Trade In At \$0 Down Pay...

Posted: 23-Nov-2017 Tags: 2009 Kia Cerato, 2009 Kia Cerato, Kia Cerato, Kia Cerato, Kia, Cerato, Cerato, Used Kia

[Details](#)

[Compare](#)



## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Friday, 2 February, 2018 11:47 AM  
**To:** MG Solution  
**Cc:** Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)  
**Subject:** Your Ref: SJR 5830A\_ACCIDENT INVOLVING VEHICLES SHB 4335C AND SJR 5830A ON 28/12/2017 LKK REF CC6/III18000331/Ahs3  
**Attachments:** SJR5830A.MP4

Without Prejudice

Dear Sharon,

ACCIDENT INVOLVING VEHICLES SHB 4335C AND SJR 5830A ON 28/12/2017

We refer to the subject matter.

We had forwarded your client's video footage to our principal for their further review.


Please be informed that we have our principal's instruction to deny your client's claim. Our principal is in the view that our Insured is not liable of this accident as it shows that your client had failed to maintain safety distance and rear-ended our Insured's vehicle. We also attached below a copy of our Insured's statement for your reference.

As such, we are unable to look further into your claim.

We will now close this matter.

Thank you.

## SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT A) SHB4335C B) SJS80A

As I was driving from Balestier Road towards Lander Street direction a car SJS 5830A hit my cab from the rear driven by Mr Tan. I hit my cab from the rear. There was 2 passengers in my cab during this time. There was no visible injury but they requested me to drive them to Tan Tock Seng Hospital for a check up.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Auto  
Consultants  
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Vic (LKKAUTO)

---

**From:** Manivel Priyadarshini <manivel@iii.com.sg>  
**Sent:** Friday, 2 February, 2018 11:07 AM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: Your Ref: MCT17120981\_Request/grant to access OI CCTV footage in merimen

Dear Vic,

We refer to your below email,

In view of both the party vehicle video footage confirms third party vehicle SJR5830A failed to maintain safe distance and rear ended into our insured vehicle SHB4335C. In view of the above please proceed to reject the claim.

Thank You

Priya

Motor claims Department

---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Friday, 2 February, 2018 10:53 AM  
**To:** Manivel Priyadarshini  
**Cc:** Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)  
**Subject:** RE: Your Ref: MCT17120981\_Request/grant to access OI CCTV footage in merimen

Dear Priya,

We refer to the above matter and to your rejection approval in merimen.

Please be informed that we had just received the TP video footage that shows the entire accident. Please see attached footage.

It was observed that Insured vehicle had slowed down and stopped with signal lights on to make a right turn from the middle lane as there was another vehicle that would like to make a right turn at the left most lane when rear-ended by TP vehicle.

We are of the opinion that TP failed to maintain safety distance and proper lookout to the vehicles in front.

Kindly confirm if we maintain our position and/or for your further instructions please.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 29 January, 2018 12:38 PM  
**To:** Manivel Priyadarshini  
**Cc:** Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)  
**Subject:** Your Ref: MCT17120981\_Request/grant to access OI CCTV footage in merimen

Your Ref: MCT17120981

Dear Priya,

Please grant us the right to access/view the OI Video footage in merimen for our further action.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.  
Registration No. 198703792-K

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 05 Jan 2018<br><a href="#">Edit Reg</a> |               | 02 Jan 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$7,100.00</b><br><a href="#">Edit Estimates</a> | <b>S\$7,100.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                          |
|-------------|------------------|----------------------|------------------|--------------------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <a href="#">Show All</a> |
|-------------|------------------|----------------------|------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS**

[Created by adjuster]

Insured: **COMFORT TRANSPORTATION PTE LTD.** Co. Reg. No.: 199303821R

Main Claimant: **TAN HAN HOE,** ID: S17868821

Vehicle Reg. No.: **SJR5830A** Date of Loss: 28/12/2017 00:00 - :59

Claim Type: **TP / MCT17120981** Policy/Cover Note No.: MCOM0015

Vehicle Reg. No. (Insured): **SH84335C** Policy No. (Claimant): DMPCSN3051421700

Excess:

Repairer: **MG Solution Pte Ltd (HQ)** 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931

Handling Insurer: **India International Insurance Pte Ltd (HQ)** - Tel: 63476100 ... [Handled by **Priya**]

Claimant's Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 16/01/2018]**

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

- III\_SG (01/02/2018): **Alert - Adj Mandate Approved (S\$0.00) - SJR5830A - Claim Handler: Priya**
- III\_SG (25/01/2018): **Alert - Adj Mandate Maintained - SJR5830A - Claim Handler: Priya**

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

**\*SJR5830A (MCT17120981)**  
**[SHB4335C]**  
**TP**  
**TAN HAN HOE**  
**Dec 28 2017 12:00AM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**MG Solution Pte Ltd**

|                  |                 |                                                                               |  |                    |  |                                                                                                |                                     |
|------------------|-----------------|-------------------------------------------------------------------------------|--|--------------------|--|------------------------------------------------------------------------------------------------|-------------------------------------|
| Upload Documents |                 | Upload Photos                                                                 |  | Compose New Letter |  | View <a href="#">View in Browser</a>                                                           |                                     |
| Video            |                 |                                                                               |  |                    |  | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No               | Finalized On    | India International Insurance Pte Ltd (HQ)                                    |  |                    |  | Thumbnail                                                                                      | Print                               |
| 1                | 29/01/18 13:46  | Video - Accident<br>From:TP BI - Reg. No: PASSENGER, Claimant: CHAN HWEE CHOO |  |                    |  |  Load MP4   |                                     |
| Photos/Images    |                 |                                                                               |  |                    |  | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                             |  |                    |  | Thumbnail                                                                                      | Print                               |
| 1                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |
| 2                | 22/02/18 15:59  | Chassis Number                                                                |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |
| 3                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |
| 4                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |
| 5                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG   | <input checked="" type="checkbox"/> |
| 6                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG  | <input checked="" type="checkbox"/> |
| 7                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 8                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 9                | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 10               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 11               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 12               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 13               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 14               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 15               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 16               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 17               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 18               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 19               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 20               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 21               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 22               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 23               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 24               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 25               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 26               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 27               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 28               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 29               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 30               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |
| 31               | 22/02/18 15:59  | General View                                                                  |  |                    |  |  Load JPG | <input checked="" type="checkbox"/> |

| 32                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
|----------------------|-----------------|--------------------------------------------|---|------------|-------------------------------------|
| 33                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 34                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 35                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 36                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 37                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 38                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 39                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 40                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 41                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 42                   | 22/02/18 15:59  | General View                               | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 43                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 44                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 45                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 46                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 47                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 48                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 49                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 50                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 51                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 52                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 53                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 54                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 55                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 56                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 57                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 58                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 59                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 60                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 61                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 62                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 63                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 64                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 65                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 66                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 67                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 68                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 69                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 70                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 71                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 72                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 73                   | 22/02/18 16:00  | Reinspection Photo                         | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| <b>Documentation</b> |                 |                                            |   | 1 per page | <input checked="" type="checkbox"/> |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          |   | Thumbnail  | Print                               |
| 1                    | 05/01/18 15:04  | TP GIA REPORT                              | 1 | Load PDF   |                                     |
| 2                    | 05/01/18 15:04  | OI GIA REPORT                              | 1 | Load PDF   |                                     |
| 3                    | 02/02/18 11:32  | EMAIL FROM III REJECT TP CLAIM             | 1 | Load PDF   |                                     |
| 4                    | 02/02/18 11:48  | EMAIL TO TP REJECT CLAIM                   | 1 | Load PDF   |                                     |
| 5                    | 22/02/18 16:31  | TP ESTIMATE - MARKED                       | 1 | Load PDF   |                                     |
| No                   | Finalized On    | India International Insurance Pte Ltd (HQ) |   | Thumbnail  | Print                               |
| 1                    | 08/01/18 08:55  | Singapore Accident Statement               |   | Load PDF   |                                     |





## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18000331/AHS3Q2

Date: 26/02/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SJR5830A Insured Vehicle No: SHB4335C  
 Date of Loss: 28/12/2017 Nature of Claim: TP Claim No: MCT17120981

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJR5830A  
 Make & Model: KIA CERATO FORTE, 1.6 SX (A) Engine No: G4FC9H264236  
 Reg. Date: 29/06/2009 (Man. Year: 2009) Chassis No: KNAFH221395087213  
 Colour: White Odometer: 152809 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 10,081.14        | 7,167.40        | 2,913.74        | 28.90        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 3,480.00         | 1,790.00        | 1,690.00        | 48.56        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>13,561.14</b> | <b>8,957.40</b> | <b>4,603.74</b> | <b>33.95</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>7,100.00</b> |                 |              |
| <b>(S\$)</b>                             | <b>13,561.14</b> | <b>7,100.00</b> | <b>6,461.14</b> | <b>47.64</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>949.28</b>    | <b>497.00</b>   | <b>452.28</b>   | <b>47.64</b> |
| <b>Nett Amount (S\$)</b>                 | <b>14,510.42</b> | <b>7,597.00</b> | <b>6,913.42</b> | <b>47.64</b> |

## INSPECTION

Date of Assignment: 02/01/2018  
 Date Inspected: 02/01/2018 Inspected At: MG Solution Pte Ltd (HQ)0.  
 23 Kaki Bukit Avenue 4 #02-03B, VICOM  
 Inspection Centre  
 Singapore 415933

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 26 Feb 2018)                                                                                                                                |
| <b>Parts:</b> 143                                            | KIA CERATO FORTE 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJR5830A) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

## Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *BONNET                          | Dented        | 788.00 FL   | *788.00 FL |
| 2   | 1   |          | *BONNET RUBBER                   | Cut           | 92.00 FL    | *92.00 FL  |
| 3   | 2   |          | *BONNET HINGE                    | Bent          | 110.00 FL   | *110.00 FL |
| 4   | 1   |          | *BONNET LOCK                     | Damaged       | 130.00 FL   | *130.00 FL |
| 5   | 1   |          | *BONNET LOCK CATCH               | Not Necessary | 80.00 FL    | *- FL      |
| 6   | 1   |          | *FRONT BUMPER                    | Deformed      | 512.00 FL   | *512.00 FL |
| 7   | 2   |          | *FRONT BUMPER SIDE RETAINER      | Necessary     | 116.00 FL   | *116.00 FL |
| 8   | 1   |          | *FRONT BUMPER LOWER GRILLE       | Deformed      | 120.00 FL   | *120.00 FL |
| 9   | 2   |          | *FRONT BUMPER FOG LAMP           | Not Necessary | 414.00 FL   | *- FL      |
| 10  | 2   |          | *FRONT BUMPER FOG LAMP GARNISH   | Not Necessary | 196.00 FL   | *- FL      |
| 11  | 1   |          | *FRONT BUMPER REINFORCEMENT      | Bent          | 328.00 FL   | *328.00 FL |
| 12  | 1   |          | *FRONT BUMPER SPONGE             | Cracked       | 120.00 FL   | *120.00 FL |
| 13  | 1   |          | *CENTRE GRILLE                   | Cracked       | 238.00 FL   | *238.00 FL |
| 14  | 1   |          | *CENTRE GRILLE CHROME            | Cracked       | 238.00 FL   | *125.00 FL |
| 15  | 1   |          | *FRONT FENDER                    | N/S Buckled   | 1,075.00 FL | *537.50 FL |
| 16  | 2   |          | *FRONT FENDER INNER COWLING      | Not Necessary | 279.20 FL   | *- FL      |
| 17  | 2   |          | *HEADLAMP                        | Cracked       | 936.00 FL   | *936.00 FL |
| 18  | 2   |          | *HEADLAMP LOWER BRACKET          | Not Necessary | 110.00 FL   | *- FL      |
| 19  | 1   |          | *AIR FILTER BOX                  | Not Necessary | 420.00 FL   | *- FL      |
| 20  | 1   |          | *AIR FILTER DUCT                 | Cracked       | 247.00 FL   | *247.00 FL |
| 21  | 1   |          | *FRONT SUPPORT PANEL             | Deformed      | 688.20 FL   | *688.20 FL |
| 22  | 2   |          | *HORN                            | Not Necessary | 118.00 FL   | *- FL      |
| 23  | 1   |          | *WIPER WASHER TANK               | Not Necessary | 103.00 FL   | *- FL      |
| 24  | 1   |          | *FRONT AIRCON CONDENSER          | Bent          | 822.00 FL   | *822.00 FL |
| 25  | 1   |          | *RADIATOR                        | Bent          | 755.30 FL   | *755.30 FL |
| 26  | 1   |          | *RADIATOR SPARE TANK             | Not Necessary | 98.00 FL    | *- FL      |
| 27  | 1   |          | *RADIATOR FAN BLADE              | Not Necessary | 79.90 FL    | *- FL      |
| 28  | 1   |          | *RADIATOR FAN MOTOR              | Damaged       | 316.00 FL   | *316.00 FL |
| 29  | 1   |          | *RADIATOR FAN COWLING            | Cracked       | 105.00 FL   | *105.00 FL |
| 30  | 1   |          | *FRONT NUMBER PLATE              | Cracked       | 50.00 FS    | *50.00 FS  |
| 31  | 1   |          | *BONNET SEALANT                  | Not Necessary | 80.00 FS    | *- FS      |
| 32  | 1   |          | *FRONT BUMPER CLIP               | Necessary     | 20.00 FS    | *20.00 FS  |
| 33  | 1   |          | *FRONT BUMPER LID                | Cracked       | 850.00 FS   | *600.00 FS |
| 34  | 1   |          | *CENTRE GRILLE LOGO              | Necessary     | 90.00 FS    | *50.00 FS  |
| 35  | 1   |          | *CENTRE GRILLE STICKER           | Necessary     | 220.00 FS   | *30.00 FS  |
| 36  | 1   |          | *FRONT FENDER INNER COWLING CLIP | Not Necessary | 20.00 FS    | *- FS      |
| 37  | 1   |          | *RADIATOR COOLANT                | Necessary     | 80.00 FS    | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)      11,044.60      7,876.00  
 - List Item Discount on L Items 10.00/10.00% (S\$)      963.46      708.60

Report was unsubmitted during this print-out.

| No.               | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|-------------------|-----|----------|-------------|-----------|------------|----------|
| Total Parts (S\$) |     |          |             |           | 10,081.14  | 7,167.40 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                         | Lab.Type | Repairer's | Amount   |
|-------------------------|-----------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                                     |          |            |          |
| 1                       | PANEL BEATING ,REMOVAL AND REPLACING PARTS          | New      | 1,600.00   | 800.00   |
| 2                       | TO SPRAY PAINT AFFECTED AREA                        | New      | 1,400.00   | 800.00   |
| 3                       | TUFF COAT                                           | New      | 150.00     | 40.00    |
| 4                       | WIRING CHECK                                        | New      | 50.00      | 30.00    |
| 5                       | REFOCUS HEADLAMP BEAM                               | New      | 80.00      | 0.00     |
| 6                       | REMOVE AND REFIX AIRCON CONDENSOR                   | New      | 120.00     | 60.00    |
| 7                       | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | New      | 80.00      | 60.00    |
| Gross Labour Cost (S\$) |                                                     |          | 3,480.00   | 1,790.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >