

ONE SINGAPORE 038987

ECICS LTD

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CS3/ICS18000333/R1d3e2 7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER Date: 20-04-2018

Code: ICS


Policy Particulars :- (THIRD PARTY CLAIM)

PRE-REPAIR INSPECTION REPORT

1.	. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SLH 3999P	Veh. Inspected	SKM 3460L			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	DMPU1700662H	Excess (\$)	0.00			
	Assign From	JANICE GOH	Assign Date	29/12/2017			
2.	. Vehicle Particulars & Condition						
	Make & Model	TOYOTA CORROLA ALTIS 1.6	c.c	1598			
	Engine No.	HIDDEN	Year of Reg.	2014			
	Chassis No.	MR053REH104000519	Colour	GREY			
	Odometer	79395 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	FAIR					
3. Conditions of Tyres							
		Size	Make	Balance			
	R/H Front Tyre	205/55Z R16	MICHELIN	6 mm			
	L/H Front Tyre	205/55Z R16	MICHELIN	6 mm			
	R/H Rear Tyre	205/55Z R16	MICHELIN	6 mm			
	L/H Rear Tyre	205/55Z R16	MICHELIN	6 mm			
4.	4. Description of Damages						

_	Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



Page No.:1 of 1

5.	General Information					
	Accident Date	22/12/2017	Inspect Date / Time	09/01/2018 (02:32 PM)		
	Survey held at	YAP LEE MOTOR				
		BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883				

5a. **Remarks**

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

Report Ref No. CS3/ICS18000333/R1d3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.