



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18000336/Uea3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 24-06-2020



ATTN: RICHARD ANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |             |                       |            |
|---------------------|-------------|-----------------------|------------|
| <b>Insured Veh.</b> | GBD 1728H   | <b>Veh. Inspected</b> | SKX 1784H  |
| <b>Policy No.</b>   | GA242776/1  | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | S8M006JS    | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | RICHARD ANG | <b>Assign Date</b>    | 05/01/2018 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | NISSAN SYLPHY (A) | <b>c.c</b>          | 1598       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2015       |
| <b>Chassis No.</b>      | MNTBBAB17Z0025052 | <b>Colour</b>       | BLUE       |
| <b>Odometer</b>         | 91195             | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD              |                     |            |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 195/60 R16  | BRIDGESTONE | 6 mm           |
| <b>L/H Front Tyre</b> | 195/60 R16  | BRIDGESTONE | 6 mm           |
| <b>R/H Rear Tyre</b>  | 195/60 R16  | BRIDGESTONE | 6 mm           |
| <b>L/H Rear Tyre</b>  | 195/60 R16  | BRIDGESTONE | 6 mm           |

### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

### 5. General Information

|                       |   |                        |            |
|-----------------------|---|------------------------|------------|
| <b>Accident Date</b>  | 02/01/2018  | <b>Inspection Date</b> | 05/01/2018 |
| <b>Survey held at</b> | YEW TEE AUTOMOBILE TECH PL<br>BLK 25 KAKI BUKIT ROAD 4<br>#01-61 SYNERGY @ KAKI BUKIT<br>SINGAPORE 417800 |                        |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>5 Working Days</b> |
|-------------------------------------|-----------------------|