

ASS. REC. BY:

REF: CS3/CT18000347/Sd302 Special Instructions

range & days

Supervisor:
Merimen

ASSIGNMENT (Office)

From (Person): Joel Goh

of

CTI

Date/Time: 05/01/2018 @ 4:26pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

F1060M

Insured:

GBC 6338Y

at Workshop m/s

Tune In Motor

Tel:

6753 4818

of Blk 1016 # 01-214 Yishun Ind. Prk A

Policy No: DMCKSN3029591702

Claim No:

SNM18D00056C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

08/01/2017 @ 12pm

H.O.D. Endorsement:

Date/Time: 4:33pm @ 05/01/18

Person Contacted:

Linda

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	F1060M-X
	GBC 6338Y-X
12/04/18	Rpm range 1.5k to 2k 3 days. 1.2k - 1.5k.
	Dismantle: 20/3/2018
	After repair: 2/4/2018

CTI

08/01/2017

F1060M

26/4/1982

Estimated Cost:

00 TP WS / TP RES / 00 RES / EVA / INV / MV

To inspect: 00410 F1060M

at Work: Tune In Motor

Bik 1016, #61-214 Yishun Ind. Pk A

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

Make of Vehicle:

12pm

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.



Bel on Market Value:

DAG Accident Report Consistent? Yes or No

GUA PP Seat Consistent? Yes or No

Est. Repair: 3 days Res: Yes or No

Lum Sum: \$ Val: Yes or No

OAT / REV / REP / 24 HRS (wp)

Date: Person Contacted: Vehicle IN / OUT

Date Time Action Instruction

bike out till Oct 2027

should be economical to repair.

RECEIVED 13 APR 2018

Date Time File Passed:



Prel. Report



Final Report

Date Time File Returned:

File Returned:

Report Number:

PRS

Date Time File:

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:



Sleeper: 3



Engine: 3



Gear: 3



Fuel: 3

Survey Fee:

Transport:

Fuel:

Food:

Tools:

Other:

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		05 Jan 2018 16:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S CGW CONSTRUCTION & ENGINEERING (S) PTE LTD , Co. Reg. No.: 199600614H		
Main Claimant:	LIM SWEE HEE , ID: S1427633E		
Vehicle Reg. No.:	F1060M	Date of Loss:	02/01/2018 19:00 - :59
Claim Type:	TP / SNM18D00056C02	Policy/Cover Note No.:	DMCVSN3029591702 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC6338Y	Policy No. (Claimant):	0081708211-14
		Excess:	S\$0.00
Repairer:	Tune In Motor. Com (HQ) Blk 1016 #01-214 Yishun Industrial Park A, 768758 Yishun - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2018]		
Driver/Custodian (Insured):	WEI YUJIANG (34 / Male), NRIC: G2088595K, Tel: +6598973673		
Adj Asg. Remarks:	NO ESTIMATE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7633E
Vehicle Details	
Vehicle No.:	F1060M
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	RXK1
Primary Colour:	Blue
Manufacturing Year:	1982
Engine No.:	13X001810
Chassis No.:	13X001810
Maximum Power Output:	-
Open Market Value:	\$0.00
Original Registration Date:	26 Apr 1982
First Registration Date:	26 Apr 1982
Transfer Count:	9
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,328.00
COE Rebate Amount:	\$5,088.00
Total Rebate Amount:	\$5,088.00

The information contained herein is correct as at 12 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2018 11:26
Date Of Accident	02/01/2018 19:20
Exact Location Of Accident	WOODLANDS AVE 12 EXIT (TURNING IN FROM SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	F1060M
Insured/Policyholder	
Name Of Registered Owner	LIM SWEE HEE
NRIC No	S1427633E
Email Address	LIMSWEEHEE@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96645014
Alternative Phone No	OTHERS-96645014
Vehicle Particulars	
Manufacturer	YAMAHA
Model	RXK1
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	0081708211-14
Cover Note Number	01/08/17 - 31/07/18
Driver	
Name of Driver	LIM SWEE HEE
NRIC No	S1427633E
Date Of Birth	06/11/1960
Occupation	INDOOR
Date Of Driving Pass	04/05/1983
Driving Experience	34 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96645014
Fax Number	
Contact Number	OTHERS-96645014
Email Address	LIMSWEEHEE@HOTMAIL.COM

Address	BLK 683B WOODLANDS DRIVE 62 #07-125
Postcode	732683
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC6338Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM SWEE HEE
Approximate Age	57
Injuries Sustain	
Injured person in which vehicle?	F1060M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 683B WOODLANDS DRIVE 62 #07-125
Postcode	732683

Sketch Plan

SKETCH PLAN

VEHICLE NO. _____

INSURER _____

DATE & TIME _____

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claim process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIACC Records Management Centre established by the General Insurance Association of Singapore (GIACC) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIACC") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (an insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIACC to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

(Driver's Signature
if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

Describe the accident circumstances in detail. Include the date, time, location, and a clear description of what happened. If there were any witnesses, include their names and contact information. If there was any damage to property or vehicles, describe it in detail. If there were any injuries, describe them in detail. If there were any other relevant details, include them.

Police Officer Report:

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

Under declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time

Driver's Signature
if driver is not the policyholder
Date & Time

Reporting Centre Personnel's Signature
 Name
 Title

☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()



**SINGAPORE
POLICE FORCE**



J/20180103/2113

1 of 2

Report No. J/20180103/2113

POLICE REPORT (NP299)

Police Station Of Origin
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE_737890
Tel No: 1800-7679999

Date/Time Report Made 03/01/2018 16:05	Vide Report No.	Station Diary No. 201
Name Of Informant LIM SWEE HEE	Address APT BLK 683B WOODLANDS DRIVE 62 #07-125 SINGAPORE 732683	
ID Type / ID No. NRIC NO / S1427633E	Contact No. Home/Office Mobile 96645014	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Carpenter	Sex Male	Age 57
Institution/School Name	Date of Birth 06/11/1960	Race Chinese
Date/Time Of Incident 02/01/2018 19:20	Location Of Incident SELETAR EXPRESSWAY SINGAPORE Woodlands Ave 12 exit, turning in from SLE	

Brief details.


On the 02/01/2018 at about 1920 hrs I was driving along Woodlands Ave 12 towards BKE when exiting Woodlands ave 12, I was on my motorcycle (F1060M) on the most left lane wanting to exit into Woodlands ave 12. It was just after the rain and the road was wet still.

When a lorry (GBC6338Y) was waiting in lane to exit woodlands ave 12 as well, the lorry was signaling when suddenly the lorry turn out . I tired to brake and my motorcycle self skidded as the floor was wet

Signature Of Officer Recording The Report: J / Sgt 2 JONATHAN LOW JIN HUA
Signature Of Interpreter: Not applicable
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Insp CHIEW YAN LIN Contact No.: 67910000

Signature Of Informant:
Date/Time: 03/01/2018 16:05
Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



J/20180103/2113

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20180103/2113

and I applied the brakes very hard. The lorry and my motorcycle did not collide at all.

after the mishap the lorry driver came down and we exchange particulars and agreed to settle the matter privately. However i decided to lodge a report for my own insurance claims purposes.

i also went to see a private doctor and was given 4 days of MC.

Signature Of Officer Recording The Report:

J / Sgt 2 JONATHAN LOW JIN HUA

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp CHIEW YAN LIN
Contact No.: 67910000

Signature Of Informant:

Date/Time:
03/01/2018 16:05

Classification Of Case:

Authentication Stamp



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2018		05 Jan 2018 16:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	M/S CGW CONSTRUCTION & ENGINEERING (S) PTE LTD , Co. Reg. No.: 199600614H		
Main Claimant:	LIM SWEE HEE , ID: S1427633E		
Vehicle Reg. No.:	F1060M	Date of Loss:	02/01/2018 19:00 - :59 [428 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00056C02	Policy/Cover Note No.:	DMCVSN3029591702 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC6338Y	Policy No. (Claimant):	0081708211-14
		Excess:	S\$0.00
Repairer:	Tune In Motor. Com (HQ) Blk 1016 #01-214 Yishun Industrial Park A, 768758 Yishun - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 16/01/2018]		
Driver/Custodian (Insured):	WEI YUJIANG (34 / Male), NRIC: G2088595K, Tel: +6598973673		
Adj Asg. Remarks:	NO ESTIMATE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***F1060M (SNM18D00056C02)**
[GBC6338Y]

TP

LIM SWEE HEE

Jan 2 2018 7:00PM

[M/S CGW CONSTRUCTION & ENGINEERING (S) PTE LTD]
Tune In Motor. Com

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)			Thumbnail		Print	
1	04/01/18 16:48	Accident Statement			Load HTM			
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)			Thumbnail		Print	
1	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
2	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
3	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
4	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
5	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
6	04/01/18 16:46	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail		Print	
1	13/04/18 09:30	LKK SURVEYOR PHOTO 1			Load PDF			
2	13/04/18 09:30	LKK SURVEYOR PHOTO 2			Load PDF			
3	13/04/18 09:30	LKK SURVEYOR PHOTO 3			Load PDF			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail		Print	
1	05/01/18 16:24	OI GIA REPORT			Load PDF			
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)			Thumbnail		Print	
1	04/01/18 16:45	Sketch Plan [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
2	04/01/18 16:45	Sketch Plan #2 [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
3	04/01/18 16:46	PR1 [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
4	04/01/18 16:46	PR2 [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	04/01/18 16:48	Accident Statement		
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	04/01/18 16:46	Accident Photo		
2	04/01/18 16:46	Accident Photo		
3	04/01/18 16:46	Accident Photo		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
4	04/01/18 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/01/18 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/01/18 16:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	04/01/18 16:45	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	04/01/18 16:45	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	04/01/18 16:46	PR1	 Load JPG	<input checked="" type="checkbox"/>
4	04/01/18 16:46	PR2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18000347/SD3E2

Date: 16/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3029591702

Claimant Vehicle
No: F1060MInsured Vehicle
No: GBC6338Y

Date of Loss: 02/01/2018

Nature of Claim: TP

Claim
No: SNM18D00056C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: F1060M

Make & Model: YAMAHA RXK, 135cc (M)

Engine No: HIDDEN

Reg. Date: 26/04/1982 (Man. Year: 1982)

Chassis No: 13X001810

Colour: Black

Odometer: 929344 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 8.0/90-18

Rear Tyre Size: 3.60-18

Front Left Side: Golden Boy 6 mm

Rear Left Side: Shinko 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 08/01/2018 Inspected At:

Tune In Motor. Com (HQ)
Blk 1016 #01-214 Yishun Industrial Park A
Singapore 768758

Estimated Period of Repair: 3.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,200.00 - \$1,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Apr 2018)

Parts: N/A YAMAHA RXK 135cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for F1060M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >