

354/Sjatz -5

ASSIGNMENT

Veh No: SLL 3813X Yr Regn: 1

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Sports van C.C

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 11786 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZTZ AHZGW 522304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~In~~order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2 25/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. D.O.I. 4/1/10

Survey held at Volkswagen Taxis

Des. of Damages : Frt / Rear / OTS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

8/1/15 : No 91A

Date/Time, File Pass to?

☐: Preli. Report

1) **Date/Time, File Return to?**

□: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$) S + RS, SI

☐ Interview (\$) Photos

☐ : Tech. Invs (\$	) Others
---	----------

☐ : Weekend (\$)

TOTAL