Remarks: Tanjin | REF: ATG | 371 | Ilea3

ASSIGNMENT

From: | Date: 05.02.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJZ 8823J

at Workshop m/s Performance

of 303 Alexandra Rd

Insured:

Policy No.:

Claims No.:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Gary

(Policy Condition) 10am owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SJZ8823J | Yr Regn: 2012 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 640 I | c.c 2979.

Colour: Black | A/C: Insured / Std / NI / NA

Sp.Reading: 19684. | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBALW320X0C79 8951

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/37R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	5/2/18 @ 2050

Survey held at PMC

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($) ☐ Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ($ + RS $)

(Photos

(Others

TOTAL