

22/03/2017

ASS. REP.

REF: CS3/MSG18000383 / (1b22

1/MSG  
Special Instruction:

Surveyor

GR

ASSIGNMENT (Office)

Meimen

From (Person):

Christina Wong

of

MSG

Date/Time:

5/01/2018 @ 6:20pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCL G291M

Insured:

GBG 7235H

at Workshop m/s

Car Body Repair

Tel:

9648 7632

of

B1K1004, Bkt Merah Lane 3 # 01-29

Policy No:

29034638 MKC

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03/01/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

9:03am @ 08/01/17

Person Contacted:

Song

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (X) Estimate

SCL G291M - X

GBG 7235H - X

Dismantle Part: 08012018

260317 6:44pm Email to Christina Wong thru Meimen.






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18000383/Gb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-01-2018		
		Code : MSG		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBG 7235H	Veh. Inspected	SCL 6291M	
Policy No.	29034638MKC	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	08/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	03/01/2018	Inspection Date	08/01/2018	
Survey held at	CAR BODY REPAIR BLK 1004 BUKIT MERAH LANE 3 #01-29 SINGAPORE 159720			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Act Assigned	Adj Spt	Ad Submitted	Ins Actified	Status
Main	04 Jan 2018		05 Jan 2018 18:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	THOMSON FOODSTUFF MANUFACTURING, Co. Reg. No.: 52858600M		
Main Claimant:	TAN GEK HUAY, ID: S1615531D		
Vehicle Reg. No.:	SCL6291M	Date of Loss:	03/01/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	29034638MKC Coverage: 11/10/2017 - 10/10/2018
Vehicle Reg. No. (Insured):	GBG7235H	Policy No. (Claimant):	
		Excess:	
Repairer:	Car Body Repair (HQ) BLK 1004 #01-29 BUKIT MERAH LANE 3, 159720 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/01/2018]		

ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			

ALL ASSOCIATED TASKS <input type="checkbox"/>										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Our Ref: CY(CBR)SCL6291M(PF/hh)  
(Please email to: helen@yoga-legal.com)

Your Ref: Your insured vehicle GBG7235H

5th January 2018

The Motor Claims Department  
**MSIG Insurance (Singapore) Pte Ltd**  
4 Shenton Way #21-01  
SGX Centre 2  
Singapore 068807

**By Email**

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
**ACCIDENT INVOLVING SCL6291M & GBG7235H ON 03/01/2018 @ 11:00 HRS ALONG**  
**CLEMENTI AVE 4 OPEN SPACE CARPARK**

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose M/s. Precision Appraisal Services to conduct a Pre-Repair inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. Car Body Repair  
Address : Block 1004 Bukit Merah Lane 3 #01-29  
Singapore 159720  
**Contact person** : **Mr. Ong Lian Song (Ah Song)**  
**Telephone number** : **96487632**  
**Fax number** : **62708258**

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a "single joint expert".

**If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.**

Yours faithfully,

  
**C. Yogarajah LLC**

c.c. client  
Tan Gek Huay  
c/o. M/s. Car Body Repair  
(By Fax)

**For Surveyor**

Please initial here after completion of pre-repair inspection.  
Thank you.

**Name:**  
**Signature:**

**Date & Time of Pre-repair inspection:**      /

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/01/2018 13:22
Date Of Accident	03/01/2018 11:00
Exact Location Of Accident	ALONG CLEMENTI AVE 4 OPENSOURCE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCL6291M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN GEK HUAY
NRIC No	S1615531D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88226127
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	mitsubishi
Model	LANCER-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5062343252-04
Cover Note Number	

### Driver

Name of Driver	TAN KIM CHENG
NRIC No	S1167206Z
Date Of Birth	04/11/1956
Occupation	INDOOR
Date Of Driving Pass	02/09/1978
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84038262
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 341 CLEMENTI AVE 5 #09-146
Postcode	120341
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG7235H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	83224309
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE


VEHICLE NO: SCL 629117  
ACCIDENT DATE: 3/1/18


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.**

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
CHARN'S CUSTOMCRAFT  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten notes in the 'DESCRIBE CIRCUMSTANCES OF THE ACCIDENT' section include 'refer to attached' written across several lines.

At the bottom of this section, there is a row of four checkboxes:
   
OWN DAMAGE ( )    3RD PARTY CLAIM ( )    REPORTING ONLY ( )    OWN WORKSHOP ( )
   
The '3RD PARTY CLAIM' and 'OWN WORKSHOP' checkboxes are marked with a checkmark.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

(X)

Policyholder's Signature  
Date & Time:

4/1/18


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



CHARN'S CUSTOMCRAFT

Reporting Centre Personne's Signature  
Name:  
NRIC/FIN No.:

MY VEHICLE WAS STATIONARY CLEMENTI AVE 4 OPENSOURCE  
CARPARK BESIDE BLK 308(COFFEEHOUSE PARKING LOT). I SAW  
THERE IS A LORRY PARKED BESIDE MY VEHICLE .SUDDENLY, THE  
LORRY START THE ENGINE AND DROVE FORWARD AND THE LORRY  
LEFT HAND SIDE METAL PARTS HIT ONTO MY DRIVER DOOR.

TAN KIM CHENG  
S1167206Z





## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5531D

### Vehicle Details

Vehicle No.: SCL6291M

Vehicle to be Exported: No

Intended De-registration Date: 10 Jan 2018

Vehicle Make: MITSUBISHI

Vehicle Model: LANC 1.6GLXI

Primary Colour: Silver

Manufacturing Year: 1996

Engine No.: 4G92GC9905

Chassis No.: CSRCK4ATU00573

Maximum Power Output: -

Open Market Value: \$18,788.00

Original Registration Date: 08 May 1996

First Registration Date: 08 May 1996

Transfer Count: 1

Actual ARF Paid: \$28,182.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 Sep 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$29,608.00

COE Rebate Amount: \$16,119.00

Total Rebate Amount: \$16,119.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jan 2018

## View Sent Message

This mail is associated with :

**\*SCL6291M (544676)**  
**[GBG7235H]**

TP  
TAN GEK HUAY  
Jan 3 2018 11:00AM  
[THOMSON FOODSTUFF MANUFACTURING]  
Car Body Repair

Resend	View Recipients	Print Message	Delete Message	Forward
--------	-----------------	---------------	----------------	---------

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 26/03/2018 18:44 PM.  
**To** MSIG\_CWSF1  
**Subject** Pre-repair Inspection

Dear Christina,

Refer to your assignment on 05.01.2018 at 6.20PM.

Please be informed that we have inspected the vehicle SCL 6291M on 08.01.2018 at 1PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2018		05 Jan 2018 18:20 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** **[Created by insurer]**

Insured:	<b>THOMSON FOODSTUFF MANUFACTURING</b> , Co. Reg. No.: 52858600M		
Main Claimant:	<b>TAN GEK HUAY</b> , ID: S1615531D		
Vehicle Reg. No.:	<b>SCL6291M</b>	Date of Loss:	03/01/2018 11:00 - :59
Claim Type:	<b>TP / 544676</b>	Policy/Cover Note No.:	A29034638MKC (Comprehensive) Coverage: 11/10/2017 - 10/10/2018
Vehicle Reg. No. (Insured):	<b>GBG7235H</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Car Body Repair (HQ)</b> BLK 1004 #01-29 BUKIT MERAH LANE 3, 159720 Bukit Merah - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Imm.Advice due 06/01/2018]</b>		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

































There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SCL6291M (544676)**  
**[GBG7235H]**  
**TP**  
**TAN GEK HUAY**  
**Jan 3 2018 11:00AM**  
**[THOMSON FOODSTUFF MANUFACTURING]**  
**Car Body Repair**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Assessment Reports</b>				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	08/01/18 17:05	<b>Accident Statement</b> From:SC - Reg. No: GBG7235H, Claimant: THOMSON FOODSTUFF MANUFACTURING		Load HTM	
<b>Photos/Images</b>				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	26/03/18 18:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
25	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
26	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
27	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
28	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
29	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
30	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
31	26/03/18 18:43	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>

32	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
33	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
34	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
35	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
36	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
37	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
38	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
39	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
40	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
41	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
42	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
43	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
44	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
45	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
46	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
47	26/03/18 18:43	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	08/01/18 17:05	SCL6291M GIA Rpt From:SC - Reg. No: GBG7235H, Claimant: THOMSON FOODSTUFF MANUFACTURING	1	Load PDF	
2	05/01/18 18:20	PRI - Name of Workshop	1	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%; position: relative;"> <div style="position: absolute; top: 0; right: 0; text-align: center;"> <span>^</span>  <span>v</span> </div> </div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000383/GBE2

Date: 28/03/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29034638MKC

Claimant Vehicle No : SCL6291M

Insured Vehicle No : GBG7235H

Date of Loss: 03/01/2018

Nature of Claim: TP

Claim No: 544676

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCL6291M

Make &amp; Model: MITSUBISHI LANCER, 1.6 GLX (A)

Engine No: 4G92GC9905

Reg. Date: 08/05/1996 (Man. Year: 1996)

Chassis No: CSRCK4ATU00573

Colour: Silver

Odometer: 730217 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Champiro 6 mm

Rear Left Side: Champiro 6 mm

Front Right Side: Champiro 6 mm

Rear Right Side: Champiro 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 05/01/2018

Date Inspected: 08/01/2018 Inspected At:

Car Body Repair (HQ)  
BLK 1004 #01-29 BUKIT MERAH LANE 3  
Singapore 159720

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 -\$2,500.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 28 Mar 2018)  
**Parts:** 143      MITSUBISHI LANCER 1.6 GLX (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SCL6291M)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >