

ASS. REC. BY:

REF: CS/SPF18000401/Uqbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office) ✓

From (Person): Abdul Rohman

of SPF

Date/Time: 80012018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 5956L

Insured: QX 785R

at Workshop m/s Pegasus

Tel: 6858 5151

of 51 Deful Lane 10

Policy No:

Claim No: AEMD/105/009/2017/168

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 11-12-2017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 30012018

Person Contacted: William

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	Not finalise
	SLT 5956L - X	
	QX 785R -	

Suzuki, mercury

REF:

SPT /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL75956L

at Workshop mis negocus

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL75956L Yr Regn: 11 17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda Vezel Hybrid: 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 18111 T.Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU 31225936

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.5 / 60 R15

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 11/1/17 D.O.I. 8/1/18

Survey held at _____

Des. of Damages: Ren / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>2/1/18</u>	<u>summ. p H/S #2600 (red @ 3877-36, 60%)</u>

RECEIVED 05 FEB 2018

Date/Time, File Pass to? : Preli. Report

1) 05/2/18 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$ _____) (\$ + RS _____)

: Interview (\$ _____) Photos

: Tech Invs (\$ _____) Others

: Weekend (\$ _____)

Report Format: TP

Lump Sum / B.I. (\$) 2600

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18000401/Uqb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 08-01-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 785R	Veh. Inspected	SLT 5956L
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2017/168	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/12/2017	Inspection Date	08/01/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. : 09/SPF18000401/1466
 Policy Type: OD / TP / TP RES / TL / EVA

SLT 5956L

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No				
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor (Maven): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

	Y-Date	N-Date	Y-Date	N-Date
C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	✓			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	✓			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	✓			
---------------------------	---	--	--	--

Check By: [Signature] | 05/07/18
 Case Handler | Date



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref: SLT5956L

Our Ref: AEMD/105/009/2017/168

Date: 13 December 2017

Tel: 64784840
Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT ON 11 DECEMBER 2017 INVOLVING GOVT VEHICLE QX785R AND YOUR CLIENT'S VEHICLE SLT5956L

We refer to the above matter.

- 2 Kindly arrange for an Inspection of vehicle no. **SLT5956L** at **Messrs Pegasus Engrg & Tdg Pte Ltd @ Tan Lim Motor Pte Ltd** of **51 Defu Lane 10**, Singapore **539216**.
- 3 For appointment kindly contact **Tel: 68585151**.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLT5956L
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	LEB5925948
Chassis No.:	RU31225936
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,675.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,189.00
COE Rebate Amount:	\$48,263.00
Total Rebate Amount:	\$52,013.00

The information contained herein is correct as at 08 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 10:37
Date Of Accident	11/12/2017 19:15
Exact Location Of Accident	MARSILING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5956L
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PYE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98235896

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20173049

Driver

Name of Driver	GERARD RAMESH S/O VATHILINGAM
NRIC No	S7208519A
Date Of Birth	09/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	19/05/1995
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91443281
Fax Number	
Contact Number	
EEmail Address	GERARDGR29@GMAIL.COM

Address	BLK 572B WOODLANDS AVENUE 1 #15-832
Postcode	732572
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report T/20171211/2192

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX785R
Vehicle Make/Model/Colour	HYUNDAI/AVANTE 1.6 AT ABS D
Details Of Properties	
Name of Driver	ALZIN SHAFIQ
NRIC/Passport Number	
Contact Number	96186131
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 12.12.2017 @ 0936hrs


Reporting Centre Personnel's Signature
Name: Caymen
NRIC/FIN No.: G2859646X

Sketch Plan Pg. 2

SKETCH PLAN

A: SLT 5956L

B: GX 785R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report
T/20171211/2192

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 12.12.2017 @ 0930hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Caywan
G2859646X



**SINGAPORE
POLICE FORCE**



T/20171211/2192

1 of 3

Report No. T/20171211/2192

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/12/2017 21:22	Vide Report No.:	Station Diary No.: 170
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: GERARD RAMESH S/O VATHILINGAM		Address: APT BLK 572B WOODLANDS AVENUE 1 #15-832 SINGAPORE 732572	
ID Type / ID No.: NRIC NO / S7208519A		Contact No.:	Mobile: 91443281
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 45	Date of Birth: 09/03/1972	Type of Informant: Driver
Race: Indian		Language:	Institution / School Name:
Occupation: Grabcar Driver		Driving Licence Information: Class: 2B,3,4,5	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 11/12/2017 19:05	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 MARSILING ROAD WOODLANDS CENTRE ROAD After Marsiling Road Shell Station				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX785R	Car				Slightly Damaged	0
SLT5956L	Car	HONDA	Vezzel	Blue	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20171211/2192

2 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20171211/2192

CONTINUATION OF REPORT

Driver			
Name	Alzrin Shafiq	ID No.	NIL
Related Vehicle	QX785R (Car)	Contact No.	96186131
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	GERARD RAMESH S/O VATHILINGAM	ID No.	S7208519A
Related Vehicle	SLT5956L (Car)	Contact No.	91443281
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/12/2107 at about 1905hrs I was driving along Marsiling Road towards Woodlands Centre Road. After passing by the Shell Station along Marsiling Road, I slowly stopped to make a U turn to go to Blk 12 Marsiling Lane to pick up a passenger. I waited for about a minute for the traffic opposite to clear when suddenly a Police vehicle QX785R hit on to the rear of my vehicle. I then went down from my vehicle and discovered that the rear of my vehicle was dented and damaged. The Police Officer identify himself as SSgt Alzrin Shafiq hp 96186131 from Jurong Division and informed me that he tried to stop but his brake failed. He then asked me to lodge a Police report regarding the matter. Both parties were not injured. The front portion of the Police vehicle was also dented due to the collision.



**SINGAPORE
POLICE FORCE**



T/20171211/2192

. 3 of 3

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20171211/2192

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 LIM MUHAMMAD HAMZAH BIN
MUHAMMAD ISMAIL LIM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/12/2017 21:22

Officer In Charge Of Case:

TP / DDGVT /

Classification Of Case:

Contact No.:

Authentication Stamp
NP168

Signature:

SN 130

Singapore Police Force



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

*not added
then
take to be kept
3 days
8/1/18
Rev
LKR
Maras
1100*

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 SINGAPORE 539216
 Officer in Charge : ALVIN LOW WAI LUN
 Tel :
 Email : 66784848

Customer :
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
 Attn :
 Tel :
 Fax : LKR
 Maras
 1100

Quotation No : QO17/12-1112	Quotation Date : 12/12/2017	Terms : 30 DAYS
Vehicle No : SLT5956L	Chassis No : RU31225936	Third Party Insurer :
Model : VEZEL	Date of Accident :	
Remarks : TP INSURER: ATTORNEY GENERAL CHAMBERS, INSURED VEHICLE NUMBER: QXZ785R , DATE OF ACCIDENT: 11/12/2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	TAILGATE LID <i>Sub 2D</i>	1	953.3000	953.30 ✓
2	TAILGATE LID LOCK TOP <i>tm</i>	1	180.0000	180.00 ✓
3	TAILGATE LID WEATHERSTRIP <i>tm</i>	1	135.0000	135.00 ✓
4	TAILGATE LID reflector <i>11</i>	1	56.3000	56.30 ✗
5	TAILGATE LID .reflector <i>11</i>	1	66.2000	66.20 ✗
6	TAILGATE LID INNER TRIMBOARD <i>11</i>	1	225.0000	225.00 ✗
7	TAILGATE LID RUBBER STOPPER <i>11</i>	2	22.5000	45.00 ✗
8	TAILGATE LID KEYLESS SENSOR <i>11</i>	1	85.6000	85.60 ✗
9	TAILGATE LID DAMPER <i>11</i>	1	18.0000	18.00 ✗
10	REAR WINDSHIELD GLASS WEATHERSTRIP <i>ru</i>	1	120.0000	120.00 ✓
11	REAR END PANEL <i>~</i>	1	514.0000	514.00 ✗
12	REAR END PANEL INNER TRIM <i>11</i>	1	92.3000	92.30 ✗
13	REAR END PANEL INNER TRIM CLIPS <i>11</i>	6	4.3000	25.80 ✗
14	REAR BUMPER CENTRE <i>no/o.e</i>	1	762.2000	762.20 ✓
15	REAR BUMPER REFLECTOR <i>11</i>	2	141.0000	282.00 ✗
16	REAR BUMPER SCREW SPACER <i>11</i>	2	12.0000	24.00 ✗
17	REAR BUMPER SIDE <i>~</i>	1	95.0000	95.00 ✗
18	REAR BUMPER SIDE RETAINER <i>11</i>	2	23.0000	46.00 ✗
19	REAR BUMPER CLIPS <i>ru</i>	10	3.9000	39.00 ✓
20	REAR BUMPER DIFFUSER COVER <i>11</i>	1	95.0000	95.00 ✗
21	REAR BUMPER DIFFUSER COVER CLIPS <i>11</i>	8	3.5000	28.00 ✗
22	REAR LAMP <i>11</i>	1	542.0000	542.00 ✗
23	REAR LAMP CLIP HOLDER <i>11</i>	1	4.5000	4.50 ✗

*2189.5
1751.6*



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 SINGAPORE 539216
 Officer in Charge : ALVIN LOW WAI LUN
 Tel :
 Email :

Customer :
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
 Attn :
 Tel :
 Fax :

Quotation No : QO17/12-1112	Quotation Date : 12/12/2017	Terms : 30 DAYS
Vehicle No : SLT5956L	Chassis No : RU31225936	Third Party Insurer :
Model : VEZEL	Date of Accident :	
Remarks : TP INSURER: ATTORNEY GENERAL CHAMBERS, INSURED VEHICLE NUMBER: QXZ785R , DATE OF ACCIDENT: 11/12/2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	LESS 20% (ITEMS 1-23)	1	-886.8400	-886.84
25	REAR WINDSHIELD GLASS SEALANT <i>see</i>	1	180.0000	<i>40</i> 180.00
26	REAR WINDSHIELD GLASS INNER SPONGE SEAL <i>see</i>	1	100.0000	<i>30</i> 100.00
27	REAR BUMPER CENTRE PARKING SENSOR <i>shard</i>	1 <i>set</i>	450.0000	<i>200</i> 450.00
28	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	30.0000	<i>20</i> 30.00
29	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	<i>50</i> 120.00
30	TO TRANSFER AND REFIT INTERIOR FITTINGS, FIXTURE AND PERFORM WATER SEEPAGE TEST	1	80.0000	<i>60</i> 80.00
31	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	120.0000	<i>✓</i> 120.00
32	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	800.0000	<i>400</i> 800.00
33	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	<i>600</i> 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3271.60
2617

Sub Total 6,427.36
GST(7.00%) 449.92
Total (SGD) 6,877.28

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18000401/Uqbn2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 07-02-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 785R	Veh. Inspected	SLT 5956L
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2017/168	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	08/01/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31225936	Colour	BLUE
Odometer	18111	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2017	Inspection Date	08/01/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5956L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LID	BADLY DENTED	953.30	953.30
1	TAILGATE LID LOCK TOP	TWISTED	180.00	180.00
1	TAILGATE LID WEATHERSTRIP	TWISTED	135.00	135.00
1	TAILGATE LID REFLECTOR	NOT NECESSARY	56.30	-
1	TAILGATE LID REFLECTOR	NOT NECESSARY	66.20	-
1	TAILGATE LID INNER TRIMBOARD	NOT NECESSARY	225.00	-
2	TAILGATE LID RUBBER STOPPER @\$22.50	NOT NECESSARY	45.00	-
1	TAILGATE LID KEYLESS SENSOR	NOT NECESSARY	85.60	-
1	TAILGATE LID DAMPER	NOT NECESSARY	18.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NECESSARY	120.00	120.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	514.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	92.30	-
6	REAR END PANEL INNER TRIM CLIPS @\$4.30	NOT NECESSARY	25.80	-
1	REAR BUMPER CENTRE	DENTED / DEFORMED	762.20	762.20
2	REAR BUMPER REFLECTOR @\$141.00	NOT NECESSARY	282.00	-
2	REAR BUMPER SCREW SPACER @\$12.00	NOT NECESSARY	24.00	-
1	REAR BUMPER SIDE	TO REPAIR SEE LABOUR	95.00	-
2	REAR BUMPER SIDE RETAINER @\$23.00	NOT NECESSARY	46.00	-
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR BUMPER DIFFUSER COVER	NOT NECESSARY	95.00	-
8	REAR BUMPER DIFFUSER COVER CLIPS @\$3.50	NOT NECESSARY	28.00	-
1	REAR LAMP	NOT NECESSARY	542.00	-
1	REAR LAMP CLIP HOLDER	NOT NECESSARY	4.50	-
	LESS 20% DISCOUNT		-886.84	-437.90
			3,547.36	1,751.60
SPECIAL NETT ITEMS				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NECESSARY	180.00	40.00
1	REAR WINDSHIELD GLASS INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SET REAR BUMPER CENTRE PARKING SENSOR (SN)	SHORTED	450.00	200.00
			730.00	270.00

Report Ref No. CS/SPF18000401/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		30.00	20.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO TRANSFER AND REFIT INTERIOR FITTINGS, FIXTURE AND PERFORM WATER SEEPAGE TEST.		80.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR BUMPER SIDE.		800.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,000.00	600.00
			2,150.00	1,250.00
	GRAND TOTAL		6,427.36	3,271.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CS/SPF18000401/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.