



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475 Fax : 6844 2474
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

India International Insurance Pte Ltd
 64 Cecil Street #05-00
 IOB Building
 Singapore 409711

Vehicle number	: SLA29X
Make / Model	: TOYOTA/VELLFIRE
Chassis number	: AGH300022205
Accident date	: 13 December 2017
Reference	: 1712-33

3RD PARTY CLAIM ESTIMATION

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT LH HEADLAMP <i>Scratched</i>	3918.00 ✓
1	FRONT LH HEADLAMP LOWER BRACKET <i>SVL</i>	438.00 ✗
1	FRONT BUMPER <i>Cut</i>	2250.00 ✓
1	FRONT BUMPER REINFORCEMENT <i>HN</i>	542.40 ✗
1	FRONT BUMPER RETAINER <i>CV&UC</i>	80.40 ✓
1	FRONT BUMPER SIDE GRILLE <i>HN</i>	282.00 ✗
1	FRONT BUMPER SIDE GRILLE MOULDING <i>HN</i>	63.30 ✗
1	FRONT LH FOG LAMP <i>HN</i>	343.20 ✗
1	FRONT GRILLE ASSY <i>HN</i>	1783.20 ✗
1	FRONT GRILLE EMBLEM <i>HN</i>	100.80 ✗
1	FRONT LH FENDER <i>ryan</i>	917.80 ✗
1	FRONT LH FENDER INNER SHIELD <i>SVL</i>	3012.40 ✓
		13731.50
	Less 25 %	3432.87
	Subtotal	10298.63
	Balance C/F	10298.63
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	10298.63
1 SET	FRONT BUMPER CLIP <i>the</i>	60.00 30/-
1 SET	FRONT FENDER INNER TRIM CLIP <i>SVL</i>	60.00 ✗
1	RIM <i>Cut</i>	1200.00 500/-
	Subtotal	1320.00
	Balance C/F	11618.63
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	11618.63
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	PANEL BEATING ON AFFECTED AREAS	800.00 500/-
3	SPRAY PAINTING ON AFFECTED AREAS	800.00 400/-
4	APPLY ANTI-RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	1810.00
	Grand total	13428.63

LKK Auto Consultants Inc. is the Repairer of the following:
 • To ensure proper spray painting
 • To display proper repair
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: *ryan*
 Date:

09/01/2018 21100hrs
 HWT Andrew
 L/S Ryan
 3 days.
 LKK Auto Check part prices.