

Summary

Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No _____
 Sum Insured: _____ Excess _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ver No: **SHC 12070** Ver Date: **19 Apr 2012**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Hyundai Santa Fe** 1991
 Colour: **Blue** A.C. Insured / Std / NI / NA
 Sp Reading: **209863** T Radio Insured / Std / NI / NA
 Eng/No: _____
 C/No: **KMHETXIVMCA822982**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size F: **215/60R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Went/ta**
 Front: _____ Rear: _____
 R/Bal: **7** mm R/Bal: **7** mm
 L/Bal: **7** mm L/Bal: **7** mm
 D.O.A: **3/1/08** D.O.I: **5/1/08**
 Survey held at: **(DHE (hwy))**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CTI
4s

Date/Time File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time File Return to?

0

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Ins \$

☐ Weekend \$

Report Format :

Lump Sum / I.B.I. / S

OMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 B Kallang Road Singapore 372701
Mainline + 65 6383 6250 Faxline + 65 6320 9755

Workshops
59 Loyang Drive Singapore 508965 24 Serangoon Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 6 Delta Avenue 1 Singapore 539537
322 Jln Rumpun Singapore 688441

member of COMFORTDELGRO

Date/Time: 04.01.2018 12:42

Page : 1

am: IN ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305103898

OMER	REGN NO: SHC1207D	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO. 7010045	MODEL SONATA	E.....1/2.....F
ESS 383 SIN MING DRIVE	DATE/TIME IN 04.01.2018 10:40	
Singapore SINGAPORE 575717	YR OF MANU 19.04.2012	TARGET DATE
65508755 (R) (O)	CHASSIS CODE KMHET41VMCA822982	COMPLETION DATE/TIME:
(P)		
DUNT CARD NO.		

JOB DESCRIPTION

ccident Date: 03.01.2018
ATURE: 3P 03.01.18

/NO LABOR CODE DESCRIPTION

CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC1207D LIMITS

Vehicle No.: SHC1207D

f Service Advisor

Signature/Date

Name of Service Advisor

Date

owed to Service Reception upon collection

To be kept by Security Guard