





PRE-REPAIR INSPECTION REPORT				
FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI18000435/Wd3s2		
36 ROBINSON ROAD		Date: 12-04-2018		
#16-01 CITY HOUSESINGAPORE 068877				
		Code: FCI2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHD 7196G	Veh. Inspected	FBD 4353K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011724MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA X-1R	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	4S3010046	Colour	BLACK	
Odometer	32845 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	DUNLOP	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	DUNLOP	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.				
5. General Information				
Accident Date	17/12/2017	Inspect Date / Time	18/01/2018 (03:22 PM)	
Survey held at	ALPS AUTO (JC MOTOR)- 13 KAKI BUKIT ROAD 4 #01-16			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE:\$2,000.00				

Report Ref No. CS3/FCI18000435/Wd3s2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.